

\\T.R.M.U.A.Main Location\REHABILITATION

53 - 2008 CHEVROLET C4500

2008 CHEVROLET C4500

Unit #: 53 Serial #: 1GBE4V1948F405912
 Tag #: XR-802C GEN. MAKE ONAN CMQD7500
 Mileage 29,286 GEN. MODE 7.5HDKAT41934K

Date	Mileage	Notes	Vendor	Employee	Total Cost
10/9/2008	2,423				\$0.00
Maintenance Performed					Cost
OIL,FUEL AND AIR FILTER check fluids					\$0.00
Total:					\$0.00
Part					Used
Name					Unit Cost
WIX-57202					1
					\$0.00
Total:					\$0.00
10/24/2008	2,423				\$0.00
Maintenance Performed					Cost
Lettered truck					\$0.00
Installed apc batt. backup and wired for computers					\$0.00
Total:					\$0.00
1/9/2009	2,752				\$0.00
Maintenance Performed					Cost
Replaced bullets on both cameras					\$0.00
Installed company radio and 2 speakers with volume controls					\$0.00
Total:					\$0.00
2/10/2009	2,816				\$0.00
Maintenance Performed					Cost
Replaced drive gear for lateral launcher					\$0.00
Total:					\$0.00
8/5/2009	4,578				\$0.00
Maintenance Performed					Cost
Removed p.c. to install new wireless card.did not have space for another card on mother board					\$0.00
Total:					\$0.00
8/14/2009	4,646				\$0.00
Maintenance Performed					Cost
Repaired bullet for lat. camera					\$0.00
Apoxyed handle for locator still does not function					\$0.00
Total:					\$0.00
10/20/2009	5,200				\$0.00
Maintenance Performed					Cost
OIL,FUEL AND AIR FILTER check fluids					\$0.00
serviced gen.					\$0.00
Total:					\$0.00

Part	Name	Used	Unit Cost	Cost
WIX-33063		1	\$0.00	\$0.00
WIX-51064		1	\$0.00	\$0.00
WIX-57202		1	\$0.00	\$0.00
WIX-33910		1	\$0.00	\$0.00
Total:				\$0.00
1/7/2010	5,440			\$0.00
Maintenance Performed				Cost
Replaced water supply pump for sink and hose				\$0.00
Total:				\$0.00
2/1/2010	5,440			\$0.00
Maintenance Performed				Cost
Replaced Sprocket in camera for lateral launcher				\$0.00
Total:				\$0.00
10/28/2010	7,673			\$0.00
Maintenance Performed				Cost
OIL,FUEL AND AIR FILTER check fluids				\$0.00
Total:				\$0.00
Part	Name	Used	Unit Cost	Cost
WIX-57202		1	\$0.00	\$0.00
WIX-33910		1	\$0.00	\$0.00
Total:				\$0.00
6/30/2011	9,229			\$0.00
Maintenance Performed				Cost
installed thermostast for A.C. unit				\$0.00
Total:				\$0.00
8/2/2011	9,249			\$0.00
Maintenance Performed				Cost
installed new drive motor for latteral camera				\$0.00
Total:				\$0.00
11/10/2011	9,943			\$0.00
Maintenance Performed				Cost
OIL,FUEL AND AIR FILTER check fluids				\$0.00
Total:				\$0.00
Part	Name	Used	Unit Cost	Cost
WIX-33910		1	\$0.00	\$0.00
WIX-57202		1	\$0.00	\$0.00
Total:				\$0.00
12/9/2011	9,943			\$0.00
Maintenance Performed				Cost
rewired bullet for camera				\$0.00
Total:				\$0.00
5/9/2012	10,819			\$0.00

Maintenance Performed				Cost
replaced side steps on side of truck				\$0.00
repaired ethernet socket on side of truck				\$0.00
Total:				\$0.00
6/27/2012	11,034			\$0.00
Maintenance Performed				Cost
replaced switch for beacons				\$0.00
replaced both rear bulbs for flood lights				\$0.00
Total:				\$0.00
11/30/2012	12,013			\$0.00
Maintenance Performed				Cost
OIL, FUEL AND AIR FILTER check fluids				\$0.00
WELDED REAR BUMPER				\$0.00
Total:				\$0.00
Part	Name	Used	Unit Cost	Cost
WIX-57202		1	\$0.00	\$0.00
WIX-33960		1	\$0.00	\$0.00
Total:				\$0.00
12/12/2012	12,013			\$0.00
Maintenance Performed				Cost
added aluminum plate to radio att.				\$0.00
replaced bulb in rear work light				\$0.00
Total:				\$0.00
2/28/2013	12,615			\$0.00
Maintenance Performed				Cost
replaced 2 group 31 screw top batt.				\$0.00
Total:				\$0.00
4/24/2013	12,974			\$0.00
Maintenance Performed				Cost
repaired steps on side of truck				\$0.00
Total:				\$0.00
10/28/2013	14,882			\$0.00
Maintenance Performed				Cost
OIL, FUEL AND AIR FILTER check fluids				\$0.00
Total:				\$0.00
Part	Name	Used	Unit Cost	Cost
WIX-57202		1	\$0.00	\$0.00
WIX-33960		1	\$0.00	\$0.00
Total:				\$0.00
5/5/2014	15,992			\$0.00
Maintenance Performed				Cost
replaced flood work lamps with LED				\$0.00
replaced bulb in directional arrow stick				\$0.00
Total:				\$0.00
7/23/2014	16,244			\$0.00

					Maintenance Performed	Cost			
					replaced trasfer switch	\$0.00			
					Total:	\$0.00			
12/16/2014	17,278						\$0.00		
					Maintenance Performed	Cost			
					OIL,FUEL AND AIR FILTER check fluids	\$0.00			
					Total:	\$0.00			
					Part	Name	Used	Unit Cost	Cost
					WIX-33960		1	\$0.00	\$0.00
					Total:			\$0.00	
7/1/2015	18,010								\$0.00
					Maintenance Performed	Cost			
					replaced rocker switch for beacon	\$0.00			
					Total:	\$0.00			
1/6/2016	19,572								\$0.00
					Maintenance Performed	Cost			
					OIL,FUEL AND AIR FILTER check fluids	\$0.00			
					Total:	\$0.00			
8/31/2016	20,450								\$0.00
					Maintenance Performed	Cost			
					replaced ethernet quil connect male and female	\$0.00			
					Total:	\$0.00			
11/29/2016	21,659								\$0.00
					Maintenance Performed	Cost			
					OIL,FUEL AND AIR FILTER check fluids	\$0.00			
					Total:	\$0.00			
11/29/2017	24,000								\$0.00
					Maintenance Performed	Cost			
					OIL,FUEL AND AIR FILTER check fluids	\$0.00			
					Total:	\$0.00			
1/25/2018	24,343								\$0.00
					Maintenance Performed	Cost			
					replaced drivers side mirror	\$0.00			
					Total:	\$0.00			
5/11/2018	25,271								\$0.00
					Maintenance Performed	Cost			
					replaced light fixture in control room	\$0.00			
					Total:	\$0.00			
12/6/2018	27,082								\$0.00
					Maintenance Performed	Cost			
					OIL,FUEL AND AIR FILTER check fluids	\$0.00			
					Total:	\$0.00			
6/11/2019	28,404								\$0.00
					Maintenance Performed	Cost			
					Replaced 4 rear tires	\$0.00			
					Total:	\$0.00			

Total:	Cost Per Mi/Km/Hr:	\$0.00	\$0.00
Grand Total:			\$0.00