14:34

<u>Display criteria</u> Period : All

Vehicle(s): Ford/Expedition/2013

Vehicle: 67-65 - Ford/Expedition/2013/HPB-8115

Install new and used lighting and radio equipment. (Service) **Service:** Technician responsible: N/D Date: 6/30/2013 Cost: \$4,380.00 IN000097449 Metropolitan Communications **Reference:** Vendor responsible: **Odometer: Unit cost Total cost Description** Qty. Type Other Install new and used lighting and radio equipment 1.00 \$4,380.00 \$4,380.00 \$4,380.00 Total service:

Service:Changed oil. (Service)Date:5/30/2013Technician responsible: N/DCost:\$35.50Reference:45805Vendor responsible: Thorntons GulfOdometer:3,764

Type Description Qty. Unit cost Total cost

TypeDescriptionQty.Unit costTotal costOtherChanged oil.1.00\$35.50\$35.50Total service : \$35.50

Service: Changed oil. (Service)

Date: 7/1/2013 **Technician responsible**: N/D **Cost**: \$35.50

Reference: 45792 **Vendor responsible**: Thorntons Gulf **Odometer**: 7,800

TypeDescriptionQty.Unit costTotal costOtherChanged oil.1.00\$35.50\$35.50Total service : \$35.50

My company
Page 1 of 7

Service :	Rotated tires	and lubed steering stops. (Service)			
Date:	8/2/2013	Technician responsible : N/D		Cost:	\$30.90
Reference:	C35754	Vendor responsible: Garnet Ford		Odometer:	10,006
Type	Description	on	Qty.	Unit cost	Total cost
Other	Rotated ti	res and lubed steering stops.	1.00	\$30.90	\$30.90
			Total ser	vice:	\$30.90

Total service : \$30.90

Service: Rotated tires, changed oil, checked brakes, repaired horn, replac Date: 11/6/2013 Technician responsible: N/D		Technician responsible: N/D	les in Temotes. (\$56.15	
Reference :	C41104	Vendor responsible: Garnet Ford		Cost : Odometer :	15,634
Type	Description		Qty.	Unit cost	Total cost
Other	Rotated tires, in remotes.	changed oil, checked brakes, repaired horn, replaced batteries	1.00	\$56.15	\$56.15

Service :	Changed oil. (Se	rvice)			
Date : Reference :	10/4/2013 45861	Technician responsible : N/D Vendor responsible : Thorntons Gulf		Cost: Odometer:	\$35.50 13,107
Type	Description		Qty.	Unit cost	Total cost
Other	Changed oil.		1.00	\$35.50	\$35.50
			Total ser	vice :	\$35.50

Service :	e: Changed oil, 4 wheel tire rotation and balancing, inspection and emissions, multi point inspection. (Service)							
Date :	2/25/2014	Technician responsible : N/D		Cost:				
Reference :	C46513	Vendor responsible: Garnet Ford		Odometer:	22,946			
Type	Description		Qty.	Unit cost	Total cos			
Other	Changed oil, 4 multi point in	4 wheel tire rotation and balancing, inspection and emissions, spection.	1.00	\$166.55	\$166.55			

My company Page 2 of 7

Total service: \$166.55

Service :	Changed oil. (Se	rvice)			
Date:	6/30/2014	Technician responsible : N/D		Cost:	\$35.50
Reference:	45688	Vendor responsible : Thorntons Gulf		Odometer:	29,810
Type	Description		Qty.	Unit cost	Total cost
Other	Changed oil.		1.00	\$35.50	\$35.50
			Total sa	omvica :	\$35.50

Total service: \$35.50

Service :	Disconnected d	aytime running lights an	nd courtesy parking lights. (Se	ervice)		
Date:	8/11/2014	Technician responsible	: N/D		Cost:	\$89.90
Reference:	C56304	Vendor responsible :	Garnet Ford		Odometer:	30,832
Type	Description			Qty.	Unit cost	Total cost
Other	Disconnected	l daytime running lights and c	courtesy parking lights.	1.00	\$89.90	\$89.90
-				m . 1		Φοο οο

Total service: \$89.90

Service :	-	d Emissions. Change oil and filter. Rotate tires. Retrieve brake pads and rotors. (Service)	e keyless entry c	code. Front Brake p	ads
Date :	4/16/2015	Technician responsible : N/D		Cost:	\$963.03
Reference:	C69306	Vendor responsible: Garnet Ford		Odometer:	36,688
Type	Description		Qty.	Unit cost	Total cost
Other		and Emissions. Change oil and filter. Rotate tires. Retrieve ode. Front Brake pads and rotors, Rear brake pads and	1.00	\$963.03	\$963.03

Total service: \$963.03

My company Page 3 of 7

Service :	Front end boo	dy work. Collision damage. (Service)			
Date : Reference :	4/3/2015 4590	Technician responsible : N/D Vendor responsible : GA Collision		Cost : Odometer :	\$6,348.29 35,308
Type	Description	n	Qty.	Unit cost	Total cost
Other	Front end	body work. Collision damage.	1.00	\$6,348.29	\$6,348.29
			Total se	prvice ·	\$6 348 29

Total service: \$6,348.29

Service :	Oil and filter ch	nange (Service)			
Date : Reference :	3/1/2016 45042	Technician responsible : N/D Vendor responsible : Thorntons Gulf		Cost : Odometer :	\$39.50 42,000
Type	Description		Qty.	Unit cost	Total cost
Other	Oil and filter	change	1.00	\$39.50	\$39.50
•			Total ser	vice ·	\$39.50

Total service: \$39.50

Service :	State inspecti	on & emissions test. (Service)			
Date : Reference :	5/2/2016 C91697	Technician responsible : N/D Vendor responsible : Garnet Ford		Cost : Odometer :	\$55.50 42,555
Type	Descriptio	n	Qty.	Unit cost	Total cost
Other	State inspe	ection & emissions test.	1.00	\$55.50	\$55.50
			Total say	nica:	\$55.50

Total service: \$55.50

Service :	Repair drivers side window regulator. Retrieve keyless code. CODE:55197 (Service)					
Date:	6/23/2016	Technician responsible : N/D		Cost:	\$403.94	
Reference:	C94550	Vendor responsible: Garnet Ford		Odometer:	43,758	
Type	Description		Qty.	Unit cost	Total cost	
Other	Repair driver	rs side window regulator. Retrieve keyless code. CODE:55197	1.00	\$403.94	\$403.94	
			Total sei	rvice ·	\$403.94	

\$403.94 Total service:

My company Page 4 of 7

Service :	Oil and Filter C	hange, Purchase and replace front Rotors (Service)			
Date:	12/7/2016	Technician responsible : N/D		Cost:	\$418.92
Reference:	10878	Vendor responsible : Mike Ivey's Auto Repair, Inc.		Odometer:	46,515
Type	Description		Qty.	Unit cost	Total cost
Other	Oil and Filter	Change, Purchase and replace front Rotors	1.00	\$418.92	\$418.92
•			Total ser	vice :	\$418.92

Service :	State and Emissi (Service)	on Insp, Replace Wiper Blades, Replace Front Marker	Light, Replace Le	ft Strut, Alignmen	ıt.
Date :	4/2/2018	Technician responsible : N/D		Cost:	\$498.14
Reference:	44828	Vendor responsible : West Goshen Automotive		Odometer:	62,865
Type	Description		Qty.	Unit cost	Total cost
Other		sion Insp, Replace Wiper Blades, Replace Front Marker Left Strut, Alignment.	1.00	\$498.14	\$498.14
			Total ser	vice :	\$498.14

Service :	Replace Battery (Service)					
Date:	9/7/2018	Technician responsible : N/D		Cost : Odometer :		
Reference :	46338	Vendor responsible: West Goshen Automotive				
Type	Description		Qty.	Unit cost	Total cost	
Other	Replace Batter	y	1.00	\$205.26	\$205.26	
			Total service :		\$205.26	

Service :	Oil and Filter Change (Service)					
Date : Reference :	11/15/2018 7725	Technician responsible : N/D Vendor responsible : Thorntons Gulf		Cost : Odometer :	\$44.95 66,762	
Type	Description		Qty.	Unit cost	Total cost	
Other	Oil and Filter	Change	1.00	\$44.95	\$44.95	
			Total ser	vice :	\$44.95	

My company Page 5 of 7

Service :	Front Brakes and Rotors (Service)					
Date : Reference :	11/28/2018 Technician responsible : N/D 7435 Vendor responsible : Thorntons Gulf		Cost : Odometer :		\$311.00 67,050	
Type	Description		Qty.	Unit cost	Total cost	
Other	Front brakes	and rotors	1.00	\$311.00	\$311.00	
•			Total ser	vice :	\$311.00	

Oil and Filter Change (Service) **Service:** Technician responsible: N/D \$44.95 Date: 2/23/2019 Cost: Vendor responsible : 8749 Thorntons Gulf 70,337 Reference: **Odometer:** Description Qty. Type **Unit cost Total cost** Other Oil and Filter Change 1.00 \$44.95 \$44.95 \$44.95 Total service:

Service: Replace Wiper Motor Assembly (Service) 3/11/2019 Technician responsible: N/D \$315.00 Date: Cost: Vendor responsible: 70,978 **Reference:** 14459 Thorntons Gulf **Odometer:** Description Unit cost **Total cost** Type Qty. \$315.00 Replace Wiper Motor Assembly 1.00 \$315.00 Other \$315.00 Total service:

Service: Emission and State inspection, Oil and Filter Change (Service) Technician responsible: N/D 5/16/2019 \$119.95 Date: Cost: **Reference:** 14974 Vendor responsible: Thorntons Gulf **Odometer:** 73,329 **Description Total cost** Type Qty. **Unit cost** Emission and State inspection, Oil and Filter Change 1.00 \$119.95 Other \$119.95 Total service: \$119.95

My company
Page 6 of 7

Service :	Emission and	State INspection, (Service)			
Date :	6/11/2020	Technician responsible : N/D		Cost:	\$76.00
Reference:	16341	Vendor responsible : Thorntons Gulf		Odometer:	75,471
Type	Description	n	Qty.	Unit cost	Total cost
Other	Emission a	nd State Inspection	1.00	\$76.00	\$76.00
			Total service :		\$76.00

Total of the vehicle : \$14,709.93

Page 7 of 7 My company