

Lakes Region Fire Apparatus

Evaluation For Denmark Maine Engine 4

4/7/2021

VIN # 44KFT42831WZ19530.

Miles: 60,406.0

Engine Hours: 3,898.1

A) Front brakes are delaminating and worn out.

B) Steering shaft U-joints are worn, pulls to one side.

Needs front tires.

C) Rear springs are in need of replacement.

D) Wheel rims have heavy corrosion, need to be evaluated, salvaged, or replaced.

E) Left front wheel hub leaks oil.

F) Rear tow hooks and support are bent into the body.

G) Cab lift pump is failing, probably won't lift the cab many more times.

H) Paint corrosion on both cab and body should be addressed.

I) Pump Primer is inoperable, fails vacuum test.

J) Master drain valve is rotted away from mount.

K) 5 drain valves are faulty and leaking.

L) Pump cooler valve leaks.

M) Auxiliary intake valve leaks.

N) LDH Valve leaks.

O) Front suction swivel leaks from seals.

P) Front suction piping is loose from mounting.

Q) Dump valve is seized, completely inoperable.

R) 2 Emergency lights are inoperable.

S) Pump panel lights are inoperable.

T) Ground lights are inoperable.

U) Left rear scene light inoperable.

V) Some dash lights inoperable.

W) Tank To Pump indicator is inoperable.

X) Lenses missing from indicator lights on pump panel.

Y) Detroit Diesel Info And Control on pump panel has part of the screen inoperable.