Detailed services/breakdown

Display criteria
Period : All
Vehicle(s) : Dodge/Durango/2019

Vehicle : 67-92 - Dodge/Durango/2019/MG3152L

Service : Complete Upfitting of new Patrol Vehicle (Service)

Date : 5/9/2019 **Technician responsible :** N/D **Cost :** $14,245.00
Reference : IN000109061 **Vendor responsible :** Metropolitan Communications **Odometer :** 1

Type	Description	Qty.	Unit cost	Total cost
Other	Complete Upfitting of new Patrol Vehicle	1.00	$14,245.00	$14,245.00
			Total service :	$14,245.00

Service : Oil and Filter Change (Service)

Date : 7/29/2019 **Technician responsible :** N/D **Cost :** $44.95
Reference : 14219 **Vendor responsible :** Thorntons Gulf **Odometer :** 2,031

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
			Total service :	$44.95

Service : Oil and Filter Change (Service)

Date : 10/2/2019 **Technician responsible :** N/D **Cost :** $44.95
Reference : 14362 **Vendor responsible :** Thorntons Gulf **Odometer :** 6,234

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
			Total service :	$44.95

Service : Oil and Filter Change (Service)

Date : 11/22/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 14839 **Vendor responsible :** Thorntons Gulf **Odometer :** 9,428

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change (Service)

Date : 1/7/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 14870 **Vendor responsible :** Thorntons Gulf **Odometer :** 12,338

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Replace Front Brakes (Service)

Date : 1/17/2020 **Technician responsible :** N/D **Cost :** $155.00

Reference : 15756 **Vendor responsible :** Thorntons Gulf **Odometer :** 12,922

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Front Brakes	1.00	$155.00	$155.00
		Total service :		$155.00

Service : Oil and Filter Change (Service)

Date : 3/13/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 15853 **Vendor responsible :** Thorntons Gulf **Odometer :** 15,841

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Emission and State Inspection, Replce Radiator (Condensor, Evac, and Freon) (Service)

Date : 3/11/2020 **Technician responsible :** N/D **Cost :** $192.70

Reference : CHCS44878 **Vendor responsible :** Videon Dodge **Odometer :** 15,804

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection, Replce Radiator (Condensor, Evac, and Freon)	1.00	$192.70	$192.70

Total service : $192.70

Service : Oil and Filter Change (Service)

Date : 5/1/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 15919 **Vendor responsible :** Thorntons Gulf **Odometer :** 18,861

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Oil and Filter Change (Service)

Date : 6/22/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 16042 **Vendor responsible :** Thorntons Gulf **Odometer :** 21,489

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Replace the Condenser. (Service)

Date : 6/26/2020 **Technician responsible :** N/D **Cost :** $58.50

Reference : CHCS48767 **Vendor responsible :** Videon Dodge **Odometer :** 22,057

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Condenser	1.00	$58.50	$58.50

Total service : $58.50

Service : Replace passenger Headlamp Bulb and secured the connection. (Service)

Date : 8/7/2020 **Technician responsible :** N/D **Cost :** $21.01

Reference : CHCS51045 **Vendor responsible :** Videon Dodge **Odometer :** 23,070

Type	Description	Qty.	Unit cost	Total cost
Other	Replace passenger Headlamp Bulb and secured the connection.	1.00	$21.01	$21.01

Total service : $21.01

Service : Replaced the Oil Cooler, Conector Filter and Oil, Replace the Thermostat and Coolant Reservoir (Service)

Date : 8/4/2020 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS50523 **Vendor responsible :** Videon Dodge **Odometer :** 23,046

Type	Description	Qty.	Unit cost	Total cost
Other	Replaced the Oil Cooler, Conector Filter and Oil, Replace the Thermostat and Coolant Reservoir	1.00	$0.00	$0.00

Total service : $0.00

Service : Install Rear Antenna, Drain and Fill Cooling System, Rerpair and tighten Pins in Headlamp and TIPM (Service)

Date : 8/18/2020 **Technician responsible :** N/D **Cost :**

Reference : CHCS51441 **Vendor responsible :** Videon Dodge **Odometer :** 23,354

Type	Description	Qty.	Unit cost	Total cost

Total service : $0.00

Service : Mount and Balance 2 Tires (Service)

Date : 9/3/2020 **Technician responsible :** N/D **Cost :** $60.00

Reference : 16681 **Vendor responsible :** Thorntons Gulf **Odometer :** 24,088

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 Tires	1.00	$60.00	$60.00

Total service :	$60.00

Service : Oil and Filter Change (Service)

Date :	10/9/2020	**Technician responsible :**	N/D	**Cost :**	$44.95
Reference :	15375	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	25,086

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Emission and State Inspection,Oil and Filter Change, Mount and Balance 2 tires (Service)

Date :	1/27/2021	**Technician responsible :**	N/D	**Cost :**	$174.95
Reference :	15704	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	27,731

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection,Oil and Filter Change, Mount and Balance 2 tires	1.00	$174.95	$174.95
		Total service :		$174.95

Service : OIl and Filter Change (Service)

Date :	3/8/2021	**Technician responsible :**	N/D	**Cost :**	$44.95
Reference :	17237	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	29,332

Type	Description	Qty.	Unit cost	Total cost
Other	OIl and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Replace Left Motor Mount (Service)

Date :	3/12/2021	**Technician responsible :**	N/D	**Cost :**	$0.00
Reference :	CHCS60973	**Vendor responsible :**	Videon Dodge	**Odometer :**	29,521

Type	Description	Qty.	Unit cost	Total cost

Other	Replace Left Motor Mount	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Drivers Door Latch Assembly, Oil and Filter Change,Replace Fob Battery, (Service)

Date : 4/20/2021 **Technician responsible :** N/D **Cost :** $55.08

Reference : CHCS62707 **Vendor responsible :** Videon Dodge **Odometer :** 32,395

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Drivers Door Latch Assembly, Oil and Filter Change,Replace Fob Battery,	1.00	$55.08	$55.08

Total service : $55.08

Service : Replace both Left and Right Headlamp Assemblys (Service)

Date : 5/5/2021 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS63477 **Vendor responsible :** Videon Dodge **Odometer :** 32,659

Type	Description	Qty.	Unit cost	Total cost
Other	Replace both Left and Right Headlamp Assemblys	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Blower Motor (Service)

Date : 6/1/2021 **Technician responsible :** N/D **Cost :**

Reference : CHCS64700 **Vendor responsible :** Videon Dodge **Odometer :** 33,279

Type	Description	Qty.	Unit cost	Total cost

Total service : $0.00

Service : Fuel Pump Fuse Tightened as a result of intermittent starts (Service)

Date : 6/22/2021 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS65516 **Vendor responsible :** Videon Dodge **Odometer :** 34,106

Type	Description	Qty.	Unit cost	Total cost
Other	Fuel Pump Fuse Tightened as a result of intermittent starts	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace PDC Assembly (Starter) (Service)

Date : 7/6/2021 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS66133 **Vendor responsible :** Videon Dodge **Odometer :** 34,642

Type	Description	Qty.	Unit cost	Total cost
Other	Replace PDC Assembly (Starter)	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Transmission Cooler (Service)

Date : 8/3/2021 **Technician responsible :** N/D **Cost :** $625.57

Reference : CHCS67541 **Vendor responsible :** Videon Dodge **Odometer :** 36,076

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Transmission Cooler	1.00	$625.57	$625.57

Total service : $625.57

Service : Replace AC Condenser and Recharge to Proper Pressure (Service)

Date : 8/17/2021 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS68362 **Vendor responsible :** Videon Dodge **Odometer :** 36,828

Type	Description	Qty.	Unit cost	Total cost
Other	Replace AC Condenser and Recharge to Proper Pressure	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 8/30/2021 **Technician responsible :** N/D **Cost :** $60.00

Reference : 18482 **Vendor responsible :** Thorntons Gulf **Odometer :** 37,467

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$60.00	$60.00

Total service : $60.00

Service : Oil and Filter Change, Replace Front and Rear Brakes (Service)

Date : 10/18/2021 **Technician responsible :** N/D **Cost :** $390.00

Reference : 18578 **Vendor responsible :** Thorntons Gulf **Odometer :** 40,277

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Front and Rear Brakes	1.00	$390.00	$390.00

Total service : $390.00

Service : Replace Left Fuel Pump Assembly (Service)

Date : 11/12/2021 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS72372 **Vendor responsible :** Videon Dodge **Odometer :** 41,880

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Left Fuel Pump Assembly	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Battery (Service)

Date : 11/23/2021 **Technician responsible :** N/D **Cost :** $445.05

Reference : CHCS72662 **Vendor responsible :** Videon Dodge **Odometer :** 42,081

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	$445.05	$445.05

Total service : $445.05

Service : Replace PDC under MPF, Replace C5 Connector (Service)

Date : 12/6/2021 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS73440 **Vendor responsible :** Videon Dodge **Odometer :** 42,259

Type	Description	Qty.	Unit cost	Total cost
Other	Replace PDC under MPF, Replace C5 Connector	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Water Pump Assembly, Replace Rear Heater Hose Assembly (Service)

Date : 12/31/2021 **Technician responsible :** N/D **Cost :** $496.84

Reference : CHCS74810 **Vendor responsible :** Videon Dodge **Odometer :** 43,430

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Water Pump Assembly, Replace Rear Heater Hose Assembly	1.00	$496.84	$496.84

Total service : $496.84

Service : Oil and Filter Change (Service)

Date : 1/18/2022 **Technician responsible :** N/D **Cost :** $60.00

Reference : 17776 **Vendor responsible :** Thorntons Gulf **Odometer :** 44,389

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$60.00	$60.00

Total service : $60.00

Service : Oil and Filter Change, Emission and State Insp., Mount and Balance 2 Tires (Service)

Date : 2/24/2022 **Technician responsible :** N/D **Cost :** $191.00

Reference : 17829 **Vendor responsible :** Thorntons Gulf **Odometer :** 46,384

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Emission and State Insp., Mount and Balance 2 Tires	1.00	$191.00	$191.00

Total service : $191.00

Service : Emission and State Insp. Replace Air Filter, Replace Front and Rear Rotors (Service)

Date : 3/10/2022 **Technician responsible :** N/D **Cost :** $582.00

Reference : 18284 **Vendor responsible :** Thorntons Gulf **Odometer :** 46,510

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Insp. Replace Air Filter, Replace Front and Rear Rotors	1.00	$582.00	$582.00

Total service : $582.00

Service : Replace Long Block Assembly and all needed Seals, Hardware and Gaskets. Replace Engine Oil and Filter, Refill Antifreeze. (Service)

Date : 3/8/2022 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS77201 **Vendor responsible :** Videon Dodge **Odometer :** 46,443

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Long Block Assembly and all needed Seals, Hardware and Gaskets. Replace Engine Oil and Filter, Refill Antifreeze.	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 5/2/2022 **Technician responsible :** N/D **Cost :** $75.00

Reference : 18379 **Vendor responsible :** Thorntons Gulf **Odometer :** 50,145

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Replace Driver side head light (Service)

Date : 5/11/2022 **Technician responsible :** N/D **Cost :** $35.00

Reference : 18415 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Driver side head light	1.00	$35.00	$35.00

Total service :	$35.00

Service : Replace Door Lock Act (Service)

Date : 5/26/2022 **Technician responsible :** N/D **Cost :** $342.00

Reference : 17989 **Vendor responsible :** Thorntons Gulf **Odometer :** 51,287

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Door Lock Act	1.00	$342.00	$342.00
	Total service :			$342.00

Service : Replace AC Condenser. (Service)

Date : 6/7/2022 **Technician responsible :** N/D **Cost :** $67.50

Reference : CHCS81866 **Vendor responsible :** Videon Dodge **Odometer :** 52,062

Type	Description	Qty.	Unit cost	Total cost
Other	Replace AC Condenser.	1.00	$67.50	$67.50
	Total service :			$67.50

Service : Oil and Filter Change (Service)

Date : 6/28/2022 **Technician responsible :** N/D **Cost :** $75.00

Reference : 000228 **Vendor responsible :** Thorntons Gulf **Odometer :** 53,352

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00
	Total service :			$75.00

Service : Mount and Balance 2 tires (Service)

Date : 6/15/2022 **Technician responsible :** N/D **Cost :** $40.00

Reference : 000179 **Vendor responsible :** Thorntons Gulf **Odometer :** 52,640

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 tires	1.00	$40.00	$40.00

Total service :	$40.00

Service : Oil and Filter Change (Service)

Date :	8/22/2022	**Technician responsible :**	N/D	**Cost :**	$75.00
Reference :	000486	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	56,479

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00
		Total service :		$75.00

Service : Mount and Balance 2 tires (Service)

Date :	9/2/2022	**Technician responsible :**	N/D	**Cost :**	$54.00
Reference :	000580	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	58,080

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 tires	1.00	$54.00	$54.00
		Total service :		$54.00

Service : Oil and Filter Change, Replace Wiper Blades, Replace both Headlight Assemblys (Service)

Date :	8/29/2022	**Technician responsible :**	N/D	**Cost :**	$1,023.00
Reference :	000522	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	57,130

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Wiper Blades, Replace both Headlight Assemblys	1.00	$1,023.00	$1,023.00
		Total service :		$1,023.00

Service : Oil and Filter Change, (Service)

Date :	10/21/2022	**Technician responsible :**	N/D	**Cost :**	$112.59
Reference :	CHCS88045	**Vendor responsible :**	Videon Dodge	**Odometer :**	60,203

Type	Description	Qty.	Unit cost	Total cost

Other	Oil and Filter Change,	1.00	$112.59	$112.59
			Total service :	$112.59

Service : Oil and Filter Change, Replace Radiator, Refill with Antifreeze, Update of ABS Module Software. (Service)

Date : 2/2/2023 **Technician responsible :** N/D **Cost :** $1,328.23

Reference : CHCS92570 **Vendor responsible :** Videon Dodge **Odometer :** 64,203

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Radiator, Refill with Antifreeze, Update of ABS Module Software.	1.00	$1,328.23	$1,328.23
			Total service :	$1,328.23

Service : Emission and State Insp (Service)

Date : 3/6/2023 **Technician responsible :** N/D **Cost :** $77.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 64,608

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Insp	1.00	$77.00	$77.00
			Total service :	$77.00

Service : Replace driver side and Pass side headlamps. (Service)

Date : 3/14/2023 **Technician responsible :** N/D **Cost :** $1,216.00

Reference : CHCB94411 **Vendor responsible :** Videon Dodge **Odometer :** 64,836

Type	Description	Qty.	Unit cost	Total cost
Other	Replace driver side and Pass side headlamps.	1.00	$1,216.00	$1,216.00
			Total service :	$1,216.00

Total of the vehicle : *$22,737.57*