Detailed services/breakdown

Display criteria
Period : All
Vehicle(s) : Ford/Explorer/2017

Vehicle : 67-81 - Ford/Explorer/2017/MG9714J

Service : Transfer the LPR system, Upfitting the entire vehicle (with equip from 68 car.) (Service)

Date : 5/2/2017 **Technician responsible :** N/D **Cost :** $5,180.00
Reference : IN000105606 **Vendor responsible :** Metropolitan Communications **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Install of LPR and Equip from 68 car	1.00	$5,180.00	$5,180.00
			Total service :	$5,180.00

Service : oil and filter change (Service)

Date : 5/15/2017 **Technician responsible :** N/D **Cost :** $39.50
Reference : 8296 **Vendor responsible :** Thorntons Gulf **Odometer :** 3,025

Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	$39.50	$39.50
			Total service :	$39.50

Service : Oil and Filter Change (Service)

Date : 6/9/2017 **Technician responsible :** N/D **Cost :** $39.50
Reference : 8574 **Vendor responsible :** Thorntons Gulf **Odometer :** 5,530

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$39.50	$39.50
			Total service :	$39.50

Service : Oil and Filter Change (Service)

Date : 7/14/2017 **Technician responsible :** N/D **Cost :** $39.50

Reference : 11323 **Vendor responsible :** Thorntons Gulf **Odometer :** 8,613

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$39.50	$39.50
		Total service :		$39.50

Service : oil and filter change (Service)

Date : 8/18/2017 **Technician responsible :** N/D **Cost :** $39.50

Reference : 7217 **Vendor responsible :** Thorntons Gulf **Odometer :** 11,396

Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	$39.50	$39.50
		Total service :		$39.50

Service : Oil and Filter Change (Service)

Date : 9/25/2017 **Technician responsible :** N/D **Cost :** $39.50

Reference : 10768 **Vendor responsible :** Thorntons Gulf **Odometer :** 14,260

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$39.50	$39.50
		Total service :		$39.50

Service : Mount, Change and Balance 4 tires (Service)

Date : 10/10/2017 **Technician responsible :** N/D **Cost :** $108.00

Reference : 7281 **Vendor responsible :** Thorntons Gulf **Odometer :** 15,444

Type	Description	Qty.	Unit cost	Total cost
Other	Mount, Change and Balance 4 tires	1.00	$108.00	$108.00
		Total service :		$108.00

Service : Multi point inspection, reseal all areas per recall instructions. (Service)

Date : 10/27/2017 **Technician responsible :** N/D **Cost :** $0.00
Reference : 32804 **Vendor responsible :** Garnet Ford **Odometer :** 16,672

Type	Description	Qty.	Unit cost	Total cost
Other	reseal all areas per recall instructions	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Bent the "Police Shield" which was hitting the exhaust causing a whining noise. (Service)

Date : 10/27/2017 **Technician responsible :** N/D **Cost :** $125.35
Reference : C32979 **Vendor responsible :** Garnet Ford **Odometer :** 16,672

Type	Description	Qty.	Unit cost	Total cost
Other	Bent the "Police Shield" which was hitting the exhaust causing a whining noise.	1.00	$125.35	$125.35
			Total service :	$125.35

Service : Front Brakes and Front Rotors (Service)

Date : 10/24/2017 **Technician responsible :** N/D **Cost :** $355.00
Reference : 7331 **Vendor responsible :** Thorntons Gulf **Odometer :** 16,534

Type	Description	Qty.	Unit cost	Total cost
Other	Front Brakes and Front Rotors	1.00	$355.00	$355.00
			Total service :	$355.00

Service : Oil and Filter Change (Service)

Date : 11/6/2017 **Technician responsible :** N/D **Cost :** $39.50
Reference : 8249 **Vendor responsible :** Thorntons Gulf **Odometer :** 17,326

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$39.50	$39.50
			Total service :	$39.50

Service : Diagnose and Replace left side turbo Assembly, Replace all spark Plugs (Service)

Date : 11/24/2017 **Technician responsible :** N/D **Cost :** $0.00

Reference : W37054 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 18,059

Type	Description	Qty.	Unit cost	Total cost
Other	Diagnose and Replace left side turbo Assembly, Replace all spark Plugs	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Remove and replace left side turbo assembly, replace spark plugs (Service)

Date : 11/20/2017 **Technician responsible :** N/D **Cost :** $0.00

Reference : W37054 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 18,053

Type	Description	Qty.	Unit cost	Total cost
Other	Remove and replace left side turbo assembly, replace spark plug	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Replace rear license place blue light (Service)

Date : 11/27/2017 **Technician responsible :** N/D **Cost :** $0.00

Reference : 32357 **Vendor responsible :** Metropolitan Communications **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Remove and replace left side turbo assembly, replace spark plug	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Oil and Filter Change, Windshield Wipers (Service)

Date : 12/1/2017 **Technician responsible :** N/D **Cost :** $79.50

Reference : 11922 **Vendor responsible :** Thorntons Gulf **Odometer :** 21,000

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Windshield Wipers	1.00	$79.50	$79.50
			Total service :	$79.50

Service : Oil and Filter Change (Service)

Date : 1/10/2018 **Technician responsible :** N/D **Cost :** $39.50

Reference : 10943 **Vendor responsible :** Thorntons Gulf **Odometer :** 23,275

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$39.50	$39.50
		Total service :		$39.50

Service : Emission and State Inspection (Service)

Date : 3/8/2018 **Technician responsible :** N/D **Cost :** $75.00

Reference : 13282 **Vendor responsible :** Thorntons Gulf **Odometer :** 26,683

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection	1.00	$75.00	$75.00
		Total service :		$75.00

Service : Replace Wiper Blades (Service)

Date : 3/7/2018 **Technician responsible :** N/D **Cost :** $28.00

Reference : 13276 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Wiper Blades	1.00	$28.00	$28.00
		Total service :		$28.00

Service : Oil and Filter Change (Service)

Date : 2/16/2018 **Technician responsible :** N/D **Cost :** $44.95

Reference : 13363 **Vendor responsible :** Thorntons Gulf **Odometer :** 25,076

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Replace Battery (Service)

Date : 3/13/2018 **Technician responsible :** N/D **Cost :** $175.00

Reference : 13297 **Vendor responsible :** Thorntons Gulf **Odometer :** 27,069

Type	Description	Qty.	Unit cost	Total cost
Other	replace battery	1.00	$175.00	$175.00
		Total service :		$175.00

Service : Repair left rear door, Replace Door Applique (Service)

Date : 5/30/2018 **Technician responsible :** N/D **Cost :** $155.78

Reference : CHCB9758 **Vendor responsible :** Videon Dodge **Odometer :** 31,988

Type	Description	Qty.	Unit cost	Total cost
Other	Repair left rear door, Replace Door Applique	1.00	$155.78	$155.78
		Total service :		$155.78

Service : Oil and Filter Change, replace windshield wipers (Service)

Date : 5/22/2018 **Technician responsible :** N/D **Cost :** $92.95

Reference : 13496 **Vendor responsible :** Thorntons Gulf **Odometer :** 31,446

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, replace windshield wipers	1.00	$92.95	$92.95
		Total service :		$92.95

Service : Oil and Filter Change, Front and rear rotors, Front brakes, change 2 tires (Service)

Date : 7/10/2018 **Technician responsible :** N/D **Cost :** $677.95

Reference : 12870 **Vendor responsible :** Thorntons Gulf **Odometer :** 34,306

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Front and rear rotors, Front brakes, change 2 tires	1.00	$677.95	$677.95
		Total service :		$677.95

Service : Repair Front end and Push Bumper bracket (Service)

Date : 7/19/2018 **Technician responsible :** N/D **Cost :** $180.00

Reference : 13051 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Repair Front end and Push Bumper bracket	1.00	$180.00	$180.00

Total service : $180.00

Service : Replace Right Side Turbo (Service)

Date : 7/26/2018 **Technician responsible :** N/D **Cost :** $0.00

Reference : W46451 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 34,544

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Right Side Turbo	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 8/1/2018 **Technician responsible :** N/D **Cost :** $44.95

Reference : 12913 **Vendor responsible :** Thorntons Gulf **Odometer :** 34,971

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Replace Vapor Management Valve/Canister Purge Valve, Replace Purge Valve (Service)

Date : 8/29/2018 **Technician responsible :** N/D **Cost :**

Reference : W48111 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 36,873

Type	Description	Qty.	Unit cost	Total cost

Total service : $0.00

Service : Remove and adjust the current pushbumper. (Service)

Date : 8/27/2018 **Technician responsible :** N/D **Cost :** $525.00

Reference : IN000107863 **Vendor responsible :** Metropolitan Communications **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Remove and adjust the current pushbumper.	1.00	$525.00	$525.00

Total service : $525.00

Service : Oil and Filter Change (Service)

Date : 9/11/2018 **Technician responsible :** N/D **Cost :** $44.95

Reference : 13148 **Vendor responsible :** Thorntons Gulf **Odometer :** 37,784

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Replace rear brakes (Service)

Date : 9/18/2018 **Technician responsible :** N/D **Cost :** $155.00

Reference : 10035 **Vendor responsible :** Thorntons Gulf **Odometer :** 38,233

Type	Description	Qty.	Unit cost	Total cost
Other	Replace rear brakes	1.00	$155.00	$155.00

Total service : $155.00

Service : Replace Rear Axel Assembly (Service)

Date : 10/5/2018 **Technician responsible :** N/D **Cost :** $0.00

Reference : W49093 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 38,342

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Rear Axel Assembly	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Bumper, Valance, and L Molding, Front Cover, Paint (Service)

Date : 11/15/2018 **Technician responsible :** N/D **Cost :** $2,149.91

Reference : CHCB18888 **Vendor responsible :** Videon Dodge **Odometer :** 40,312

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Bumper, Valance, and L Molding, Front Cover, Paint	1.00	$2,149.91	$2,149.91
		Total service :		$2,149.91

Service : Mount and balance 2 tires, Front end alignment (Service)

Date : 12/11/2018 **Technician responsible :** N/D **Cost :** $143.00

Reference : 7495 **Vendor responsible :** Thorntons Gulf **Odometer :** 41,669

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and balance 2 tires, Front end alignment	1.00	$143.00	$143.00
		Total service :		$143.00

Service : Oil and Filter Change (Service)

Date : 12/3/2018 **Technician responsible :** N/D **Cost :** $44.95

Reference : 7456 **Vendor responsible :** Thorntons Gulf **Odometer :** 41,115

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Replace Spark Plug, Gasket, 2 seal valves, Boot-ignition wire, V belt, Oil change and filter, Replace Water pump, Replace Timing Belt/ Chain, Replace anti freeze, Replace Gaskets and tube Asy. (Service)

Date : 1/10/2019 **Technician responsible :** N/D **Cost :** $1,880.36

Reference : W53525 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 42,370

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Spark Plug, Gasket, 2 seal valves, Boot-ignition wire, V belt, Oil change and filter, Replace Water pump, Replace Timing Belt/ Chain, Replace anti freeze, Replace Gaskets and tube Asy.	1.00	$1,880.36	$1,880.36

Total service :	$1,880.36

Service : Replace Low Side Fuel Pressure Sensor (Replacing the Fuel Pump was covered Under Warranty) (Service)

Date :	1/18/2019	**Technician responsible :**	N/D	**Cost :**	$99.95
Reference :	C53974	**Vendor responsible :**	Pacifico Marple Ford	**Odometer :**	42,551

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Low Side Fuel Pressure Sensor (Replacing the Fuel Pump was covered Under Warranty)	1.00	$99.95	$99.95

Total service :	$99.95

Service : Oil and Filter Change (Service)

Date :	2/9/2019	**Technician responsible :**	N/D	**Cost :**	$44.95
Reference :	8703	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	44,325

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service :	$44.95

Service : Emission and State Insp, Oil and Filter Change (Service)

Date :	3/22/2019	**Technician responsible :**	N/D	**Cost :**	$119.95
Reference :	14503	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	47,494

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Insp, Oil and Filter Change	1.00	$119.95	$119.95

Total service :	$119.95

Service : Oil and Filter Change (Service)

Date :	5/10/2019	**Technician responsible :**	N/D	**Cost :**	$44.95
Reference :	14750	**Vendor responsible :**	Thorntons Gulf	**Odometer :**	50,648

Type	Description	Qty.	Unit cost	Total cost

Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Replace Battery (Service)

Date : 5/30/2019 **Technician responsible :** N/D **Cost :** $220.00

Reference : 13844 **Vendor responsible :** Thorntons Gulf **Odometer :** 51,364

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	$220.00	$220.00
		Total service :		$220.00

Service : Oil and Filter Change (Service)

Date : 7/8/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 14179 **Vendor responsible :** Thorntons Gulf **Odometer :** 53,842

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change (Service)

Date : 8/14/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 14285 **Vendor responsible :** Thorntons Gulf **Odometer :** 57,553

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change, Replace Wiper Blades (Service)

Date : 9/23/2019 **Technician responsible :** N/D **Cost :** $96.95

Reference : 15005 **Vendor responsible :** Thorntons Gulf **Odometer :** 60,266

Type	Description	Qty.	Unit cost	Total cost

Other	Oil and Filter Change, Replace Wiper Blades	1.00	$96.95	$96.95
			Total service :	$96.95

Service : Replace front Brakes and Rotors, Mount, Balance, and change 4 tires. (Service)

Date : 10/3/2019 **Technician responsible :** N/D **Cost :** $403.00

Reference : 14367 **Vendor responsible :** Thorntons Gulf **Odometer :** 61,176

Type	Description	Qty.	Unit cost	Total cost
Other	Replace front Brakes and Rotors, Mount, Balance, and change 4 tires.	1.00	$403.00	$403.00
			Total service :	$403.00

Service : Change Oil and Filter, Remove and Replace Turbo Charger Assembly, Replace Heated Oxygen Sensor (Service)

Date : 11/7/2019 **Technician responsible :** N/D **Cost :** $251.04

Reference : C65705 & W65705 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 62,826

Type	Description	Qty.	Unit cost	Total cost
Other	Change Oil and Filter, Remove and Replace Turbo Charger Assembly, Replace Heated Oxygen Sensor	1.00	$251.04	$251.04
			Total service :	$251.04

Service : Oil and Filter Change (Service)

Date : 1/29/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 15799 **Vendor responsible :** Thorntons Gulf **Odometer :** 66,935

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
			Total service :	$44.95

Service : Replace Battery (Service)

Date : 2/14/2020 **Technician responsible :** N/D **Cost :** $175.00

Reference : 16291 **Vendor responsible :** Thorntons Gulf **Odometer :** 67,934

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	$175.00	$175.00

Total service : $175.00

Service : Emission and State Inspection, Oil and Filter Change, Replace Rear Brakes, 2 Rear Rotors, and 2 Wiper Blades (Service)

Date : 3/13/2020 **Technician responsible :** N/D **Cost :** $447.95

Reference : 15852 **Vendor responsible :** Thorntons Gulf **Odometer :** 70,322

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection, Oil and Filter Change, Replace Rear Brakes, 2 Rear Rotors, and 2 Wiper Blades	1.00	$447.95	$447.95

Total service : $447.95

Service : Installed FU5Z 9D370 B: Control Unit, INstalled BA5Z 9G4444 A: Sensor- Exhaust Gas - OXY, Replaced Bank 1 Sensor, 2 Oxygen Senssor and Fuel Pump Driver Moduel (Service)

Date : 4/15/2020 **Technician responsible :** N/D **Cost :** $598.46

Reference : 6112514 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 72,123

Type	Description	Qty.	Unit cost	Total cost
Other	Installed FU5Z 9D370 B: Control Unit, INstalled BA5Z 9G4444 A: Sensor - Exhaust Gas - OXY, Replaced Bank 1 Sensor, 2 Oxygen Senssor and Fuel Pump Driver Moduel	1.00	$598.46	$598.46

Total service : $598.46

Service : Replace Low Pressure Fuel Pump (Service)

Date : 4/20/2020 **Technician responsible :** N/D **Cost :** $1,122.86

Reference : 6112605/1 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 72,341

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Low Pressure Fuel Pump	1.00	$1,122.86	$1,122.86

Total service : $1,122.86

Service : Oil and Filter Change (Service)

Date : 5/13/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 16213 **Vendor responsible :** Thorntons Gulf **Odometer :** 73,865

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Oil and Filter Change (Service)

Date : 6/29/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 16380 **Vendor responsible :** Thorntons Gulf **Odometer :** 77,638

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Oil and Filter Change (Service)

Date : 8/19/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 16521 **Vendor responsible :** Thorntons Gulf **Odometer :** 81,494

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter CHange	1.00	$44.95	$44.95

Total service : $44.95

Service : Oil and Filter Change, Mount and Balance 2 Tires (Service)

Date : 9/28/2020 **Technician responsible :** N/D **Cost :** $98.95

Reference : 16720 **Vendor responsible :** Thorntons Gulf **Odometer :** 84,777

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 2 Tires	1.00	$98.95	$98.95

Total service : $98.95

Service : Replace Battery (Service)

Date : 10/3/2020 **Technician responsible :** N/D **Cost :** $175.00

Reference : 16744 **Vendor responsible :** Thorntons Gulf **Odometer :** 85,241

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$175.00	$175.00

Total service : $175.00

Service : Front Brakes and Rotors, Oil and Filter Change, Replace Lower Contriol Bushing (Service)

Date : 12/24/2020 **Technician responsible :** N/D **Cost :** $793.95

Reference : 15661 **Vendor responsible :** Thorntons Gulf **Odometer :** 88,000

Type	Description	Qty.	Unit cost	Total cost
Other	Front Brakes and Rotors, Oil and Filter Change, Replace Lower Contriol Bushing	1.00	$793.95	$793.95

Total service : $793.95

Service : Intake manafold, Replace Fuel Rail pressure sensor and Fuel Injector Pressure Sensor, Replace Injector Assembly (Service)

Date : 1/11/2021 **Technician responsible :** N/D **Cost :** $972.48

Reference : 15178 **Vendor responsible :** Garnet Ford **Odometer :** 88,550

Type	Description	Qty.	Unit cost	Total cost
Other	Intake manafold, Replace Fuel Rail pressure sensor and Fuel Injector Pressure Sensor, Replace Injector Assembly	1.00	$972.48	$972.48

Total service :	$972.48

Service : Converter Assembly, AA Gasket, Bolt, A Gasket, Stud, Nut, Engine Front Support Bracket, Housing, Insulator Assembly, Antifreeze, Replace Battery, Replace Trans Mount, Spark Plugs, Ignition Wire (Service)

Date : 2/9/2021 **Technician responsible :** N/D **Cost :** $3,026.04
Reference : 6119954 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 88,987

Type	Description	Qty.	Unit cost	Total cost
Other	Converter Assembly, AA Gasket, Bolt, A Gasket, Stud, Nut, Engine Front Support Bracket, Housing, Insulator Assembly, Antifreeze, Replace Battery, Replace Trans Mount, Spark Plugs, Ignition Wire	1.00	$3,026.04	$3,026.04

Total service : $3,026.04

Service : Replace #4 fuel Injector, Emission and State Inspection, Replace Water Pump and Gaskets, (Service)

Date : 3/22/2021 **Technician responsible :** N/D **Cost :** $1,285.42
Reference : 6120616/1 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 90,434

Type	Description	Qty.	Unit cost	Total cost
Other	Replace #4 fuel Injector, Emission and State Inspection, Replace Water Pump and Gaskets,	1.00	$1,285.42	$1,285.42

Total service : $1,285.42

Service : Replace fans for Radiator (Service)

Date : 6/23/2021 **Technician responsible :** N/D **Cost :** $555.00
Reference : 17255 **Vendor responsible :** Thorntons Gulf **Odometer :** 97,300

Type	Description	Qty.	Unit cost	Total cost
Other	Replace fans for Radiator	1.00	$555.00	$555.00

Total service : $555.00

Service : Oil and Filter Change (Service)

Date : 6/21/2021 **Technician responsible :** N/D **Cost :** $44.95

Reference : 17036 **Vendor responsible :** Thorntons Gulf **Odometer :** 97,253

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Emission and State Insp., Oil and Filter Change, Replace Rear Shocks,Mount and Balance 4 tires (Service)

Date : 7/19/2022 **Technician responsible :** N/D **Cost :** $590.00

Reference : 000322 **Vendor responsible :** Thorntons Gulf **Odometer :** 99,964

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Insp., Oil and Filter Change, Replace Rear Shocks,Mount and Balance 4 tires	1.00	$590.00	$590.00

Total service : $590.00

Total of the vehicle : *$23,978.65*