Detailed services/breakdown

Display criteria
Period : All
Vehicle(s) : Dodge/Durango/2020

Vehicle : 67-96 - Dodge/Durango/2020/MG8963L

Service : Oil and Filter Change, Mount and Balance 1 tire (Service)
Date : 8/24/2020 **Technician responsible :** N/D **Cost :** $71.95
Reference : 16533 **Vendor responsible :** Thorntons Gulf **Odometer :** 3,079

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 1 tire	1.00	$71.95	$71.95
		Total service :		$71.95

Service : Oil and Filter Change (Service)
Date : 11/13/2020 **Technician responsible :** N/D **Cost :** $44.95
Reference : 15561 **Vendor responsible :** Thorntons Gulf **Odometer :** 6,437

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change (Service)
Date : 1/12/2021 **Technician responsible :** N/D **Cost :** $44.95
Reference : 15540 **Vendor responsible :** Thorntons Gulf **Odometer :** 9,881

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change (Service)

Date : 3/18/2021 **Technician responsible :** N/D **Cost :** $44.95

Reference : 19781 **Vendor responsible :** Thorntons Gulf **Odometer :** 12,978

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Evacuate Condenser and Recharge AC Systemto Propper Pressure,Oil and Filter Change, Emmission and State Inspection, Replace Front Brake Pads and Rotors, Pad Kit and Rotor Bra (Service)

Date : 4/12/2021 **Technician responsible :** N/D **Cost :** $670.69

Reference : CHCS62226 **Vendor responsible :** Videon Dodge **Odometer :** 15,038

Type	Description	Qty.	Unit cost	Total cost
Other	Evacuate Condenser and Recharge AC Systemto Propper Pressure,Oil and Filter Change, Emmission and State Inspection, Replace Front Brake Pads and Rotors, Pad Kit and Rotor Bra	1.00	$670.69	$670.69

Total service : $670.69

Service : Oil and Filter Change (Service)

Date : 6/16/2021 **Technician responsible :** N/D **Cost :** $44.95

Reference : 17021 **Vendor responsible :** Thorntons Gulf **Odometer :** 20,130

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Replace AC Condenser and recharge System with Freon (Service)

Date : 7/2/2021 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS66177 **Vendor responsible :** Videon Dodge **Odometer :** 21,273

Type	Description	Qty.	Unit cost	Total cost

Other	Replace AC Condenser and recharge System with Freon	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Replace Fuel Pump Wiring PDC and PDC C5 Connector (Service)

Date : 8/20/2021 **Technician responsible :** N/D **Cost :** $0.00
Reference : CHCS68432 **Vendor responsible :** Videon Dodge **Odometer :** 25,361

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Fuel Pump Wiring PDC and PDC C5 Connector	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Oil and Filter Change, Mount and Balance 2 tires (Service)

Date : 7/29/2021 **Technician responsible :** N/D **Cost :** $114.00
Reference : 17627 **Vendor responsible :** Thorntons Gulf **Odometer :** 23,543

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 2 tires	1.00	$114.00	$114.00
			Total service :	$114.00

Service : Mount and Balance 2 tires (Service)

Date : 8/23/2021 **Technician responsible :** N/D **Cost :** $54.00
Reference : 17533 **Vendor responsible :** Thorntons Gulf **Odometer :** 25,494

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 tires	1.00	$54.00	$54.00
			Total service :	$54.00

Service : Replace 2 headlamps (Service)

Date : 9/4/2021 **Technician responsible :** N/D **Cost :** $70.00
Reference : 17557 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost

Other	Replace 2 headlamps	1.00	$70.00	$70.00
			Total service :	$70.00

Service : Oil and Filter Change (Service)

Date : 9/2/2021 **Technician responsible :** N/D **Cost :** $60.00

Reference : 18499 **Vendor responsible :** Thorntons Gulf **Odometer :** 26,666

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$60.00	$60.00
			Total service :	$60.00

Service : Replace Front Brakes and Rotors (Service)

Date : 9/15/2021 **Technician responsible :** N/D **Cost :** $455.00

Reference : 17597 **Vendor responsible :** Thorntons Gulf **Odometer :** 27,929

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Front Brakes and Rotors	1.00	$455.00	$455.00
			Total service :	$455.00

Service : Replace Left Motor Mount, Oil and Filter Change, Replace Fuel Filler Housing. (Service)

Date : 12/13/2021 **Technician responsible :** N/D **Cost :** $50.67

Reference : CHCS73751 **Vendor responsible :** Videon Dodge **Odometer :** 34,034

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Left Motor Mount, Oil and Filter Change, Replace Fuel Filler Housing.	1.00	$50.67	$50.67
			Total service :	$50.67

Service : Replace 2 Headlight bulbs (Service)

Date : 12/18/2021 **Technician responsible :** N/D **Cost :** $59.49

Reference : **Vendor responsible :** N/D **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Replace 2 Headlight bulbs	1.00	$59.49	$59.49

Total service : $59.49

Service : Replace Water Pump (Service)

Date : 1/19/2022 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS75584 **Vendor responsible :** Videon Dodge **Odometer :** 36,432

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Water Pump	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 3/15/2022 **Technician responsible :** N/D **Cost :** $75.00

Reference : 18296 **Vendor responsible :** Thorntons Gulf **Odometer :** 39,674

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Replace Condenser and Recharge System (Service)

Date : 4/19/2022 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS79658 **Vendor responsible :** Videon Dodge **Odometer :** 41,926

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Condenser and Recharge System	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 5/16/2022 **Technician responsible :** N/D **Cost :** $75.00

Reference : 18430 **Vendor responsible :** Thorntons Gulf **Odometer :** 43,009

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Emission and State Inspection (Service)

Date : 5/27/2022 **Technician responsible :** N/D **Cost :** $77.00

Reference : 17991 **Vendor responsible :** Thorntons Gulf **Odometer :** 43,541

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection	1.00	$77.00	$77.00

Total service : $77.00

Service : Diagnose AC issue and Replace Fuse (Service)

Date : 6/13/2022 **Technician responsible :** N/D **Cost :** $74.20

Reference : CHCS81926 **Vendor responsible :** Videon Dodge **Odometer :** 44,299

Type	Description	Qty.	Unit cost	Total cost
Other	Diagnose AC issue and Replace Fuse	1.00	$74.20	$74.20

Total service : $74.20

Service : Replace Radiator Assembly and recharge AC (Service)

Date : 6/20/2022 **Technician responsible :** N/D **Cost :** $67.50

Reference : CHCS82360 **Vendor responsible :** Videon Dodge **Odometer :** 44,604

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Radiator Assembly and recharge AC	1.00	$67.50	$67.50

Total service : $67.50

Service : Oil and Filter Change (Service)

Date : 7/8/2022 **Technician responsible :** N/D **Cost :** $75.00

Reference : 000280 **Vendor responsible :** Thorntons Gulf **Odometer :** 46,048

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Replace F70 Fuse (Service)

Date : 8/12/2022 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS84850 **Vendor responsible :** Videon Dodge **Odometer :** 46,913

Type	Description	Qty.	Unit cost	Total cost
Other	Replace F70 Fuse	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace 4 wheel drive control moduel, Replace Outer Driver Seat Shield (Service)

Date : 8/10/2022 **Technician responsible :** N/D **Cost :** $115.15

Reference : CHCS83723 **Vendor responsible :** Videon Dodge **Odometer :** 46,892

Type	Description	Qty.	Unit cost	Total cost
Other	Replace 4 wheel drive control moduel, Replace Outer Driver Seat Shield	1.00	$115.15	$115.15

Total service : $115.15

Service : Oil and Filter Change, Mount and Balance 2 tires (Service)

Date : 9/14/2022 **Technician responsible :** N/D **Cost :** $115.00

Reference : 000592 **Vendor responsible :** Thorntons Gulf **Odometer :** 49,620

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 2 tires	1.00	$115.00	$115.00

Total service : $115.00

Service : Replace Fuel Pump Fuse, Replace TIPM (Service)

Date : 10/14/2022 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS86891 **Vendor responsible :** Videon Dodge **Odometer :** 50,475

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Fuel Pump Fuse, Replace TIPM	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 11/9/2022 **Technician responsible :** N/D **Cost :** $75.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 52,677

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Replace Battery (Service)

Date : 12/5/2022 **Technician responsible :** N/D **Cost :** $485.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 54,420

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	$485.00	$485.00

Total service : $485.00

Service : Oil and Filter Change, Replace Starter (Service)

Date : 12/22/2022 **Technician responsible :** N/D **Cost :** $440.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 55,320

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Starter	1.00	$440.00	$440.00

Total service : $440.00

Service : Replace TIMP (Totally Integrated Power Module) and Wiring Harness (Service)

Date : 1/20/2023 **Technician responsible :** N/D **Cost :** $0.00

Reference : CHCS91975 **Vendor responsible :** Videon Dodge **Odometer :** 57,132

Type	Description	Qty.	Unit cost	Total cost
Other	Replace TIMP (Totally Integrated Power Module) and Wiring Harness	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 2/16/2023 **Technician responsible :** N/D **Cost :** $75.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 58,777

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Oil and Filter Change, Mount and Balance 2 Tires (Service)

Date : 4/11/2023 **Technician responsible :** N/D **Cost :** $129.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 62,216

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 2 Tires	1.00	$129.00	$129.00

Total service : $129.00

Service : Replace 5.7 Liter engine (Long Block) (Service)

Date : 6/23/2023 **Technician responsible :** N/D **Cost :** $0.00

Reference : 101251 **Vendor responsible :** Videon Dodge **Odometer :** 64,968

Type	Description	Qty.	Unit cost	Total cost
Other	Replace 5.7 Liter engine (Long Block)	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Passenger Side Headlight (Service)

Date : 6/27/2023 **Technician responsible :** N/D **Cost :** $35.00

Reference : 18015 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Passenger Side Headlight	1.00	$35.00	$35.00

Total service : $35.00

Service : Oil and Filter Change (Service)

Date : 9/13/2023 **Technician responsible :** N/D **Cost :** $75.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 70,254

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Replace Module and Fuel Pump (Service)

Date : 10/6/2023 **Technician responsible :** N/D **Cost :** $0.00

Reference : 105796 **Vendor responsible :** Videon Dodge **Odometer :** 71,746

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Module and Fuel Pump	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Fuel Pump O Ring (Service)

Date : 10/9/2023 **Technician responsible :** N/D **Cost :** $0.00

Reference : 106010 **Vendor responsible :** Videon Dodge **Odometer :** 71,794

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Fuel Pump O Ring	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace driver and Passanger side headlamp, Replace Catalytic Converter (Service)

Date : 10/23/2023 **Technician responsible :** N/D **Cost :** $1,687.05

Reference : 106941 **Vendor responsible :** Videon Dodge **Odometer :** 73,034

Type	Description	Qty.	Unit cost	Total cost
Other	Replace driver and Passanger side headlamp, Replace Catalytic Converter	1.00	$1,687.05	$1,687.05

Total service : $1,687.05

Service : Oil and Filter Change (Service)

Date : 11/27/2023 **Technician responsible :** N/D **Cost :** $75.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 73,711

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Recharge AC Compressor (Service)

Date : 12/13/2023 **Technician responsible :** N/D **Cost :** $0.00

Reference : 108895 **Vendor responsible :** Videon Dodge **Odometer :** 74,429

Type	Description	Qty.	Unit cost	Total cost
Other	Recharge AC Compressor	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Left Fuel Pump Assembly (Service)

Date : 12/26/2023 **Technician responsible :** N/D **Cost :** $0.00

Reference : 109221 **Vendor responsible :** Videon Dodge **Odometer :** 74,662

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Left Fuel Pump Assembly	1.00	$0.00	$0.00

Total service : $0.00

Service : Repair corroded connectors to the fuel tank (Service)

Date : 1/17/2024 **Technician responsible :** N/D **Cost :** $0.00

Reference : 109938 **Vendor responsible :** Videon Dodge **Odometer :** 75,229

Type	Description	Qty.	Unit cost	Total cost
Other	Repair corroded connectors to the fuel tank	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change, Replace Wiper Blades (Service)

Date : 2/8/2024 **Technician responsible :** N/D **Cost :** $154.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 76,587

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Wiper Blades	1.00	$154.00	$154.00

Total service : $154.00

Service : Replace Front and Rear Brakes,Resurface Front Rotors, Mount and Balance 2 tires (Service)

Date : 2/12/2024 **Technician responsible :** N/D **Cost :** $510.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 76,914

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Front and Rear Brakes,Resurface Front Rotors, Mount and Balance 2 tires	1.00	$510.00	$510.00

Total service : $510.00

Service : Oil and Filter Change (Service)

Date : 4/10/2024 **Technician responsible :** N/D **Cost :** $75.00

Reference : **Vendor responsible :** Videon Dodge **Odometer :** 79,970

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Emission and State Ins., Alignment, Replace 2 Upper and Lower Control Arms, Replace left front running light (Service)

Date : 5/9/2024 **Technician responsible :** N/D **Cost :** $2,801.98

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 81,986

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Ins., Alignment, Replace 2 Upper and Lower Control Arms, Replace left front running light	1.00	$2,801.98	$2,801.98

Total service : $2,801.98

Service : Oil and Filter Change, Mount and Balance 2 tires (Service)

Date : 5/13/2024 **Technician responsible :** N/D **Cost :** $105.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 82,230

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 2 tires	1.00	$105.00	$105.00

Total service : $105.00

Service : Oil and Filter Change, Replace Heater Hose, Replace Coolant (Service)

Date : 7/1/2024 **Technician responsible :** N/D **Cost :** $380.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 85,248

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Heater Hose, Replace Coolant	1.00	$380.00	$380.00

Total service : $380.00

Service : Replace Heater Hose and Coolant (Service)

Date : 7/17/2024 **Technician responsible :** N/D **Cost :** $175.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 86,427

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Heater Hose and Coolant	1.00	$175.00	$175.00

Total service :	$175.00

Service : Replace Heater Hose and Coolant (Service)

Date : 7/26/2024 **Technician responsible :** N/D **Cost :** $139.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 87,014

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Heater Hose and Coolant	1.00	$139.00	$139.00
		Total service :		$139.00

Service : Replace Thermostate and Gasket, Replace Heater Hose and Collant (Service)

Date : 8/1/2024 **Technician responsible :** N/D **Cost :** $182.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 87,333

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Thermostate and Gasket, Replace Heater Hose and Collant	1.00	$182.00	$182.00
		Total service :		$182.00

Service : Replace Heater Hose Assembly, Oil and Filter Change, Replace Coolant (Service)

Date : 8/21/2024 **Technician responsible :** N/D **Cost :** $585.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 88,419

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Heater Hose Assembly, Oil and Filter Change, Replace Coolant	1.00	$585.00	$585.00
		Total service :		$585.00

Service : Replace Thermostate, Lower Hose, and Right Front Headlight (Service)

Date : 9/5/2024 **Technician responsible :** N/D **Cost :** $328.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 88,936

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Thermostate, Lower Hose, and Right Front Headlight	1.00	$328.00	$328.00

Total service :	$328.00

Service : Replace Heater Hose, Refill Coolant (Service)

Date : 9/16/2024 **Technician responsible :** N/D **Cost :** $210.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 89,673

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Heater Hose, Refill Coolant	1.00	$210.00	$210.00
		Total service :		$210.00

Service : Replace Wiper Blades (Service)

Date : 9/25/2024 **Technician responsible :** N/D **Cost :** $28.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Wiper Blades	1.00	$28.00	$28.00
		Total service :		$28.00

Service : Replace Belt, Belt Tensioner, and engine Coolant (Service)

Date : 10/4/2024 **Technician responsible :** N/D **Cost :** $356.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 90,626

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Belt, Belt Tensioner, and engine Coolant	1.00	$356.00	$356.00
		Total service :		$356.00

Service : Oil and Filter Change (Service)

Date : 10/26/2024 **Technician responsible :** N/D **Cost :** $75.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 91,725

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service :	$75.00

Service : Flush Radiator and Hoses, Replace Coolant (Service)

Date : 11/5/2024 **Technician responsible :** N/D **Cost :** $185.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 91,942

Type	Description	Qty.	Unit cost	Total cost
Other	Flush Radiator and Hoses, Replace Coolant	1.00	$185.00	$185.00

Total service : $185.00

Total of the vehicle : *$11,824.48*