NOMENCLATURE (SIDE 1)

EQUIPMENT: FORD F350 (2007) Super Duty XL INVENTORY NO: V8. CARD NO:

REFERENCE:

VIN 1FDWF37507EA84227 5.4 3valve, 6spd ZF, DRW 4X4

MANUFACTURER:	SALES & SERVICE:
Marker Plate 9851	

DATE OF MANUF:	DATE PUT INTO SERVICE:	DATE REPLACED:	LENGTH OF SERVICE:
9-2006	10-19-06		

NAMEPLATE DATA – MODEL	SERIAL NO.	SIZE	RPM	TYPE

MOTOR DATA – MODEL	SERIAL NO.	FRAME	TYPE	CODE LETTER

H.P.	VOLTS	AMPS	RPM	HERTZ	PHASE	RATING	NEMA DESIGN

INSULATION CLASS	SERVICE FACTOR

REMARKS:

SPARE PARTS

PARTS DESCRIPTION	UNITS RECOMMENDED			INVENTORY RECORD (NO. IN STOCK & DATE)							
Oil Filter - Napa 1372	Every	5,000	Miles								
Car Quest - 85372											
fuel filter - NAPA 3243											
Plugs - Ford PZH14F											
Flywheel - NAPA, 88152											
Clutch master/slave cyl.	ASSY										
(Ford) 6C3Z-7C522-B											
New Clutch set - NAPA - 1107	1	79									
Air filter NAPA 6804											
blower Motor - NAPA 455-2470											

DATE	59,500 miles COMMENTS (SIDE 4)	INITIAL
3-25-11	LOF service, R&R fuel filter, R&R Plugs, Extract 2 broken plugs, Replace 8 coils, ck over Rt outer tie rod has some play, front tires starting to wear uneven	TG
8-9-13	80,811 - R&R wheel bearings, races & seal on RR - leaking, metal filings	TG
1-13-14	84,797 - R&R clutch master cylinder/line & slave cylinder, reinstall clutch switch double check operation - good.	TG
2-10-14	Change oil + filter	
3-18-14	86059 - Replace front shocks - LR axel seal blown - replace seal & bearings - reck ck. Rotate front tires to inside Rear	TG
8-25-14	Change oil + filter 90,984 miles	
8-11-15	98,000± miles change oil & filter, R&R air & fuel filters, Replace serpentine belt, ck brakes fronts ck - 60% left Replace Rear pads, adj parking brake, Replace 1 bodylight, ordered all hoses, waiting to install in select, inspect hoist, bed is rough -	TG
9-9-15	100,000 - Change oil + filter	
2-17-16	104,423 miles - Change oil + filter, Change Transmission Fluid, All New Radiator and Heating Hoses, Change Coolant, New fuel filter [redacted], Check Fluids, check Battery. 6 New Tires + Valve Stems Replace upper and lower front Right Ball Joints with outer and inner Axle shaft Seal, Grease	
4-11-17	Hartford Truck - New Dump Body Install, TG - Install New Trailer 7 pin harness connector Cut off broken/Bent Rear Bumpers, paint, Remove trans, Replace Complete Clutch SET, + Pilot bearing and New Flywheel assembly, Replace headpipe To Cat gasket & bolts, Replace Dowels to clutch plate, Road test - good,	TG
4-26-17	115,000 miles - Change oil + filter	
7-11-18	135,000 ck. Brakes grinding; Replace front rotors, calipers & brackets, pads, brake hoses, Rear rotors & pads, calipers, brackets & hoses, Rear axel seals (leaking), Replace Rt outer tie rod end on drag link, Replace Left upper & lower ball joints, top Rear diff, flush brake fluid, 1½ QTS, Road test & Reck - good	TG

12-3-18 135,300 miles Replace Both U-Joints in Rear Drive Shaft

PREVENTIVE MAINTENANCE RECORD (SIDE 3)

CODE	TYPE MAINTENANCE PERFORMED	CODE	TYPE MAINTENANCE PERFORMED	CODE	TYPE MAINTENANCE PERFORMED

DATE	CODE	BY WHOM	REMARKS	DATE	CODE	BY WHOM	REMARKS	DATE	CODE	BY WHOM	REMARKS
135,500 1-10-19	Rear end locked up-135,500, broke & bent everything- all new bearings, spline Roadtest & Reck-good.			Pinion gear pin retainer fell out, Replace carrier assy with new Ring & pinion Repair on LR Axel, fill gear oil				locked up rear diff, 4.2 TS 75w140 Synth.			
5-30-19	ck engine light on- T-Stat & "O" Ring- running @ 192°F			Insufficient temp for closed loop operation - Replace Refill coolant - universal Extended life & Reck -							
9-20-19	Ck. blower motor inop - fuses good - ck. blower motor - R&R blower motor & Reck - good.							Resistor - diag as blower			
2-14-20	145000		Replace Clutch, PP & T/O Bearing, bleed clutch. Replace seal on Rear diff & Retorque pinion nut, loose - Roadtest & Reck -								Oil Change
12-15-20	146,600	MT	& balance 6 TIRES, ck all fluids, ck over, order PS hose T-Ford								
		New	Air filter								
4-21-21	?		Replaced 8 plugs and 8 Coil on plugs (Focus)					16#			
7-9-21	150,750	Oil	Change - check fluids (add Power STEERING FLUID) New Wiper Blades								
1-25-22	151,630	Oil	change, check fluids - O.K., replace headlight pigtail								
1-13-23	167,050	oil	+ filter, New Air filter								
3--23		New	Fuel Pump - Parts Geek #117								
4-25-23		Replace	Radiator - Parts Geek #209				. New Coolant,	Top off	Transmission fluid		
~~4-28-23~~											

REPAIR RECORD (SIDE 2)

1FDWF37507EA84227

EQUIPMENT REPORT SHEET Golf-Mike's Truck

DATE 10-28-11 EQUIPMENT # 07 F350 Dump

MILEAGE _____ HOUR METER —

WORK PERFORMED LOF service, ck & top levels, mt 6 tires (Laurel Auto to balance & align) R&R Rt outer tie rod on drag link, ck brakes, Remove front calipers, clean & lube slides pads good, backing plates rotted, shoe hold downs pulled through →

39.00 PARTS USED 6 valve stems PART # TWS-STM11

762.60 10 ea 6 Tires-GY Silent Armor LT 245/75R17

T-Ford 1 Rt tie rod BC3Z-3A131-F

2 rear rotors BC3Z-2C026-A

2 rear seals 2C3Z-1177-AB

1 Backing plate rear 8C3Z-2209-A

1 Backing plate rear 8C3Z-2210-A

NAPA 12 Bulbs 74

1605.92

TOTAL PART COST 1605.92 + Align & balance

GREASE ✓ 10-30 OIL 7 Qts 10-40 OIL ___ ATF-F ___

15-40 OIL ___ DEXRON ATF ___ HYDRAULIC FLUID ___

ANTI-FREEZE -34°F POWER STEERING FLUID ✓ 1 Qt rear diff 75W 140

REMARKS OR WORK NEEDING ATTENTION _____

Cylinder for Dump weeping —

R&R rear backing plate/parking brake assy's, Replace rear rotors, scored & overheated for parking brake. adj shoes for parking brake, Install new grease seals for rear hub assemblies, clean and lube slides for rear calipers, pads good 80% ± left.

Remove dash trim, Instrument cluster, 5 of 12 bulb burnt out for cluster illumination, Replace all 12 bulbs, Reinstall cluster & trim,

EQUIPMENT REPORT SHEET

DATE 12-13-12 EQUIPMENT # Golf Dump Truck 07

MILEAGE 74448 HOUR METER _____

WORK PERFORMED ck. E Brake inop – warning light inop – LR cable hung up on rust – Replace both rear cable assy's, clean adj parking brakes Replace rear axel seals – Remove pedal assy – repair/reinstall & reck – good – replace switch

PARTS USED _____ PART # _____

1 cable assy		6C3Z-2A635-AA
1 cable assy	(1 Ford)	6C3Z-2A635-B
2 rear axl seals		2 C3Z-1177-AB
switch assy		(in stk)
1 oil filter	Mike's STK	51372

TOTAL PART COST _____

GREASE X 10-30 OIL 6 QTS 10-40 OIL ___ ATF-F ___

15-40 OIL ___ DEXRON ATF ___ HYDRAULIC FLUID ___

ANTI-FREEZE -30°F POWER STEERING FLUID ___

REMARKS OR WORK NEEDING ATTENTION _____

Performed LOF service, top fluids set tire pressures – ck over for winter – good

EQUIPMENT REPORT SHEET

DATE 8-9-13 EQUIPMENT # Mikes 07 F350

MILEAGE 80,811 HOUR METER _____

WORK PERFORMED RR axel seal leaking Remove caliper, rotor & hub assy & inspect - loaded with metal, Replace inner & outer bearings & races & seal on RR - clean housing & brakes, park shoes, Reinstall - Top

PARTS USED fluid & rock - PART # ~~Good~~ NAPA

1 outer bearing ASSY	BR38
1 inner bearing	NP114036
1 inner race	NP064306
1 Grease seal	29425
2 Brake Clean	091314CA

TOTAL PART COST $98.69

GREASE ✓ 10-30 OIL ___ 10-40 OIL ___ ATF-F ___

15-40 OIL ___ DEXRON ATF ___ HYDRAULIC FLUID ___

ANTI-FREEZE ___ POWER STEERING FLUID ___

REMARKS OR WORK NEEDING ATTENTION _____

.80 QT 85W 140 Gear oil

WORK DONE BY _____ TIME _____