INVOICE

Pine Hill Trailers
5140 Martin Drive
Gap, PA, USA, 17527
P: (888) 897-1925
E: info@pinehilltrailers.com

SOLD TO

Upper Leacock Township*
161 Newport Road
Leola, PA, USA, 17540

P: (717) 656-9755
E: invoices@ultwp.com

INVOICE# INV-00016684
August 03, 2026
Order: CO-0022913

SERVICE JOB 1 **Sold by: April Vogelsong** [redacted]

Unit Details	Mileage In	Mileage Out
2009 FOREST RIVER, INC ENCLOSED - 5NHUHA627AW056652 - MG7393G	0	0
[Color Exterior: BLACK] [Plate#: MG7393G]		

Concern
INSPECTION

Correction
INSPECTION, REPACKED BEARINGS, REPLACED BRAKES, DRUMS AND TIRES, REPLACED BREAKAY BATTERY AND SWITCH

Item	Description	Qty	MSRP	Disc	Price	Total
O-INSPEC-TRL	Inspection-Trl	1			[redacted]	[redacted]
18-00042	PA STATE INSPECTION STICKER	1	[redacted]	[redacted]	[redacted]	[redacted]
O-SERLAB-TRL	Hourly Service Labor-Trl	3			[redacted]	[redacted]
10-02058	7/16"-20 HEX FLG LOCKNUT (10K-15K BRK)	16	[redacted]	[redacted]	[redacted]	[redacted]
12-00624	Elect Brk 10"x2.25" LH 3.5K Dex	2	[redacted]	[redacted]	[redacted]	[redacted]
12-00610	ELEC BRK 10"x2.25" RH DEX 3.5K/PR	2	[redacted]	[redacted]	[redacted]	[redacted]
235-00359	10" X 2.25" BRAKE DRUM, 5 ON 4.5", DEXTER	4	[redacted]	[redacted]	[redacted]	[redacted]
12-00560	GREASE CAP, 1.986" OD DRIVE IN, EZ LUBE	4	[redacted]	[redacted]	[redacted]	[redacted]
12-00025	GREASE CAP PLUG, FOR EZ LUBE GREASE CAPS	4	[redacted]	[redacted]	[redacted]	[redacted]
12-00561	GREASE SEAL 2.565" OD X 1.719"ID,DBLLIP3.5K&4.4K	4	[redacted]	[redacted]	[redacted]	[redacted]
10-02056	1/8" COTTER PIN, 1 3/4" (2 1/4" OVERALL)	4	[redacted]	[redacted]	[redacted]	[redacted]
13-00440	Rainier ST205/75R15 D Range	4	[redacted]	[redacted]	[redacted]	[redacted]
PA-TT	13-00440 Pa Tire Tax	4			[redacted]	[redacted]
13-00042	VALVE STEM, METAL, FOR PRESSURES OVER 100PSI	4	[redacted]	[redacted]	[redacted]	[redacted]
HD TIRE DISPOSAL	HD TIRE DISPOSAL	4			[redacted]	[redacted]
11-00118	5 AMP BREAKAWAY BATTERY	1	[redacted]	[redacted]	[redacted]	[redacted]
11-00117	BREAKAWAY SWITCH W/PIN & CABLE(2010)	1	[redacted]	[redacted]	[redacted]	[redacted]
SUP	Shop Supplies Detail	1			[redacted]	[redacted]

INVOICE PAYMENTS

Charge Account 08/03/2026 [redacted]

[redacted]

Signature :

15% restocking fees will apply to any returns after 15 days. Returns of special order parts are on the discretion of the vendor. No returns on opened electrical parts. No cash refunds after 30 days, in-store credit only. After notification of completion of work, the customer will have 5 days to pick up their unit, after which time a per day storage fee of $50.00 a day will be assessed.

LUG NUT TORQUE – CUSTOMER RESPONSIBILITY (Initial Required)
Lug nuts must be re-torqued at 25, 50, and 100 miles after a wheel has been removed or installed.

This step is critical for your safety. Wheels can loosen if not properly re-torqued, leading to serious damage or injury. Pine Hill is not responsible for failures caused by missed torque checks.

By initialing, you acknowledge this requirement and accept full responsibility.

Customer Initials: _____Date: _____

LEVELING AXLE WARRANTY ACKNOWLEDGMENT AND DISCLAIMER.
Customer acknowledges that leveling axles are a non-standard modification and agrees that such modification voids all axle manufacturer warranties and any Pine Hill Trailers axle warranty coverage applicable to the modified axle(s). Customer accepts all risks and responsibilities associated with the installation and operation of leveling axles.