Detailed services/breakdown

Display criteria
Period : All
Vehicle(s) : Ford/Explorer/2018

Vehicle : 67-85 - Ford/Explorer/2018/MG5627K

Service : Complete Transfer of Car 68 Equipment into 85. Lights Cage Push bumper ect. (Service)
Date : 4/10/2018 **Technician responsible :** N/D **Cost :**
Reference : **Vendor responsible :** Metropolitan Communications **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost

Total service : $0.00

Service : Oil and Filter Change (Service)
Date : 6/11/2018 **Technician responsible :** N/D **Cost :** $44.95
Reference : 12803 **Vendor responsible :** Thorntons Gulf **Odometer :** 3,673

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Oil and Filter Change (Service)
Date : 8/1/2018 **Technician responsible :** N/D **Cost :** $44.95
Reference : 12915 **Vendor responsible :** Thorntons Gulf **Odometer :** 7,104

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Oil and Filter Change (Service)

Date : 9/5/2018 **Technician responsible :** N/D **Cost :** $44.95

Reference : 13125 **Vendor responsible :** Thorntons Gulf **Odometer :** 10,352

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change (Service)

Date : 10/30/2018 **Technician responsible :** N/D **Cost :** $44.95

Reference : 12049 **Vendor responsible :** Thorntons Gulf **Odometer :** 13,619

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change (Service)

Date : 12/13/2018 **Technician responsible :** N/D **Cost :** $44.95

Reference : 8608 **Vendor responsible :** Thorntons Gulf **Odometer :** 16,660

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
		Total service :		$44.95

Service : Oil and Filter Change (Service)

Date : 1/15/2019 **Technician responsible :** N/D **Cost :** $57.24

Reference : C53840 **Vendor responsible :** Pacifico Marple Ford **Odometer :** 18,078

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$57.24	$57.24
		Total service :		$57.24

Service : Oil and Filter Change (Service)

Date : 2/6/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 14436 **Vendor responsible :** Thorntons Gulf **Odometer :** 19,699

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
			Total service :	$44.95

Service : Emission and State Insp (Service)

Date : 3/21/2019 **Technician responsible :** N/D **Cost :** $75.00

Reference : 14501 **Vendor responsible :** Thorntons Gulf **Odometer :** 22,312

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Insp	1.00	$75.00	$75.00
			Total service :	$75.00

Service : Oil and Filter Change, Mount and Balance 2 tires. (Service)

Date : 4/1/2019 **Technician responsible :** N/D **Cost :** $94.95

Reference : 14545 **Vendor responsible :** Thorntons Gulf **Odometer :** 23,014

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 2 tires.	1.00	$94.95	$94.95
			Total service :	$94.95

Service : Replace Battery (Service)

Date : 4/29/2019 **Technician responsible :** N/D **Cost :** $175.00

Reference : 13787 **Vendor responsible :** Thorntons Gulf **Odometer :** 24,986

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	$175.00	$175.00
			Total service :	$175.00

Service : Mount and Balance 2 tires. (Service)

Date : 5/30/2019 **Technician responsible :** N/D **Cost :** $50.00

Reference : 13839 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 tires.	1.00	$50.00	$50.00

Total service : $50.00

Service : Oil and Filter Change (Service)

Date : 5/22/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 13811 **Vendor responsible :** Thorntons Gulf **Odometer :** 26,453

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Oil and Filter Change (Service)

Date : 7/22/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 13981 **Vendor responsible :** Thorntons Gulf **Odometer :** 29,543

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Replace outside Passenger side door panel. (Paint) (Service)

Date : 8/5/2019 **Technician responsible :** N/D **Cost :** $957.20

Reference : CHCB33631 **Vendor responsible :** Videon Dodge **Odometer :** 29,648

Type	Description	Qty.	Unit cost	Total cost
Other	Replace outside Passenger side door panel. (Paint)	1.00	$957.20	$957.20

Total service : $957.20

Service : Oil and Filter Change (Service)

Date : 10/11/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 15158 **Vendor responsible :** Thorntons Gulf **Odometer :** 32,956

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Remove and Install Injector Assembly, Replace Fuel Pump COntroller /Driver Module, Replace Fuel Pump Module (Service)

Date : 10/31/2019 **Technician responsible :** N/D **Cost :** $0.00

Reference : 6108492/1 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 33,128

Type	Description	Qty.	Unit cost	Total cost
Other	Remove and Install Injector Assembly, Replace Fuel Pump COntroller /Driver Module, Replace Fuel Pump Module	1.00	$0.00	$0.00

Total service : $0.00

Service : Replace Both Front Brakes and Rotors, Replace Both Rear Brakes and Rotors (Service)

Date : 11/14/2019 **Technician responsible :** N/D **Cost :** $670.00

Reference : 14799 **Vendor responsible :** Thorntons Gulf **Odometer :** 33,359

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Both Front Brakes and Rotors, Replace Both Rear Brakes and Rotors	1.00	$670.00	$670.00

Total service : $670.00

Service : Replace Fuel Injector Assembly. Installed A, D and BA Gaskets on the Intake Manifold.Replace Hex Nut, Replace "O" Ring installed Spark Plug (Service)

Date : 12/23/2019 **Technician responsible :** N/D **Cost :** $0.00

Reference : 6109799/1 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 34,128

Type	Description	Qty.	Unit cost	Total cost

Other	Replace Fuel Injector Assembly. Installed A, D and BA Gaskets on the Intake Manifold.Replace Hex Nut, Replace "O" Ring installed Spark Plug	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Remove and Install Injector Assembly, Remove and install Fuel Tank, Install Bolt, 2 Gaskets, Sender and Pump Assembly, Replace Fuel Pump (Service)

Date : 1/8/2020 **Technician responsible :** N/D **Cost :** $0.00

Reference : 6110075 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 35,059

Type	Description	Qty.	Unit cost	Total cost
Other	Remove and Install Injector Assembly, Remove and install Fuel Tank, Install Bolt, 2 Gaskets, Sender and Pump Assembly, Replace Fuel Pump	1.00	$0.00	$0.00
			Total service :	$0.00

Service : Oil and Filter Change (Service)

Date : 12/27/2019 **Technician responsible :** N/D **Cost :** $44.95

Reference : 15320 **Vendor responsible :** Thorntons Gulf **Odometer :** 34,737

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
			Total service :	$44.95

Service : Replace Battery (Service)

Date : 1/24/2020 **Technician responsible :** N/D **Cost :** $150.00

Reference : 15779 **Vendor responsible :** Thorntons Gulf **Odometer :** 37,935

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	$150.00	$150.00
			Total service :	$150.00

Service : Emission and State Inspection (Service)

Date : 3/19/2020 **Technician responsible :** N/D **Cost :** $76.00

Reference : 15866 **Vendor responsible :** Thorntons Gulf **Odometer :** 40,908

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection	1.00	$76.00	$76.00

Total service : $76.00

Service : Remove Replace and install Fuel Injector Assembly, Remove Replace and install Catalytic Converter (all Covered Under Warranty) Replace Spark Plugs and Boots, Ignition Witre and Coil Packs. (Not Covered) (Service)

Date : 4/17/2020 **Technician responsible :** N/D **Cost :** $320.74

Reference : 6112568/1 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 42,539

Type	Description	Qty.	Unit cost	Total cost
Other	Remove Replace and install Fuel Injector Assembly, Remove Replace and install Catalytic Converter (all Covered Under Warranty) Replace Spark Plugs and Boots, Ignition Witre and Coil Packs. (Not Covered)	1.00	$320.74	$320.74

Total service : $320.74

Service : Replaced Injector Assembly, Replace Heated Oxygen Sensor, Replaced Bank 1 sensor 2 (Oxygen Sensor) (Service)

Date : 5/20/2020 **Technician responsible :** N/D **Cost :** $0.00

Reference : 6113178/1 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 43,726

Type	Description	Qty.	Unit cost	Total cost
Other	Replaced Injector Assembly, Replace Heated Oxygen Sensor, Replaced Bank 1 sensor 2 (Oxygen Sensor)	1.00	$0.00	$0.00

Total service : $0.00

Service : Oil and Filter Change (Service)

Date : 5/21/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 15955 **Vendor responsible :** Thorntons Gulf **Odometer :** 43,873

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
			Total service :	$44.95

Service : Replace Rear Driver Side Lens (Service)

Date : 6/10/2020 **Technician responsible :** N/D **Cost :** $651.00

Reference : 16333 **Vendor responsible :** Thorntons Gulf **Odometer :** 45,087

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Rear Driver Side Lens	1.00	$651.00	$651.00
			Total service :	$651.00

Service : Mount and Balance 2 tires, Oil and filter change (Service)

Date : 7/20/2020 **Technician responsible :** N/D **Cost :** $98.95

Reference : 16093 **Vendor responsible :** Thorntons Gulf **Odometer :** 47,205

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 tires, Oil and filter change	1.00	$98.95	$98.95
			Total service :	$98.95

Service : Oil and Filter Change (Service)

Date : 9/10/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 16552 **Vendor responsible :** Thorntons Gulf **Odometer :** 50,693

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95
			Total service :	$44.95

Service : Mount and Balance 2 tires (Service)

Date : 9/14/2020 **Technician responsible :** N/D **Cost :** $54.00

Reference : 16571 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 tires	1.00	$54.00	$54.00

Total service : $54.00

Service : Replace Battery (Service)

Date : 9/24/2020 **Technician responsible :** N/D **Cost :** $175.00

Reference : 16708 **Vendor responsible :** Thorntons Gulf **Odometer :** 51,261

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	$175.00	$175.00

Total service : $175.00

Service : Replace 2 Connecting Purge Hoses (Service)

Date : 10/22/2020 **Technician responsible :** N/D **Cost :** $387.68

Reference : 6117220 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 52,635

Type	Description	Qty.	Unit cost	Total cost
Other	Replace 2 Connecting Purge Hoses	1.00	$387.68	$387.68

Total service : $387.68

Service : Oil and Filter Change (Service)

Date : 11/10/2020 **Technician responsible :** N/D **Cost :** $44.95

Reference : 15552 **Vendor responsible :** Thorntons Gulf **Odometer :** 53,927

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Replace Fuel Pump Assembly and O2 Sensor (Service)

Date : 1/11/2021 **Technician responsible :** N/D **Cost :** $1,312.74

Reference : 6118902 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 55,792

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Fuel Pump Assembly and O2 Sensor	1.00	$1,312.74	$1,312.74

Total service : $1,312.74

Service : OIl and Filter Change, Emission and State Inspection (Service)

Date : 3/12/2021 **Technician responsible :** N/D **Cost :** $120.95

Reference : 17247 **Vendor responsible :** Thorntons Gulf **Odometer :** 58,304

Type	Description	Qty.	Unit cost	Total cost
Other	OIl and Filter Change, Emission and State Inspection	1.00	$120.95	$120.95

Total service : $120.95

Service : Oil and Filter Change (Service)

Date : 4/21/2021 **Technician responsible :** N/D **Cost :** $44.95

Reference : 16990 **Vendor responsible :** Thorntons Gulf **Odometer :** 62,513

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Alternator Belt (Service)

Date : 5/10/2021 **Technician responsible :** N/D **Cost :** $125.00

Reference : 17720 **Vendor responsible :** Thorntons Gulf **Odometer :** 63,691

Type	Description	Qty.	Unit cost	Total cost
Other	Alt. Belt	1.00	$125.00	$125.00

Total service : $125.00

Service : Oil and Filter Change (Service)

Date : 6/22/2021 **Technician responsible :** N/D **Cost :** $44.95

Reference : 17044 **Vendor responsible :** Thorntons Gulf **Odometer :** 66,400

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$44.95	$44.95

Total service : $44.95

Service : Replace Front Brakes and Front Rotors (Service)

Date : 7/13/2021 **Technician responsible :** N/D **Cost :** $443.00

Reference : 17100 **Vendor responsible :** Thorntons Gulf **Odometer :** 68,622

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Front Brakes and Front Rotors	1.00	$443.00	$443.00

Total service : $443.00

Service : Replace Gasket Manifold A, D & BA, Replace the "O" ring, Injector Asy, Filled with Refrigerant for AC,Replace Battery (Service)

Date : 8/23/2021 **Technician responsible :** N/D **Cost :** $1,718.25

Reference : 6123832 **Vendor responsible :** Matthews Paoli Ford **Odometer :** 69,852

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Gasket Manifold A, D & BA, Replace the "O" ring, Injector Asy, Filled with Refrigerant for AC,Replace Battery	1.00	$1,718.25	$1,718.25

Total service : $1,718.25

Service : Oil and Filter Change (Service)

Date : 8/31/2021 **Technician responsible :** N/D **Cost :** $60.00

Reference : 18490 **Vendor responsible :** Thorntons Gulf **Odometer :** 69,906

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$60.00	$60.00

Total service : $60.00

Service : Oil and Filter Change, Emission and State Insp., Replace Rear Shocks (Service)

Date : 2/24/2022 **Technician responsible :** N/D **Cost :** $405.00

Reference : 17832 **Vendor responsible :** Thorntons Gulf **Odometer :** 70,139

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Emission and State Insp., Replace Rear Shocks	1.00	$405.00	$405.00

Total service : $405.00

Service : Oil and Filter Change (Service)

Date : 8/4/2022 **Technician responsible :** N/D **Cost :** $75.00

Reference : 000408 **Vendor responsible :** Thorntons Gulf **Odometer :** 72,197

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	$75.00	$75.00

Total service : $75.00

Service : Emission and State Insp (Service)

Date : 3/3/2023 **Technician responsible :** N/D **Cost :** $77.00

Reference : **Vendor responsible :** Thorntons Gulf **Odometer :** 73,815

Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Insp	1.00	$77.00	$77.00

Total service : $77.00

Total of the vehicle : *$9,003.95*