Fleet Maintenance Log

Fleet Maintenance Log with Part, Labor and Fuel Cost (updated in library 3/7/18)
Schedule Name <> Mileage Entry
Maintenance Date = In The Past
Maintenance Date = In The Past
Unit Number = Ambulance 940 (2015)

Unit Number: Ambulance 940 (2015)

Maintenance Date	Work Order	Schedule Name	Notes	Repair Description	Mileage	Cost of Parts	Cost of Labor	Cost Total	View ID
4/23/2026		Annual State Inspections	Passed; no issues. Tires - front 6, rear 13 ;; Brakes - front 7, rear 12		263,217	$12.00	$29.99	$41.99	2945
12/8/2025		5K Services		5 K service, No issues, All tires filled to 70 PSI.	263,082	$0.00	$0.00	$0.00	2880
4/23/2025		Annual State Inspections	inspection at STTC 5/13 -- tires - front 7, rear 15 ;; brakes - front 11, rear 12.		262,101	$11.00	$29.99	$40.99	2773
4/23/2025		Non-Scheduled Maint.		Replaced both batteries, tested no issues back in service.	262,030	$0.00	$0.00	$0.00	2774
5/17/2024		Annual State Inspections	Required brake master cylinder and regen ;; Passed ;; Tires - F9, R12 ;; Brakes - F 6, R 12.		261,842	$736.00	$800.00	$1,536.00	2637
5/12/2023		Annual State Inspections	State inspection - multiple repairs made. 4 new tires; 2 new batteries; rear brakes. tires - Front 7; Rear 15 ;;; Brakes - Front 10 ; Rear 14		261,764	$2,495.67	$503.99	$2,999.66	2469
3/15/2023		5K Services		Oil and filter change; Brakes - front 8/32, rear 9/32; confirmed tire pressures	261,752	$119.95	$15.50	$135.45	2444

6/17/2022	Non-Scheduled Maint.		replaced #2 EGT sensor and Door track	259,275	$119.43	$0.00	$119.43	2323
4/13/2022	Annual State Inspections	Required tape to cover a sharp edge; difficulty aligning front end -- replaced RF upper control arm.		0	$466.65	$169.50	$636.15	2291
4/12/2022	5K Services		PM to be performed while at J&J Diesel for transmission replacement. Cost logged under transmission replacement of same date.	258,733	$0.00	$0.00	$0.00	2283
10/4/2021	5K Services		Brakes - Front 8/32 ; Rear 6/32. Oil change performed.	251,235	$119.95	$27.00	$146.95	2233
5/27/2021	5K Services		Replaced front rotors and pads. 5k Service No other issues, Wheels pulled re torqued at 140 ft/lb placed back in service.	245,538	$220.92	$0.00	$220.92	2169
4/30/2021	Annual State Inspections	This is set to be sent to highlands on 5/4. Inspected no issues		0	$0.00	$0.00	$30.00	2159
3/3/2021	Non-Scheduled Maint.		replaced passenger side wiper arm.	241,707	$43.96	$0.00	$43.96	2132
1/30/2021	5K Services		Fix a previous work order with wrong mileage.	238,704	$0.00	$0.00	$0.00	2116
1/29/2021	5K Services		5 K service, Sent to Highlands for front tires and alignment check.	0	$0.00	$0.00	$0.00	2113
11/30/2020	5K Services		repaired drivers side siren, noted un even front tire ware 5K PM done visual tire and break inspection WNL, no further issues noted.	232,504	$0.00	$0.00	$0.00	2092
9/16/2020	5K Services		sent to highlands for alignment, replaced pass side tie rod and balanced tires. 5 K PM visual break inspection no issues.	224,286	$396.08	$0.00	$396.08	2067
7/5/2020	5K Services		Oil change no issues, just had a state inspection no wheels pulled.	216,007	$0.00	$0.00	$0.00	2048
5/28/2020	Annual State Inspections	Inspection at highlands		0	$0.00	$0.00	$0.00	2032
3/19/2020	Non-Scheduled Maint.		found leak in rear AC line cut spliced and tested.	207,699	$141.51	$0.00	$141.51	2012

			working no issues. back in service					
2/21/2020	5K Services		5 K	205,203	$0.00	$0.00	$0.00	1994
1/3/2020	Non-Scheduled Maint.		replaced both the duct and tubing from the intercooler due to air leaks.	201,824	$168.15	$0.00	$168.15	1954
10/16/2019	Non-Scheduled Maint.		replaced idler pulley and AC compressor.	198,532	$348.66	$0.00	$348.66	1917
10/3/2019	5K Services		5 K service noted screw in rear inside tire took to highlands repaired inside patch, unable to remove other tires lugs tight will soak next pm with penetrant to remove. All lugs retorqued at 140 ft/lb	198,189	$25.00	$0.00	$25.00	1909
8/26/2019	5K Services		Noted rear pass side caliper pin stripped threads. replaced tested all tires pulled re torqued at 140 ft/lb	193,027	$147.36	$0.00	$147.36	1876
6/18/2019	5K Services		Front rotors and breaks replaced/ all tires pulled re torqued at 140 ft/lb. both front tires toed in sent to highlands for tire replacement/alignment.	186,314	$179.06	$0.00	$179.06	1844
3/26/2019	Annual State Inspections	State inspection. NO issues. All tires pulled re torqued at 140 ft/lb,		0	$0.00	$0.00	$0.00	1781
3/15/2019	5K Services		state inspection. PM all tires pulled re torqued at 140 ft/lb	179,653	$0.00	$0.00	$0.00	1770
1/19/2019	10K Services		5 K service no issues, all tires removed re torqued at 140 ft/lb	173,172	$0.00	$0.00	$0.00	1727
12/18/2018	Non-Scheduled Maint.		replace knox 1 and 2 sensor	170,516	$518.36	$0.00	$518.36	1704
12/13/2018	5K Services		5 K service, noted knox sensor #2 needs replaced. Ordered from GRAM will arrive 12-14. All tires pulled re torqued at 140 ft/lb. replaced air filter.	170,516	$0.00	$0.00	$0.00	1698
10/18/2018	5K Services		5 K service, replaced front tires, replaced both batteries, sent to highlands for alignment and front tires, all tires pulled re torqued at 140 ft/lb.	162,154	$57.98	$0.00	$57.98	1664

10/18/2018	Non-Scheduled Maint.		alignment and new tires	162,154	$346.95	$0.00	$346.95	1666
10/12/2018	Non-Scheduled Maint.		Replaced pass side headlight.	161,372	$127.19	$0.00	$127.19	1657
9/6/2018	5K Services		5 K PM, replaced oil drain plug, all tires removed re torqued at 140 ft/lb	157,561	$4.23	$0.00	$4.23	1631
8/10/2018	Non-Scheduled Maint.		Noted low on 134a refrigerant, added 1.0lb tested no issues back in service.	155,612	$0.00	$0.00	$0.00	1604
7/9/2018	10K Services		5 K service, replaced passenger side rear caliper, tested no issues. All tires pulled re torqued at 140 ft/lb	151,894	$97.77	$0.00	$97.77	1574
6/28/2018	Non-Scheduled Maint.		screw in tire, inside patch done, no issues.	150,861	$22.17	$0.00	$22.17	1571
6/14/2018	10K Services		5 K service, no issues, swapped the drivers for pass side front tire. All tires pulled torqued at 140 ft/lb	148,944	$0.00	$0.00	$0.00	1566
5/25/2018	Non-Scheduled Maint.		DEF fluid added	146,007	$23.74	$0.00	$23.74	1558
5/3/2018	Non-Scheduled Maint.		replaced and reprogrammed direct injector	142,550	$318.08	$0.00	$318.08	1543
4/14/2018	5K Services		5 K service, no issues, all tires pulled re torqued at 140 ft/lb	140,981	$0.00	$0.00	$0.00	1540
4/4/2018	Non-Scheduled Maint.		chip in windshield replaced	139,117	$162.07	$0.00	$162.07	1531
3/15/2018	Annual State Inspections	Annual state inspection, No issues noted, All tires pulled and re torqued at 140 ft/lb		0	$0.00	$0.00	$0.00	1512
2/8/2018	Non-Scheduled Maint.		alignment/6 tires.	135,708	$909.65	$0.00	$909.65	1495
2/7/2018	10K Services		10K service, front tires noted to be wearing on outsides will send to highlands for alignment check and two new tires. All tires pulled retorqued at 140 ft/lb.	135,562	$0.00	$0.00	$0.00	1492
12/28/2017	5K Services		5K, replaced rear breaks and passenger side seized caliper, Road tested no issues, all tires removed re torqued at 140 ft/lb.	130,358	$115.89	$0.00	$115.89	1466

10/24/2017	10K Services		10 K service, noted a torn upper control arm bushing. to grams replaced all 4 and alignment. All tires removed torqued at 140 ft lb	124,966	$431.06	$0.00	$431.06	1414
9/25/2017	Non-Scheduled Maint.		Replaced flywheel housing and transmission. tested no issues returned in service.	119,321	$3,054.27	$0.00	$3,054.27	1389
8/28/2017	10K Services		10 K service no issues noted	119,321	$0.00	$0.00	$0.00	1374
7/18/2017	Non-Scheduled Maint.		Replaced oil plug.	114,487	$4.11	$0.00	$4.11	1346
7/13/2017	5K Services		5 K Service, replaced oil plug. all tires removed re torqued at 140 ft/lb.	114,427	$24.21	$0.00	$24.21	1338
5/23/2017	5K Services		5 K service/ No issues noted. All tires removed re-torqued at 140 ft lb	108,552	$0.00	$0.00	$0.00	1297
4/30/2017	Non-Scheduled Maint.		Replaced windshield, Also replaced state inspection sticker. Printed and filed in folder. Replaced rear vent cover.	0	$0.00	$0.00	$0.00	1282
3/9/2017	Non-Scheduled Maint.		rotor and breaks replaced due to cracked driver side rotor.	101,610	$0.00	$0.00	$0.00	1251
3/8/2017	Annual State Inspections	Annual Inspection		0	$0.00	$0.00	$0.00	1242
2/28/2017	Non-Scheduled Maint.		replaced passenger side visor.	100,233	$98.75	$0.00	$98.75	1235
1/26/2017	5K Services		5 K service, Fuel filter replaced, Wipers changed, both front tires changed, All tires removed re-torqued at 140ft/Lb	96,535	$0.00	$0.00	$0.00	1209
1/26/2017	Non-Scheduled Maint.		Alignment.	96,559	$59.95	$0.00	$59.95	1215
1/12/2017	Non-Scheduled Maint.		drivers side front fender and door repair and repaint. Due to deer damage.	96,535	$284.58	$1,630.00	$1,914.58	1194
12/15/2016	Non-Scheduled Maint.		DEF tank reservoir recall.	92,859	$0.00	$0.00	$0.00	1189
11/16/2016	10K Services		10 K service, Pulled passenger side front and rear tires, Replaced and retoured all tires at 140 Ft LB	88,241	$0.00	$0.00	$0.00	1173
10/5/2016	Annual Registration			0	$0.00	$0.00	$0.00	1153
10/2/2016	5K Services		Replace Air filter, Oil and filter noted small amount of water in pass headlight and light bar.	0	$0.00	$0.00	$0.00	1142

8/7/2016	5K Services		Leaking AC line in back drivers side.repaired AC line by Turner Hydraulics, 5 K service replaced all 4 rear tires, torqued all tires to 140 ft lbs. Vacuum and recharge AC system.	72,959	$249.05	$0.00	$249.05	1106
5/28/2016	5K Services		5 K No issues	0	$0.00	$0.00	$0.00	1074
4/21/2016	10K Services		10 K Service replaced both front tires. Send to highlands for alignment 04/13/16	0	$276.14	$0.00	$276.14	1058
4/15/2016	Non-Scheduled Maint.		alignment	0	$54.95	$0.00	$54.95	1055
4/2/2016	Non-Scheduled Maint.		Tires and alignment	0	$633.40	$94.95	$728.35	1035
3/10/2016	5K Services		5 K service replaced fuel filter.	0	$0.00	$0.00	$0.00	1027
3/1/2016	Non-Scheduled Maint.		3 amp Fuses. Replaced for DriveCam Software	0	$4.50	$0.00	$4.50	1018
2/2/2016	10K Services		10 K Service. Replaced lower Oil pan gasket.	0	$50.44	$0.00	$50.44	1009
2/1/2016	Non-Scheduled Maint.		5K PM	0	$24.82	$0.00	$24.82	1014
1/9/2016	5K Services		10 K Replaced Air filter.	0	$25.85	$0.00	$25.85	993
11/19/2015	5K Services		5 K service/ change fuel filter.	0	$40.43	$0.00	$40.43	976
9/29/2015	Non-Scheduled Maint.		repair onspot lines in rear.	0	$25.87	$0.00	$25.87	941
9/28/2015	10K Services		10 K Added DEF fluid no issues/	0	$0.00	$0.00	$0.00	936
8/21/2015	Non-Scheduled Maint.		Alignment/ 2 new front tires.	0	$378.13	$0.00	$378.13	918
8/17/2015	5K Services		Needs two front tires, alignment. Scheduled with highlands for 08/20/15 @ 1400 . Replaced wipers.	0	$0.00	$0.00	$0.00	910
7/7/2015	10K Services		10K	0	$0.00	$0.00	$0.00	887
6/26/2015	Non-Scheduled Maint.		installation of Voyager system.	0	$937.04	$0.00	$937.04	880
6/3/2015	5K Services		5K PM. No repairs needed.	0	$0.00	$0.00	$0.00	856
6/3/2015	Non-Scheduled Maint.		Replaced Mirror	0	$137.23	$0.00	$137.23	858
4/2/2015	Annual State Inspections	Inspection		0	$44.40	$0.00	$44.40	816
4/2/2015	Non-Scheduled Maint.		New Ambulance (Radio Install, and other components)	0	$203.58	$0.00	$203.58	815