Work History Report

Date Produced: 1/21/2025
Account: 28 Adult Probation
Reg: ADU14 PA
Vehicle Details CHEVROLET IMPALA 3.5 2008
Blue

Cumberland County Courthouse
310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num V6 3.5L 3490cc 213CID FI GAS N / **Vin** 2G1WB58NX89165436 **Mileage** 86866

Invoice Number I002965 **Date** 1/11/2024 **Mileage** 86866 **Job Value** 131.90
Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
PM Service check lights,brake and overall safety of vehicle	33.09
State Inspection	33.09
State Emission Inspection	27.58
Rotate Tires	16.55

Parts		Qty	Value
CNVWWFliud Clearv	Windshield Washer Fluid	1	1.32
CNV75-053	5W30 Oil syn blend	5	12.75
CNVEMI	Emissions, Phone Transaction Fee	1	1.57
CNV85522	Oil Filter	1	3.95

Invoice Number I002650 **Date** 8/4/2023 **Mileage** 85852 **Job Value** 51.75
Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
PCM throwing different codes for pedal assembly, new pedal assembly defective part is under warranty. Test drove vehicle multiple times with no issues present	51.75

Parts		Qty	Value
CNVAPS128	Accelerator Pedal Assembly *Warrantied*	1	0.00

Invoice Number I002620 **Date** 7/18/2023 **Mileage** 85693 **Job Value** 152.09
Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
Check engine light on, code PO2138 Accelerator position sensor 1-2 correlation. Found throttle pedal sensor to be faulty. R&R throttle pedal assembly.	62.10

Parts		Qty	Value
CNVAPS128	Accelerator Pedal Sensor	1	87.99

Invoice Number I002298 **Date** 1/31/2023 **Mileage** 84897 **Job Value** 494.76
Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
PM Service check lights,brake and overall safety of vehicle	31.05
State Inspection	31.05
State Emission Inspection	25.88
Vehicle would not start to perform state inspection, found transmission harness and ground wires chewed off under hood. Pushed vehicle in and checked over entire vehicle for damage to wiring harnesses, no other damage found. Installed new ground wiring, removed transmisson connector and re spliced all wires. Test drove vehicle to verify no other issues occurred related to damage from rabbit.	310.50
Upon test drive, TPMS light came on while driving. Found LR sensor battery died, R&R TPMS sensor and reprogrammed to car.	25.88

Parts		Qty	Value
CNV5w-30 PPC	Oil	5	15.90
CNVWWFliud Clearv	Windshield Washer Fluid	1	1.20
CNVEMI	Emissions, Phone Transaction Fee	1	1.57
CNV85522	Oil Filter	1	3.14
CNV85244AZ	Butt Connectors (Red Shrink Wrap)	25	11.50
CNV20153	TPMS Sensor	1	33.09

Invoice Number I001868 **Date** 6/7/2022 **Mileage** 83214 **Job Value** 263.67
Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
Left rear window not working, removed door cover and found window regulator had broken. Installed new regulator, and replaced window switch as well.	60.30

Parts		Qty	Value
CNV748-510	LR Window Regulator Assembly	1	181.89
CNV10340138	LR Window Switch	1	21.48

Invoice Number I001791 **Date** 4/21/2022 **Mileage** 83149 **Job Value** 85.34

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
Shop Labor- Cumberland County. Service tire monitor system light is on. Diagnosed tire monitor system and found right front tire pressure sensor not reading. Replaced right front tire pressure sensor and relearned tire sensors.	50.25

Parts		Qty	Value
CNV20153	Tire Pressure Sensor	1	33.09

Invoice Number I001567 **Date** 12/15/2021 **Mileage** 82996 **Job Value** 109.90

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
PM Service check lights,brake and overall safety of vehicle	27.61
Rotate Tires	13.81
State Inspection	27.61
State Emission Inspection	23.01

Parts		Qty	Value
CNV5w-30 PPC	Oil	5	9.95
CNVWWFliu d Clearv	Windshield Washer Fluid	1	1.20
CNVEMI	Emissions, Phone Transaction Fee	1	1.57
CNV85522	oil filter	1	3.14

Invoice Number I001347 **Date** 8/11/2021 **Mileage** 82910 **Job Value** 78.11

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Labor	Value
Clicking noise in dash, found temperature blend door actuator gear stripped. Removed and replaced temp blend door actuator	46.02

Parts		Qty	Value
CNV15-741 22	ACDelco Temperature Blend Door Actuator	1	32.09

Invoice Number K11111 **Date** 1/6/2021 **Mileage** 81859 **Job Value** 156.74

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Tested tire pressure sensors found 2 sensors are bad. Replaced right front and right rear tire pressure sensors and valve stems. Relearned tire pressure sensors. Checked for ses codes no codes are stored and light is off.

Labor	Value
Tire pressure light and ses lights are on	69.03

Parts		Qty	Value
CNV20153 az	Tire Pressure Sensor	2	75.58
CNVMXSEN SORRVK adv	Valve Stem Kit	1	10.13

Invoice Number K11084 **Date** 12/21/2020 **Mileage** 81732 **Job Value** 744.72

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
Mounted and balanced all 4 tires. Went to Highlands to pick up tires.
NULL
NULL
NULL
State Inspection
Checked power steering system and found air in system. Checked for leaks steering rack is leaking out end seals. Rack is under warranty. Replaced power steering rack and pinion. Pump is still loud pump is also under warranty. Replaced power steering pump.

Labor	Value
Service	26.53
Replace tires	106.10
Tire Disposal Fee 4 tires Highlands	8.00
State Emissions Inspection	21.22
Emissions Phone Transaction Fee	1.57
State inspection	31.83
Power steering making noise	265.25

Parts		Qty	Value
CNVWWFliu d	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	5	9.68
CNV85522 advance	Oil Filter	1	3.14
CNV18430 highlands	22560r16 uniroyal tire	4	257.48
CNV333333	Wheel Weights	8	4.00
CNV36-125 5 napa	Power Steering Rack- under warranty from Napa	1	0.00
CNV63139 az	Power steering pump -under warranty from a.z.	1	0.00

CNVazpsf32 az	Power Steering Fluid	1	2.78

Invoice Number K10658 **Date** 5/22/2020 **Mileage** 81167 **Job Value** 138.78

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked for clicking noise coming from dash. Air inlet actuator clicking. Replaced air inlet actuator.

Labor	Value
Loud clicking noise after being turned off.	92.84

Parts		Qty	Value
CNV22754988 carlisle	Actuator	1	43.94

Invoice Number K10447 **Date** 1/23/2020 **Mileage** 80475 **Job Value** 16.61

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Replaced wiper blades

Labor	Value
replace wiper blades	10.61

Parts		Qty	Value
CNVDL22 az	Wiper Blade	2	6.00

Invoice Number K10340 **Date** 12/6/2019 **Mileage** 80435 **Job Value** 100.31

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL
NULL
State Inspection

Labor	Value
Service	27.63
State Emissions Inspection	22.10
Emissions Phone Transaction Fee	1.57
State inspection	33.15

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	5	9.68
CNV85522 advance	Oil Filter	1	3.04

Invoice Number K10200 **Date** 9/26/2019 **Mileage** 79924 **Job Value** 575.04

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked ac system and found fuse blown. Checked wiring for shorts and tested ac clutch. AC clutch is shor ted to ground causing fuse to blow. Replaced ac compressor ac fuse and recharged ac.

Labor	Value
AC not cold	193.38

Parts		Qty	Value
CNV98271 az	AC Compressor	1	371.99
CNV10 Amp	10 Amp Mini Fuse	1	0.69
CNV11111 az	AC Oil Dye	1	1.99
CNVR134A AZ	Refrigerant Per Pound	2	5.00

Invoice Number K10104 **Date** 8/19/2019 **Mileage** 79795 **Job Value** 179.45

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked and charged AC
Replaced passenger side blend door actuator.

Labor	Value
Check AC	55.25
Check Noise when shutting off vehicle	82.88

Parts		Qty	Value
CNVR134A AZ	Refrigerant Per Pound	1	3.33
CNV604108 AZ	Actuator	1	35.99

Invoice Number K9824 **Date** 4/11/2019 **Mileage** 79512 **Job Value** 381.55

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked power steering fluid is low. Checked for leaks and found return line rusted through and leaking. Replaced ps return line to steering rack.
Checked for coolant leak and found water pump is leaking. Replaced water pump and refilled cooling system.

Labor	Value
Power steering issue	138.13
Coolant leak	110.50

Parts		Qty	Value
CNV209579 15 carlisle	Pipeps line	1	50.77
CNVazpsf32 az	Power Steering Fluid	1	2.78
CNVT1205 advance	Water Pump	1	54.39
CNVAQA05 3 AZ	Anti-freeze Dexcool	2	20.99

Invoice Number K9645 **Date** 1/29/2019 **Mileage** 79169 **Job Value** 140.17

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description NULL

Labor	Value
Change Battery	27.63

Parts		Qty	Value
CNV34FT2 ADV	Battery	1	110.54

Invoice Number K9575 **Date** 1/3/2019 **Mileage** 79169 **Job Value** 73.95

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description NULL
NULL
State Inspection
Replaced wiper blades

Labor	Value
State Emissions Inspection	22.10
Emissions Phone Transaction Fee	1.65
State inspection	33.15
replace wiper blades	11.05

Parts		Qty	Value
CNVDL22 az	Wiper Blade	2	6.00

Invoice Number K9394 **Date** 10/9/2018 **Mileage** 78489 **Job Value** 135.57

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Diagnosed check engine light has code p0449 evap. vent solenoid circuit. Found vent solenoid bad. Replaced evap. vent solenoid and wire harness.

Labor	Value
SES light on	73.06

Parts		Qty	Value
CNV192576 03 carlisle	Wire Harness	1	26.41
CNV209525 23 carlisle	Vent Solenoid	1	34.10

Invoice Number K9265 **Date** 8/10/2018 **Mileage** 78260 **Job Value** 800.86

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
Replaced Power steering pump and Rack. Replaced power steering pump a second time due to defective pump. Replaced both outer tie rod ends. Took to Grahams for alignment.
Front End Alignment Carlisle Cadilac

Labor	Value
Service	28.10
Check power steering	281.00
Front End Alignment	52.00

Parts		Qty	Value
CNVWWFliu d	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	5	9.25
CNVPH2 BC	Oil Filter	1	3.54
CNV63139 AZ	Power Steering Pump	1	71.99
CNV36-125 5 Napa	Steering Rack	1	220.49

CNV269-30 45 Napa	Tie Rods		2	129.34

Invoice Number K8801 **Date** 1/23/2018 **Mileage** 76604 **Job Value** 57.85

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description NULL
NULL
State Inspection

Labor	Value
State Emissions Inspection	22.48
Emissions Phone Transaction Fee	1.65
State inspection	33.72

Parts		Qty	Value

Invoice Number K8379 **Date** 8/1/2017 **Mileage** 73514 **Job Value** 40.70

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Labor	Value
Service	28.86

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	4	5.96
CNVPH9837BC	Oil Filter	1	2.73

Invoice Number K8240 **Date** 5/26/2017 **Mileage** 72004 **Job Value** 23.09

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked all tire pressures. Relearned tire pressure sensors and test drove. All sensors working now.

Labor	Value
tire pressure light on	23.09

Parts		Qty	Value

Invoice Number K7925 **Date** 12/28/2016 **Mileage** 70631 **Job Value** 238.42

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description NULL
NULL
State Inspection
NULL
Replaced front brakes and rotors

Labor	Value
State Emissions Inspection	23.30
Emissions Phone Transaction Fee	1.65
State inspection	34.94
Rotate Tires	11.65
replace front brakes and rotors	69.89

Parts		Qty	Value
CNVDGC1159 az	Brake Pads	1	23.25
CNV55126 az	Brake RotorDisc	2	71.74

Invoice Number K7653 **Date** 8/24/2016 **Mileage** 68335 **Job Value** 84.64

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
Checked codes. Found code P0455. Removed gas cap and tested for leaks. Cap tested good.
Tightened cap and cleared codes.

Labor	Value
Service	29.12
Check engine Light on	43.68

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	4	5.96
CNVPH9837BC	Oil Filter	1	2.73

Invoice Number K7163 **Date** 1/15/2016 **Mileage** 65088 **Job Value** 216.08

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description NULL
NULL
NULL
Replaced rear brakes rear rotors and installed brake hardware kit.

Labor	Value
State Emissions Inspection	23.58
Emissions Phone Transaction Fee	1.47
State Inspection	35.36
replace rear brakes	73.68

Parts		Qty	Value
CNVDG814az	rear brakes	1	27.99
CNV55125az	Brake RotorDisc	2	45.48
CNVH5626Q az	hardware kit	1	6.52

Invoice Number K6943 **Date** 10/14/2015 **Mileage** 63446 **Job Value** 86.37

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed
NULL
NULL

Labor	Value
Service	26.35
Rotate Tires	21.08
Replace blades	10.54

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30Petro	Oil	5	6.71
CNVPH9837BC	Oil Filter	1	2.64
CNV89001016 Graham	Wiper Blade 22 inch	2	15.90

Invoice Number K6237 **Date** 12/16/2014 **Mileage** 58486 **Job Value** 254.84

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed
NULL
NULL
NULL
Replaced front sway bar bushings and end links.

Labor	Value
Service	25.31
State Emissions Inspection	16.88
Emissions Phone Transaction Fee	1.47
State Inspection	25.31
Replace front sway bar sway bar is broken	84.38

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30Petro	Oil	5	6.71
CNVPH9837BC	Oil Filter	1	2.64
CNV927-100 az	sway bar kit	1	86.99

Invoice Number K5715 **Date** 4/24/2014 **Mileage** 54466 **Job Value** 111.38

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed
NULL
Replaced engine air filter
Replaced cabin air filter

Labor	Value
Service	25.31
Rotate Tires	16.88
replace engine air filter	10.55
replace cabin filter	21.10

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30Petro	Oil	5	8.06
CNVPH9837BC	Oil Filter	1	2.64
CNVSA10014 az	Air Filter	1	12.08
CNVCAF1706 az	Cabin Air Filter	1	9.62

Invoice Number K5500 **Date** 1/13/2014 **Mileage** 52580 **Job Value** 122.02

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description NULL
NULL
NULL
Changed transmission fluid and filter. Refilled with new transmission fluid.

Labor	Value
State Emissions Inspection	16.88
Emissions Phone Transaction Fee	1.47
State Inspection	25.31
change transmission fluid and filter	42.19

Parts		Qty	Value
CNVTF207az	transmission filter	1	13.29
CNVDexron 6 Petro	Automatic Transmission Fluid Dextron 6	8	20.88

Invoice Number K5379 **Date** 10/24/2013 **Mileage** 51919 **Job Value** 14.32

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Replaced right rear reverse light bulb

Labor	Value
reverse light out	13.52

Parts		Qty	Value
CNV67 CQ	Light Bulb	1	0.80

Invoice Number K5124 **Date** 6/21/2013 **Mileage** 0 **Job Value** 85.92

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description NULL
Lube Oil Filter Changed
NULL

Labor	Value
Rotate Tires	18.03
Service	27.05
Replace blades	11.27

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	0.99
CNV5w-30 Petro	Oil	5	8.06
CNVPH9837BC	Oil Filter	1	2.52
CNVCWP22-51-CQ	Windshield Wiper Blade	2	16.00

Invoice Number K4748 **Date** 12/18/2012 **Mileage** 46151 **Job Value** 79.10

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed
NULL
NULL
NULL

Labor	Value
Service	24.36
State Emissions Inspection	16.24
Emissions Phone Transaction Fee	1.47
State Inspection	24.36

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	0.99
CNV5w-30 Petro	Oil	4	7.16
CNVPH9837BC	Oil Filter	1	2.52

Invoice Number K4693 **Date** 11/14/2012 **Mileage** 45585 **Job Value** 107.55

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Jump started vehicle. Checked and charged battery. Tested battery and found to be bad. Replaced battery.

Labor	Value
Jump Start Check battery	40.60

Parts		Qty	Value
CNV34-BAZ	Duralast battery	1	64.95

Invoice Number K4668 **Date** 10/31/2012 **Mileage** 45401 **Job Value** 81.20

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked brakes. Brakes ok. Removed all brake pads and sanded pads. sprayed pads with ant-squeal. Cleaned rust off brake rotors and lubed caliper pins.

Labor	Value	Parts		Qty	Value
Check brake Noise	81.20				

Invoice Number K4420 **Date** 7/10/2012 **Mileage** 43338 **Job Value** 141.50

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked for vibration. Found front brake rotors warped. Replaced front brake rotors and brakes

Labor	Value	Parts		Qty	Value
Check for vibration	33.11	CNVDG1159 AZ	Brake Pads	1	35.69
		CNV55126 AZ	Brake Rotors	2	70.70

Invoice Number K4391 **Date** 6/19/2012 **Mileage** 42814 **Job Value** 386.96

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed
Mount and balance 4 new tires.
NULL

Labor	Value	Parts		Qty	Value
Service	19.87	CNVWWFliud	Windshield Washer Fluid	1	0.99
Mount 4 new tires.	33.11	CNV5w-30 Petro	Oil	5	8.95
Tire Disposal Fee	9.00	CNVPH9837 BC	Oil Filter	1	2.08
		CNV732-354-500 STTC	Goodyear 2256016 Tires	4	308.96

Invoice Number K4186 **Date** 2/9/2012 **Mileage** 39312 **Job Value** 16.56

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Checked battery. Reading 12-51 volts. Checked charging. Vehicle is charging at 14.5 volts. System OK.

Labor	Value	Parts		Qty	Value
Check battery and charging system	16.56				

Invoice Number K4138 **Date** 1/23/2012 **Mileage** 38641 **Job Value** 159.57

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed
NULL
Emissions Inspection
NULL
Replaced front brake pads for inspection

Labor	Value	Parts		Qty	Value
Service	19.87	CNVWWFliud	Windshield Washer Fluid	1	0.99
State Inspection	19.87	CNV5w-30 Petro	Oil	5	8.25
Emissions Inspection	13.24	CNVS3675 AZ	Oil Filter	1	4.13
Emissions Phone Transaction Fee	2.40	CNVSS-8269-X Napa	Brake Pads	1	61.99
Replace front brakes	24.83				

Invoice Number K3878 **Date** 9/2/2011 **Mileage** 34432 **Job Value** 32.93

Vehicle Details ADU14 PA CHEVROLET IMPALA 2008

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	18.08			

CNVWWFliud	Windshield Washer Fluid	1	0.99
CNV5w-30 PPC	Oil	5	8.25
CNVPF61AZ	Oil Filter	1	3.61