EQUIPMENT MAINTENANCE RECORD
2005 Ford Explorer SUV 4x4

Date	Miles/Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
		Napa Motorcraft				
		Oil Filter 1372 FL820S				
		Fuel Filter 3243 FG1083				
		Air Filter 2284 AF1127F				
Apr-05	250	Bought the Ford Explorer new from Winner Ford for				
		$21,074.00				
4/19/2005	254	Fabricate and installed radios and antennas.	Antenna and bracket	$58.34	16	$282.40
			Extra cable	$26.91		
			Radio tower	$57.54		
4/21/2005	310	Had a spare key made at Keystone Ford.	Spare key	$18.75	1	$17.65
		I programmed the key.				
4/27/2005	405	Installed Antrim decals on doors.	2 Decals	$24.00	1	$17.65
6/14/2005	1583	Troubleshoot 2-way radio not working.	2 Way-radio mic.	$38.50	3	$52.95
		Replaced 2-way radio mic.	Light receptacle	$6.29		
		Mounted fire extinguisher.	Pintle hook assembly	$156.53		
		Installed a trailer plug receptacle.				
		Bought a pintle hook assemble from Statlers.				
9/16/2005	3109	Changed oil and oil filter. (Serviced)	5 qts. oil	$8.35	1	$17.65
			Oil filter	$4.59		
4/27/2006	5680	Inspection at Myers Diesel.	Insp. fee	$18.87		
6/1/2006	6586	Changed oil and oil filter. (Serviced)	5 qts. oil	$8.75	1	$18.55
			Oil filter	$4.69		
3/2/2007	10084	Changed oil and oil filter. (Serviced)	5 qts. oil	$10.75	3	$60.00
		Installed window visors.	Oil filter	$4.69		
			Window visors	$68.87		
3/20/2007	10205	Repaired rear wiper arm assembly.			1	$20.00
4/18/2007	10413	Inspection at Myers Diesel.	Insp. fee	$18.87		
5/15/2007	10667	Troubleshoot no electric at power point.			2	$40.00

		Removed center console and repaired loose connection.				
4/9/2008	13181	Took the vehicle to Decals and More.	Decals & More bill	$70.00		
		They installed a 3M reflective decal on the rear hatch door.				
4/14/2008	13208	Inspection at Myers Diesel.	Insp. fee	$21.70		
5/19/2008	13481	Changed oil and oil filter. (Serviced)	5 qts. oil	$11.30	2	$41.40
		Rotate tires.	Oil filter	$4.69		
4/15/2009	16874	State Inspection at Myers Diesel.	Insp. fee	$21.70		
6/18/2009	17575	Changed oil and oil filter. (Serviced)	5 qts. oil	$14.55	7	$149.45
		Installed a rear cargo mat.	Oil filter	$4.95		
		Washed and cleaned inside and out.	Cargo mat	$95.65		
4/15/2010	20293	Inspection at Myers Diesel.	Insp. fee	$21.70		
5/3/2010	20561	Changed oil and oil filter.	5qts. oil	$12.75	8	$170.80
		Washed and cleaned inside and out.	Oil filter	$5.35		
			Seal	$4.23		
8/6/2010	21384	Troubleshoot check engine light staying on at dash panel.	Fuel pump assy.	$349.10	10	$213.50
		Troubleshoot erratic fuel gauge.	2 Fuel filters	$27.28		
		Removed the fuel tank and replaced the fuel pump assy.				
		Replaced the fuel filter.				
		(I put 2 fuel filters on because I damaged the first one				
		installing it into its holding bracket)				
		Installed the fuel tank back on the vehicle.				
		Labeled emergency flashing light switches on the console.				
4/12/2011	22937	Inspection at Myers Diesel.	Insp. fee	$21.70		
4/15/2011	22950	Com-Pros came to our shop removed the old 2-way radio				
		and partially installed the new 2500 series digital radio.				
		(A copy of the bill is kept in the digital radio files)				
June, 2011		Received Com-Pros bill for the new 2500 series digital	Digital 2-way radio	$2,987.50		
		2-way radio, labor cost to remove the old 2-way radio and	Partial instillation	$100.00		
		partially install the new digital radio.				
		(A copy of the bills are kept in the digital radio files)				

8/29/2011	24464	Changed oil and oil filter. (Serviced)	5 qts. oil	$13.15	10	$219.90
		Rotate tires.	Oil filter	$1.79		
		Troubleshoot rear hatch leaking when it rains.	2 Front wiper blades	$9.76		
		Sealed left hatch window hinge assembly.	1 Rear wiper blade	$4.74		
		Replaced wiper blades.				
		Fabricate and installed a mic bracket for the new digital				
		2-way radio.				
		Mount speaker to the new digital 2-way radio.				
		Ran and hooked up switch wire to the new digital radio.				
		Removed the old scanner radio, antenna and wiring.				
9/12/2011	24662	Got the Explorer back from Dave Shockeys Auto Body.	Dave Shockeys bill	$490.80		
		They repaired the damaged left rear quarter panel.				
		Dave Shockeys bill was $490.80.				
		(A copy of the bill is kept in the vehicles files)				
		We took the vehicle to them on 9/6/2011.				
4/23/2012	27165	Inspection at Myers Diesel.	Insp. fee	$26.42		
7/31/2012	28480	Changed oil and oil filter.	5 qts. oil	$14.75	16	$355.36
		(Serviced)	Oil filter	$5.53		
		Rotate tires.	Battery	$85.46		
		Troubleshoot engine not starting.	Screws, bushings & etc.	$6.65		
		Replaced battery.	2 Antrim decals	$24.00		
		Cleaned and repaired battery cables.	Repair manuals	$57.14		
		Troubleshoot AC air only coming out of the defroster				
		vents.				
		Removed dash panels, 2 way radio and etc.				
		Fabricate and repaired an arm assembly on the blend door				
		to the air flow system.				
		Removed old and installed new Antrim Township decals				
		on the 2 front doors.				
		Bought repair manuals.				
12/17/2012	29722	Replaced broken drivers seat panel.	Panel assembly	$27.86	3	$66.63
		Replaced broken drivers seat latch handle.	Seat latch handle	$10.82		
4/25/2013	31187	Inspection at Myers Diesel.	Insp. fee	$26.42		
6/14/2013	32523	Changed oil, oil and air filters. (Serviced)	5 qts. oil	$14.75	12	$266.52
		Troubleshoot rattle noise in the back of the vehicle.	Oil filter	$5.53		
		Adjust rear hatch door.	Air filter	$10.40		

		Rotate tires.	2 Front wiper blades	$7.90		
		Replaced front and rear wiper blades.	1 Rear wiper blade	$3.95		
		Washed and cleaned the Explorer inside and out.				
3/4/2014	36638	Troubleshoot engine miss.	6 Spark plugs	$29.70	8	$180.32
		Replaced spark plugs.	5 qts. oil	$14.75		
		Changed oil, oil and fuel filters.	Oil filter	$3.13		
		Greased. (Serviced)	Fuel filter	$12.79		
		Replaced all 3 wiper blades.	Fuel line retaining clips	$17.16		
		Rotate tires.	2 Front wiper blades	$9.18		
			1 Rear wiper blade	$4.59		
			Fuel additive	$12.31		
4/11/2014	37453	Inspection at E.L.M garage.	Insp. fee	$30.00		
10/15/2014	39838	Bought 4 tires at Byers Tire.	4 Tires	$413.36	8	$180.32
		Took all 4 tires off of the explorer and took them to Byers	4 Mounts/Balance	$80.00		
		Tire to have new tires put on.	4 Valve stems	$9.56		
		Replaced front brake pads and rotors.	4 Tire disposals	$8.00		
		Replaced rear brake pads and rotors.	Front & rear brake pads	$75.90		
			Front & rear brake rotors	$141.32		
3/26/2015	42411	Changed oil and oil filter.	5 qts. oil	$15.80	4	$91.96
		(Serviced)	Oil filter	$4.98		
		Replaced wiper blades.	2 Wiper blades	$9.18		
		Repaired emergency safety triangle type flares.	C batteries for flares	$14.99		
4/7/2015	42644	Bought a storage bag for the MSDS hand book and the	Storage bag	$29.99		
		safety S.O.S type flares.				
4/27/2015	43074	Inspection at E.L.M garage.	Insp. fee	$30.00		
5/6/2015	43134	Troubleshoot no windshield washers.	Numbers	$5.16	2	$45.98
		Repaired windshield washers.				
		Replaced the # 39 decals on the front fenders.				
6/23/2015	43926	Replaced broken flash light.	Flash light	$4.99	1	$22.99
		Repaired 2-way radio mounting.				
9/3/2015	44546	The Explorer was backed into with Truck #25. It damaged				
		the hood, grill and etc.				
		Truck #25 was not damaged.				

EQUIPMENT MAINTENANCE RECORD
2005 Ford Explorer SUV 4x4

4/26/2016	46291	Got the SUV back from Keystone Ford.	Keystone Fords bill	$303.26		
		They serviced the transmission.				
		They changed the transmission filter, fluid and flushed.				
		They did a Pa. Inspection.				
		Keystone Fords bill was $303.26.				
		(A copy of the bill is kept in the SUV's file)				
4/20/2017	49471	Inspection at Myers Diesel.	Insp. fee	$31.15		
5/2/2017	49690	Change oil and oil filter.	2 Ball joint/Control arms	$277.27	8	$191.36
		Greased. (Serviced)				
		Replaced both left and right upper ball joints and control				
		arm assemblies.				
5/3/2017	49699	Took the Explorer to Byers Tire for a front end alignment.	Front end alignment	$69.95		
10/19/2017	51370	Troubleshoot clicking noise in rear wheels.			2	$47.84
		Could not find anything wrong.				
		Came to the conclusion the small stones in the tires might				
		be causing the noise.				
		Cleaned the stones out of the tire tread and took it for a				
		test run and did not hear any noise in the wheels.				
11/28/2017	51552	Got the Explorer back from Dave Shockeys Auto Body.	Dave Shockeys bill	$937.50		
		They replaced the damaged hood and repaired the grille.				
		Dave Shockeys bill was $937.50.				
		The bill was $548.09 less than the quote because he was				
		able to repair the grille and not replace it.				
		(A copy of the bill and quote is kept in the vehicles file)				
11/30/2017	51584	Replaced both front wiper blades.	2 Wiper blades	$9.38		
4/26/2018	52551	Inspection at Myers Diesel.	Insp. fee	$33.02		
12/13/2018	54696	Changed oil and oil filter.	5 qts. oil	$15.80	8	$195.20
		Greased. (Serviced)	Oil filter	$5.77		
		Washed, cleaned and waxed vehicle.				
1/31/2019	54831	Troubleshoot engine not starting.	Battery	$113.99	3	$74.67
		Replaced battery.	2 Hyd. hood cylinders.	$44.26		
		Cleaned and repaired battery cables.				

		Replaced hyd. hood cylinders.				
4/25/2019	55319	Inspection at Myers Diesel.	Insp. fee	$35.85		
4/16/2020	56840	Inspection at Myers Diesel.	Insp. fee	$37.74		
4/17/2020	56885	Troubleshoot engine miss.	6 Spark plugs	$27.00	6	$152.34
		Replaced all 6 spark plugs.				
		Repaired vacuum line.				
		(I pulled check engine light code P0302 cylinder number				
		2 miss fire. I found cylinder #2 spark plugs electron was				
		broken.)				
4/21/2021	57916	Inspection at Myers Diesel.	Insp. fee	$37.74		
2/15/2022	59744	Changed oil, air and fuel filters.	5 qts. oil	$15.80	8	$212.24
		Greased. (Serviced)	Oil filter	$7.19		
		Aired and rotated tires.	Air filter	$8.51		
		Replaced both front and rear wiper blades.	Fuel filter	$7.57		
		Checked lights.	2 Front wiper blades	$9.88		
		Replaced SOS safety flare batteries.	1 Rear wiper blade	$7.58		
		Washed SUV.	SOS batteries	$28.98		
4/5/2022	60064	Inspection at Myers Diesel.	Insp. fee	$43.40		
12/20/2022		Replaced batteries in SOS flares.	SOS batteries	$39.98	1	$26.53
		Repaired loose fire extinguisher.				
4/20/2022	62244	Inspection at Myers Diesel.	Insp. fee	$43.40		
9/13/2023	62598	Removed old Antrim door decals.	2 Antrim decals	$28.00	4	$127.20
		Installed new Green/Gold Antrim door decals.				
		Removed old #39 decals.				
		Installed new #39 decals.				
2/6/2024	64101	Serviced vehicle			4	$94.76
		Changed oil	5qt. @3.63/qt	$18.15		
		Oil filter		$6.58		
		Air filter		$19.87		
		Antifreeze		$3.59		
		Fuel stable		$4.99		
		Batteries for flares	C batteries, 8 pack	$12.99		

EQUIPMENT MAINTENANCE RECORD
2005 Ford Explorer SUV 4x4

4/22/2024	65443	State inspection Myers Diesel	State inspection	$51.89		
1/15/2025	68270	Serviced vehicle				
		Changed oil	5qt. @3.63/qt	$18.15		
		Oil filter		$7.13		
		Air filter		$19.87		
		Fuel filter		$22.22		