\T.R.M.U.A.\Main Location\REHABILITATION

73 - 2009 CHEVROLET 3500 SERVICE BOD

2009 CHEVROLET 3500 SERVICE BODY

Unit #: 73 Serial #: 1GBJK74K69E134180
Tag #: XT211G
Mileage 76,288

Date	Mileage	Notes	Vendor	Employee	Total Cost
8/5/2009	124			,	$0.00

Maintenance Performed

	Cost
Installed company radio	$0.00
installed strobe lights	$0.00
Installed beacon	$0.00
outside speaker	$0.00
Installed cabinet lights	$0.00
Installed floor mats	$0.00
Installed flash light	$0.00
Total:	**$0.00**

9/2/2009	928			,	$0.00

Maintenance Performed

	Cost
OIL AND FILTER check fluids	$0.00
Installed grab handles on rear of body	$0.00
Installed computer stand	$0.00
Total:	**$0.00**

11/4/2009	1,527		Jim Curley	,	$0.00

Maintenance Performed

	Cost
Installed trailer plug	$0.00
EVAP system check engine light under warenty	$0.00
Total:	**$0.00**

Labor - Tech	Description	Hours	Rate	Cost
Jim Curley		1	$0.00	$0.00
			Total:	**$0.00**

12/17/2009	2,554			,	$0.00

Maintenance Performed

	Cost
Installed rain guards	$0.00
Installed mud flaps for front tires	$0.00
Total:	**$0.00**

1/4/2010	2,554			,	$0.00

Maintenance Performed

	Cost
Replaced left rear turn signal lamp	$0.00
Total:	**$0.00**

3/24/2010	4,403			,	$0.00

Maintenance Performed

	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

8/10/2010	7,238			,	$0.00

Maintenance Performed

	Cost
OIL AND FILTER check fluids	$0.00
Reset check engine light	$0.00
Fabricated reciever for vise	$0.00
Total:	**$0.00**

8/11/2010 7,238 , $0.00

Maintenance Performed	Cost
Replaced right and left cab marker lights	$0.00
Total:	**$0.00**

2/23/2011 9,975 , $0.00

Maintenance Performed	Cost
Installed priority start	$0.00
Total:	**$0.00**

3/22/2011 10,310 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

Part	Name	Used	Unit Cost	Cost
WIX-57060		1	$0.00	$0.00
			Total:	**$0.00**

10/7/2011 13,810 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
rotaed tires	$0.00
Total:	**$0.00**

Part	Name	Used	Unit Cost	Cost
WIX-57060		1	$0.00	$0.00
WIX-42487	AIR FILTER	1	$0.00	$0.00
			Total:	**$0.00**

3/8/2012 15,048 , $0.00

Maintenance Performed	Cost
replaced communications radio	$0.00
Total:	**$0.00**

4/4/2012 15,048 , $0.00

Maintenance Performed	Cost
repaired right rear tire	$0.00
Total:	**$0.00**

6/18/2012 17,217 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

Part	Name	Used	Unit Cost	Cost
WIX-57060		1	$0.00	$0.00
			Total:	**$0.00**

8/8/2012 18,077 , $0.00

Maintenance Performed	Cost
cleared c/k engine light codes for evap leak	$0.00
Total:	**$0.00**

12/5/2012 20,358 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
replaced group 48 batt.	$0.00
replaced priority start	$0.00
cleared codes	$0.00
Total:	**$0.00**

Part	Name	Used	Unit Cost	Cost
WIX-57060		1	$0.00	$0.00
			Total:	**$0.00**

2/27/2013 22,000 , $0.00

Maintenance Performed	Cost
Replaced 2 Front TIRES	$0.00
Total:	**$0.00**

5/16/2013 23,663 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

Part	Name	Used	Unit Cost	Cost
WIX-57060		1	$0.00	$0.00
			Total:	**$0.00**

7/17/2013 25,198 , $0.00

Maintenance Performed	Cost
replaced EVAP vent control selanoid	$0.00
Total:	**$0.00**

3/19/2014 28,630 , $0.00

Maintenance Performed	Cost
Replaced 4 rear tires	$0.00
Total:	**$0.00**

6/18/2014 30,169 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

Part	Name	Used	Unit Cost	Cost
WIX-57060		1	$0.00	$0.00
			Total:	**$0.00**

3/3/2015 33,688 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

11/2/2015 37,150 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
clearded ck eng light	$0.00
Total:	**$0.00**

8/31/2016 40,957 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
repared rt rear tire	$0.00
Total:	**$0.00**

1/23/2017 43,008 , $0.00

Maintenance Performed	Cost
replaced front rotors and pads	$0.00
replaced rear rotors and pads	$0.00
OIL AND FILTER check fluids	$0.00
replaced pass. side rear tire	$0.00
replaced wiper blades	$0.00
checked roof leak	$0.00
Total:	**$0.00**

6/21/2017 43,868 , $0.00

Maintenance Performed	Cost
ck for oil leak	$0.00
installed computer mount	$0.00
Total:	**$0.00**

8/29/2017 45,582 , $0.00

Maintenance Performed	Cost
replaced 4 O2 sensors	$0.00
replaced drivers side headlight	$0.00
Total:	**$0.00**

10/19/2017 46,204 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

11/8/2017 46,687 , $0.00

Maintenance Performed	Cost
replaced rear rotors ,pads and seals	$0.00
Total:	**$0.00**

11/28/2017 46,687 , $0.00

Maintenance Performed	Cost
Replaced batt:	$0.00
Total:	**$0.00**

3/2/2018 48,281 , $0.00

Maintenance Performed	Cost
replaced batt with a gel batt and replaced terminals	$0.00
Total:	**$0.00**

3/7/2018 48,281 , $0.00

Maintenance Performed	Cost
replaced drivers side rear oil seal	$0.00
Total:	**$0.00**

3/15/2018 48,281 , $0.00

Maintenance Performed	Cost
replaced evap vent selanoid	$0.00
Total:	**$0.00**

5/11/2018 49,542 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

8/14/2018 50,923 , $0.00

Maintenance Performed	Cost
replaced rear outside tires	$0.00
Total:	**$0.00**

2/21/2019 53,645 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

3/5/2019 53,645 , $0.00

Maintenance Performed	Cost
replaced AC belt and serp belt and tensioner and pully	$0.00
Total:	**$0.00**

10/29/2019 57,513 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
replaced front tires	$0.00
Total:	**$0.00**

12/9/2020 62,630 , $0.00

Maintenance Performed	Cost
replaced group 48 batt and charger	$0.00
Total:	**$0.00**

1/13/2021 63,622 , $0.00

Maintenance Performed	Cost
replaced 4x4 shifter and linkage	$0.00
Total:	**$0.00**

1/22/2021 63,793 , $0.00

Maintenance Performed	Cost
installed new golight	$0.00
Total:	**$0.00**

4/23/2021 65,078 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

9/16/2021 68,917 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Replaced knock sensors	$0.00
Total:	**$0.00**

1/5/2022 71,933 , $0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
replaced starter	$0.00
Replaced batt:	$0.00
serviced trans	$0.00
Total:	**$0.00**

8/24/2022	73,336	,	$0.00

Maintenance Performed	Cost
replaced trans cooler lines	$0.00
Total:	**$0.00**

1/10/2023	74,515	,	$0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

11/2/2023	76,288	,	$0.00

Maintenance Performed	Cost
OIL AND FILTER check fluids	$0.00
Total:	**$0.00**

Total:	**Cost Per Mi/Km/Hr:**	**$0.00**	**$0.00**

Grand Total: **$0.00**