Veh #	Year	Make	Model	VIN	Registration Number	Purchase cost	
28	2001	International	4900 Telelect 46OM	1HTSDAAR0IH355787	M65557	$129,470.00	
Date	**Miles/Hrs**	**Description of Repairs**				**Repair Cost**	**Shop**
5/21/03	10168/	PM Service				$276.70	On-Site
6/12/03		Cab Guard & PTO Shaft Repair				$1,141.02	Kiley
8/14/03		Jib Ext. Pin (TT66947)				$30.72	Kiley
8/27/03	/3151	PM Service				$256.70	On-Site
9/16/03		Mirror (BE ZEE2515) Rt Heated				$49.14	Coastal
11/26/03	/3417	PM Service				$265.00	On-Site
2/19/04	12519/	R&R Clutch Assy				$1,192.10	Minuteman
5/11/04	/3947	PM Service				$345.50	On-Site
6/22/04		List of Repairs				$1,133.46	Kiley
7/22/04	13799/	List of Repairs				$347.83	Minuteman
7/28/04	13898	Clutch Adjustment				$52.00	Minuteman
8/11/04	/4228	PM Service				$275.50	On-Site
10/30/04	14388/	Front End Pulls Right				$306.10	Minuteman
10/22/04		Dash Panel (1659929C2)				$8.19	Coastal
10/21/04		Bucket Scuff Pad (UPDS-8)				$130.80	Kiley
11/17/04	/4500	PM Service				$281.50	On-Site
12/1/04		Tires (4) 11R22.5 Goodyear G164				$904.16	Sullivan
1/5/05		Strobe Light 1200DHA				$294.01	Kiley
2/16/05	/4734	PM Service				$281.50	On-Site
4/15/05		Replace Bucket				$3,179.15	Kiley
4/25/05		Rope Assy 1/2 x 75' (TT73620)				$283.12	Kiley
4/27/05	16270	ABS Light on				$68.00	Minuteman
5/25/05	/5011	PM Service				$275.50	On-Site
6/21/05	16656/	ABS Light On / Adjust Clutch				$231.84	Coastal
8/24/05	/5205	PM Service				$280.00	On-Site

9/9/05		Hydraulic Fittings	$49.48	Nor-Will
11/14/05	18071/	ABS Light On	$333.26	Coastal
11/16/05	/5403	PM Service	$286.00	On-Site
12/6/05		Mud Flap	$28.85	Kiley
2/23/06	/5637	PM Service	$286.00	On-Site
5/17/06	/5841	PM Service	$289.00	On-Site
8/16/06	/6103	PM Service	$289.00	On-Site
9/5/06		Mirror (BE ZEE2515) Rt Heated / Pocket / Fastener	$107.53	Coastal
12/31/06		Replace Bucket / Emergency Pump / Hardware	$3,894.22	DC Bates
12/18/06		Tow	$285.00	Mike's
12/20/06	22395/	Troubleshoot Fuel Problem	$95.00	Minuteman
1/5/07	22396/	Fuel Problem / Clutch Adjust / PM Service	$862.35	Coastal
1/23/07	22554/	Electrical Problem	$106.74	Coastal
3/1/07		Lift Rotator Problem	$123.58	DC Bates
6/18/07		Repair Pedistal Crack	$1,178.70	Kiley
6/29/07		Hydraulic Pump Replace	$1,660.09	DC Bates
8/8/07		Rope Assy 1/2 x 75' (TT73620)	$311.34	Kiley
8/22/07	/6837	PM Service	$294.00	On-Site
9/11/07		Boom Rest	$43.35	Kiley
		Total	**$22,413.03**	
10/25/07		Tires (2) 11R22.5 G149	$622.00	Sullivan
11/28/07	/7109	PM Service	$377.00	On-Site
1/18/08	24847/	R&R Water Pump	$576.75	Minuteman
2/8/08		Repair Seat	$363.45	Mark's
4/30/08	25686/	R&R Parking Brake Valve	$854.94	Minuteman
6/6/08		Floor Mats	$13.64	Carquest
7/16/08	/7686	PM Service	$316.50	On-Site
10/28/08		48" Alum Chest	$569.00	NE Trk.Cap

11/19/08	/7875	PM Service	$309.00	On-Site
12/9/08		Spot Mirror	$46.60	Minuteman
3/9/09		GFI Cover	$12.19	True Value
3/25/09	/8182	PM Service	$339.00	On-Site
3/30/09	28414/	R&R Directional Switch	$273.75	Minuteman
5/8/09		Cover Plate (TT427903)	$21.12	Kiley
11/24/09		Screw (TT451367) (TT455886)	$76.46	Kiley
12/7/09		Boom Rest (TT408298) Adj. Boom Rest (TT68345)	$186.42	Kiley
12/23/09	/8877	PM Service	$297.00	On-Site
2/9/10		Handle (166512C1)	$58.31	Minuteman
2/16/10	31800/	ABS Light On	$158.21	Minuteman
4/21/10	/9150	PM Service	$300.00	On-Site
5/26/10		Refrigerant	$13.68	Allied
7/19/10		Strobe Tube	$160.60	MHQ
8/16/10		Boom Rest (TT408298) Adj. Boom Rest (TT68345)	$196.25	Kiley
8/25/10	/9472	PM Service	$303.00	On-Site
8/30/10		R&R PTO Shaft	$555.45	DC Bates
10/9/10		Switch (3564004C1) Lamp (TL/15200R)	$34.74	Minuteman
10/15/10		Switch (1661240C2)	$63.82	Minuteman
10/27/10		Universal Stud Breaker 30A (Buss BP/CBC-30B)	$3.74	Allied
10/27/10		Twist Lok Receptacle (L520R P&S 20A) Twist Lok Plug (L520P P&S 20A)	$28.91	Rexel
10/27/10		Receptacle Cover (FCLG 1 5/8" Rd.)	$32.40	Rexel
12/2/10		Mount (4) Tires	$125.00	Jake's
12/8/10		Tires (4) 11R22.5 Goodyear G622 RSD TL	$1,393.20	Sullivan
12/29/10	/9819	PM Service	$303.00	On-Site
1/25/11	35757/	Compressor Govenor	$289.80	Minuteman
2/14/11	35991/	On-Spot Chain Not Working	$635.00	Greenwood
4/25/11	/10054	PM Service	$307.50	On-Site

4/26/11	36411/	Air Modulator Valve / Air Dryer Kit / Pinion Seal / Adjust Clutch	$1,586.99	Minuteman
6/1/11		Repair Hydraulic Leak @ Boom Tip / Grind & Grease Outriggers	$495.98	DC Bates
8/17/11		Strobe Tube	$103.68	Minuteman
8/25/11	37617/	Ignition Switch	$344.65	Minuteman
11/2/11		Repair Crack at Base of Pedistal / Replace Broken Bucket / Replace Broken Upper Control Cover	$4,755.81	DC Bates
4/18/12	39317/	R&R Clutch Assy / R&R Muffler	$2,358.93	Fleet Maint.
4/18/12		Mount Tire	$284.50	Jake's
5/14/12		Boom Rest (TT426749)	$170.94	Kiley
8/1/12		Micro Switch / Fiber Switch / Pivot Kit	$1,011.70	DC Bates
9/5/12	/10831	PM Service	$319.50	On-Site
9/19/12		Replace Spool Forks / Out Rigger Alarm	$686.96	DC Bates
		Total	**$44,750.10**	
10/5/12	40019/	Two Speed Repair	$173.00	Minuteman
10/24/12		Two Speed Repair / Replace Relay & Control Pendant	$843.40	DC Bates
11/16/12	40026/	Two Speed Repair	$827.56	Minuteman
1/8/13	40636/	Two Speed Repair / Replace Switch	$317.50	Minuteman
1/9/13	/11022	PM Service	$312.00	On-Site
2/27/13		Two Speed Repair / Sent To Taylor & Lloyd	$986.00	DC Bates
3/21/13		Replace Foot Valve	$676.20	Fleet Maint.
3/29/13		Mount Tire (2)	$189.50	Jake's
4/24/12		Tires (2) 11R22.5 G622 RSD	$893.12	Ocean State
6/15/13		Dielectric Insp. - Leveling Knuckle Cracked / Upper Boom Rest Pads / Safety Hook on Winch / Crack @ Beacon Lts.	$345.00	Diversified
6/30/13		Repair Crack at Leveling Device, Boom Rest	$683.15	Kiley
10/2/13	46878	Repair oil leaks- Pwr Steer Hose	$338.10	Fleet Maint.
3/19/14	42442	Ma.Insp	$29.00	TD&I
3/26/14		Repair Strobe Lights- Switch	$200.00	P&E
4/22/14	42599	Oil Leak- HP Oil Manifold	$770.37	Minuteman
6/11/14	11517	PM Service	$323.00	On-Site
9/2/14		Winch Line 1/2 x 65'	$132.02	DC Bates
10/1/14		Dielectric Insp.	$345.00	Diversified
10/9/14		Decal- Bucket Control (TT421210)	$14.21	Kiley
10/27/14		2 Strobe Lamps (80DTUBE)	$169.54	Minuteman
11/24/14	44420	Insp for Engine Oil Leak- No Sign of Leak	$110.00	Minuteman

2/25/15	44950/11900	PM Service	$323.00	On-Site
3/24/15		Ma.Insp	$99.95	Tri.St
8/7/15		Repair Bucket Support- Reweld & Gusset	$130.00	Ren's
8/28/15	45928	Tow / AC Belt / LF Hub Cvr Seal / Clutch Adj. (brkn belt knocked off cam sensor- eng.stop)	$1,094.14	Minuteman
12/1/15	47147	Altenator / Batteries (2) / Belts	$1,017.91	Minuteman
3/22/16	47865	Ma.Insp	$99.95	Tri.St
11/15/16		**Change Truck # from 22 to # 28**		
12/22/16	12621	PM Service	$336.50	On-Site
3/16/17		Ma.Insp	$99.95	Tri.St
2/21/18		PTO Shaft Seal / Pressure Guage	$1,001.21	DC Bates
10/26/18	48969	Pressure Regulator at Foot Valve (378414)	$296.94	Minuteman
11/13/18	49058	Repair ABS Module Bracket- Rotted off Frame	$582.47	Minuteman
12/4/18	48968	Towing From Foxboro to Minutemen	$312.50	Sterry St
12/13/18	49056	PM Service	$376.90	On-Site
6/20/20	50235	MA state insp.	$135.00	Tri.St
7/31/20		Brake work	$165.00	Ira
9/29/20	13001 H	PM Service	$417.00	On-Site
9/23/21	51106/13186	PM Service	$525.00	
11/10/21		**Change Truck # from 28 to #44**		
11/29/22		Road service call, truck wont stay running	$797.58	Ira
12/5/22		Replace rear leaf spring	$1,059.93	Woodward
		Total	**$62,298.70**	
