Veh #	Year	Make	Model	VIN
28	2001	International	4900 Telelect 46OM	1HTSDAAR0IH355787

Date	Miles/Hrs	Description of Repairs
5/21/03	10168/	PM Service
6/12/03		Cab Guard & PTO Shaft Repair
8/14/03		Jib Ext. Pin (TT66947)
8/27/03	/3151	PM Service
9/16/03		Mirror (BE ZEE2515) Rt Heated
11/26/03	/3417	PM Service
2/19/04	12519/	R&R Clutch Assy
5/11/04	/3947	PM Service
6/22/04		List of Repairs
7/22/04	13799/	List of Repairs
7/28/04	13898	Clutch Adjustment
8/11/04	/4228	PM Service
10/30/04	14388/	Front End Pulls Right
10/22/04		Dash Panel (1659929C2)
10/21/04		Bucket Scuff Pad (UPDS-8)
11/17/04	/4500	PM Service
12/1/04		Tires (4) 11R22.5 Goodyear G164
1/5/05		Strobe Light 1200DHA
2/16/05	/4734	PM Service
4/15/05		Replace Bucket
4/25/05		Rope Assy 1/2 x 75' (TT73620)
4/27/05	16270	ABS Light on
5/25/05	/5011	PM Service
6/21/05	16656/	ABS Light On / Adjust Clutch
8/24/05	/5205	PM Service
9/9/05		Hydraulic Fittings
11/14/05	18071/	ABS Light On
11/16/05	/5403	PM Service
12/6/05		Mud Flap
2/23/06	/5637	PM Service
5/17/06	/5841	PM Service
8/16/06	/6103	PM Service
9/5/06		Mirror (BE ZEE2515) Rt Heated / Pocket / Fastener
12/31/06		Replace Bucket / Emergency Pump / Hardware
12/18/06		Tow

12/20/06	22395/	Troubleshoot Fuel Problem
1/5/07	22396/	Fuel Problem / Clutch Adjust / PM Service
1/23/07	22554/	Electrical Problem
3/1/07		Lift Rotator Problem
6/18/07		Repair Pedistal Crack
6/29/07		Hydraulic Pump Replace
8/8/07		Rope Assy 1/2 x 75' (TT73620)
8/22/07	/6837	PM Service
9/11/07		Boom Rest
10/25/07		Tires (2) 11R22.5 G149
11/28/07	/7109	PM Service
1/18/08	24847/	R&R Water Pump
2/8/08		Repair Seat
4/30/08	25686/	R&R Parking Brake Valve
6/6/08		Floor Mats
7/16/08	/7686	PM Service
10/28/08		48" Alum Chest
11/19/08	/7875	PM Service
12/9/08		Spot Mirror
3/9/09		GFI Cover
3/25/09	/8182	PM Service
3/30/09	28414/	R&R Directional Switch
5/8/09		Cover Plate (TT427903)
11/24/09		Screw (TT451367) (TT455886)
12/7/09		Boom Rest (TT408298) Adj. Boom Rest (TT68345)
12/23/09	/8877	PM Service
2/9/10		Handle (166512C1)
2/16/10	31800/	ABS Light On
4/21/10	/9150	PM Service
5/26/10		Refrigerant
7/19/10		Strobe Tube
8/16/10		Boom Rest (TT408298) Adj. Boom Rest (TT68345)
8/25/10	/9472	PM Service
8/30/10		R&R PTO Shaft
10/9/10		Switch (3564004C1) Lamp (TL/15200R)
10/15/10		Switch (1661240C2)
10/27/10		Universal Stud Breaker 30A (Buss BP/CBC-30B)
10/27/10		Twist Lok Receptacle (L520R P&S 20A) Twist Lok Plug (L520P P&S 20A)

10/27/10		Receptacle Cover (FCLG 1 5/8" Rd.)
12/2/10		Mount (4) Tires
12/8/10		Tires (4) 11R22.5 Goodyear G622 RSD TL
12/29/10	/9819	PM Service
1/25/11	35757/	Compressor Govenor
2/14/11	35991/	On-Spot Chain Not Working
4/25/11	/10054	PM Service
4/26/11	36411/	Air Modulator Valve / Air Dryer Kit / Pinion Seal / Adjust Clutch
6/1/11		Repair Hydraulic Leak @ Boom Tip / Grind & Grease Outriggers
8/17/11		Strobe Tube
8/25/11	37617/	Ignition Switch
11/2/11		Repair Crack at Base of Pedistal / Replace Broken Bucket / Replace Broken Up
4/18/12	39317/	R&R Clutch Assy / R&R Muffler
4/18/12		Mount Tire
5/14/12		Boom Rest (TT426749)
8/1/12		Micro Switch / Fiber Switch / Pivot Kit
9/5/12	/10831	PM Service
9/19/12		Replace Spool Forks / Out Rigger Alarm
10/5/12	40019/	Two Speed Repair
10/24/12		Two Speed Repair / Replace Relay & Control Pendant
11/16/12	40026/	Two Speed Repair
1/8/13	40636/	Two Speed Repair / Replace Switch
1/9/13	/11022	PM Service
2/27/13		Two Speed Repair / Sent To Taylor & Lloyd
3/21/13		Replace Foot Valve
3/29/13		Mount Tire (2)
4/24/12		Tires (2) 11R22.5 G622 RSD
6/15/13		Dielectric Insp. - Leveling Knuckle Cracked / Upper Boom Rest Pads / Safety Hook on Winch / Cra
6/30/13		Repair Crack at Leveling Device, Boom Rest
10/2/13	46878	Repair oil leaks- Pwr Steer Hose
3/19/14	42442	Ma.Insp
3/26/14		Repair Strobe Lights- Switch
4/22/14	42599	Oil Leak- HP Oil Manifold
6/11/14	11517	PM Service
9/2/14		Winch Line 1/2 x 65'
10/1/14		Dielectric Insp.
10/9/14		Decal- Bucket Control (TT421210)
10/27/14		2 Strobe Lamps (80DTUBE)
11/24/14	44420	Insp for Engine Oil Leak- No Sign of Leak
2/25/15	44950/11900	PM Service
3/24/15		Ma.Insp
8/7/15		Repair Bucket Support- Reweld & Gusset
8/28/15	45928	Tow / AC Belt / LF Hub Cvr Seal / Clutch Adj. (brkn belt knocked off cam senso

12/1/15	47147	Altenator / Batteries (2) / Belts
3/22/16	47865	Ma.Insp
11/15/16		**Change Truck # from 22 to # 28**
12/22/16	12621	PM Service
3/16/17		Ma.Insp
2/21/18		PTO Shaft Seal / Pressure Guage
10/26/18	48969	Pressure Regulator at Foot Valve (378414)
11/13/18	49058	Repair ABS Module Bracket- Rotted off Frame
12/4/18	48968	Towing From Foxboro to Minutemen
12/13/18	49056	PM Service
6/20/20	50235	MA state insp.
7/31/20		Brake work
9/29/20	13001 H	PM Service
9/23/21	51106/13186	PM Service
11/10/21		**Change Truck # from 28 to #44**
11/29/22		Road service call, truck wont stay running
12/5/22		Replace rear leaf spring

Registration Number	Purchase cost	
M65557	$129,470.00	
	Repair Cost	Shop
	$276.70	On-Site
	$1,141.02	Kiley
	$30.72	Kiley
	$256.70	On-Site
	$49.14	Coastal
	$265.00	On-Site
	$1,192.10	Minuteman
	$345.50	On-Site
	$1,133.46	Kiley
	$347.83	Minuteman
	$52.00	Minuteman
	$275.50	On-Site
	$306.10	Minuteman
	$8.19	Coastal
	$130.80	Kiley
	$281.50	On-Site
	$904.16	Sullivan
	$294.01	Kiley
	$281.50	On-Site
	$3,179.15	Kiley
	$283.12	Kiley
	$68.00	Minuteman
	$275.50	On-Site
	$231.84	Coastal
	$280.00	On-Site
	$49.48	Nor-Will
	$333.26	Coastal
	$286.00	On-Site
	$28.85	Kiley
	$286.00	On-Site
	$289.00	On-Site
	$289.00	On-Site
	$107.53	Coastal
	$3,894.22	DC Bates
	$285.00	Mike's

	$95.00	Minuteman
	$862.35	Coastal
	$106.74	Coastal
	$123.58	DC Bates
	$1,178.70	Kiley
	$1,660.09	DC Bates
	$311.34	Kiley
	$294.00	On-Site
	$43.35	Kiley
Total	**$22,413.03**	
	$622.00	Sullivan
	$377.00	On-Site
	$576.75	Minuteman
	$363.45	Mark's
	$854.94	Minuteman
	$13.64	Carquest
	$316.50	On-Site
	$569.00	NE Trk.Cap
	$309.00	On-Site
	$46.60	Minuteman
	$12.19	True Value
	$339.00	On-Site
	$273.75	Minuteman
	$21.12	Kiley
	$76.46	Kiley
	$186.42	Kiley
	$297.00	On-Site
	$58.31	Minuteman
	$158.21	Minuteman
	$300.00	On-Site
	$13.68	Allied
	$160.60	MHQ
	$196.25	Kiley
	$303.00	On-Site
	$555.45	DC Bates
	$34.74	Minuteman
	$63.82	Minuteman
	$3.74	Allied
	$28.91	Rexel

	$32.40	Rexel
	$125.00	Jake's
	$1,393.20	Sullivan
	$303.00	On-Site
	$289.80	Minuteman
	$635.00	Greenwood
	$307.50	On-Site
	$1,586.99	Minuteman
	$495.98	DC Bates
	$103.68	Minuteman
	$344.65	Minuteman
pper Control Cover	$4,755.81	DC Bates
	$2,358.93	Fleet Maint.
	$284.50	Jake's
	$170.94	Kiley
	$1,011.70	DC Bates
	$319.50	On-Site
	$686.96	DC Bates
Total	**$44,750.10**	
	$173.00	Minuteman
	$843.40	DC Bates
	$827.56	Minuteman
	$317.50	Minuteman
	$312.00	On-Site
	$986.00	DC Bates
	$676.20	Fleet Maint.
	$189.50	Jake's
	$893.12	Ocean State
ack @ Beacon Lts.	$345.00	Diversified
	$683.15	Kiley
	$338.10	Fleet Maint.
	$29.00	TD&I
	$200.00	P&E
	$770.37	Minuteman
	$323.00	On-Site
	$132.02	DC Bates
	$345.00	Diversified
	$14.21	Kiley
	$169.54	Minuteman
	$110.00	Minuteman
	$323.00	On-Site
	$99.95	Tri.St
	$130.00	Ren's
r- eng.stop)	$1,094.14	Minuteman

	$1,017.91	Minuteman
	$99.95	Tri.St
	$336.50	On-Site
	$99.95	Tri.St
	$1,001.21	DC Bates
	$296.94	Minuteman
	$582.47	Minuteman
	$312.50	Sterry St
	$376.90	On-Site
	$135.00	Tri.St
	$165.00	Ira
	$417.00	On-Site
	$525.00	
	$797.58	Ira
	$1,059.93	Woodward
Total	**$62,298.70**	
