# *Detailed services/breakdown*



Display criteria
Period : All
Vehicle(s) : Dodge/Charger/2018

## *Vehicle : 67-84 - Dodge/Charger/2018/KTB4981*

**Service :** Oil and Filter Change (Service )
**Date :** 11/26/2018 **Technician responsible :** N/D **Cost :** $44.95
**Reference :** 7411 **Vendor responsible :** Thorntons Gulf **Odometer :** 3,634

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )
**Date :** 12/28/2018 **Technician responsible :** N/D **Cost :** $44.95
**Reference :** 8675 **Vendor responsible :** Thorntons Gulf **Odometer :** 6,728

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )
**Date :** 1/22/2019 **Technician responsible :** N/D **Cost :** $44.95
**Reference :** 10968 **Vendor responsible :** Thorntons Gulf **Odometer :** 9,645

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 3/5/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14585 **Vendor responsible :** Thorntons Gulf **Odometer :** 12,912

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 4/5/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14517 **Vendor responsible :** Thorntons Gulf **Odometer :** 15,904

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Change and Balance 2 tires (Service )

**Date :** 4/23/2019 **Technician responsible :** N/D **Cost :** $54.00

**Reference :** 13759 **Vendor responsible :** Thorntons Gulf **Odometer :** 17,362

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Change and Balance 2 tires | 1.00 | $54.00 | $54.00 |
| | | *Total service :* | | $54.00 |

**Service :** Alignment (Service )

**Date :** 4/26/2019 **Technician responsible :** N/D **Cost :** $90.00

**Reference :** 13782 **Vendor responsible :** Thorntons Gulf **Odometer :** 17,622

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Alignment | 1.00 | $90.00 | $90.00 |
| | | *Total service :* | | $90.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 5/7/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14731 **Vendor responsible :** Thorntons Gulf **Odometer :** 18,700

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Emission and State Inspection, Oil and Filter Change, Front and Rear Brakes, Front and Rear Rotors (Service )

**Date :** 6/17/2019 **Technician responsible :** N/D **Cost :** $817.95

**Reference :** 13876 **Vendor responsible :** Thorntons Gulf **Odometer :** 22,613

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Emission and State Inspection, Oil and Filter Change, Front and Rear Brakes, Front and Rear Rotors | 1.00 | $817.95 | $817.95 |
| | | *Total service :* | | $817.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 7/17/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 13967 **Vendor responsible :** Thorntons Gulf **Odometer :** 25,341

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 8/19/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14304 **Vendor responsible :** Thorntons Gulf **Odometer :** 28,300

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 10/1/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14354 **Vendor responsible :** Thorntons Gulf **Odometer :** 32,170

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Replace 2 head lights (Service )

**Date :** 10/24/2019 **Technician responsible :** N/D **Cost :** $70.00

**Reference :** 15064 **Vendor responsible :** Thorntons Gulf **Odometer :** 0

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | replace 2 headlights | 1.00 | $70.00 | $70.00 |
| | | *Total service :* | | $70.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 11/11/2019 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14787 **Vendor responsible :** Thorntons Gulf **Odometer :** 35,150

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Mount and Balance 4 Tires, Front End Alignment (Service )

**Date :** 11/26/2019 **Technician responsible :** N/D **Cost :** $195.00

**Reference :** 15205 **Vendor responsible :** Thorntons Gulf **Odometer :** 36,176

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Mount and Balance 4 Tires, Front End Alignment | 1.00 | $195.00 | $195.00 |
| | | *Total service :* | | $195.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 1/7/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 14869 **Vendor responsible :** Thorntons Gulf **Odometer :** 38,253

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | oil and filter change | 1.00 | $44.95 | $44.95 |

*Total service :* $44.95

**Service :** Front Brakes (Service )

**Date :** 2/6/2020 **Technician responsible :** N/D **Cost :** $165.00

**Reference :** 16251 **Vendor responsible :** Thorntons Gulf **Odometer :** 39,156

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Front Brakes | 1.00 | $165.00 | $165.00 |

*Total service :* $165.00

**Service :** Oil and FIlter Change (Service )

**Date :** 3/23/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 15875 **Vendor responsible :** Thorntons Gulf **Odometer :** 41,567

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and FIlter Change | 1.00 | $44.95 | $44.95 |

*Total service :* $44.95

**Service :** Replace Starter Assembly,Replace both Washers Nozzles, Update HVAC Software (Service )

**Date :** 4/21/2020 **Technician responsible :** N/D **Cost :** $84.60

**Reference :** CHCS46142 **Vendor responsible :** Videon Dodge **Odometer :** 43,382

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Starter Assembly,Replace both Washers Nozzles, Update HVAC Software | 1.00 | $84.60 | $84.60 |

*Total service :* $84.60

**Service :** Oil and Filter Change (Service )

**Date :** 5/11/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 15947 **Vendor responsible :** Thorntons Gulf **Odometer :** 44,720

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Replace Left Fuel Pump Assembly (Service )

**Date :** 5/28/2020 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS47401 **Vendor responsible :** Videon Dodge **Odometer :** 45,614

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Left Fuel Pump Assembly | 1.00 | $0.00 | $0.00 |
| | | *Total service :* | | $0.00 |

**Service :** Replace Radiator and coolant (Service )

**Date :** 6/17/2020 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS48422 **Vendor responsible :** Videon Dodge **Odometer :** 46,867

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Radiator and coolant | 1.00 | $0.00 | $0.00 |
| | | *Total service :* | | $0.00 |

**Service :** Replaced Upper and Lower Radiator Hoses, Refill Antifreez (Service )

**Date :** 7/7/2020 **Technician responsible :** N/D **Cost :** $429.62

**Reference :** CHCS49335 **Vendor responsible :** Videon Dodge **Odometer :** 47,510

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replaced Upper and Lower Radiator Hoses, Refill Antifreez | 1.00 | $429.62 | $429.62 |
| | | *Total service :* | | $429.62 |

**Service :** Replace Right Fan Motor and Blade (Service )

**Date :** 7/9/2020 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS49536 **Vendor responsible :** Videon Dodge **Odometer :** 47,545

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Right Fan Motor and Blade | 1.00 | $0.00 | $0.00 |

*Total service :* $0.00

**Service :** Replace Left Fan Motor and Blade (Service )

**Date :** 7/13/2020 **Technician responsible :** N/D **Cost :** $0.00

**Reference :** CHCS49699 **Vendor responsible :** Videon Dodge **Odometer :** 47,807

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Left Fan Motor and Blade | 1.00 | $0.00 | $0.00 |

*Total service :* $0.00

**Service :** Front End Alignment (Service )

**Date :** 7/17/2020 **Technician responsible :** N/D **Cost :** $95.00

**Reference :** 16085 **Vendor responsible :** Thorntons Gulf **Odometer :** 48,015

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Front End Alignment | 1.00 | $95.00 | $95.00 |

*Total service :* $95.00

**Service :** Emission and State Inspection, Oil and Filter Change, Mount and Balance 2 Tires (Service )

**Date :** 7/15/2020 **Technician responsible :** N/D **Cost :** $174.95

**Reference :** 16074 **Vendor responsible :** Thorntons Gulf **Odometer :** 47,907

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Emission and State Inspection, Oil and Filter Change, Mount and Balance 2 Tires | 1.00 | $174.95 | $174.95 |

*Total service :* $174.95

**Service :** Oil and Filter Change (Service )

**Date :** 8/31/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 16666 **Vendor responsible :** Thorntons Gulf **Odometer :** 50,462

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Replace 2 front brakes and 2 front Rotors (Service )

**Date :** 11/23/2020 **Technician responsible :** N/D **Cost :** $430.00

**Reference :** 15455 **Vendor responsible :** Thorntons Gulf **Odometer :** 54,948

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace 2 front brakes and 2 front Rotors | 1.00 | $430.00 | $430.00 |
| | | *Total service :* | | $430.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 11/11/2020 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 15557 **Vendor responsible :** Thorntons Gulf **Odometer :** 54,495

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter Change (Service )

**Date :** 2/12/2021 **Technician responsible :** N/D **Cost :** $44.95

**Reference :** 17105 **Vendor responsible :** Thorntons Gulf **Odometer :** 58,188

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $44.95 | $44.95 |
| | | *Total service :* | | $44.95 |

**Service :** Oil and Filter chang, Replace Drivers side Headlamp bulb, Replace left and right front axle joints. (Service )

**Date :** 4/8/2021 **Technician responsible :** N/D **Cost :** $116.32
**Reference :** CHCS62281 **Vendor responsible :** Videon Dodge **Odometer :** 60,292

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter chang, Replace Drivers side Headlamp bulb, Replace left and right front axle joints. | 1.00 | $116.32 | $116.32 |

*Total service :* $116.32

**Service :** Install Starter, Replace Battery (Service )

**Date :** 7/2/2021 **Technician responsible :** N/D **Cost :** $290.00
**Reference :** 17056 **Vendor responsible :** Thorntons Gulf **Odometer :** 64,367

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Install Starter, Replace Battery | 1.00 | $290.00 | $290.00 |

*Total service :* $290.00

**Service :** Emission and State Inspection, Oil and Filter Change, Mount and balance 4 tires (Service )

**Date :** 7/23/2021 **Technician responsible :** N/D **Cost :** $229.95
**Reference :** 17601 **Vendor responsible :** Thorntons Gulf **Odometer :** 65,624

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Emission and State Inspection, Oil and Filter Change, Mount and balance 4 tires | 1.00 | $229.95 | $229.95 |

*Total service :* $229.95

**Service :** Replace Starter Motor, Replace Starter Wire Harness (Service )

**Date :** 8/17/2021 **Technician responsible :** N/D **Cost :** $154.80
**Reference :** CHCS68389 **Vendor responsible :** Videon Dodge **Odometer :** 66,033

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Starter Motor, Replace Starter Wire Harness | 1.00 | $154.80 | $154.80 |

| | |
|---|---|
| *Total service :* | $154.80 |

**Service :** Replace Wiper Blades (Service )

**Date :** 9/20/2021 **Technician responsible :** N/D **Cost :** $26.00
**Reference :** 18523 **Vendor responsible :** Thorntons Gulf **Odometer :** 66,949

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Wiper Blades | 1.00 | $26.00 | $26.00 |
| | | *Total service :* | | $26.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 1/13/2022 **Technician responsible :** N/D **Cost :** $60.00
**Reference :** 17759 **Vendor responsible :** Thorntons Gulf **Odometer :** 68,660

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $60.00 | $60.00 |
| | | *Total service :* | | $60.00 |

**Service :** Installed Washer Harness (Service )

**Date :** 2/11/2022 **Technician responsible :** N/D **Cost :** $45.04
**Reference :** CHCS76729 **Vendor responsible :** Videon Dodge **Odometer :** 69,615

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Installed Washer Harness | 1.00 | $45.04 | $45.04 |
| | | *Total service :* | | $45.04 |

**Service :** Replace Front and Rear break pads and Rotors (Service )

**Date :** 3/10/2022 **Technician responsible :** N/D **Cost :** $1,282.35
**Reference :** CHCS77834 **Vendor responsible :** Videon Dodge **Odometer :** 70,245

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Front and Rear break pads and Rotors | 1.00 | $1,282.35 | $1,282.35 |

| | |
|---|---|
| *Total service :* | $1,282.35 |

**Service :** Replace and Program a new Key FOB (Service )

| | | | | | |
|---|---|---|---|---|---|
| **Date :** | 4/14/2022 | **Technician responsible :** | N/D | **Cost :** | $241.42 |
| **Reference :** | CHCS79478 | **Vendor responsible :** | Videon Dodge | **Odometer :** | 70,985 |

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace and Program a new Key FOB | 1.00 | $241.42 | $241.42 |
| | | *Total service :* | | $241.42 |

**Service :** Oil and filter change (Service )

| | | | | | |
|---|---|---|---|---|---|
| **Date :** | 6/8/2022 | **Technician responsible :** | N/D | **Cost :** | $75.00 |
| **Reference :** | 00152 | **Vendor responsible :** | Thorntons Gulf | **Odometer :** | 72,124 |

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and filter change | 1.00 | $75.00 | $75.00 |
| | | *Total service :* | | $75.00 |

**Service :** Replace left headlamp assembly, Replace Gas Tank Assembly, Emission and State Inspection (Service )

| | | | | | |
|---|---|---|---|---|---|
| **Date :** | 8/2/2022 | **Technician responsible :** | N/D | **Cost :** | $2,660.08 |
| **Reference :** | CHCS83614 | **Vendor responsible :** | Videon Dodge | **Odometer :** | 73,185 |

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace left headlamp assembly, Replace Gas Tank Assembly, Emission and State Inspection | 1.00 | $2,660.08 | $2,660.08 |
| | | *Total service :* | | $2,660.08 |

**Service :** Oil and Filter Change (Service )

| | | | | | |
|---|---|---|---|---|---|
| **Date :** | 11/15/2022 | **Technician responsible :** | N/D | **Cost :** | $75.00 |
| **Reference :** | | **Vendor responsible :** | Thorntons Gulf | **Odometer :** | 75,191 |

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|

| | | | | |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | | *Total service :* | | $75.00 |

**Service :** Replace Wiper Blades (Service )

**Date :** 1/6/2023 **Technician responsible :** N/D **Cost :** $30.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 0

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Replace Wiper Blades | 1.00 | $30.00 | $30.00 |
| | | *Total service :* | | $30.00 |

**Service :** Oil and Filter Change (Service )

**Date :** 3/21/2023 **Technician responsible :** N/D **Cost :** $75.00

**Reference :** **Vendor responsible :** Thorntons Gulf **Odometer :** 78,120

| Type | Description | Qty. | Unit cost | Total cost |
|---|---|---|---|---|
| Other | Oil and Filter Change | 1.00 | $75.00 | $75.00 |
| | | *Total service :* | | $75.00 |

*Total of the vehicle :* *$8,686.28*