EQUIPMENT NO. 34 **EQUIPMENT MAINTENANCE RECORD**

2005 Ford Taurus 4 Door SDN Car

Date	Miles/ Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
		Napa				
		Oil Filter 1516				
		Fuel Filter				
		Air Filter				
Feb. 2005	New	Bought the car new from Northeast Auto Outlet C/O				
		Pacifico Ford for $12,950.00.				
10/4/2005	3000	Changed oil and oil filer.	5 qts. oil	$8.35	1	$17.65
		(Serviced)	Oil filter	$4.31		
1/6/2006	3755	Inspection at Myers Diesel.	Insp. fee	$18.87		
9/25/2006	6037	Changed oil and oil filter.	5 qts. oil	$8.75	1	$18.55
		(Serviced)	Oil filter	$4.42		
2/12/2007	6982	Took the car to Keystone Ford for the ABS, fuel cap and	Keystone Ford bill	$59.50		
		the emergency brake lights coming on in the dash while				
		driving.				
		Also the car seems to start hard at times.				
		Keystone Ford checked the problems. They reprogrammed				
		the PCM for the latest calibration and also found a low				
		voltage code.				
		We were told the low voltage check wasn't covered under				
		warranty. They charged us $59.50 for the work performed				
		and suggested us running the car for longer periods of				
		time so the battery will charge.				

EQUIPMENT NO. 34 **EQUIPMENT MAINTENANCE RECORD**

2005 Ford Taurus 4 Door SDN Car

Date	Miles/ Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
10/30/2007	9178	Changed oil and oil filter.	5 qts. oil	$11.30	2	$40.00
		(Serviced)	Oil filter	$4.42		
		Replaced wiper blades.	2 Wiper blades	$10.23		
		Repaired rear parking light.				
1/25/2008	9991	Inspection at Myers Diesel.	Insp. fee	$18.87		
1/29/2009	13022	Inspection at Myers Diesel.	Insp. fee	$21.70		
2/19/2009	13192	Changed oil and oil filter.	5 qts. oil	$12.05	8	$170.80
		(Serviced)	Oil filter	$4.67		
		Rotate tires.				
		Adjust rear brakes.				
		Repaired license plate light.				
		Washed engine and engine compartment.				
		Clean and washed car inside and out.				
8/13/2009	15345	Troubleshoot no current at the power outlet.			1	$21.35
		Replaced fuse.				
12/3/2009	15600	Troubleshoot engine not starting.	Battery	$102.95	1	$21.35
		Replaced battery.				
		Cleaned battery cables.				
1/21/2010	15738	Inspection at Myers Diesel.	Insp. fee	$21.70		
1/11/2011	17339	Changed oil and oil filter.	5 qts. oil	$13.15	1	$21.99
		Greased. (Serviced)	Oil filter	$1.78		

EQUIPMENT NO. 34 **EQUIPMENT MAINTENANCE RECORD**

2005 Ford Taurus 4 Door SDN Car

Date	Miles/ Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
1/17/2011	17371	Inspection at Myers Diesel.	Insp. fee	$21.70		
12/2/2011	19312	Got the car back from Keystone Ford.	Keystone Fords bill	$561.21		
		The air bag warning light stayed on at the dash panel.				
		Keystone Ford replaced the sensor assembly, clock spring				
		ring, cover and control plate to the air bag system.				
		Keystone Fords bill was $561.21.				
		(We took the car to Keystone Ford on 11/29/2011)				
1/13/2012	19345	Inspection at Myers Diesel.	Insp. fee	$26.42		
1/24/2013	21424	Inspection at Myers Diesel.	Insp. fee	$26.42		
2/28/2013	21564	Changed oil, oil and fuel filter. (Serviced)	5 qts. oil	$14.75	16	$355.36
		Rotate tires.	Oil filter	$5.12		
		Replaced both wiper blades.	Fuel filter	$6.79		
		Removed and cleaned cab filter.	Fuel line	$75.41		
		Dropped fuel tank and replaced broken fuel line from fuel	Fuel line clip	$6.00		
		filter to the fuel tank.	Fuel line clip	$6.38		
1/14/2014	23454	Inspection at E.L.M garage.	Insp. fee	$30.00		
6/10/2014	24536	Went to Grant Shook Road on a service call.	Cunninghams Bill	$185.00	1	$22.54
		The car drifted off of the road and went into a ditch.				
		I could not pull it out with a chain.				
		I called Cunninghams Towing. They winched it out and				
		towed it to our shop.				
		Cunninghams Towing bill was $185.00.				

EQUIPMENT NO. 34 **EQUIPMENT MAINTENANCE RECORD**

2005 Ford Taurus 4 Door SDN Car

Date	Miles/ Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
6/26/2014	24536	Checked car over after it went into the ditch on 6/10/2014.	1 Control arm	$95.27	16	$360.64
		Repaired right front bumper.	1 Control arm	$108.86		
		Replaced both right rear control arms.	Control arm adjuster	$30.08		
		Replaced right rear wheel ABS sensor.	ABS sensor	$47.97		
		The bumper, control arms and ABS sensor were damaged	5 qts. oil	$14.75		
		on 6/10/2014 when the car drifted off the road and into a	Oil filter	$4.61		
		ditch.	2 Wiper blades	$7.50		
		Changed oil and oil filter. (Serviced)	Floor mats	$27.99		
		Replaced wiper blades.				
		Installed floor mats.				
		Washed and cleaned car.				
7/2/2014	24595	Took the car to Byers Tire for a four wheel alignment.	Byers Tire bill	$59.95		
11/17/2014	25228	Troubleshoot left turn signals not working.			1	$22.54
		Replaced left rear turn signal bulb.				
		Repaired plastic truck panel.				
1/92015	25358	Inspection at Myers Diesel.	Insp. fee	$31.00		
1/14/2016	26450	Troubleshoot engine not starting.	Battery	$101.80	2	$46.90
		Replaced battery.	20" Wiper blade	$4.69		
		Cleaned battery cables.	24" Wiper blade	$5.80		
		Replaced both wiper blades.				
		Temporarily repaired broken emergency brake handle.				
		(I ordered a new emergency brake handle assembly)				
1/18/2016	26456	Replaced emergency brake handle/cable assembly.	Emg. brake handle assy.	$23.57	1	$23.45

EQUIPMENT NO. 34 **EQUIPMENT MAINTENANCE RECORD**

2005 Ford Taurus 4 Door SDN Car

Date	Miles/ Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
1/20/2016	26465	Inspection at Myers Diesel.	Insp. fee	$31.15		
4/19/2016	27233	Repaired right front parking light.	Floor mats	$32.37	1	$23.45
		Bought and installed floor mats.				
1/10/2017	28143	Inspection at Myers Diesel.	Insp. fee	$31.15		
1/19/2017	28200	Tom Walburn done the following work while Dave was	5 qts. oil	$14.75	2	$36.62
		off due to arm surgery.	Oil filter	$5.39		
		Changed oil, oil and air filters.	Air filter	$11.54		
		Greased. (Serviced)				
		Removed and cleaned cab filter.				
11/30/2017	29437	Replaced both wiper blades.	1 Wiper blade	$5.80		
			1 Wiper blade	$4.69		
1/31/2018	29783	Inspection at Myers Diesel.	Insp. fee	$33.02		
12/12/2018	30490	Changed oil and oil filter.	5 qts. oil	$15.80	8	$195.20
		Greased. (Serviced)	Oil filter	$1.97		
		Charged battery.				
		Washed, cleaned and waxed vehicle.				
		Cleaned inside.				
1/4/2019	30521	Troubleshoot engine not starting.	Battery	$108.88	1	$24.89
		Replaced battery.				
1/31/2019	30579	Inspection at Myers Diesel.	Insp. fee	$35.85		

EQUIPMENT NO. 34 **EQUIPMENT MAINTENANCE RECORD**

2005 Ford Taurus 4 Door SDN Car

Date	Miles/ Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
9/10/2019	31374	Troubleshoot no right rear turn signal.			1	$24.89
		Replaced bulbs.				
		Repaired loose wiring.				
1/16/2020	31856	Inspection at Myers Diesel.	Insp. fee	$37.74		
4/15/2020	32250	Took the car to Byers Tire for a front end alignment,	Byers Tire bill	$102.95		
		balance and rotate all 4 tires.				
		Byers Tire bill was $102.95.				
5/29/2020	32276	Replaced flash light.	Flash light	$9.99		
8/11/2020	32298	Troubleshoot engine miss.	6 Spark plugs	$27.00	4	$101.56
		Replaced all 6 spark plugs.				
1/14/2021	32509	Inspection at Myers Diesel.	Insp. fee	$37.74		
1/27/2022	34009	Inspection at Myers Diesel.	Insp. fee	$43.40		
2/25/2022	34072	Service Tire Truck Centers Inc. replaced all 4 tires and	STTC bill	$406.00		
		done an alignment.				
		STTC bill was $406.00.				
		(A copy of the bill is kept in the cars file)				
1/19/2023	34964	Inspection at Myers Diesel.	Insp. fee	$43.40		
3/30/2023	35592	Changed oil and oil filter.	5 qts. oil	$15.80	2	$63.60
		Greased. (Serviced)	Oil filter	$11.26		
		Replaced both wiper blades.	2 Wiper blades	$11.08		

EQUIPMENT NO. 34 **EQUIPMENT MAINTENANCE RECORD**

2005 Ford Taurus 4 Door SDN Car

Date	Miles/ Hours	Description of Work Done	Item	Cost of Item	Labor (Hrs.)	Cost of Labor
8/11/2023	39300	Changed oil and oil filter.	5 qts oil	$15.15	2	$63.60
		Greased. (Serviced)	Oil filter	$11.26		
8/24/2023		Washed and cleaned car inside and out.	Floor mats	$4.95	8	$254.40
		Replaced floor mats.	2 Wiper blades	$10.83		
		Replaced both wiper blades.				