WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:AD0 AUTOMOTIVE DAYSHIFT

CUSTOMER COPY

WO#: 0000770152
Date In: 10/17/2022 09:41
Date Out: 10/20/2022 18:47
WO Total Cost: 297.75
WO Status: F Last WO#:0000770152
Bill Code: B Last WO Date: 10/17/2022
Operator: PMC

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	1953		M	1953	1953

PM SERVICE

Due	Type	Type Description

NO PM Service Scheduled at this time.

REPAIRS PERFORMED

MID	Date	SH	RTY	Description	Labor Cost
708	10/20/2022	N	2TV0UNI025BN	GENERAL VEHICLE REPAIR | Total Vehicle | Unit | Quality Check	47.75

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description
SF10073	10/18/2022	3TV0UNI500BN	VENDOR REPAIR: (SUBLET) | Total Vehicle | Unit | Towing/Breakdow

Parts: 0.00 Labor: 0.00 Other: 0.00 Tax: 0.00 Sublet Cost: 250.00

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 297.75

Parts: 0.00 Labor: 47.75 Sublet: 250.00 Misc Cost: 0.00 Credit: 0.00

NOTES

TOW-IN STOPPED RUNNING

FITZGERALD 240/876-3083

CK MILES_____

TOW FROM CHEVY CHASE TO LINDSAY
10/17/2022 @ 09:58:08

TOWED BY GEYERS

708- DEALER CHECK IN/QUALITY INSPECTED: DEALER REPLACED ALL OF THE SPARK PLUGS AND

REPROGRAMMED THE SOBDMC AND PCM

CALLED VOICEMAIL
10/20/2022 @ 18:47:12

Work Order Report - WO# 0000782221

3/24/2023 12:09:00 PM

WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:AD0 AUTOMOTIVE DAYSHIFT

CUSTOMER COPY

WO#: 0000782221

Date In: 03/24/2023 05:19
Date Out: 03/24/2023 09:59
WO Total Cost: 269.23

WO Status: F
Bill Code: B
Last WO#:0000782221
Last WO Date: 03/24/2023
Operator: PMC

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	3616		M	3616	3616

PM SERVICE

Due	Type	Type Description

NO PM Service Scheduled at this time.

REPAIRS PERFORMED

MID	Date	SH	RTY	Description	Labor Cost
746	03/24/2023	N	1TV0UNI025NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Quality Check	14.13
722	03/24/2023	N	1TV0UNI030NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Test Drive	59.71
722	03/24/2023	N	1035RNICALNS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Multi-Electroni | RNI System | Calibrate	20.86
722	03/24/2023	N	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	141.84

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost
7	5W20	OIL BULK 5W20	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	7	3.25	22.75
7	AA5Z6714A	OIL FILTER # FL-500S	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	1	5.99	5.99
7	92006	WASHER FLUID	1007000Z52NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Glass-Component | System | Parts	1	3.95	3.95

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 269.23

Parts: 32.69	Labor: 236.54	Sublet: 0.00	Misc Cost: 0.00	Credit: 0.00

NOTES

PMC 03/24/2023 done
pads
f 11/32
r 11/32
rotors
f 1.261
r 1.012

301-654-7300

CHECK MILEAGE ----------6987----------

CALLED
03/24/2023 @ 10:03:06

Work Order Report - WO# 0000790412

7/24/2023 4:01:23 PM

WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:AD0 AUTOMOTIVE DAYSHIFT

CUSTOMER COPY

WO#: 0000790412

Date In: 07/03/2023 10:23
Date Out: 07/24/2023 16:00
WO Total Cost: 393.81

WO Status: F
Bill Code: B
Last WO#:0000790412
Last WO Date: 07/03/2023
Operator: PMC

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	8374	Y	M	8374	8374

PM SERVICE

Due	Type	Type Description
NO PM Service Scheduled at this time.		

REPAIRS PERFORMED

MID	Date	SH	RTY	Description	Labor Cost
805	07/03/2023	N	1035RNICALNS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Multi-Electroni | RNI System | Calibrate	36.18
805	07/03/2023	N	1007BJ0110NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Glass-Component | Blade W/S Wiper | Replace Front	15.63
805	07/03/2023	N	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	190.06
805	07/03/2023	N	1TV0UNI030NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Test Drive	29.50
805	07/03/2023	N	2056AE6160NN	GENERAL VEHICLE REPAIR | CommunicationEq | Antenna Two Way | Remove	29.92
763	07/24/2023	N	1TV0UNI025NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Quality Check	37.37

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost
7	5W20	OIL BULK 5W20	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	6	3.25	19.50
7	AA5Z6714A	OIL FILTER # FL-500S	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	1	5.99	5.99
7	XC20	WIPER BLADE 20"	1007000Z52NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Glass-Component | System | Parts	1	12.85	12.85
7	XC26	WIPER BLADE 26"	1007000Z52NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Glass-Component | System | Parts	1	12.85	12.85
7	92006	WASHER FLUID	1007000Z52NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Glass-Component | System | Parts	1	3.96	3.96

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 393.81

Parts: 55.15 Labor: 338.66 Sublet: 0.00 Misc Cost: 0.00 Credit: 0.00

NOTES

C SVC 07/03/23

SCREEN FOR THE RADIO AND CLOCK WILL NOT ILLUMINATE

CCV 301-654-7300

CK MILES 8,377.9

TEST DRIVE VEHICLE

PMC IS DONE

TIRE MEASUREMENTS
L/F 7/32 R/F 7/32
L/R 7/32 R/R 7/32

BRAKE MEASUREMENTS
L/F 13/32 R/F 13/32
L/R 10/32 R/R 13/32

ROTOR MEASUREMENTS
L/F 1.262 R/F 1.264 FRONT ROTOR MIN THICKNESS 1.201
L/R 1.009 R/R 1.007 REAR ROTOR MIN THICKNESS .965

CALIBRATED RNI FUEL MASTER

DISCONNECT POLICE RADIO

PLEASE SEND TO THE DEALER FOR - SCREEN FOR THE RADIO & CLOCK WILL NOT

ILLUMUNATE

SHEEHY
07/05/2023 @ 09:35:06

QC/OK/#763--RADIO WORKS AS DESIGNED AT THIS TIME

spoke to front desk
07/24/2023 @ 16:01:17

Work Order Report - WO# 0000801595

11/13/2023 12:22:32 PM

WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:ATP AUTOMOTIVE THIRD PARTY

CUSTOMER COPY

WO#: 0000801595
Date In: 11/08/2023 12:28
Date Out: 11/09/2023 20:13
WO Total Cost: 155.99
WO Status: C
Bill Code: B
Last WO#:0000801595
Last WO Date: 11/08/2023
Operator: CS

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	8374	A	M	8374	8374

PM SERVICE

Due	Type	Type Description

NO PM Service Scheduled at this time.

REPAIRS PERFORMED

MID	Date	Labor Hrs	OT	SH	RTY	RTY Description	Labor Cost

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description
SF10026	11/13/2023	3040F10100BN	VENDOR REPAIR: (SUBLET) | Engine | Filter/Oil | Replace

Parts: 0.00 Labor: 0.00 Other: 0.00 Tax: 0.00 Sublet Cost: 155.99

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 155.99

Parts: 0.00 Labor: 0.00 Sublet: 155.99 Misc Cost: 0.00 Credit: 0.00

NOTES

MOBILE TECH

C SVC 11/9/2023

CCV 301-654-7300

MILES: 9776

BRAKE SPECS: L/F 10MM, R/F 10MM, L/R 10MM, R/R 10MM

TIRE SPECS: L/F 7/32, R/F 7/32, L/R 7/32, R/R 7/32
VIDEO QC BY KOONS MOBILE

spoke to front desk
11/09/2023 @ 20:57:04

WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:AD0 AUTOMOTIVE DAYSHIFT

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

CUSTOMER COPY

WO#: 0000828392
Date In: 10/09/2024 05:50
Date Out: 10/09/2024 10:23
WO Total Cost: 448.44

WO Status: F
Bill Code: B
Last WO#:0000828392
Last WO Date: 10/09/2024
Operator: TPI

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	15970	A	M	8374	8374

PM SERVICE

Due	Type	Type Description

NO PM Service Scheduled at this time.

REPAIRS PERFORMED

MID	Date	Labor Hrs	OT	SH	RTY	RTY Description	Labor Cost
842	10/09/2024	0.16611	N	N	1035RNICALNS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Multi-Electroni | RNI System | Calibrate	32.42
842	10/09/2024	1.27278	N	N	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	248.42
842	10/09/2024	0.47278	N	N	1TV0UNI030NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Test Drive	92.28
702	10/09/2024	0.28694	N	N	1TV0UNI025NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Quality Check	56.01

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost
7	302000	OIL, BULK, 5W20, SYNTHETIC BLEND	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	7	1.76	12.31
7	84502	OIL FILTER	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	1	2.60	2.60
7	f2001	WASHER FLUID	1007000Z52NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Glass-Component | System | Parts	1	4.40	4.40

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 448.44

Parts: 19.31	Labor: 429.13	Sublet: 0.00	Misc Cost: 0.00	Credit: 0.00

NOTES

C SERVICE - 10/9/2024

842
BRAKES
LF 9/32 RF 9/32 LR 9/32 RR 9/32
ROTORS
LF 1.260 RF 1.258 LR 1.020 RR 1.018

ROTORS DISCARD
FRONT 1.201 REAR .965
TIRES
LF 10/32 RF 10/32 LR 10/32 RR 10/32

OL CHANGE AND FILTER

CHEVY CHASE VILLAGE - 301-654-7300

CHECK MILEAGE ____15,973____

QC COMPLETE---702

WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:AD0 AUTOMOTIVE DAYSHIFT

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

CUSTOMER COPY

WO#: 0000843318

Date In: 04/09/2025 05:50
Date Out: 04/09/2025 08:24
WO Total Cost: 364.57

WO Status: F
Bill Code: B
Last WO#:0000843318
Last WO Date: 04/09/2025
Operator: PMC

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	8374		M	8374	8374

PM SERVICE

Due	Type	Type Description

NO PM Service Scheduled at this time.

REPAIRS PERFORMED

MID	Date	Labor Hrs	OT	SH	RTY	RTY Description	Labor Cost
677	04/09/2025	1.35444	N	N	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	264.36
677	04/09/2025	0.44639	N	N	1TV0UNI030NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Test Drive	87.13

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost
7	302000	OIL, BULK, SW20, SYNTHETIC BLEND	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	6	1.75	10.48
7	84502	OIL FILTER	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	1	2.60	2.60

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 364.57

Parts: 13.08 Labor: 351.49 Sublet: 0.00 Misc Cost: 0.00 Credit: 0.00

NOTES

C SVC 04/09/25

CCV 301-654-7300

CK MILES:19,520

PMC PERFORMED

BRAKE MEASUREMENTS:
L/F:11/32 R/F:11/32
L/R:11/32 R/R:11/32

TIRE MEASUREMENTS:
L/F:9/32 R/F:9/32
L/R:9/32 R/R:9/32

ROTOR MEASUREMENTS:
L/F:1.247 R/F:1.247
L/R:0.990 R/R:0.990

TALKED TO DESK
04/09/2025 @ 08:24:57

WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:AD0 AUTOMOTIVE DAYSHIFT

CUSTOMER COPY

WO#: 0000856174
Date In: 09/09/2025 06:12
Date Out: 09/09/2025 10:45
WO Total Cost: 138.02
WO Status: F Last WO#:0000856174
Bill Code: B Last WO Date: 09/09/2025
Operator: MNE

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	24283	Y	M	24283	24283

PM SERVICE

Due	Type	Type Description

NO PM Service Scheduled at this time.

REPAIRS PERFORMED

MID	Date	Labor Hrs	OT	SH	RTY	RTY Description	Labor Cost
842	09/09/2025	0.98111	N	N	1002MH0100NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Cab/Body | Misc Parts | Replace	68.31
842	09/09/2025	1.39694	N	N	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	97.27
842	09/09/2025	0.58528	N	N	1TV0UNI030NS	REPAIRED FROM PM: (DISCOVERED REPAIRS) | Total Vehicle | Unit | Test Drive	40.75

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 138.02

Parts: 0.00 Labor: 138.02 Sublet: 0.00 Misc Cost: 0.00 Credit: 0.00

NOTES

C SVC 9-9-25
TIRES
LF 7/32 RF 7/32 LR 7/32 RR 7/32
BRAKES
LF 9/32 RF 9/32 LR 9/32 RR 9/32
ROTORS

LF 1:240 RF 1.240 LR .989 RR .989
OIL CHANGE AND FILTER

DRIVER SIDE DOOR PANEL WINDOW SWITCH / THE TIP BROKE OFF
REPLACE DRIVE SIDE DOOR PANEL SWITCH , I USED ONE FROM THE JUNKYARD PARTS

CHEVY CHASE VILLAGE 301-654-7300

CHECK MILES 24 287

TALKED TO DESK
09/09/2025 @ 10:45:53

Work Order Report - WO# 0000864122

12/10/2025 5:09:13 AM

WO Company:001 MONTGOMERY COUNTY, MARYLAND
WO Department:CV0000 CHEVY CHASE VILLAGE
WO Shop:AD0 AUTOMOTIVE DAYSHIFT

CUSTOMER COPY

WO#: 0000864122

Date In: 12/09/2025 13:56
Date Out: 12/09/2025 23:47
WO Total Cost: 116.30

WO Status: F
Bill Code: B
Last WO#:0000864173
Last WO Date: 12/09/2025
Operator: MNE

Equipment: CCV743 License: 20693LG

Color:	WHITE	Engine:	
Year:	2020	GVW:	0
Make:	FORD	Serial:	1FM5K8AWXNNA00417
Model:	INTERCEPTOR UT	Misc. Field:	
Location:			

Department: CV0000:CHEVY CHASE VILLAGE
Class: 1345:1345/GVW<8600/AUTOMOBILE/FULL SIZE/CUV(FWD or AWD)
Company: 001 MONTGOMERY COUNTY, MARYLAND
Monitor Group:
Site: CCV001:CHEVY CHASE VILLAGE

METERS

WO Meter	Reading	Override?	Eq Meter	Actual	LTD
M	27283	Y	M	27283	27283

PM SERVICE

Due	Type	Type Description

NO PM Service Scheduled at this time.

REPAIRS PERFORMED

MID	Date	Labor Hrs	OT	SH	RTY	RTY Description	Labor Cost
859	12/09/2025	1.05333	N	N	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	73.34
859	12/09/2025	0.37417	N	N	2TV0UNI030NN	GENERAL VEHICLE REPAIR | Total Vehicle | Unit | Test Drive	26.05

SUBLET REPAIRS

Vendor	Date Back	RTY	RTY Description

PARTS ISSUED

Strm	Part Number	Part Description	RTY	RTY Description	QTY	Unit Cost	Total Cost
7	302000	OIL, BULK, 5W20, SYNTHETIC BLEND	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	6	1.75	10.48
7	FL500S	OIL FILTER	PMC NS	PM SERVICE REPAIR: (PREVENTIVE MAINTENANCE) | C Service List	1	6.43	6.43

MISCELLANEOUS COSTS

Code	Code Description	RTY	RTY Description	Misc. Cost

CREDITS

Date	Description	Credit Amount

Work Order Total: 116.30

Parts: 16.91 Labor: 99.39 Sublet: 0.00 Misc Cost: 0.00 Credit: 0.00

NOTES

C SVC

CHEVY CHASE VILLAGE 301-654-7300

CHECK MILES_____27293_____

PMC DONE.

FRONT PADS 12/32
REAR 12/32

FRONT ROTORS 1.274
REAR 1.030

TIRE DEPTH
LF 7/32 RF 11/32
LR7/32 RR7/32

ALL TIRES 35PSI

IT HAS ACM TICKET FOR RR TIRE SIDE WALL DSMAGE