

# Detailed services/breakdown

Display criteria

Period : All

Vehicle(s) : Dodge/Durango/2020

## Vehicle : 67-95 - Dodge/Durango/2020/MG8962L

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b> 8/24/2020		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$44.95
<b>Reference :</b> 16529		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 3,917
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b> 11/20/2020		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$44.95
<b>Reference :</b> 15598		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 10,430
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b> 10/5/2020		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$44.95
<b>Reference :</b> 15351		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 7,342
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	1/11/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	15530	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 13,849
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Emission and State Inspection, Replace Front Brakes (Service )				
<b>Date :</b>	1/26/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$241.00
<b>Reference :</b>	15149	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 14,940
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Emission and State Inspection, Replace Front Brakes	1.00	\$241.00	\$241.00
<i>Total service :</i>				\$241.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	3/8/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	17228	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 18,056
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Replace AC Condenser and recharge system, Oil and Filter Change (Service )				
<b>Date :</b>	4/8/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$50.49
<b>Reference :</b>	CHCS62225	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 19,189
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace AC Condenser and recharge system, Oil and Filter Change	1.00	\$50.49	\$50.49
<i>Total service :</i>				\$50.49

<b>Service :</b>	Oil and Filter Change (Service )					
<b>Date :</b>	5/5/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95	
<b>Reference :</b>	17710	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	21,202	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	oil and filter change			1.00	\$44.95	\$44.95
					<i>Total service :</i>	\$44.95

<b>Service :</b>	Break Test and Identification of a noise from the rotors (Service )					
<b>Date :</b>	6/4/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$65.25	
<b>Reference :</b>	CHCS64793	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	23,720	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Break Test and Identification of a noise from the rotors			1.00	\$65.25	\$65.25
					<i>Total service :</i>	\$65.25

<b>Service :</b>	Mount and Balance 2 Tires (Service )					
<b>Date :</b>	6/25/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$54.00	
<b>Reference :</b>	17266	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	25,198	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Mount and Balance 2 Tires			1.00	\$54.00	\$54.00
					<i>Total service :</i>	\$54.00

<b>Service :</b>	Replace 2 headlights (Service )					
<b>Date :</b>	6/13/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$70.00	
<b>Reference :</b>	17026	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	0	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace 2 headlights			1.00	\$70.00	\$70.00
					<i>Total service :</i>	\$70.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	6/14/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	17011	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 24,424
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Replace Battery (Service )				
<b>Date :</b>	7/7/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$261.00
<b>Reference :</b>	CHCS66338	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 25,840
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Battery	1.00	\$261.00	\$261.00
<i>Total service :</i>				\$261.00

<b>Service :</b> Mount and Balance 2 tires (Service )				
<b>Date :</b>	7/8/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$54.00
<b>Reference :</b>	17079	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 25,952
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Mount and Balance 2 tires	1.00	\$54.00	\$54.00
<i>Total service :</i>				\$54.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	8/11/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$60.00
<b>Reference :</b>	17687	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 28,203
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$60.00	\$60.00
<i>Total service :</i>				\$60.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	9/14/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$60.00
<b>Reference :</b>	17590	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 31,102
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$60.00	\$60.00
<i>Total service :</i>				\$60.00

<b>Service :</b> Replace Wiper Blades (Service )				
<b>Date :</b>	9/21/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$28.00
<b>Reference :</b>	18549	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 0
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Wiper Blades	1.00	\$28.00	\$28.00
<i>Total service :</i>				\$28.00

<b>Service :</b> Replace left and right cylinder head gaskets along with all other gaskets and seals (Service )				
<b>Date :</b>	10/19/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$0.00
<b>Reference :</b>	CHCS71193	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 32,245
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace left and right cylinder head gaskets along with all other gaskets and seals	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

<b>Service :</b> Oil and Filter Change, Replace Left Headlight (Service )				
<b>Date :</b>	11/19/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$95.00
<b>Reference :</b>	17487	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 34,331
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change, Replace Left Headlight	1.00	\$95.00	\$95.00
<i>Total service :</i>				\$95.00

<b>Service :</b>	Replace Water Pump, Replace Antifreeze (Service )			<b>Cost :</b>	\$0.00
<b>Date :</b>	12/20/2021	<b>Technician responsible :</b>	N/D	<b>Odometer :</b>	36,528
<b>Reference :</b>	CHCS73995	<b>Vendor responsible :</b>	Videon Dodge		
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Water Pump, Replace Antifreeze	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

<b>Service :</b>	Oil and Filter Change (Service )			<b>Cost :</b>	\$60.00
<b>Date :</b>	12/29/2021	<b>Technician responsible :</b>	N/D	<b>Odometer :</b>	37,098
<b>Reference :</b>	18710	<b>Vendor responsible :</b>	Thorntons Gulf		
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$60.00	\$60.00	
				<i>Total service :</i>	\$60.00

<b>Service :</b>	Replace Downstream Oxygen Sensor (Service )			<b>Cost :</b>	\$0.00
<b>Date :</b>	1/26/2022	<b>Technician responsible :</b>	N/D	<b>Odometer :</b>	38,653
<b>Reference :</b>	CHCS75983	<b>Vendor responsible :</b>	Videon Dodge		
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Downstream Oxygen Sensor	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

<b>Service :</b>	Replace Right Downstream Oxygen Sensor Connector, Replace Left Motor Mount (Service )			<b>Cost :</b>	\$0.00
<b>Date :</b>	2/10/2022	<b>Technician responsible :</b>	N/D	<b>Odometer :</b>	39,059
<b>Reference :</b>	CHCS76454	<b>Vendor responsible :</b>	Videon Dodge		
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Right Downstream Oxygen Sensor Connector, Replace Left Motor Mount	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

<b>Service :</b>	Oil and Filter Change, Emission and State Insp., Replace Front Brakes (Service )				
<b>Date :</b>	2/14/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$296.00
<b>Reference :</b>	18232	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	39,245
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change, Emission and State Insp., Replace Front Brakes	1.00	\$296.00	\$296.00	
				<i>Total service :</i>	\$296.00

<b>Service :</b>	Replace 2 front headlamps (Service )				
<b>Date :</b>	3/7/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$35.00
<b>Reference :</b>	18263	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	0
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace 2 front headlamps	1.00	\$35.00	\$35.00	
				<i>Total service :</i>	\$35.00

<b>Service :</b>	Repair 02 Connector (Service )				
<b>Date :</b>	3/10/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$0.00
<b>Reference :</b>	CHCS77886	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	41,366
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Repair 02 Connector	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

<b>Service :</b>	Oil and Filter Change (Service )				
<b>Date :</b>	3/23/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$75.00
<b>Reference :</b>	17873	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	42,347
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$75.00	\$75.00	
				<i>Total service :</i>	\$75.00

<b>Service :</b> Replace Condenser and Recharge System (Service )				
<b>Date :</b> 4/19/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$67.50
<b>Reference :</b> CHCS79467		<b>Vendor responsible :</b> Videon Dodge		<b>Odometer :</b> 44,334
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Condenser and Recharge System	1.00	\$67.50	\$67.50
<i>Total service :</i>				\$67.50

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b> 5/18/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$75.00
<b>Reference :</b> 18445		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 46,177
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

<b>Service :</b> Mount and Balance 4 tires (Service )				
<b>Date :</b> 6/28/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$108.00
<b>Reference :</b> 000225		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 49,837
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Mount and Balance 4 tires	1.00	\$108.00	\$108.00
<i>Total service :</i>				\$108.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b> 6/24/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$75.00
<b>Reference :</b> 000215		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 49,521
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00



<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	8/20/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$75.00
<b>Reference :</b>	000481	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 52,560
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	9/28/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$75.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 55,136
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

<b>Service :</b> Replace Thermostate, Replace Oil Cooler Assembly, Oil and Filter Change (Service )				
<b>Date :</b>	10/14/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$66.90
<b>Reference :</b>	CHCS87594	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 56,170
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Thermostate, Replace Oil Cooler Assembly, Oil and Filter Change	1.00	\$66.90	\$66.90
<i>Total service :</i>				\$66.90

<b>Service :</b> Replace Both Front Sway Bar's and Links (Service )				
<b>Date :</b>	10/20/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$0.00
<b>Reference :</b>	CHCS87860	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 56,303
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Both Front Sway Bar's and Links	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

<b>Service :</b> Replace Front and Rear, Breaks and Rotors (Service )				
<b>Date :</b> 10/18/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$788.00
<b>Reference :</b>		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 56,298
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Front and Rear, Breaks and Rotors	1.00	\$788.00	\$788.00
<i>Total service :</i>				\$788.00

<b>Service :</b> Replace Radiator Drain Lock (Service )				
<b>Date :</b> 11/4/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$0.00
<b>Reference :</b> CHCS88616		<b>Vendor responsible :</b> Videon Dodge		<b>Odometer :</b> 57,129
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Radiator Drain Lock	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

<b>Service :</b> Replace Heater Core Supply Hose Assembly (Service )				
<b>Date :</b> 11/14/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$0.00
<b>Reference :</b> CHCS88785		<b>Vendor responsible :</b> Videon Dodge		<b>Odometer :</b> 57,203
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Heater Core Supply Hose Assembly	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

<b>Service :</b> Replace Upper Hose, Thermostate and Coolant (Service )				
<b>Date :</b> 11/23/2022		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$210.00
<b>Reference :</b>		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 57,879
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Upper Hose, Thermostate and Coolant	1.00	\$210.00	\$210.00
<i>Total service :</i>				\$210.00

<b>Service :</b>	Replace Upper and Lower Radiator Hose, Refill antifreeze (Service )				
<b>Date :</b>	11/28/2022	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$179.41
<b>Reference :</b>	CHCS89625	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	57,894
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Upper and Lower Radiator Hose, Refill antifreeze	1.00	\$179.41	\$179.41	
				<i>Total service :</i>	\$179.41

<b>Service :</b>	Oil and Filter Change (Service )				
<b>Date :</b>	2/1/2023	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$75.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	61,794
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$75.00	\$75.00	
				<i>Total service :</i>	\$75.00

<b>Service :</b>	Replace Radiator and Coolant, Replace Right Side Washer Nozzle, Replace right side headlight bulb, Replace Thermostat (Service )				
<b>Date :</b>	2/8/2023	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$72.22
<b>Reference :</b>	CHCS92805	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	62,022
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Radiator and Coolant, Replace Right Side Washer Nozzle, Replace right side headlight bulb, Replace Thermostat	1.00	\$72.22	\$72.22	
				<i>Total service :</i>	\$72.22

<b>Service :</b>	Emission and State Insp., Mount and Balance 2 Tires (Service )				
<b>Date :</b>	3/23/2023	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$131.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	62,831
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Emission and State Insp., Mount and Balance 2 Tires	1.00	\$131.00	\$131.00	
				<i>Total service :</i>	\$131.00

**Service :** Replace Front Bumper, Hood, Left Fender, Radiator. Condenser, Trans Cooler, Headlights, and Right rear door (Service )  
**Date :** 3/21/2023      **Technician responsible :** N/D      **Cost :** \$10,541.00  
**Reference :** CHCB94224      **Vendor responsible :** Videon Dodge      **Odometer :** 62,826

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Front Bumper, Hood, Left Fender, Radiator. Condenser, Trans Cooler, Headlights, and Right rear door	1.00	\$10,541.00	\$10,541.00
<i>Total service :</i>				\$10,541.00

**Service :** Replace Starter (Service )  
**Date :** 5/2/2023      **Technician responsible :** N/D      **Cost :** \$558.00  
**Reference :**      **Vendor responsible :** Thorntons Gulf      **Odometer :** 64,553

Type	Description	Qty.	Unit cost	Total cost
Other	Replace Starter	1.00	\$558.00	\$558.00
<i>Total service :</i>				\$558.00

**Service :** Oil and Filter Change (Service )  
**Date :** 5/15/2023      **Technician responsible :** N/D      **Cost :** \$75.00  
**Reference :**      **Vendor responsible :** Thorntons Gulf      **Odometer :** 65,580

Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

**Service :** Oil and Filter Change (Service )  
**Date :** 6/28/2023      **Technician responsible :** N/D      **Cost :** \$75.00  
**Reference :** 18019      **Vendor responsible :** Thorntons Gulf      **Odometer :** 69,593

Type	Description	Qty.	Unit cost	Total cost
------	-------------	------	-----------	------------

Other	Oil and Filter Change	1.00	\$75.00	\$75.00
			<i>Total service :</i>	\$75.00

<b>Service :</b> Replace 5.7 Liter Engine (Service )				
<b>Date :</b>	9/29/2023	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$0.00
<b>Reference :</b>	105387	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 70,716
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace 5.7 Liter Engine	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

<b>Service :</b> AC Recharge, (Service )				
<b>Date :</b>	10/9/2023	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$0.00
<b>Reference :</b>	105998	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 70,745
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	AC Recharge,	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

<b>Service :</b> Replace Battery (Service )				
<b>Date :</b>	9/29/2023	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$582.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 70,719
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Battery	1.00	\$582.00	\$582.00
			<i>Total service :</i>	\$582.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	12/14/2023	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$75.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 72,628
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>

Other	Oil and Filter Change	1.00	\$75.00	\$75.00
			<i>Total service :</i>	\$75.00

<b>Service :</b> Emission and State Insp., Oil and Filter Change, Resurface Front Rotors, Replace right front Lower Ball Joint (Service )				
<b>Date :</b>	3/12/2024	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$614.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 75,336
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Emission and State Insp., Oil and Filter Change, Resurface Front Rotors, Replace right front Lower Ball Joint	1.00	\$614.00	\$614.00
			<i>Total service :</i>	\$614.00

<b>Service :</b> Replace Water Pump and Coolant (Service )				
<b>Date :</b>	5/6/2024	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$505.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 76,461
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Water Pump and Coolant	1.00	\$505.00	\$505.00
			<i>Total service :</i>	\$505.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	7/17/2024	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$75.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 79,206
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$75.00	\$75.00
			<i>Total service :</i>	\$75.00

<b>Service :</b> Resurface Rotors (Service )				
<b>Date :</b>	7/31/2024	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$200.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 79,928
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Resurface Rotors	1.00	\$200.00	\$200.00
<i>Total service :</i>				\$200.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	9/26/2024	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$75.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 82,424
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

<b>Service :</b> Replace Wiper Blades (Service )				
<b>Date :</b>	10/18/2024	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$32.00
<b>Reference :</b>		<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 0
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Wiper Blades	1.00	\$32.00	\$32.00
<i>Total service :</i>				\$32.00

*Total of the vehicle :* \$17,224.42