

Valley Forge Volunteer Fire Company

P. O. Box 62 Valley Forge, PA 19481

Reference: Engine 68-2 (2002 Pierce Job #13434 – VIN:4PICT02S52A002494)

This letter is to confirm Fire Line Equipment has notified Valley Forge Volunteer Fire Company the above referenced vehicle has corrosion perforation (holes) on the top flange of the driver's side frame rail between the fire pump and rear axle.

By signing below, the Valley Forge Volunteer Fire Company acknowledges that although Fire Line Equipment highly recommends replacing the frame rails or removing the vehicle from service, representatives of the fire company, including yourself, have personally seen the corrosion perforation and have elected to have Fire Line Equipment descale the area and coat with POR-15 prior to reassembly, without making any permanent repairs to the frame rails.

Printed Name:	
Signature	,
Title:	V:
Date:	

This letter must be completed and returned to Fire Line Equipment prior to the above referenced work being performed to the vehicle.

Regards,

