

Work History Report

Cumberland County
Courthouse

Date Produced: 4/3/2024
Account: 34 Planning Department
Reg: MG1476D PA
Vehicle Details FORD CROWN VICTORIA 4.6 2007
White

310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num V8 4.6L 281CID FI GAS N W / Vin 2FAFP71W07X107584 Mileage 87614

Invoice Number I003082 Date 3/13/2024 Mileage 87614 Job Value 332.36
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	33.09	CNV85372 Oil Filter advance	1	2.62
State Inspection	33.09	CNVWWFlu Windshield Washer Fluid d Clearv	1	1.32
State Emission Inspection	27.58	CNV75-053 5W30 Oil syn blend	6	15.30
Front brake pads low, install new pads and cleaned caliper brackets and slider pins	44.12	CNVEMI Emissions, Phone Transaction Fee	1	1.57
Jump start vehicle at Allen Rd, brought vehicle to 1601. Removed battery and charged, battery held charge and alternator is charging properly. Reinstall battery and checked for battery draw, noticed when spot light was disconnected there was a drop in meter reading. Disconnected spot light and let vehicle sit over night. No issues are reoccurring	137.88	CNVGNAD9 Front Brake Pads 31	1	33.79

Invoice Number I002956 Date 1/9/2024 Mileage 87261 Job Value 39.99
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Labor	Value	Parts	Qty	Value
Nail in tire tread, removed wheel and patched from the inside	33.09	CNV15-296 Tire Patch	1	1.90

Invoice Number I002389 Date 3/15/2023 Mileage 85280 Job Value 115.78
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	31.05	CNV85372 Oil Filter advance	1	3.95
State Inspection	31.05	CNVWWFlu Windshield Washer Fluid d Clearv	1	1.20
State Emission Inspection	25.88	CNV75-053 5W30 Oil syn blend	6	19.08
		CNVEMI Emissions, Phone Transaction Fee	1	1.57

Invoice Number I001697 Date 3/4/2022 Mileage 83252 Job Value 219.03
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	30.15	CNV85372 Oil Filter advance	1	3.14
State Inspection	30.15	CNV5w-30 Oil PPC	6	11.94
State Emission Inspection	25.13	CNVWWFlu Windshield Washer Fluid d Clearv	1	1.20
Serpentine belt cracking, also belt tensioner was weak, replaced both.	50.25	CNVEMI Emissions, Phone Transaction Fee	1	1.57
		CNV89291 Belt Tensioner	1	33.57
		CNV506092 Serpentine Belt 0	1	29.93

Invoice Number	I001002	Date	2/17/2021	Mileage	80996	Job Value	46.02
-----------------------	---------	-------------	-----------	----------------	-------	------------------	-------

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Jump start vehicle at Allen Rd, brought back to shop and charged Battery. Charging system is ok as well as battery.

Labor	Value	Parts	Qty	Value
Jump start at Allen Rd, brought vehicle to garage to charge battery and check charging system	46.02			

Invoice Number	K10943	Date	10/1/2020	Mileage	80994	Job Value	545.16
-----------------------	--------	-------------	-----------	----------------	-------	------------------	--------

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description NULL
NULL
State Inspection
Mounted and balanced 4 new tires.
NULL

Labor	Value	Parts	Qty	Value
State Emissions Inspection	21.22	CNV732002 2355R17Goodyear Eagle RSA	4	396.00
Emissions Phone Transaction Fee	1.57	500		
State inspection	31.83	highlands		
Replace tires	79.58	CNV333333 Wheel Weights	8	4.00
Tire Disposal Fee 4 tires Highlands	8.00	CNV17-413- Valve Stem 1.25 Rubber	4	0.96
		50 az		

Invoice Number	K10690	Date	6/8/2020	Mileage	80472	Job Value	320.23
-----------------------	--------	-------------	----------	----------------	-------	------------------	--------

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Diagnosed ac system. Found temperature is not changing from hot to cold because blend door actuator is faulty. Removed dash and replaced blend door actuator.
Check and charge AC

Labor	Value	Parts	Qty	Value
AC is not cold	212.20	CNV604-20 Air Door Actuator	1	44.32
Charge AC	53.05	8 az		
		CNVR134A Refrigerant Per Pound	2	6.66
		AZ		

Invoice Number	K10331	Date	12/5/2019	Mileage	79103	Job Value	103.19
-----------------------	--------	-------------	-----------	----------------	-------	------------------	--------

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL
NULL
State Inspection

Labor	Value	Parts	Qty	Value
Service	27.63	CNVWWFlu Windshield Washer Fluid	1	1.15
State Emissions Inspection	22.10	d		
Emissions Phone Transaction Fee	1.57	CNV5w-30 Oil	6	12.90
State inspection	33.15	Petro		
		CNV85372M Oil Filter	1	2.69
		P ADV.		

Invoice Number	K10116	Date	8/23/2019	Mileage	77899	Job Value	180.63
-----------------------	--------	-------------	-----------	----------------	-------	------------------	--------

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description NULL
Replaced wiper blades

Labor	Value	Parts	Qty	Value
Change Battery	27.63	CNVMT-65 Interstate Battery	1	127.95
replace wiper blades	11.05	CNVDL22 Wiper Blade	2	12.00
		az		

Invoice Number K9585	Date 1/7/2019	Mileage 75888	Job Value 55.25
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007			
Work Description Removed prisoner cage.			
Labor	Value	Parts	Qty Value
Remove Cage	55.25		

Invoice Number K9521	Date 12/6/2018	Mileage 75749	Job Value 116.12
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007			
Work Description NULL			
NULL			
State Inspection			
Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.			
NULL			

Labor	Value	Parts	Qty	Value
State Emissions Inspection	22.48	CNVWWFlu d Windshield Washer Fluid	1	1.15
Emissions Phone Transaction Fee	1.65	CNV5w-30 Oil	6	12.24
State inspection	33.72	Petro		
Service	28.10	CNVPH2 Oil Filter	1	3.54
Rotate Tires	11.24	BC		

Invoice Number K9449	Date 11/2/2018	Mileage 75748	Job Value 33.72
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007			
Work Description Removed power inverter and wiring from vehicle.			

Labor	Value	Parts	Qty	Value
Remove power inverter	33.72			

Invoice Number K8636	Date 11/7/2017	Mileage 72037	Job Value 257.15
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007			
Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.			
NULL			
NULL			
State Inspection			
Replaced rear brakes and rotors			

Labor	Value	Parts	Qty	Value
Service	28.86	CNVWWFlu d Windshield Washer Fluid	1	1.15
State Emissions Inspection	23.09	CNV5w-30 Oil	6	10.56
Emissions Phone Transaction Fee	1.65	Petro		
State inspection	34.63	CNVPH2 Oil Filter	1	3.31
Rear brakes Rotors	57.72	BC		
		CNV54105D Brake Rotors	2	61.84
		G AZ		
		CNVVG932 Brake Pads	1	30.34
		C AZ		

Invoice Number K8221	Date 5/18/2017	Mileage 66722	Job Value 182.26
Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007			
Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.			
NULL			
Replaced air filter			
Checked ses codes. Has code P2272. Replaced oxygen sensor bank 2 sensor 2 on drivers side. Cleared code.			

Labor	Value	Parts	Qty	Value
Service	28.86	CNVWWFlu d Windshield Washer Fluid	1	1.15
Rotate Tires	23.09	CNV5w-30 Oil	6	8.94
replace air filter	5.77	Petro		
SES light is on	57.72	CNVPH2 Oil Filter	1	3.31
		BC		
		CNVSA5056 Air Filter	1	6.09
		az		

Invoice Number K7694 Date 9/7/2016 Mileage 60374 Job Value 104.57

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

NULL

NULL

State Inspection

Labor	Value	Parts	Qty	Value
Service	29.12	CNVWWFlu Windshield Washer Fluid	1	1.15
State Emissions Inspection	23.30	CNV5w-30 Oil	6	8.94
Emissions Phone Transaction Fee	1.65	Petro		
State inspection	34.94	CNVPH2 Oil Filter	1	3.47
		BC		

Invoice Number K7115 Date 12/29/2015 Mileage 0 Job Value 40.53

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Service call to Old prison. Changed flat tire. brought tire back to garage. plugged hole in tire

Labor	Value	Parts	Qty	Value
Service Call	26.35	CNV710-10 tire plug	1	1.00
plug tire	13.18	36 Napa		

Invoice Number K7040 Date 11/24/2015 Mileage 51674 Job Value 199.19

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Got door unstuck and found Lock Actuator bad. Replaced door lock actuator.

Labor	Value	Parts	Qty	Value
LR door not unlocking	131.75	CNV746-18 Lock Actuator	1	65.44
		8 AZ		

Invoice Number K6901 Date 9/30/2015 Mileage 50585 Job Value 155.70

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed

NULL

NULL

NULL

Cleaned rims and painted all 4 rims.

Labor	Value	Parts	Qty	Value
Service	26.35	CNVWWFlu Windshield Washer Fluid	1	1.15
State Emissions Inspection	21.08	CNV5w-30 Oil	6	8.94
Emissions Phone Transaction Fee	1.47	Petro		
State Inspection	31.62	CNVPH2 Oil Filter	1	3.20
Paint Rims	52.70	BC		
		CNV248643 Black Spray paint	1	5.19
		az		

Invoice Number K6518 Date 4/27/2015 Mileage 47563 Job Value 40.62

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description NULL

plugged hole in tire left rear tire had a nail in it

Labor	Value	Parts	Qty	Value
Replace blades	10.54	CNV890010 Wiper Blade 22 inch	2	15.90
plug tire	13.18	16 Graham		
		CNV710-10 tire plug	1	1.00
		36 Napa		

Invoice Number K5903 Date 7/14/2014 Mileage 42835 Job Value 84.26

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed
NULL
NULL
State safety inspection. 6790 Miles Driven since last inspection

Labor	Value	Parts	Qty	Value
Service	25.31	CNVWWFlu d	1	1.15
State Emissions Inspection	16.88	CNV5w-30 Petro	6	8.94
Emissions Phone Transaction Fee	1.47	CNVPH2 BC	1	3.20
State Inspection	25.31			

Invoice Number K5575 Date 2/12/2014 Mileage 109621 Job Value 579.55

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Mounted and balanced all 4 new tires.
Replaced front brake pads.
Replaced fuel filter

Labor	Value	Parts	Qty	Value
Replace tires	63.29	CNV732002 500 sttc	4	396.00
Replace front brakes	42.19	CNV22222	4	6.00
Replace fuel filter	21.10	CNVVG931 az	1	33.99
		CNVG8018 az	1	10.99

Invoice Number K5539 Date 1/27/2014 Mileage 39336 Job Value 63.29

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Hooked up computer and checked for codes. Has code p061b stored in history. Followed code diagnostic chart. Cleaned carbon from throttle bore. Cleared history code and test drove. Car running normal now.

Labor	Value	Parts	Qty	Value
SES light came on and engine ran rough.	63.29			

Invoice Number K5302 Date 9/18/2013 Mileage 36045 Job Value 108.56

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description NULL
NULL
NULL
NULL
Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
State Emissions Inspection	18.03	CNVWWFlu d	1	0.99
Emissions Phone Transaction Fee	1.47	CNV5w-30 Petro	6	10.74
State Inspection	27.05	CNVPH2 BC	1	3.20
Rotate Tires	18.03			
Service	27.05			

Invoice Number K4646 Date 10/23/2012 Mileage 33427 Job Value 27.55

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Checked filters. Driver said they had just gotten gas. Added dry gas and gas treatment. Shook vehicle to spread treatment around in tank. Restarted vehicle and allowed to idle. Reveved up engine a few times. Idle returned to normal and vehicle no longer s

Labor	Value	Parts	Qty	Value
Check rough idle and car shutting off	20.30	CNV22222	1	2.50
		CNV22222	1	4.75

Invoice Number K4583 Date 9/27/2012 Mileage 32936 Job Value 114.74

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description NULL
Emissions Inspection
NULL
Lube Oil Filter Changed
found wires broken to lighter. Rewired cig. lighter

Labor	Value	Parts	Qty	Value
State Inspection	24.36	CNVWWFlu d	1	0.99
Emissions Inspection	16.24	CNV5w-30 Oil	6	10.74
Emissions Phone Transaction Fee	2.40	Petro CNVPH2	1	3.20
Service	24.36	BC		
no power out of cig. lighter	30.45			

Invoice Number K3938 Date 10/4/2011 Mileage 31181 Job Value 171.07

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed
NULL
NULL
NULL
replace left front turn signal lamp

Labor	Value	Parts	Qty	Value
Service	18.08	CNVPH2 Oil Filter	1	2.50
State Inspection	15.07	CNVWWFlu d	1	0.99
Emissions Inspection	15.00	CNV5w-20 Oil	6	9.12
Take Vehicle to Middlesex Township to have Emissions Inspection Done	22.60	PPC CNV6w7z15	1	61.12
replace left front turn signal lamp	22.60	a201ba		

Invoice Number K3181 Date 9/7/2010 Mileage 26928 Job Value 105.81

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed
NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	19.42	CNVPH2 Oil Filter	1	2.50
State Inspection	29.13	CNVWWFlu d	1	0.89
Emissions Inspection	15.00	CNV5w-20 Oil	6	7.74
Take Vehicle to Middlesex Township to have Emissions Inspection Done	29.13	PPC		

Invoice Number K2559 Date 8/31/2009 Mileage 21917 Job Value 123.29

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed
NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	20.64	CNVPH2 Oil Filter	1	2.50
State Inspection	41.28	CNVWWFlu d	1	0.89
Emissions Inspection	15.00	CNV5w-20 Oil	6	10.02
Take Vehicle out to Middlesex Township to have Emissions Inspection done.	30.96	PPC		

Invoice Number K1973 Date 8/27/2008 Mileage 17803 Job Value 96.27

Vehicle Details MG1476D PA FORD CROWN VICTORIA 2007

Work Description Lube Oil Filter Changed

NULL

NULL

NULL

Labor	Value	Parts	Qty	Value
Service	16.77	CNVPH2 Oil Filter	1	2.50
State Inspection	33.53	CNV5w-30 Oil	6	8.82
Emissions Inspection	15.00	CNVWWFlu Windshield Washer Fluid	1	0.89
Rotate Tires	16.77	d		