



Shop: Public Works Garage
Tel: 4846383624
Email: wrb.mechanic@gmail.com
Address: 123 1st ave

Report ID: MAXIA20250521143155
Test Time: 2025-05-21 14:31:55
Technician: --
Shop Number: 1

EOBD Pre-scan Report

Vehicle Information

--/EOBD/ISO 15765-4(CAN)/
VIN: 1FAHP2MK0HG126406

Odometer Reading: --
License Plate: --


Customer Information

Name: --
Tel: --

Device information

Scanner: MaxiSys MS906 TS
Version: V4.90
Serial Number: VT8GK4V01283
Repair Order Number: 389

System Scanned(1)

System	Calibration	Status/DTC
\$7E8		 20

Pre-scan DTC (20)

\$7E8 (20 DTCs)

DTC	Description	Status
P0201	Cylinder 1 injector 'A' circuit	Current
P0202	Cylinder 2 injector 'A' circuit	Current
P0203	Cylinder 3 injector 'A' circuit	Current
P0300	Random/multiple cylinder misfire detected	Current
P0301	Cylinder 1 misfire detected	Current
P0302	Cylinder 2 misfire detected	Current
P0303	Cylinder 3 misfire detected	Current
P0201	Cylinder 1 injector 'A' circuit	Pending
P0202	Cylinder 2 injector 'A' circuit	Pending
P0203	Cylinder 3 injector 'A' circuit	Pending
P0300	Random/multiple cylinder misfire detected	Pending
P0301	Cylinder 1 misfire detected	Pending
P0302	Cylinder 2 misfire detected	Pending
P0303	Cylinder 3 misfire detected	Pending
P0303	Cylinder 3 misfire detected	Permanent
P0420	Catalyst system efficiency below threshold bank 1	Permanent
P0355	Ignition coil 'E' primary control circuit/open	Permanent

P0201	Cylinder 1 injector 'A' circuit	Permanent
P0202	Cylinder 2 injector 'A' circuit	Permanent
P0203	Cylinder 3 injector 'A' circuit	Permanent

Pre-scan Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.