



SHULTS FORD INC.
1300 GULF LAB ROAD
PITTSBURGH, PA 15238
(412) 828-2300

www.shultsford.com



CELL: 412-215-1259

CUSTOMER NO. 94538	ADVISOR BAILIE TABACHECK	TAG NO. 8545	INVOICE DATE 06/16/22	INVOICE NO. HCCS245082
TOWNSHIP OF SHALER 300 WETZEL RD STE 1 GLENSHAW, PA 15116-2281	LABOR RATE	LICENSE NO. MG5713M	MILEAGE 35,480	COLOR BLUE/
	YEAR / MAKE / MODEL 21/FORD TRUCK/POLICE INTERCEP/4DR AW	DELIVERY DATE 06/08/22		
	VEHICLE I.D. NO. 1 F M 5 K 8 A W X M N A 1 0 8 5 0	SELLING DEALER NO.		
	F.T.E. NO. LOCAL GOVERNMENT	P.O. NO.	R.O. DATE 06/08/22	
NONE	COMMENTS			
RESIDENCE PHONE 412-487-6655	BUSINESS PHONE 412-486-9700	MO: 35480		

LABOR & PARTS

J# 1 06FTZ ENGINE REPAIR TECH(S):8616 WARRANTY

CHECK ENGINE AND WRENCH LIGHTS ON
SCAN DTC'S BECM POB24 PPT AM1 SCAN DTC'S NO CODES LISTED
PRESENT. AM2 CHARGE BATTERY PERFORM BECM SELF TEST YES,
POB24 AM3 VERIFY BECM CONNECTORS SEATED (REMOVED) HIGH
VOLTAGE BATTERY. STATES R&R BECM. DE ENERGIZE SYSTEM.
REMOVED BATTERY FROM VEHICLE. REPLACED BECM MODULE REINSTALL
BATTERY. RE ENERGIZE SYSTEM BLEED COOLANT SYSTEM (VACUUM
FILLED). PERFORM PMI ON BECM. PERFORM UPDATE ON PCM. PERFORM
UPDATE ON SOBDMC. PERFORM COOLANT BLEED PROCEDURE THROUGH
FDRS. ROAD TEST VEHICLE

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. I, THE UNDERSIGNED, AGREE TO PAY ANY AND ALL COLLECTION OR ATTORNEY FEES MADE NECESSARY BY A NONSUFFICIENT FUND, STOP PAYMENT, REFER TO MAKER, OR ACCOUNT CLOSED CHECK OR CHARGE CARD OR UNPAID REPAIR ORDER.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
JOB # 1	1	L1MZ-10B687-A	CONTROL AND BA		
				JOB # 1 TOTAL PARTS	0.00
				JOB # 1 TOTAL LABOR & PARTS	0.00

ALL PARTS ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE.

J# 2+20FTZ BODY TECH(S):8616 WARRANTY

ADD LINE C/S THAT THE DRIVERS FRONT MAT AREA HAS A HOLE WHERE THE PEDAL AREA IS
VERIFY DRIVER MAT WORN THOUGH. REPLACE DRIVER FLOOR MAT
REMOVE SEAT, REMOVED CENTER CONSOLE/REPOSITIONED WITH WIRING
M TIME PUNCH REINSTALL CENTER CONSOLE/SEAT



PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
JOB # 2	1	LB5Z-7813001-PA	CARPET - FLOOR		
				JOB # 2 TOTAL PARTS	0.00
				JOB # 2 TOTAL LABOR & PARTS	0.00

TOTALS

SERVICE AND PARTS HOURS	TOTAL LABOR....	0.00
	TOTAL PARTS....	0.00
	TOTAL SUBLET...	0.00
	TOTAL G.O.G....	0.00
	TOTAL MISC CHG.	0.00
	TOTAL MISC DISC	0.00
	TOTAL TAX.....	0.00
	TOTAL INVOICE \$	0.00

FORDPASS APP
Download the FordPass App today for free to start earning FordPass Rewards!
Find parking. And fuel. And with a SYNC* Connect-enabled vehicle, you can even control your Ford remotely. All to help you get from A to B, better.



CUSTOMER SIGNATURE

214

The Reynolds and Reynolds Company EFANTS14E CC220917 Q (08/19)