

2
0
1
9

DODGE

DURANGO PURSUIT AWD

THIS VEHICLE IS MANUFACTURED TO MEET SPECIFIC UNITED STATES REQUIREMENTS. THIS VEHICLE IS NOT MANUFACTURED FOR SALE OR REGISTRATION OUTSIDE OF THE UNITED STATES.

MANUFACTURER'S SUGGESTED RETAIL PRICE OF THIS MODEL INCLUDING DEALER PREPARATION

Base Price: \$34,370

DODGE DURANGO PURSUIT VEHICLE AWD

Exterior Color: White Knuckle Exterior Paint

Interior Color: Black Interior Color

Interior: Cloth-Trimmed Bucket Seats

Engine: 5.7-Liter V8 HEMI® MDS VVT Engine

Transmission: 8-Speed Automatic Transmission

STANDARD EQUIPMENT (UNLESS REPLACED BY OPTIONAL EQUIPMENT) FUNCTIONAL/SAFETY FEATURES

- Advanced Multistage Front Airbags
- Supplemental Side-Curtain Airbags in All Rows
- Supplemental Front Seat-Mounted Side Airbags
- ParkView® Rear Back-Up Camera
- ParkSense® Rear Park-Assist with Stop
- Auto-Dimming Rear View Mirror
- Sport Mode
- Selectable Steering Modes
- 4-Wheel Traction Control
- 4-Wheel Disc Heavy-Duty Brakes
- Active Head Restraints
- Enhanced Accident Response System
- Electronic Stability Control
- Hill Start Assist
- Rain Brake Support
- 24.6-Gallon Fuel Tank
- Remote Keyless Entry
- Keyless Go™
- 220-Amp Alternator
- Spot Lamp Wiring Prep

INTERIOR FEATURES

- Uconnect® 4 with 7-Inch Display
- Apple CarPlay®
- Google Android Auto™
- Integrated Voice Command with Bluetooth®
- Media Hub (2 USB, Aux)
- 6-Speakers
- Perforated Leather-Wrapped Steering Wheel
- Steering Wheel Mounted Audio Controls
- Air Conditioning with 3-Zone Automatic Temp Control
- Speed Control
- Power Door Locks
- Tilt / Telescope Steering Column

- Tire Pressure Monitoring Display
- Luxury Front and Rear Floor Mats
- 12-Volt Auxiliary Power Outlet
- Full-Length Floor Console
- Front and Rear Interior LED Lamps

EXTERIOR FEATURES

- 18.0-Inch x 8.0-Inch Painted Aluminum Wheels
- P265/60R18 BSW On/Off-Road Tires
- Premium LED Fog Lamps
- Power-Heated Mirrors with Manual Fold-Away
- Automatic Headlamps
- Halogen Headlamps
- Rear Window Wiper / Washer
- Performance Front Fascia
- Performance Grille with Black Texture

OPTIONAL EQUIPMENT (May Replace Standard Equipment)

Customer Preferred Package 22Z

- Durango Pursuit Vehicle
- 5.7-Liter V8 HEMI® MDS VVT Engine \$2,995
- Sport Suspension
- 2-Speed On-Demand Transfer Case
- 800-Amp Maintenance Free Battery
- Dual Rear-Exhaust with Bright Tips
- Full-Size Spare Tire
- 99595A

DESTINATION CHARGE \$1,49

TOTAL PRICE: * \$38,860

WARRANTY COVERAGE

- 5-year or 60,000-mile Powertrain Limited Warranty.
- 3-year or 36,000-mile Basic Limited Warranty.
- Ask Dealer for a copy of the limited warranties or see your owner's manual for details.

**5 YEAR / 60,000 MILE
POWERTRAIN WARRANTY**

Assembly Point/Port of Entry: DETROIT, MICHIGAN, U.S.A.

VIN: 1C4-SDJFT7KC-685135

L4-VON: 1105


0312

SHIP TO: 45677 39
NEW HOLLAND AUTO GROUP
508 WEST MAIN ST.
NEW HOLLAND PA 17557-1121

SOLO TO: 35 45677
NEW HOLLAND AUTO GROUP
508 WEST MAIN ST.
NEW HOLLAND PA 17557-1121

THIS LABEL IS ADDED TO THIS VEHICLE TO COMPLY WITH FEDERAL LAW. THE LABEL CANNOT BE REMOVED OR ALTERED PRIOR TO DELIVERY TO THE ULTIMATE PURCHASER.

* STATE AND/OR LOCAL TAXES IF ANY, LICENSE AND TITLE FEES AND DEALER SUPPLIED AND INSTALLED OPTIONS AND ACCESSORIES ARE NOT INCLUDED IN THIS PRICE. DISCOUNT, IF ANY, IS BASED ON PRICE OF OPTIONS IF PURCHASED SEPARATELY.



This vehicle was built especially for
FLEET

FCA US LLC



Fuel Economy and Environment



Gasoline Vehicle

Fuel Economy

These estimates reflect new EPA methods beginning with 2017 models.



17
combined city/hwy

MPG

14
city

22
highway

combined city/hwy

city

highway

5.9 gallons per 100 miles

Standard SUV 4WD range from 13 to 93 MPGe.
The best vehicle rates 136 MPGe.

You spend
\$5,250


more in fuel costs
over 5 years
compared to the
average new vehicle.

Annual fuel cost

\$2,450

Fuel Economy & Greenhouse Gas Rating (tailpipe only)

Smog Rating (tailpipe only)



This vehicle emits 533 grams CO2 per mile. The best emits 0 grams per mile (tailpipe only). Producing and distributing fuel also creates emissions; learn more at fuel economy.gov

Actual results will vary for many reasons, including driving conditions and how you drive and maintain your vehicle. The average new vehicle gets 27 MPG and cost \$7,000 to fuel over 5 years. Cost estimates are based on 15,000 miles per year at \$2.80 per gallon. MPGe is miles per gasoline gallon equivalent. Vehicle emissions are a significant cause of climate change and smog.

fuel economy.gov

Calculate personalized estimates and compare vehicles

Smartphone
QR Code™



GOVERNMENT 5-STAR SAFETY RATINGS

Overall Vehicle Score

Not Rated

Based on the combined ratings of frontal, side, and rollover.
Should ONLY be compared to other vehicles of similar size and weight.

Frontal Crash

Driver
Passenger

Not Rated
Not Rated

Based on the risk of injury in a frontal impact.
Should ONLY be compared to other vehicles of similar size and weight.

Side Crash

Front seat
Rear seat

Not Rated
Not Rated

Based on the risk of injury in a side impact.

Rollover

★★★

Based on the risk of rollover in a single-vehicle crash.

PARTS CONTENT INFORMATION

FOR VEHICLES IN THIS CARLINE:

U.S./CANADIAN PARTS CONTENT: 60%

MAJOR SOURCES OF FOREIGN PARTS
CONTENT:

MEXICO: 26%

NOTE: PARTS CONTENT DOES NOT INCLUDE FINAL
ASSEMBLY, DISTRIBUTION, OR OTHER
NON-PARTS COSTS.

FOR THIS VEHICLE:

FINAL ASSEMBLY POINT:

DETROIT, MICHIGAN, U.S.A.

COUNTRY OF ORIGIN:

ENGINE: MEXICO

TRANSMISSION: GERMANY

Star ratings range from 1 to 5 stars (★★★★★) with 5 being the highest.

Source: National Highway Traffic Safety Administration (NHTSA)

www.safercar.gov or 1-888-327-4236

The safety ratings above are based on Federal Government tests of particular vehicles equipped with certain features and options. The performance of this vehicle may differ.



**VEHICLE
PROTECTION**

A PRODUCT OF FCA US LLC

Ask for Mopar Vehicle Protection for your vehicle. We Built It. We Back It.

Detailed services/breakdown

Display criteria

Period : All

Vehicle(s) : Dodge/Durango/2019

Vehicle : 67-93 - Dodge/Durango/2019/MG3151L

Service :	Complete Upfitting of New Patrol Vehicle. (Service)			Cost :	\$14,245.00
Date :	5/9/2019	Technician responsible :	N/D	Odometer :	1
Reference :	IN000109062	Vendor responsible :	Metropolitan Communications		
Type	Description	Qty.	Unit cost	Total cost	
Other	Complete Upfitting of new Patrol Vehicle	1.00	\$14,245.00	\$14,245.00	
		<i>Total service :</i>		\$14,245.00	

Service :	Seal Crank Shaft (Service)			Cost :	\$0.00
Date :	5/24/2019	Technician responsible :	N/D	Odometer :	794
Reference :	CHCS29739	Vendor responsible :	Videon Dodge		
Type	Description	Qty.	Unit cost	Total cost	
Other	Seal Crank Shaft	1.00	\$0.00	\$0.00	
		<i>Total service :</i>		\$0.00	

Service :	Oil and Filter Change (Service)			Cost :	\$44.95
Date :	8/23/2019	Technician responsible :	N/D	Odometer :	3,914
Reference :	14324	Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
		<i>Total service :</i>		\$44.95	

Service : Oil and Filter Change (Service)		Cost : \$44.95	
Date : 10/31/2019	Technician responsible : N/D	Odometer : 7,045	
Reference : 15094	Vendor responsible : Thorntons Gulf		
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$44.95
<i>Total service :</i>			\$44.95

Service : Resurface Front and Rear, Left and Right Rotors (Service)		Cost : \$0.00	
Date : 11/5/2019	Technician responsible : N/D	Odometer : 7,343	
Reference : CHCS38616	Vendor responsible : Videon Dodge		
Type	Description	Qty.	Unit cost
Other	Resurface Front and Rear, Left and Right Rotors	1.00	\$0.00
<i>Total service :</i>			\$0.00

Service : Oil and Filter Change (Service)		Cost : \$44.95	
Date : 11/26/2019	Technician responsible : N/D	Odometer : 8,191	
Reference : 15204	Vendor responsible : Thorntons Gulf		
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$44.95
<i>Total service :</i>			\$44.95

Service : Replace AC Condensorand EVAC, Recharge Freon (Service)		Cost : \$0.00	
Date : 12/4/2019	Technician responsible : N/D	Odometer : 8,793	
Reference : CHCS40068	Vendor responsible : Videon Dodge		
Type	Description	Qty.	Unit cost
Other	Replace AC Condensorand EVAC, Recharge Freon	1.00	\$0.00
<i>Total service :</i>			\$0.00

Service : Oil and Filter Change, Replace Turn Signal Bulb (Service)			
Date : 1/22/2020	Technician responsible : N/D		Cost : \$59.95
Reference : 15771	Vendor responsible : Thorntons Gulf		Odometer : 11,252
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change, Replace Turn Signal Bulb	1.00	\$59.95
<i>Total service :</i>			\$59.95

Service : Replace Front Brakes, Emission and State Inspection. (Service)			
Date : 3/5/2020	Technician responsible : N/D		Cost : \$241.00
Reference : 15832	Vendor responsible : Thorntons Gulf		Odometer : 13,171
Type	Description	Qty.	Unit cost
Other	Replace Front Brakes, Emission and State Inspection.	1.00	\$241.00
<i>Total service :</i>			\$241.00

Service : Replace AC Condenser (Covered Under Warranty) (Service)			
Date : 3/31/2020	Technician responsible : N/D		Cost : \$50.00
Reference : CHCS45572	Vendor responsible : Videon Dodge		Odometer : 14,276
Type	Description	Qty.	Unit cost
Other	Replace AC condenser	1.00	\$50.00
<i>Total service :</i>			\$50.00

Service : Oil and Filter Change (Service)			
Date : 4/9/2020	Technician responsible : N/D		Cost : \$44.95
Reference : 16166	Vendor responsible : Thorntons Gulf		Odometer : 14,847
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$44.95
<i>Total service :</i>			\$44.95

Service :	Oil and Filter Change, Replace cracked seat seal. (Service)	Cost :	\$48.69
Date :	5/8/2020	Technician responsible :	N/D
Reference :	CHCS46801	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Fix cracked seat seal, oil and filter change	1.00	\$48.69
<i>Total service :</i>			\$48.69

Service :	Remove Dent from Left Front Door (Service)	Cost :	\$250.00
Date :	5/28/2020	Technician responsible :	N/D
Reference :	CHCB47523	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Remove Dent from Left Front Door	1.00	\$250.00
<i>Total service :</i>			\$250.00

Service :	Replace Radiator Cap (Service)	Cost :	\$0.00
Date :	7/10/2020	Technician responsible :	N/D
Reference :	CHCS49524	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Replace Radiator Cap	1.00	\$0.00
<i>Total service :</i>			\$0.00

Service :	Replace Transmission Cooler and Refill system, Replace Heater Hose. (Service)	Cost :	\$65.00
Date :	7/22/2020	Technician responsible :	N/D
Reference :	CHCS50049	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Replace Transmission Cooler and Refill system, Replace Heater Hose.	1.00	\$65.00
<i>Total service :</i>			\$65.00

Service : Replace the A/C Condensor and Refill with Freon (Service)		Cost : \$0.00
Date : 8/3/2020	Technician responsible : N/D	Odometer : 19,326
Reference : CHCS50740	Vendor responsible : Videon Dodge	
Type	Description	Qty. Unit cost Total cost
Other	Replace the A/C Condensor and Refill with Freon	1.00 \$0.00 \$0.00
<i>Total service :</i>		\$0.00

Service : Front end Alignment, Mount and Balance 4 tires (Service)		Cost : \$203.00
Date : 8/26/2020	Technician responsible : N/D	Odometer : 20,285
Reference : 16544	Vendor responsible : Thorntons Gulf	
Type	Description	Qty. Unit cost Total cost
Other	Front end Alignment, Mount and Balance 4 tires	1.00 \$203.00 \$203.00
<i>Total service :</i>		\$203.00

Service : Oil and Filter Change, Replace Wiper Blades, replace passenger side Headlight bulb (Service)		Cost : \$102.95
Date : 8/25/2020	Technician responsible : N/D	Odometer : 20,232
Reference : 16531	Vendor responsible : Thorntons Gulf	
Type	Description	Qty. Unit cost Total cost
Other	Oil and Filter Change, Replace Wiper Blades, replace passenger side Headlight bulb	1.00 \$102.95 \$102.95
<i>Total service :</i>		\$102.95

Service : Replace left front headlight (Service)		Cost : \$35.00
Date : 10/16/2020	Technician responsible : N/D	Odometer : 0
Reference : 14908	Vendor responsible : Thorntons Gulf	
Type	Description	Qty. Unit cost Total cost
Other	Replace left front headlight	1.00 \$35.00 \$35.00
<i>Total service :</i>		\$35.00

Service : Emission and State Inspection, Replace Condenser, Recharge AC System, Replace Left front Motor mount, Replace driver side headlamp, Replace Front brake pads and Rotors (Service)		Cost : \$615.70
Date : 3/10/2021	Technician responsible : N/D	Odometer : 27,107
Reference : CHCS60769	Vendor responsible : Videon Dodge	
Type	Description	Qty. Unit cost Total cost
Other	Emission and State Inspection, Replace Condenser, Recharge AC System, Replace Left front Motor mount, Replace driver side headlamp, Replace Front brake pads and Rotors	1.00 \$615.70 \$615.70
<i>Total service :</i>		\$615.70

Service : Replace Oil Cooler Assembly, Replace Oil Cooler Hose, Replace both Upper and Lower Radiator Hose, Oil and Filter Change (Service)		Cost : \$50.49
Date : 4/7/2021	Technician responsible : N/D	Odometer : 28,425
Reference : CHCS62026	Vendor responsible : Videon Dodge	
Type	Description	Qty. Unit cost Total cost
Other	Replace Oil Cooler Assembly, Replace Oil Cooler Hose, Replace both Upper and Lower Radiator Hose, Oil and Filter Change	1.00 \$50.49 \$50.49
<i>Total service :</i>		\$50.49

Service : Replace Overflow Bottle (Service)		Cost : \$0.00
Date : 4/16/2021	Technician responsible : N/D	Odometer : 28,711
Reference : CHCS62638	Vendor responsible : Videon Dodge	
Type	Description	Qty. Unit cost Total cost
Other	Replace Overflow Bottle	1.00 \$0.00 \$0.00
<i>Total service :</i>		\$0.00

Service : Replace Water Pump, Replace "O" ring and Antifreeze (Service)			
Date :	10/5/2021	Technician responsible :	N/D
Reference :	CHCS70737	Vendor responsible :	Videon Dodge
Cost :	\$0.00	Odometer :	38,338
Type	Description	Qty.	Unit cost
Other	Replace Water Pump, Replace "O" ring and Antifreeze	1.00	\$0.00
<i>Total service :</i>			\$0.00

Service : Oil and Filter Change (Service)			
Date :	10/19/2021	Technician responsible :	N/D
Reference :	18592	Vendor responsible :	Thorntons Gulf
Cost :	\$60.00	Odometer :	39,496
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$60.00
<i>Total service :</i>			\$60.00

Service : Front Brakes, Front end Alignment, Mount and balance 2 tires, Head Gasket, Coolant (Service)			
Date :	10/25/2021	Technician responsible :	N/D
Reference :	17418	Vendor responsible :	Thorntons Gulf
Cost :	\$432.00	Odometer :	39,732
Type	Description	Qty.	Unit cost
Other	Front Brakes, Front end Alignment, Mount and balance 2 tires, Head Gasket, Coolant	1.00	\$432.00
<i>Total service :</i>			\$432.00

Service : Replace Left Front Wheel Flare (Service)			
Date :	9/13/2021	Technician responsible :	N/D
Reference :	CHCS69701	Vendor responsible :	Videon Dodge
Cost :	\$278.80	Odometer :	37,461
Type	Description	Qty.	Unit cost
Other	Replace Left Front Wheel Flare	1.00	\$278.80
<i>Total service :</i>			\$278.80

Service : Oil and Filter Change (Service)		Cost : \$60.00	
Date : 12/2/2021	Technician responsible : N/D	Odometer :	42,225
Reference : 18695	Vendor responsible : Thorntons Gulf		
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$60.00
<i>Total service :</i>			\$60.00

Service : Replace Headlight (Service)		Cost : \$35.00	
Date : 11/24/2021	Technician responsible : N/D	Odometer :	0
Reference : 18661	Vendor responsible : Thorntons Gulf		
Type	Description	Qty.	Unit cost
Other	Replace Headlight	1.00	\$35.00
<i>Total service :</i>			\$35.00

Service : Replace Right Front Headlight (Service)		Cost : \$35.00	
Date : 1/10/2022	Technician responsible : N/D	Odometer :	0
Reference : 18745	Vendor responsible : Thorntons Gulf		
Type	Description	Qty.	Unit cost
Other	Replace Right Front Headlight	1.00	\$35.00
<i>Total service :</i>			\$35.00

Service : Oil and Filter Change (Service)		Cost : \$60.00	
Date : 1/19/2022	Technician responsible : N/D	Odometer :	45,107
Reference : 17786	Vendor responsible : Thorntons Gulf		
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$60.00
<i>Total service :</i>			\$60.00

Service : Oil and Filter Change (Service)			
Date :	3/28/2022	Technician responsible :	N/D
Reference :	17890	Vendor responsible :	Thorntons Gulf
Cost :			\$75.00
Odometer :			50,000
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$75.00
<i>Total service :</i>			\$75.00

Service : Replace AC Condenser and recharge System (Service)			
Date :	4/18/2022	Technician responsible :	N/D
Reference :	CHCS79494	Vendor responsible :	Videon Dodge
Cost :			\$67.50
Odometer :			51,477
Type	Description	Qty.	Unit cost
Other	Replace AC Condenser and recharge System	1.00	\$67.50
<i>Total service :</i>			\$67.50

Service : Replace Driver Seat Trim, Replace Washer Nozzle (Service)			
Date :	5/26/2022	Technician responsible :	N/D
Reference :	CHCS81284	Vendor responsible :	Videon Dodge
Cost :			\$168.16
Odometer :			53,609
Type	Description	Qty.	Unit cost
Other	Replace Driver Seat Trim, Replace Washer Nozzle	1.00	\$168.16
<i>Total service :</i>			\$168.16

Service : Oil and Filter Change (Service)			
Date :	5/19/2022	Technician responsible :	N/D
Reference :	17951	Vendor responsible :	Thorntons Gulf
Cost :			\$75.00
Odometer :			53,367
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$75.00
<i>Total service :</i>			\$75.00

Service :	Replace Wiper Blades (Service)	Cost :	\$30.00
Date :	5/27/2022	Technician responsible :	N/D
Reference :	17990	Vendor responsible :	Thorntons Gulf
Type	Description	Qty.	Unit cost
Other	Replace Wiper Blades	1.00	\$30.00
<i>Total service :</i>			\$30.00

Service :	Replace connector and TIMP along with all wiring (Service)	Cost :	\$972.00
Date :	6/14/2022	Technician responsible :	N/D
Reference :	CHCS81859	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Replace connector and TIMP along with all wiring	1.00	\$972.00
<i>Total service :</i>			\$972.00

Service :	Replace Battery (Service)	Cost :	\$489.00
Date :	7/21/2022	Technician responsible :	N/D
Reference :	000334	Vendor responsible :	Thorntons Gulf
Type	Description	Qty.	Unit cost
Other	Replace Battery	1.00	\$489.00
<i>Total service :</i>			\$489.00

Service :	Replace Engine Long Block, Replace Intake Manifold, Oil and Filter Change. Replace all Gaskets and seals, Recharge AC (Service)	Cost :	\$0.00
Date :	9/30/2022	Technician responsible :	N/D
Reference :	CHCS86952	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Replace Engine Long Block, Replace Intake Manifold, Oil and Filter Change. Replace all Gaskets and seals, Recharge AC	1.00	\$0.00
<i>Total service :</i>			\$0.00

Total service : \$394.78

Service :	Replace Wiper Blades and Washer Fluid (Service)			Cost :	\$78.00
Date :	1/20/2023	Technician responsible :	N/D	Odometer :	0
Reference :		Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Wiper Blades and Washer Fluid	1.00	\$78.00	\$78.00	
				Total service :	\$78.00

Service :	Oil and Filter Change (Service)			Cost :	\$75.00
Date :	3/1/2023	Technician responsible :	N/D	Odometer :	65,384
Reference :		Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	oil and filter change	1.00	\$75.00	\$75.00	
				Total service :	\$75.00

Service :	Emission and State Insp. Replace Front and Rear Brakes,Mount and Balance 4 Tires (Service)			Cost :	\$461.00
Date :	3/7/2023	Technician responsible :	N/D	Odometer :	66,792
Reference :		Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Emission and State Insp. Replace Front and Rear Brakes,Mount and Balance 4 Tires	1.00	\$461.00	\$461.00	
				Total service :	\$461.00

Service :	Oil and Filter Change (Service)			Cost :	\$75.00
Date :	3/30/2023	Technician responsible :	N/D	Odometer :	68,495
Reference :		Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	

Other	Oil and Filter Change	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

Service :	Replace Water Pump and Coolant (Service)		Cost :	\$410.00
Date :	3/21/2023		Odometer :	67,729
Reference :				
	Technician responsible : N/D			
	Vendor responsible : Thorntons Gulf			
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Water Pump and Coolant	1.00	\$410.00	\$410.00
<i>Total service :</i>				\$410.00

Service :	Replace AC Condenser and Recharge Systemto Propper Pressure, Replace Motor Mount (Service)		Cost :	\$703.00
Date :	4/17/2023		Odometer :	69,051
Reference :	CHCS95901			
	Technician responsible : N/D			
	Vendor responsible : Videon Dodge			
Type	Description	Qty.	Unit cost	Total cost
Other	Replace AC Condenser and Recharge Systemto Propper Pressure, Replace Motor Mount	1.00	\$703.00	\$703.00
<i>Total service :</i>				\$703.00

Service :	Replace Belt and Tensioner (Service)		Cost :	\$216.00
Date :	5/5/2023		Odometer :	70,258
Reference :				
	Technician responsible : N/D			
	Vendor responsible : Thorntons Gulf			
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Belt and Tensioner	1.00	\$216.00	\$216.00
<i>Total service :</i>				\$216.00

Service :	Oil and Filter Change, Hose Fitting, Thermostat, Antifreeze (Service)			Cost :	\$291.00
Date :	5/15/2023	Technician responsible :	N/D	Odometer :	70,725
Reference :		Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change, Hose Fitting, Thermostat, Antifreeze	1.00	\$291.00	\$291.00	
	<i>Total service :</i>				\$291.00

Service :	Replaced Leaking AC Condensor (Service)			Cost :	\$0.00
Date :	7/6/2023	Technician responsible :	N/D	Odometer :	74,537
Reference :	101641	Vendor responsible :	Videon Dodge		
Type	Description	Qty.	Unit cost	Total cost	
Other	Replaced Leaking AC Condensor	1.00	\$0.00	\$0.00	
	<i>Total service :</i>				\$0.00

Service :	Mount and Balance 1 tire, Oil and Filter Change, Change Battery (Service)			Cost :	\$192.00
Date :	8/23/2023	Technician responsible :	N/D	Odometer :	77,028
Reference :		Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Mount and Balance 1 tire, Oil and Filter Change, Change Battery	1.00	\$192.00	\$192.00	
	<i>Total service :</i>				\$192.00

Service :	Replace Front and Rear Brakes and Rotors, Mount and balance 2 tires, Oil and Filter Change, Replace 2 Upper and 2 Lower Control Arms, Front end alignment (Service)			Cost :	\$3,250.00
Date :	10/6/2023	Technician responsible :	N/D	Odometer :	79,471
Reference :		Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Front and Rear Brakes and Rotors, Mount and balance 2 tires, Oil and Filter Change, Replace 2 Upper and 2 Lower Control Arms, Front end alignment	1.00	\$3,250.00	\$3,250.00	

Total service : \$3,250.00

Service : Replace Battery (Service)			
Date :	12/8/2023	Technician responsible :	N/D
Reference :	108694	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Replace Battery	1.00	\$569.35
		Total cost	\$569.35
Cost : \$569.35			
Odometer : 82,307			
Total service : \$569.35			

Service : Replace Fuel Pump, Fuse and Repaired Connector (Service)			
Date :	1/3/2024	Technician responsible :	N/D
Reference :	109423	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Replace Fuel Pump, Fuse and Repaired Connector	1.00	\$1,225.10
		Total cost	\$1,225.10
Cost : \$1,225.10			
Odometer : 83,049			
Total service : \$1,225.10			

Service : Oil and Filter Change (Service)			
Date :	12/20/2023	Technician responsible :	N/D
Reference :		Vendor responsible :	Thorntons Gulf
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change	1.00	\$75.00
		Total cost	\$75.00
Cost : \$75.00			
Odometer : 82,676			
Total service : \$75.00			

Service : Emission and State Insp. Oil and Filter Change, Mount and Balance 3 tires (Service)			
Date :	2/15/2024	Technician responsible :	N/D
Reference :		Vendor responsible :	Thorntons Gulf
Type	Description	Qty.	Unit cost
Other	Emission and State Insp. Oil and Filter Change, Mount and Balance 3 tires	1.00	\$274.00
		Total cost	\$274.00
Cost : \$274.00			
Odometer : 85,708			
Total service : \$274.00			

Total service : \$274.00

Service :	Replace Actuator-Blend Door, replace Actuator Gear (Service)		
Date :	4/11/2024	Technician responsible :	N/D
Reference :	113790	Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Replace Actuator-Blend Door, replace Actuator Gear	1.00	\$467.84
			Total cost
			\$467.84
			Cost :
			\$467.84
			Odometer :
			88,261
			Total cost
			\$467.84

Total service : \$467.84

Service :	Oil and Filter Change, Heater Hose and Coolant (Service)		
Date :	4/16/2024	Technician responsible :	N/D
Reference :		Vendor responsible :	Videon Dodge
Type	Description	Qty.	Unit cost
Other	Oil and Filter Change, Heater Hose and Coolant	1.00	\$275.00
			Total cost
			\$275.00
			Cost :
			\$275.00
			Odometer :
			88,272
			Total cost
			\$275.00

Total service : \$275.00

Service :	Replace Thermostat, Refill Coolant (Service)		
Date :	6/4/2024	Technician responsible :	N/D
Reference :		Vendor responsible :	Thorntons Gulf
Type	Description	Qty.	Unit cost
Other	Replace Thermostat, Refill Coolant	1.00	\$166.00
			Total cost
			\$166.00
			Cost :
			\$166.00
			Odometer :
			91,502
			Total cost
			\$166.00

Total service : \$166.00

Service :	Replace Heater Hose, Replace Coolant, Replace Starter (Service)		
Date :	7/2/2024	Technician responsible :	N/D
Reference :		Vendor responsible :	Thorntons Gulf
Type	Description	Qty.	Unit cost
Other	Replace Heater Hose, Replace Coolant, Replace Starter	1.00	\$732.00
			Total cost
			\$732.00
			Cost :
			\$732.00
			Odometer :
			93,617
			Total cost
			\$732.00

Total service : \$732.00

Total service :

\$732.00

Total of the vehicle :

\$31,934.49