

TUB-04**2002 MORBARK 1300 TUB GRINDER**

Date Serviced	Comments
11/12/2018	check all fluid levels, charge batteries, replace wheel seal fill caps, grease entire machine
6/29/2018	clutch will not engage and the auger that feeds the discharge belt will not turn. DEACON EQUIPMENT REPAIRED.
5/1/2018	seem to have a fuel issue, will not come up off of idle. REPAIRED WIRING. REPLACED A PRESSURE SWITCH.
4/27/2018	TUB CHAIN JUMPED OFF
11/14/2017	needs a new tub motor
7/29/2017	Fill in gouge around both sides of mill
6/5/2017	Temp Gauge is not working
5/10/2017	plastic oil cap on the axles are cracked, repack mill bearings
2/18/2017	replace discharge rubber flaps, fix temp gauge, replace chain and sprockets on tub, front tub motor shaft seal is leaking, fix grease lines going to idler bearings on the end of discharge belt, replace deflector shield in bottom of tub
1/31/2017	PM SERVICE
1/18/2017	WELD PLATE FLOOR OF TUB AND REPAIR HAMMER
1/14/2017	hard face welding, fix wear plate in bottom of tub, replace rubber discharge flaps on conveyor belt, fix grease line on idler bearing at top of belt
12/6/2016	needs some new wiring put in, do to small fire
11/11/2016	Bad vibration, possibly the clutch. GOING TO DEACON EQUIPMENT FOR REPAIR.
11/9/2016	need tub chain repaired before we take it to Deacon for the torque limiter.
9/7/2016	clam does not work may need Deacon to look at it Doug thinks it is one of the valves under the cab not working.
8/26/2016	Check grease in mill bearings, noise coming from unknown source
7/26/2016	overheating (240 at an idle)
6/29/2016	Hydraulic line on top of trasmission is blown, needs power washed before repair
4/21/2016	needs a new belt on discharge conveyor. ANDY INSTALLED.
4/19/2016	NEEDS TIRE ON FRONT AXLE ON CAB SIDE FIXED
12/30/2015	Air compressor needs repaired.
12/29/2015	auger not turning, fan reverse not working, and exhaust manifold gaskets need replaced
10/5/2015	PM SERVICE
9/28/2015	chain skipping tub will not spin. WORKING AT THIS TIME.
9/4/2015	rear tub motor shaft seal leaking, cooling fan doesn't reverse, leaking brake chamber on rear axle, tighten discharge belt,replace discharge belt rollers(1 missing, 1 bad bearings) REPAIR AS SOON AS POSSIBLE!
3/26/2015	Hammer repair
3/12/2015	Repair cutter bar
3/4/2015	FIX MARKER LIGHTS - TUB-04 NEEDS TO BE ROAD WORTHY BY THE END OF NEXT WEEK (3/6/15)
12/16/2014	PM SERVICE
11/25/2014	CRACK IN CLAM NEEDS WELDED
7/17/2014	hammer needs welded (as soon as possible)

6/5/2014	WELD HAMMERS AND REPAIR WEAR PLATES
5/29/2014	replace belts for hydraulic pump
5/5/2014	FIRE DAMAGE. CLEVELAND BROTHERS-CAT PERFORMED WORK. REPLACED WIRING HARNESS'S & ETC.
2/11/2014	needs a hammer welded
12/18/2013	Please have Ty weld on a hammer in Tub-04. Thank you so very much
9/3/2013	PM SERVICE
7/11/2013	CHANGE HYDRAULIC FILTERS & OIL. WRONG EQUIOMENT.
6/27/2013	Needs bearing replaced on bottom roller of belt, and A C needs fixed. REPLACED ROLLER BEARINGS & CHARGE AC UNIT.
3/29/2013	Weld 2 hammers so that the tips set flat on the surface. Need done asap.
2/7/2013	TAKE BOOM CYLINDER OFF & TOOK TO FIELD TEC TO HAVE IT REBUILT.
1/23/2013	WON'T START. BAD BATTERIES.
1/18/2013	Need hour meter replaced and next service will be 160hrs. REPAIRED WIRES ON HOUR METER. NEXT PM SERVICE WILL BE 1,686 HOURS.
10/12/2012	Please have the exhaust manifold gaskets replaced and also replace the thermostat.
8/16/2012	Please make repairs to the hammers
8/7/2012	Fluid leak on turret, and the radio needs fixed
8/3/2012	PM Service due
4/20/2012	Weld corners on 4 hammmers so that the tips sit flat.
1/20/2012	REPLACE WHEELS ON TUB. REPLACE HYDRAULIC HOSES ON BOOM.
12/14/2011	Floor in tub is lifting again where it was welded the last time.
10/5/2011	Hydraulic leak underneath near the middle somewhere. Replace 2 oil pan bolts.
10/5/2011	PM SERVICE
7/25/2011	CHAIN OFF OF TUB. INSTALL CHAIN FOR TUB. REPAIR FLOOR. REPLACE WEAR PLATES FOR MILL. REPLACE WEAR PLATES FOR TUB.
6/13/2011	Air Conditioning is not working and it is not safe to operate the grinder with the windows open. There has been 1 injury that was close to being very serious. RECHARGED AC. PUT DYE IN SYSTEM.
4/29/2011	Hydraulic line for the tub tilt, coming off the rear valve, the hose blew. Needs relaced asap. See Doug or Andy for exact location.
1/14/2011	PM SERVICE
1/11/2011	Please have Mr. Hyde weld the wear plates on tub-04 down at the shop. Please I need this critical piece welded before thursday afternoon. Thanks Jason
1/11/2011	Please replace the screw auger on tub-04, and switch hydrualic hoses to change direction of the auger. Bill & Vince did other side.
12/21/2010	Boom up hydraulics will not work.
10/7/2010	Rubber vag joint between auger moter and auger needs fixed on right side (looking from the cab). See Doug for details.
6/24/2010	The air conditioning does not work, compressor clutch siezed up and belt broke.
4/26/2010	FIRE DAMAGE

3/29/2010	Upper rim of the tub is cracked and the tub chain guard, both items need welded.
12/8/2009	Fix heater hose, has a leak. See Doug for exact location.
9/23/2009	Need heat applied to get the rods out to replace the hammers.
9/8/2009	Screen cradle needs welded. Hardfacing on mill needs redone. Plate in bottom of tub needs repaired.
8/20/2009	PM SERVICE
8/7/2009	Air conditioning does not work.
5/18/2009	KNOCK IN ENGINE. SENT TO CAT IN MILESBURG FOR REPAIR.
2/2/2009	Auger system not working / turning - reported by Doug on 11/21. WELDSHOP FIXED IT.
1/28/2009	HARDFACE AUGER
12/5/2008	Mount the air compressor from Tub 02 on a portable skid to aid in the support of
9/24/2008	The wear plates and bars need replaced. ASAP. Done by Recycling.
8/8/2008	ANTIFREEZE LEAK. ALSO DID PM SERVICE.