

Detailed services/breakdown

My company
 Monday, June 17, 2019
 23:05

Display criteria

Period : All

Vehicle(s) : Dodge/Charger AWD/2016

Vehicle : 67-75 - Dodge/Charger AWD/2016/MG4074J

Service : Install camera system. (Service)				
Date :	4/18/2016	Technician responsible :	N/D	Cost : \$461.39
Reference :	A033217	Vendor responsible :	West Goshen Automotive	Odometer : 62
Type	Description	Qty.	Unit cost	Total cost
Other	Install camera system.	1.00	\$461.39	\$461.39
<i>Total service :</i>				\$461.39

Service : Upfit vehicle with lighting and equipment from 67-61. Price include removal from 67-61 (Service)				
Date :	4/19/2016	Technician responsible :	N/D	Cost : \$4,890.00
Reference :	IN000103360	Vendor responsible :	Metropolitan Communications	Odometer : 65
Type	Description	Qty.	Unit cost	Total cost
Other	Upfit vehicle with lighting and equipment from 67-61. Price include removal from 67-61	1.00	\$4,890.00	\$4,890.00
<i>Total service :</i>				\$4,890.00

Service : New Lens for lightbar (Service)				
Date :	8/7/2016	Technician responsible :	N/D	Cost : \$82.50
Reference :	IN000103894	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	New Lens for lightbar	1.00	\$82.50	\$82.50

Total service : \$82.50

Service : Purchase and Installation of LED lights for the Push Bumpers (Service)				
Date :	11/19/2016	Technician responsible :	N/D	Cost : \$1,095.00
Reference :	IN000104440	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Purchase and Installation of LED lights for the Push Bumpers	1.00	\$1,095.00	\$1,095.00
<i>Total service :</i>				\$1,095.00

Service : Oil and Filter Change. MAP TMAP replace Sensor (Service)				
Date :	12/17/2016	Technician responsible :	N/D	Cost : \$43.96
Reference :	256232	Vendor responsible :	Videon Dodge	Odometer : 14,297
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, State and Emission Insp. replace sensor	1.00	\$43.96	\$43.96
<i>Total service :</i>				\$43.96

Service : Inspection and Emission oil change (Service)				
Date :	1/16/2017	Technician responsible :	N/D	Cost : \$74.00
Reference :	11824	Vendor responsible :	Thorntons Gulf	Odometer : 15,117
Type	Description	Qty.	Unit cost	Total cost
Other		1.00	\$74.00	\$74.00
Other	Inspection and Emission	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$74.00

Service : Oil and Filter Change, Change and Balance 4 tires, Front end Allignment. (Service)				
Date :	2/20/2017	Technician responsible :	N/D	Cost : \$232.50
Reference :	12238	Vendor responsible :	Thorntons Gulf	Odometer : 23,475
Type	Description	Qty.	Unit cost	Total cost

Other	Oil and Filter Change, Change and Balance 4 tires, Front end Allignmen	1.00	\$232.50	\$232.50
			<i>Total service :</i>	\$232.50

Service : replace front and rear breaks, Resurface Rotors (Service)					
Date :	3/8/2017	Technician responsible :	N/D	Cost :	\$490.00
Reference :	8337	Vendor responsible :	Thorntons Gulf	Odometer :	24,778
Type	Description	Qty.	Unit cost	Total cost	
Other	replace front and rear breaks, Resurface Rotors	1.00	\$490.00	\$490.00	
			<i>Total service :</i>	\$490.00	

Service : Oil and Filter Changes (Service)					
Date :	3/29/2017	Technician responsible :	N/D	Cost :	\$39.50
Reference :	8404	Vendor responsible :	Thorntons Gulf	Odometer :	26,318
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Changes	1.00	\$39.50	\$39.50	
			<i>Total service :</i>	\$39.50	

Service : Front Propeller Shaft Fasteners (Service)					
Date :	4/14/2017	Technician responsible :	N/D	Cost :	\$0.00
Reference :	260801	Vendor responsible :	Videon Dodge	Odometer :	27,805
Type	Description	Qty.	Unit cost	Total cost	
Other	Front Propeller Shaft Fasteners	1.00	\$0.00	\$0.00	
			<i>Total service :</i>	\$0.00	

Service : oil and filter change (Service)					
Date :	6/5/2017	Technician responsible :	N/D	Cost :	\$39.50
Reference :	8554	Vendor responsible :	Thorntons Gulf	Odometer :	31,268
Type	Description	Qty.	Unit cost	Total cost	

Other	oil and filter change	1.00	\$39.50	\$39.50
			<i>Total service :</i>	\$39.50

Service : Replace Camshaft (Service)				
Date :	6/12/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	263710	Vendor responsible :	Videon Dodge	Odometer : 31,484
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Camshaft	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

Service : Reposition and bend the exhaust so as to prevent rubbing. (Service)				
Date :	6/14/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	263906	Vendor responsible :	Videon Dodge	Odometer : 31,548
Type	Description	Qty.	Unit cost	Total cost
Other	Reposition and bend exhaust so as to prevent rubbing.	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

Service : Replace Fuel Pump Module (Service)				
Date :	6/30/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	264658	Vendor responsible :	Videon Dodge	Odometer : 32,255
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Fuel Pump Module	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

Service : Replace the Starter & Replace Left front Window (Service)				
Date :	7/21/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	265663	Vendor responsible :	Videon Dodge	Odometer : 33,058
Type	Description	Qty.	Unit cost	Total cost

Other	Replace the Starter & Replace Left front Window	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

Service : Replace windshield washer nozzle (Service)				
Date :	7/26/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	266068	Vendor responsible :	Videon Dodge	Odometer : 33,210
Type	Description	Qty.	Unit cost	Total cost
Other	replace windshield washer nozzle	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

Service : Replace both AWD shaft Axle's (Service)				
Date :	8/29/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	267668	Vendor responsible :	Videon Dodge	Odometer : 35,346
Type	Description	Qty.	Unit cost	Total cost
Other	Replace both AWD shaft Axle's	1.00	\$0.00	\$0.00
			<i>Total service :</i>	\$0.00

Service : Oil and Filter Change (Service)				
Date :	8/24/2017	Technician responsible :	N/D	Cost : \$39.50
Reference :	7238	Vendor responsible :	Thorntons Gulf	Odometer : 35,332
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
			<i>Total service :</i>	\$39.50

Service : Replace Right Front headlight (Service)				
Date :	9/14/2017	Technician responsible :	N/D	Cost : \$60.00
Reference :	11418	Vendor responsible :	Thorntons Gulf	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost

Other	Replace Right Front headlight	1.00	\$60.00	\$60.00
			<i>Total service :</i>	\$60.00

Service : Oil and Filter Change, Change Mount & balance 2 tires, Front end alignment (Service)				
Date :	10/6/2017	Technician responsible :	N/D	Cost : \$178.50
Reference :	7272	Vendor responsible :	Thorntons Gulf	Odometer : 38,766
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Change Mount & balance 2 tires, Front end alignment	1.00	\$178.50	\$178.50
			<i>Total service :</i>	\$178.50

Service : State and Emission Insp, Oil and Filter Change, replace Passanger Side headlight. (Service)				
Date :	11/20/2017	Technician responsible :	N/D	Cost : \$149.50
Reference :	7062	Vendor responsible :	Thorntons Gulf	Odometer : 42,387
Type	Description	Qty.	Unit cost	Total cost
Other	State and Emission Insp, Oil and Filter Change, replace Passanger Side headlight.	1.00	\$149.50	\$149.50
			<i>Total service :</i>	\$149.50

Service : Oil and filter change (Service)				
Date :	12/29/2017	Technician responsible :	N/D	Cost : \$39.50
Reference :	10882	Vendor responsible :	Thorntons Gulf	Odometer : 45,534
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change	1.00	\$39.50	\$39.50
			<i>Total service :</i>	\$39.50

Service : Oil and Filter Change (Service)				
Date :	2/13/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	13445	Vendor responsible :	Thorntons Gulf	Odometer : 49,503
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Wiper Blades	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : replace headlight bulb (Service)				
Date :	3/13/2018	Technician responsible :	N/D	Cost : \$35.00
Reference :	13302	Vendor responsible :	Thorntons Gulf	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	replace headlight	1.00	\$35.00	\$35.00
<i>Total service :</i>				\$35.00

Service : Replace Wiper Blades (Service)				
Date :	3/21/2018	Technician responsible :	N/D	Cost : \$24.00
Reference :	13331	Vendor responsible :	Thorntons Gulf	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replce Wiper Blades	1.00	\$24.00	\$24.00
<i>Total service :</i>				\$24.00

Service : Oil and Filter Change, Replace the two front and the two rear rotors, and Break Pads (Service)				
Date :	3/22/2018	Technician responsible :	N/D	Cost : \$840.95
Reference :	13333	Vendor responsible :	Thorntons Gulf	Odometer : 52,384
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace the two front and the two rear rotors, and Break Pads	1.00	\$840.95	\$840.95
<i>Total service :</i>				\$840.95

Service :	Oil and Filter Change (Service)			
Date :	5/2/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	13711	Vendor responsible :	Thorntons Gulf	Odometer : 55,584
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service :	Front End Alignment, Change and balance 2 tires (Service)			
Date :	4/12/2018	Technician responsible :	N/D	Cost : \$143.00
Reference :	13617	Vendor responsible :	Thorntons Gulf	Odometer : 54,428
Type	Description	Qty.	Unit cost	Total cost
Other	Front End Alignment, Change and balance 2 tires	1.00	\$143.00	\$143.00
<i>Total service :</i>				\$143.00

Service :	Oil and Filter Change (Service)			
Date :	6/11/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	12802	Vendor responsible :	Thorntons Gulf	Odometer : 59,020
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service :	Change and balance 2 tires (Service)			
Date :	7/9/2018	Technician responsible :	N/D	Cost : \$48.00
Reference :	12859	Vendor responsible :	Thorntons Gulf	Odometer : 61,333
Type	Description	Qty.	Unit cost	Total cost
Other	change and balance 2 tires	1.00	\$48.00	\$48.00
<i>Total service :</i>				\$48.00

Service :	Oil and Filter Change, Replace Air Filter (Service)			
Date :	7/27/2018	Technician responsible :	N/D	Cost : \$62.95
Reference :	13082	Vendor responsible :	Thorntons Gulf	Odometer : 62,849
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Air Filter	1.00	\$62.95	\$62.95
<i>Total service :</i>				\$62.95

Service :	Replace Battery (Service)			
Date :	8/31/2018	Technician responsible :	N/D	Cost : \$220.00
Reference :	13107	Vendor responsible :	Thorntons Gulf	Odometer : 65,203
Type	Description	Qty.	Unit cost	Total cost
Other	replace battery	1.00	\$220.00	\$220.00
<i>Total service :</i>				\$220.00

Service :	Replace the Starter (Service)			
Date :	9/4/2018	Technician responsible :	N/D	Cost : \$412.00
Reference :	13116	Vendor responsible :	Thorntons Gulf	Odometer : 65,709
Type	Description	Qty.	Unit cost	Total cost
Other	Replace the Starter	1.00	\$412.00	\$412.00
<i>Total service :</i>				\$412.00

Service :	Oil and Filter Change (Service)			
Date :	9/11/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	13147	Vendor responsible :	Thorntons Gulf	Odometer : 66,529
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace front left headlight (Service)				
Date : 9/10/2018		Technician responsible : N/D		Cost : \$35.00
Reference : 13145		Vendor responsible : Thorntons Gulf		Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replace front left headlight	1.00	\$35.00	\$35.00
<i>Total service :</i>				\$35.00

Service : State and Emission, Change Mount and balance 2 tires, Front end allignment. (Service)				
Date : 10/3/2018		Technician responsible : N/D		Cost : \$218.00
Reference : 11047		Vendor responsible : Thorntons Gulf		Odometer : 68,312
Type	Description	Qty.	Unit cost	Total cost
Other	State and Emission, Change Mount and balance 2 tires, Front end allignment.	1.00	\$218.00	\$218.00
<i>Total service :</i>				\$218.00

Service : Oil and Filter Change (Service)				
Date : 10/23/2018		Technician responsible : N/D		Cost : \$44.95
Reference : 12034		Vendor responsible : Thorntons Gulf		Odometer : 70,260
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Oil and Filter Change (Service)				
Date : 12/7/2018		Technician responsible : N/D		Cost : \$44.95
Reference : 7483		Vendor responsible : Thorntons Gulf		Odometer : 73,358
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service :	Oil and Filter Change, Replace Front Left Headlight (Service)				
Date :	1/17/2019	Technician responsible :	N/D	Cost :	\$79.95
Reference :	7548	Vendor responsible :	Thorntons Gulf	Odometer :	76,436
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change, Replace Front Left Headlight	1.00	\$79.95	\$79.95	
				<i>Total service :</i>	\$79.95

Service :	Oil and Filter Change (Service)				
Date :	2/26/2019	Technician responsible :	N/D	Cost :	\$44.95
Reference :	14558	Vendor responsible :	Thorntons Gulf	Odometer :	79,851
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

Service :	Replace Front Brakes and Rotors, Replace Radiator and fill with Antifreeze, Mount and Balance 4 tires, Front End Allignment (Service)				
Date :	3/8/2019	Technician responsible :	N/D	Cost :	\$1,160.00
Reference :	14451	Vendor responsible :	Thorntons Gulf	Odometer :	80,816
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Front Brakes and Rotors, Replace Radiator and fill with Antifreeze, Mount and Balance 4 tires, Front End Allignment	1.00	\$1,160.00	\$1,160.00	
				<i>Total service :</i>	\$1,160.00

Service :	Oil and Filter Change (Service)				
Date :	4/8/2019	Technician responsible :	N/D	Cost :	\$44.95
Reference :	14623	Vendor responsible :	Thorntons Gulf	Odometer :	83,620
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	

Total service : \$44.95

Total of the vehicle : \$11,553.80