

Detailed services/breakdown

My company
 Wednesday, June 19, 2019
 05:21

Display criteria

Period : All

Vehicle(s) : Dodge/Charger/2012

Vehicle : 67-62 - Dodge/Charger/2012/GMP-9163

Service : Transfer and installation of new equipment from 67-52. Also included strip of car 67-30 (Service)				
Date :	7/5/2012	Technician responsible :	N/D	Cost : \$7,235.80
Reference :	IN000095344	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	new vehicle equipment and installation	1.00	\$7,235.80	\$7,235.80
<i>Total service :</i>				\$7,235.80

Service : Install camera system and auxiliary battery, misc. parts. (Service)				
Date :	6/28/2012	Technician responsible :	N/D	Cost : \$1,068.85
Reference :	A021597	Vendor responsible :	West Goshen Automotive	Odometer : 138
Type	Description	Qty.	Unit cost	Total cost
Other	Install auxiliary battery and camera system, misc. parts	1.00	\$1,068.85	\$1,068.85
<i>Total service :</i>				\$1,068.85

Service : Lube, oil, and filter. (Service)				
Date :	8/15/2012	Technician responsible :	N/D	Cost : \$35.50
Reference :	45963	Vendor responsible :	Thorntons Gulf	Odometer : 3,100
Type	Description	Qty.	Unit cost	Total cost
Other	LOF	1.00	\$35.50	\$35.50
<i>Total service :</i>				\$35.50

Service :	Lube, oil, and filter. (Service)					
Date :	9/25/2012	Technician responsible :	N/D	Cost :	\$35.50	
Reference :	45976	Vendor responsible :	Thorntons Gulf	Odometer :	6,234	
Type	Description			Qty.	Unit cost	Total cost
Other	LOF			1.00	\$35.50	\$35.50
					<i>Total service :</i>	\$35.50

Service :	Changed oil. (Service)					
Date :	11/8/2012	Technician responsible :	N/D	Cost :	\$35.50	
Reference :	45996	Vendor responsible :	Thorntons Gulf	Odometer :	10,128	
Type	Description			Qty.	Unit cost	Total cost
Other	Changed oil			1.00	\$35.50	\$35.50
					<i>Total service :</i>	\$35.50

Service :	Front brakes and rotors. (Service)					
Date :	11/26/2012	Technician responsible :	N/D	Cost :	\$290.00	
Reference :	45868	Vendor responsible :	Thorntons Gulf	Odometer :	11,304	
Type	Description			Qty.	Unit cost	Total cost
Other	front brakes and rotors.			1.00	\$290.00	\$290.00
					<i>Total service :</i>	\$290.00

Service :	Oil change. (Service)					
Date :	12/31/2012	Technician responsible :	N/D	Cost :	\$35.50	
Reference :	45882	Vendor responsible :	Thorntons Gulf	Odometer :	14,227	
Type	Description			Qty.	Unit cost	Total cost
Other	Oil change.			1.00	\$35.50	\$35.50
					<i>Total service :</i>	\$35.50

Service :	Oil change. (Service)					
Date :	1/30/2013	Technician responsible :	N/D	Cost :	\$35.50	
Reference :	45897	Vendor responsible :	Thorntons Gulf	Odometer :	17,711	
Type	Description			Qty.	Unit cost	Total cost
Other	Oil change.			1.00	\$35.50	\$35.50
					<i>Total service :</i>	\$35.50

Service :	Removed in- car camera system. (Service)					
Date :	3/29/2013	Technician responsible :	N/D	Cost :	\$138.90	
Reference :	A023736	Vendor responsible :	West Goshen Automotive	Odometer :	21,031	
Type	Description			Qty.	Unit cost	Total cost
Other	Removed in-car camera system.			1.00	\$138.90	\$138.90
					<i>Total service :</i>	\$138.90

Service :	Changed oil. (Service)					
Date :	3/28/2013	Technician responsible :	N/D	Cost :	\$35.50	
Reference :	45746	Vendor responsible :	Thorntons Gulf	Odometer :	21,005	
Type	Description			Qty.	Unit cost	Total cost
Other	Changed oil.			1.00	\$35.50	\$35.50
					<i>Total service :</i>	\$35.50

Service :	Alignment and replaced 2 tension struts. (Service)					
Date :	4/25/2013	Technician responsible :	N/D	Cost :	\$79.95	
Reference :	190844	Vendor responsible :	Videon Dodge	Odometer :	21,946	
Type	Description			Qty.	Unit cost	Total cost
Other	Alignment and replaced 2 tension struts.			1.00	\$79.95	\$79.95
					<i>Total service :</i>	\$79.95

Service :	Mount, balance, and dispose of 4 tires. (Service)			Cost :	\$88.00
Date :	4/22/2013	Technician responsible :	N/D	Odometer :	21,858
Reference :	45760	Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Mount balance and dispose of 4 tires.	1.00	\$88.00	\$88.00	
				<i>Total service :</i>	\$88.00

Service :	Changed oil. (Service)			Cost :	\$35.50
Date :	7/30/2013	Technician responsible :	N/D	Odometer :	23,730
Reference :	45804	Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Changed oil.	1.00	\$35.50	\$35.50	
				<i>Total service :</i>	\$35.50

Service :	Replaced AC vent. (Service)			Cost :	
Date :	9/9/2013	Technician responsible :	N/D	Odometer :	24,557
Reference :	196648	Vendor responsible :	Videon Dodge		
Type	Description	Qty.	Unit cost	Total cost	
				<i>Total service :</i>	\$0.00

Service :	Changed oil and filter. (Service)			Cost :	\$35.50
Date :	12/11/2013	Technician responsible :	N/D	Odometer :	26,809
Reference :	45843	Vendor responsible :	Thorntons Gulf		
Type	Description	Qty.	Unit cost	Total cost	
Other	Changed oil and filter.	1.00	\$35.50	\$35.50	
				<i>Total service :</i>	\$35.50

Service : Repaired antenna issue. (Service)				
Date :	12/11/2013	Technician responsible :	N/D	Cost : \$75.00
Reference :	IN000098849	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Repaired antenna issue.	1.00	\$75.00	\$75.00
<i>Total service :</i>				\$75.00

Service : Inspection and emissions, changed oil, front and rear brakes and rotors. (Service)				
Date :	4/10/2014	Technician responsible :	N/D	Cost : \$673.50
Reference :	45660	Vendor responsible :	Thorntons Gulf	Odometer : 29,562
Type	Description	Qty.	Unit cost	Total cost
Other	Inspection and emissions, changed oil, front and rear brakes and rotors.	1.00	\$673.50	\$673.50
<i>Total service :</i>				\$673.50

Service : Changed oil and filter. Rotate tires. (Service)				
Date :	9/2/2014	Technician responsible :	N/D	Cost : \$55.50
Reference :	45521	Vendor responsible :	Thorntons Gulf	Odometer : 32,702
Type	Description	Qty.	Unit cost	Total cost
Other	Changed oil and filter. Rotate tires.	1.00	\$55.50	\$55.50
<i>Total service :</i>				\$55.50

Service : State inspection & emissions test. Oil and filter change. (Service)				
Date :	2/11/2015	Technician responsible :	N/D	Cost : \$39.95
Reference :	45536	Vendor responsible :	Thorntons Gulf	Odometer : 35,775
Type	Description	Qty.	Unit cost	Total cost
Other	State inspection & emissions test. Oil and filter change.	1.00	\$39.95	\$39.95
<i>Total service :</i>				\$39.95

Service : Replace wiper blades (Service)				
Date :	4/27/2015	Technician responsible :	N/D	Cost : \$26.00
Reference :	45567	Vendor responsible :	Thorntons Gulf	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replace wiper blades	1.00	\$26.00	\$26.00
<i>Total service :</i>				\$26.00

Service : Oil and filter change. (Service)				
Date :	9/2/2015	Technician responsible :	N/D	Cost : \$39.50
Reference :	45613	Vendor responsible :	Thorntons Gulf	Odometer : 38,670
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change.	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Performed R35 safety recall. Occupant restraint control module. (Service)				
Date :	11/12/2015	Technician responsible :	N/D	Cost : \$0.00
Reference :	234632	Vendor responsible :	Videon Dodge	Odometer : 39,634
Type	Description	Qty.	Unit cost	Total cost
Other	Performed R35 safety recall. Occupant restraint control module.	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Change 4 tires and balance. (Service)				
Date :	1/15/2016	Technician responsible :	N/D	Cost : \$96.00
Reference :	45027	Vendor responsible :	Thorntons Gulf	Odometer : 40,602
Type	Description	Qty.	Unit cost	Total cost
Other	Change 4 tires and balance.	1.00	\$96.00	\$96.00
<i>Total service :</i>				\$96.00

Service :	Oil and filter change. State inspection & emission test. (Service)			
Date :	2/22/2016	Technician responsible :	N/D	Cost : \$113.50
Reference :	45041	Vendor responsible :	Thorntons Gulf	Odometer : 41,683
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change. State inspection & emission test.	1.00	\$113.50	\$113.50
<i>Total service :</i>				\$113.50

Service :	oil and filter change (Service)			
Date :	10/21/2016	Technician responsible :	N/D	Cost : \$39.50
Reference :	11086	Vendor responsible :	Thorntons Gulf	Odometer : 47,935
Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service :	Oil and Filter Change (Service)			
Date :	9/1/2017	Technician responsible :	N/D	Cost : \$39.50
Reference :	8171	Vendor responsible :	Thorntons Gulf	Odometer : 55,081
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service :	replace driver side visor clip (Service)			
Date :	9/1/2017	Technician responsible :	N/D	Cost : \$17.38
Reference :	58413	Vendor responsible :	Videon Dodge	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	replace driver side visor clip	1.00	\$17.38	\$17.38
<i>Total service :</i>				\$17.38

Service : Replace Radiator and Antifreeze (Service)					
Date :	11/8/2017	Technician responsible :	N/D	Cost :	\$464.00
Reference :	10809	Vendor responsible :	Thorntons Gulf	Odometer :	57,114
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Radiator and Antifreeze	1.00	\$464.00	\$464.00	
				<i>Total service :</i>	\$464.00

Service : Oil and Filter Change (Service)					
Date :	1/10/2018	Technician responsible :	N/D	Cost :	\$39.50
Reference :	10942	Vendor responsible :	Thorntons Gulf	Odometer :	58,569
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter Change	1.00	\$39.50	\$39.50	
				<i>Total service :</i>	\$39.50

Service : Emission and State Insp.Front and Rear Brakes, Front and Rear Rotors, Oil and Filter Change, Replace 2 strut arms, Front end Alignment (Service)					
Date :	4/25/2018	Technician responsible :	N/D	Cost :	\$1,385.95
Reference :	13674	Vendor responsible :	Thorntons Gulf	Odometer :	62,197
Type	Description	Qty.	Unit cost	Total cost	
Other	Emission and State Insp.Front and Rear Brakes, Front and Rear Rotors, Oil and Filter Change, Replace 2 strut arms, Front end Alignment	1.00	\$1,385.95	\$1,385.95	
				<i>Total service :</i>	\$1,385.95

Service : Repair AC Compressor and wiring to the connector, Oil and Filter Change, (Service)					
Date :	7/30/2018	Technician responsible :	N/D	Cost :	\$529.77
Reference :	CHCS13478	Vendor responsible :	Videon Dodge	Odometer :	65,063
Type	Description	Qty.	Unit cost	Total cost	
Other	Repair AC Compressor and wiring to the connector, Oil and Filter Change,	1.00	\$529.77	\$529.77	
				<i>Total service :</i>	\$529.77

Service : Replace Passenger Side Windshield Washer Nozzle (Service)				
Date :	11/14/2018	Technician responsible :	N/D	Cost : \$29.68
Reference :	16222 CHR	Vendor responsible :	Videon Dodge	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Passenger Side Windshield Washer Nozzle	1.00	\$29.68	\$29.68
<i>Total service :</i>				\$29.68

Service : Replace Driver Side Windshield Washer Nozzle (Service)				
Date :	11/14/2018	Technician responsible :	N/D	Cost : \$29.68
Reference :	16219 CHR	Vendor responsible :	Videon Dodge	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Driver Side Windshield Washer Nozzle	1.00	\$29.68	\$29.68
<i>Total service :</i>				\$29.68

Service : Oil and Filter Change (Service)				
Date :	1/25/2019	Technician responsible :	N/D	Cost : \$44.95
Reference :	10981	Vendor responsible :	Thorntons Gulf	Odometer : 71,180
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Emission and State inspection, Oil and Filter Change (Service)				
Date :	4/18/2019	Technician responsible :	N/D	Cost : \$119.95
Reference :	14685	Vendor responsible :	Thorntons Gulf	Odometer : 74,029
Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State inspection, Oil and Filter Change	1.00	\$119.95	\$119.95
<i>Total service :</i>				\$119.95

Total of the vehicle :

\$13,044.31