

2002

# Chevrolet Tahoe



VIN: 1GNEK13V62J216291

Recall data refreshed on Jan 13,2020

## **1 Unrepaired Recalls** associated with this VIN

Aug 29,2005

**Manufacturer Recall Number** N050068

**NHTSA Recall Number** 05V379

**Recall Status** Recall Incomplete

### Summary

Certain pickup trucks and sport utility vehicles may experience unwanted antilock brake system (ABS) activation. This condition is more likely to occur in environmentally corrosive areas. This recall will be launched in the "salt belt" states of Connecticut, Delaware, Illinois, Indiana, Iowa,

Maryland, Massachusetts, Maine, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, Wisconsin and the District of Columbia only.

### **Safety Risk**

This can cause increased stopping distances during low-speed brake applications, which could result in a crash.

### **Remedy**

Dealers will remove the wheel speed sensor and thoroughly clean the wheel speed sensor mounting surface on the bearing, apply rust inhibitor to the cleaned surface, grease the mounting surface, reinstall the wheel speed sensor, and check the peak-to-peak output voltage to ensure the wheel speed signal is within specifications free of charge.

### **Manufacturer's Notes**

Visit manufacturer website at <https://my.gm.com/recalls> for more information.

**If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner,**

please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an online complaint with NHTSA.