

Detailed services/breakdown

Display criteria

Period : All

Vehicle(s) : Dodge/Charger/2016

Vehicle : 67-76 - Dodge/Charger/2016/MG4076J

Service : Install lights and equipment from 67-60. (Service)				
Date : 6/10/2016	Technician responsible : N/D	Cost :		\$4,760.00
Reference : IN000103612	Vendor responsible : Metropolitan Communications	Odometer :		0
Type	Description	Qty.	Unit cost	Total cost
Other	Install lights and equipment from 67-60.	1.00	\$4,760.00	\$4,760.00
<i>Total service :</i>				\$4,760.00

Service : Install camera system. (Service)				
Date : 6/21/2016	Technician responsible : N/D	Cost :		\$461.39
Reference : A033784	Vendor responsible : West Goshen Automotive	Odometer :		63
Type	Description	Qty.	Unit cost	Total cost
Other	Install camera system.	1.00	\$461.39	\$461.39
<i>Total service :</i>				\$461.39

Service : Oil and Filter Change (Service)				
Date : 8/9/2016	Technician responsible : N/D	Cost :		\$39.50
Reference : 11548	Vendor responsible : Thorntons Gulf	Odometer :		3,719
Type	Description	Qty.	Unit cost	Total cost
Other		1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service :	Wheel Alignment (Service)			
Date :	9/15/2016	Technician responsible :	N/D	Cost : \$137.75
Reference :	250123	Vendor responsible :	Videon Dodge	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other		1.00	\$137.75	\$137.75
<i>Total service :</i>				\$137.75

Service :	New Lens for lightbar (Service)			
Date :	8/7/2016	Technician responsible :	N/D	Cost : \$82.50
Reference :	IN000103894	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	New Lens for lightbar	1.00	\$82.50	\$82.50
<i>Total service :</i>				\$82.50

Service :	oil and filter change (Service)			
Date :	10/4/2016	Technician responsible :	N/D	Cost : \$39.50
Reference :	11707	Vendor responsible :	Thorntons Gulf	Odometer : 7,621
Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service :	Oil and filter change (Service)			
Date :	10/21/2016	Technician responsible :	N/D	Cost : \$39.50
Reference :	11079	Vendor responsible :	Thorntons Gulf	Odometer : 13,720
Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Oil and filter change (Service)				
Date : 11/5/2016		Technician responsible : N/D		Cost : \$39.50
Reference : 11152		Vendor responsible : Thorntons Gulf		Odometer : 16,470
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Purchase and Installation of LED lights for the Push Bumpers (Service)				
Date : 11/19/2016		Technician responsible : N/D		Cost : \$1,095.00
Reference : IN000104437		Vendor responsible : Metropolitan Communications		Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Purchase and Install LED lights for the Push Bumpers	1.00	\$1,095.00	\$1,095.00
<i>Total service :</i>				\$1,095.00

Service : Oil and Filter Change (Service)				
Date : 12/5/2016		Technician responsible : N/D		Cost : \$113.50
Reference : 11218		Vendor responsible : Thorntons Gulf		Odometer : 16,564
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, insp and emission	1.00	\$113.50	\$113.50
<i>Total service :</i>				\$113.50

Service : Mount and Balance 4 tires (Service)				
Date : 1/6/2017		Technician responsible : N/D		Cost : \$88.00
Reference : 11782		Vendor responsible : Thorntons Gulf		Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other		1.00	\$88.00	\$88.00
Other	Mount and Balance 4 tires	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$88.00

Service : Replace Canister Vapor (Service)				
Date :	2/8/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	257297	Vendor responsible :	Videon Dodge	Odometer : 16,822
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Canister Vapor	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Oil and Filter Change (Service)				
Date :	3/22/2017	Technician responsible :	N/D	Cost : \$39.50
Reference :	8375	Vendor responsible :	Thorntons Gulf	Odometer : 19,070
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Reprogram Power Module (Check Engine light) Replace Front Propeller Shaft Bolts (Service)				
Date :	4/10/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	260534	Vendor responsible :	Videon Dodge	Odometer : 20,070
Type	Description	Qty.	Unit cost	Total cost
Other	Reprogram Power Module (Check Engine light) Replace Front Propeller Shaft Bolts	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Replace Valve/Solenoid (Service)				
Date :	5/24/2017	Technician responsible :	N/D	Cost : \$0.00
Reference :	262711	Vendor responsible :	Videon Dodge	Odometer : 22,757
Type	Description	Qty.	Unit cost	Total cost
Other	Replace valve/solenoid	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : oil and filter change (Service)					
Date :	5/18/2017	Technician responsible :	N/D	Cost :	\$39.50
Reference :	7353	Vendor responsible :	Thorntons Gulf	Odometer :	22,616
Type	Description	Qty.	Unit cost	Total cost	
Other	oil and filter change	1.00	\$39.50	\$39.50	
				<i>Total service :</i>	\$39.50

Service : Replace Hood Latch (Service)					
Date :	6/30/2017	Technician responsible :	N/D	Cost :	\$0.00
Reference :	264805	Vendor responsible :	Videon Dodge	Odometer :	25,832
Type	Description	Qty.	Unit cost	Total cost	
Other	Replace Hood Latch	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

Service : Oil and Filter change (Service)					
Date :	7/12/2017	Technician responsible :	N/D	Cost :	\$39.50
Reference :	11309	Vendor responsible :	Thorntons Gulf	Odometer :	26,712
Type	Description	Qty.	Unit cost	Total cost	
Other	Oil and Filter change	1.00	\$39.50	\$39.50	
				<i>Total service :</i>	\$39.50

Service : replace starter (Service)					
Date :	8/29/2017	Technician responsible :	N/D	Cost :	\$377.00
Reference :	8156	Vendor responsible :	Thorntons Gulf	Odometer :	29,216
Type	Description	Qty.	Unit cost	Total cost	
Other	replace starter	1.00	\$377.00	\$377.00	
				<i>Total service :</i>	\$377.00

Service : Replace Driver side headlight, Replace vehicle Battery (Service)				
Date : 8/24/2017		Technician responsible : N/D		Cost : \$255.00
Reference : 7237		Vendor responsible : Thorntons Gulf		Odometer : 28,937
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Driver side headlight, Replace vehicle Battery	1.00	\$255.00	\$255.00
<i>Total service :</i>				\$255.00

Service : Oil and Filter Change (Service)				
Date : 9/8/2017		Technician responsible : N/D		Cost : \$39.50
Reference : 8196		Vendor responsible : Thorntons Gulf		Odometer : 29,793
Type	Description	Qty.	Unit cost	Total cost
Other	oil and filter change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

Service : Front end alignment, Change and balance 2 tires (Service)				
Date : 9/5/2017		Technician responsible : N/D		Cost : \$137.00
Reference : 8181		Vendor responsible : Thorntons Gulf		Odometer : 29,536
Type	Description	Qty.	Unit cost	Total cost
Other	Front end alignment, Change and balance 2 tires	1.00	\$137.00	\$137.00
<i>Total service :</i>				\$137.00

Service : Replace Cam Shaft (Service)				
Date : 9/27/2017		Technician responsible : N/D		Cost : \$0.00
Reference : 269458		Vendor responsible : Videon Dodge		Odometer : 30,879
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Cam Shaft	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Replace front and rear brakes, Resurface front and rear rotars (Service)				
Date : 9/25/2017		Technician responsible : N/D		Cost : \$470.00
Reference : 107654		Vendor responsible : Thorntons Gulf		Odometer : 30,844
Type	Description	Qty.	Unit cost	Total cost
Other	Replace front and rear brakes, Resurface front and rear rotars	1.00	\$470.00	\$470.00
<i>Total service :</i>				\$470.00

Service : replace front right head light (Service)				
Date : 10/6/2017		Technician responsible : N/D		Cost : \$60.00
Reference : 7269		Vendor responsible : Thorntons Gulf		Odometer : 31,198
Type	Description	Qty.	Unit cost	Total cost
Other	Replace front right head light	1.00	\$60.00	\$60.00
<i>Total service :</i>				\$60.00

Service : Oil and filter change, State Insp. and emission (Service)				
Date : 1/9/2018		Technician responsible : N/D		Cost : \$114.50
Reference : 10937		Vendor responsible : Thorntons Gulf		Odometer : 36,317
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change, State Insp. and emission	1.00	\$114.50	\$114.50
<i>Total service :</i>				\$114.50

Service : Oil and Filter Change (Service)				
Date : 3/12/2018		Technician responsible : N/D		Cost : \$44.95
Reference : 13295		Vendor responsible : Thorntons Gulf		Odometer : 40,001
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace Front Left Headlight (Service)				
Date :	4/18/2018	Technician responsible :	N/D	Cost : \$35.00
Reference :	13636	Vendor responsible :	Thorntons Gulf	Odometer : 41,764
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Front Left Headlight	1.00	\$35.00	\$35.00
<i>Total service :</i>				\$35.00

Service : Change Mount and Balance 2 tires (Service)				
Date :	5/8/2018	Technician responsible :	N/D	Cost : \$54.00
Reference :	13730	Vendor responsible :	Thorntons Gulf	Odometer : 42,545
Type	Description	Qty.	Unit cost	Total cost
Other	Change Mount and Balance 2 tires	1.00	\$54.00	\$54.00
<i>Total service :</i>				\$54.00

Service : Oil and Filter Change (Service)				
Date :	6/11/2018	Technician responsible :	N/D	Cost : \$44.95
Reference :	12801	Vendor responsible :	Thorntons Gulf	Odometer : 43,765
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace Grille, Fascia, and under Panel, Replace Lower Support, Paint and Materials, Refinish, Bezel Fog (Service)				
Date :	8/3/2018	Technician responsible :	N/D	Cost : \$1,773.45
Reference :	CHCB13295	Vendor responsible :	Videon Dodge	Odometer : 45,665
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Grille, Fascia, and under Panel, Replace Lower Support, Paint and Materials, Refinish, Bezel Fog	1.00	\$1,773.45	\$1,773.45
<i>Total service :</i>				\$1,773.45

Service : Replace Right side fuel pump (Service)				
Date : 8/31/2018		Technician responsible : N/D		Cost : \$0.00
Reference : CHCS15598		Vendor responsible : Videon Dodge		Odometer : 46,222
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Right side fuel pump	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Oil and Filter Change (Service)				
Date : 8/31/2018		Technician responsible : N/D		Cost : \$44.95
Reference : 13108		Vendor responsible : Thorntons Gulf		Odometer : 46,224
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Remove and replace push bumper (Service)				
Date : 8/27/2018		Technician responsible : N/D		Cost : \$875.00
Reference : IN000107862		Vendor responsible : Metropolitan Communications		Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Remove and replace push bumper	1.00	\$875.00	\$875.00
<i>Total service :</i>				\$875.00

Service : Oil and Filter Change (Service)				
Date : 11/7/2018		Technician responsible : N/D		Cost : \$44.95
Reference : 7687		Vendor responsible : Thorntons Gulf		Odometer : 49,473
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service :	Mount and balance 4 tires (Service)			
Date :	11/20/2018	Technician responsible :	N/D	Cost : \$96.00
Reference :	7744	Vendor responsible :	Thorntons Gulf	Odometer : 50,425
Type	Description	Qty.	Unit cost	Total cost
Other	Mount and balance 4 tires	1.00	\$96.00	\$96.00
<i>Total service :</i>				\$96.00

Service :	Replace Radio (Service)			
Date :	12/5/2018	Technician responsible :	N/D	Cost : \$420.00
Reference :	CHCS20648	Vendor responsible :	Videon Dodge	Odometer : 51,090
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Radio	1.00	\$420.00	\$420.00
<i>Total service :</i>				\$420.00

Service :	Replace Battery (Service)			
Date :	1/3/2019	Technician responsible :	N/D	Cost : \$220.00
Reference :	8690	Vendor responsible :	Thorntons Gulf	Odometer : 52,275
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	\$220.00	\$220.00
<i>Total service :</i>				\$220.00

Service :	Emission and State Inspection, Front and Rear Brakes, Front and Rear Rotors, Replace Upper Ball Joints, Front End Alignment (Service)			
Date :	1/29/2019	Technician responsible :	N/D	Cost : \$1,483.00
Reference :	14403	Vendor responsible :	Thorntons Gulf	Odometer : 53,836
Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection, Front and Rear Brakes, Front and Rear Rotors, Replace Upper Ball Joints, Front End Alignment	1.00	\$1,483.00	\$1,483.00

Total service : \$1,483.00

Service : Oil and Filter Change (Service)				
Date :	1/24/2019	Technician responsible :	N/D	Cost : \$44.95
Reference :	10978	Vendor responsible :	Thorntons Gulf	Odometer : 53,070
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace Headlight (Service)				
Date :	2/13/2019	Technician responsible :	N/D	Cost : \$35.00
Reference :	8713	Vendor responsible :	Thorntons Gulf	Odometer : 54,407
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Headlight	1.00	\$35.00	\$35.00
<i>Total service :</i>				\$35.00

Service : Replace and paint driver side fender. (Service)				
Date :	3/15/2019	Technician responsible :	N/D	Cost : \$1,470.40
Reference :	CHCB25648	Vendor responsible :	Videon Dodge	Odometer : 56,019
Type	Description	Qty.	Unit cost	Total cost
Other	Replace and paint driver side fender.	1.00	\$1,470.40	\$1,470.40
<i>Total service :</i>				\$1,470.40

Service : Front end Alignment, Oil and Filter Change (Service)				
Date :	3/25/2019	Technician responsible :	N/D	Cost : \$139.95
Reference :	14518	Vendor responsible :	Thorntons Gulf	Odometer : 56,054
Type	Description	Qty.	Unit cost	Total cost
Other	Front end Alignment, Oil and Filter Change	1.00	\$139.95	\$139.95

Total service : \$139.95

Service : Replace Water Pump and Coolant (Service)				
Date :	5/2/2019	Technician responsible :	N/D	Cost : \$401.00
Reference :	14712	Vendor responsible :	Thorntons Gulf	Odometer : 58,453
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Water Pump and Coolant	1.00	\$401.00	\$401.00
<i>Total service :</i>				\$401.00

Service : Oil and Filter Change (Service)				
Date :	5/16/2019	Technician responsible :	N/D	Cost : \$44.95
Reference :	14967	Vendor responsible :	Thorntons Gulf	Odometer : 59,465
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Windshield Wipers, Healiight, air filter (Service)				
Date :	7/8/2019	Technician responsible :	N/D	Cost : \$71.00
Reference :	14171	Vendor responsible :	Thorntons Gulf	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Windshield Wipers, Healiight, air filter	1.00	\$71.00	\$71.00
<i>Total service :</i>				\$71.00

Service : Oil and Filter Change (Service)				
Date :	7/29/2019	Technician responsible :	N/D	Cost : \$44.95
Reference :	14220	Vendor responsible :	Thorntons Gulf	Odometer : 62,384
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95

Total service :

\$44.95

Service : Replace Right Bank Catalyst (Covered under warranty) replaced Right Bank Oxygen Sensor (Not Covered) (Service)				
Date :	8/20/2019	Technician responsible :	N/D	Cost : \$166.40
Reference :	CHCS33687	Vendor responsible :	Videon Dodge	Odometer : 62,727
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Right Bank Catalyst (Covered under warranty) replaced Right Bank Oxygen Sensor (Not Covered)	1.00	\$166.40	\$166.40
<i>Total service :</i>				\$166.40

Service : Replce Battery, Replace Trans fluid and Filter, Replace Trans Oil Pan Gasket (Service)				
Date :	7/22/2019	Technician responsible :	N/D	Cost : \$600.22
Reference :	CHCS32849	Vendor responsible :	Videon Dodge	Odometer : 62,250
Type	Description	Qty.	Unit cost	Total cost
Other	Replce Battery, Replace Trans fluid and Filter, Replace Trans Oil Pan Gasket	1.00	\$600.22	\$600.22
<i>Total service :</i>				\$600.22

Service : Replace all 16 Spark Plugs (Service)				
Date :	10/4/2019	Technician responsible :	N/D	Cost : \$584.63
Reference :	CHCS36363	Vendor responsible :	Videon Dodge	Odometer : 64,085
Type	Description	Qty.	Unit cost	Total cost
Other	Replace all 16 Spark Plugs	1.00	\$584.63	\$584.63
<i>Total service :</i>				\$584.63

Service : Oil and Filter Change (Service)				
Date :	10/28/2019	Technician responsible :	N/D	Cost : \$44.95
Reference :	15085	Vendor responsible :	Thorntons Gulf	Odometer : 65,686
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replaced Left Bank Catalytic Converter (Service)				
Date :	11/11/2019	Technician responsible :	N/D	Cost : \$0.00
Reference :	CHCS38779	Vendor responsible :	Videon Dodge	Odometer : 66,232
Type	Description	Qty.	Unit cost	Total cost
Other	Replaced Left Bank Catalytic Converter	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

Service : Mount and Balance 2 Tires (Service)				
Date :	12/9/2019	Technician responsible :	N/D	Cost : \$50.00
Reference :	15248	Vendor responsible :	Thorntons Gulf	Odometer : 67,223
Type	Description	Qty.	Unit cost	Total cost
Other	Mount and Balance 2 Tires	1.00	\$50.00	\$50.00
<i>Total service :</i>				\$50.00

Service : State Inspection and Emission, Oil Change (Service)				
Date :	1/10/2020	Technician responsible :	N/D	Cost : \$120.95
Reference :	14884	Vendor responsible :	Thorntons Gulf	Odometer : 69,227
Type	Description	Qty.	Unit cost	Total cost
Other	State Inspection and Emission, Oil Change	1.00	\$120.95	\$120.95
<i>Total service :</i>				\$120.95

Service : Replace Overflow Bottle (Service)				
Date :	2/20/2020	Technician responsible :	N/D	Cost : \$143.00
Reference :	16118	Vendor responsible :	Thorntons Gulf	Odometer : 71,277
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Overflow Bottle	1.00	\$143.00	\$143.00
<i>Total service :</i>				\$143.00

Service : Replace Radiator, Fan Blades, 2 Fan Motors, Anti Freeze. (Service)				
Date :	2/17/2020	Technician responsible :	N/D	Cost : \$1,249.00
Reference :	16111	Vendor responsible :	Thorntons Gulf	Odometer : 71,223
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Radiator, Fan Blades, 2 Fan Motors, Anti Freeze.	1.00	\$1,249.00	\$1,249.00
<i>Total service :</i>				\$1,249.00

Service : Oil and Filter Change (Service)				
Date :	4/24/2020	Technician responsible :	N/D	Cost : \$44.95
Reference :	16199	Vendor responsible :	Thorntons Gulf	Odometer : 73,625
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

Service : Replace Heater Hoses and Antifreeze (Service)				
Date :	5/11/2020	Technician responsible :	N/D	Cost : \$365.00
Reference :	15949	Vendor responsible :	Thorntons Gulf	Odometer : 74,248
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Heater Hoses and Antifreeze	1.00	\$365.00	\$365.00
<i>Total service :</i>				\$365.00

Service :	Testing for Stalling issue. Diagnosed with Liquid Fuel in the EVAP System (Service)				
Date :	3/10/2020	Technician responsible :	N/D	Cost :	\$130.00
Reference :	CHCS44260	Vendor responsible :	Videon Dodge	Odometer :	71,806
Type	Description	Qty.	Unit cost	Total cost	
Other	Testing for Stalling issue. Diagnosed with Liquid Fuel in the EVAP System	1.00	\$130.00	\$130.00	
				<i>Total service :</i>	\$130.00
				<i>Total of the vehicle :</i>	\$19,355.19