

# Detailed services/breakdown

My company  
 Wednesday, July 28, 2021  
 07:51

Display criteria

Period : All

Vehicle(s) : Dodge /Charger/2016

**Vehicle : 67-80 - Dodge /Charger/2016/MG7370J**

<b>Service :</b> Install graphics and Police Logo's (Service )				
<b>Date :</b> 3/3/2017		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$1,108.00
<b>Reference :</b> 5896		<b>Vendor responsible :</b> Lucky Sign Shop		<b>Odometer :</b> 0
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Install graphics and Logos	1.00	\$1,108.00	\$1,108.00
<i>Total service :</i>				\$1,108.00

<b>Service :</b> Oil and Filter Changes (Service )				
<b>Date :</b> 3/27/2017		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$39.50
<b>Reference :</b> 8387		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 3,541
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Changes	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

<b>Service :</b> Oil and filter change (Service )				
<b>Date :</b> 4/28/2017		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$39.50
<b>Reference :</b> 8484		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 6,490
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and filter change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

<b>Service :</b>	oil and filter change (Service )			
<b>Date :</b>	6/6/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$43.40
<b>Reference :</b>	263456	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 9,865
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	oil and filter change	1.00	\$43.40	\$43.40
<i>Total service :</i>				\$43.40

<b>Service :</b>	Repair rear end body damage from two minor collisions." Fascia-Rear Upper", "Lamp- side marker", "Fascia support Bracket", Paint and finish (Service )			
<b>Date :</b>	6/6/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$1,957.86
<b>Reference :</b>	263056	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 9,865
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Repair rear end body damage from two minor collisions	1.00	\$1,957.86	\$1,957.86
<i>Total service :</i>				\$1,957.86

<b>Service :</b>	Replace Ignition Coil (Service )			
<b>Date :</b>	7/13/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b>
<b>Reference :</b>	265402	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 13,727
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
<i>Total service :</i>				\$0.00

<b>Service :</b>	front end alignment (Service )			
<b>Date :</b>	7/25/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$95.00
<b>Reference :</b>	11365	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 14,956
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	front end alignment	1.00	\$95.00	\$95.00
<i>Total service :</i>				\$95.00

<b>Service :</b>	Oil and Filter Change (Service )			
<b>Date :</b>	7/24/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$39.50
<b>Reference :</b>	11361	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 14,858
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

<b>Service :</b>	Oil and Filter Change (Service )			
<b>Date :</b>	9/1/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$39.50
<b>Reference :</b>	8175	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 17,822
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

<b>Service :</b>	Inspection and Emission (Service )			
<b>Date :</b>	9/12/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$74.00
<b>Reference :</b>	11402	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 18,486
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Inspection and Emission	1.00	\$74.00	\$74.00
<i>Total service :</i>				\$74.00

<b>Service :</b>	Oil and Filter Change (Service )			
<b>Date :</b>	10/26/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$39.50
<b>Reference :</b>	8204	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 20,448
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$39.50	\$39.50
<i>Total service :</i>				\$39.50

<b>Service :</b>	Oil and Filter Change (Service )				
<b>Date :</b>	12/28/2017	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$39.50
<b>Reference :</b>	10873	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	23,530
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$39.50	\$39.50	
				<i>Total service :</i>	\$39.50

<b>Service :</b>	Oil and Filter Change, Front and rear brakes and Rotors (Service )				
<b>Date :</b>	2/13/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$804.95
<b>Reference :</b>	13446	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	26,067
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change, Front and rear brakes and Rotors	1.00	\$804.95	\$804.95	
				<i>Total service :</i>	\$804.95

<b>Service :</b>	Replace Starter (Service )				
<b>Date :</b>	4/6/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$0.00
<b>Reference :</b>	CHCS6979	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	29,297
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Starter	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

<b>Service :</b>	Change and balance 2 Tires, and Replace Wiper Blades, (Service )				
<b>Date :</b>	3/22/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$58.00
<b>Reference :</b>	13332	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	28,493
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Change and balance 2 Tires, and Replace Wiper Blades,	1.00	\$58.00	\$58.00	
				<i>Total service :</i>	\$58.00

<b>Service :</b> Oil and Filter Change (Service )					
<b>Date :</b>	4/5/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95
<b>Reference :</b>	13594	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	29,260
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

<b>Service :</b> Oil and Filter Change (Service )					
<b>Date :</b>	6/5/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95
<b>Reference :</b>	12778	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	32,347
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

<b>Service :</b> Replace left side fuel pump. Replace front left side axel (Service )					
<b>Date :</b>	7/10/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$0.00
<b>Reference :</b>	CHCS12171	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	34,605
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace left side fuel pump. Replace front left side axel	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

<b>Service :</b> Replace Evap Canister (Service )					
<b>Date :</b>	7/25/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$0.00
<b>Reference :</b>	CHCS13185	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	35,607
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Evap Canister	1.00	\$0.00	\$0.00	
				<i>Total service :</i>	\$0.00

<b>Service :</b> Oil and Filter Chnage (Service )				
<b>Date :</b>	7/23/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	13068	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 35,533
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Chnage	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Replace left side fuel pump, Replace front prop shaft, Software update, Replace Cabin Filter, (Service )				
<b>Date :</b>	8/2/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$0.00
<b>Reference :</b>	CHCS13630	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 36,089
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace left side fuel pump, Replace front prop shaft, Software update, Replace Cabin Filter,	1.00	\$0.00	\$0.00
<i>Total service :</i>				\$0.00

<b>Service :</b> Inspection and Emission, (Wires in the connector were crossed which caused a check engine light: repaired) (Service )				
<b>Date :</b>	8/10/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$82.13
<b>Reference :</b>	CHCS14043	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 36,505
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Inspection and Emission, (Wires in the connector were crossed which caused a check engine light: repaired)	1.00	\$82.13	\$82.13
<i>Total service :</i>				\$82.13

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	8/31/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	13109	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 38,500
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95

Total service : \$44.95

<b>Service :</b> mount and balance two new tires, replace both upper ball joints, front end alignment (Service )				
<b>Date :</b>	9/10/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$791.00
<b>Reference :</b>	13144	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 39,258
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	mount and balance two new tires, replace both upper ball joints, front end alignment	1.00	\$791.00	\$791.00
<i>Total service :</i>				\$791.00

<b>Service :</b> Replace right front headlight (Service )				
<b>Date :</b>	9/14/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$35.00
<b>Reference :</b>	10022	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 39,452
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace right front headlight	1.00	\$35.00	\$35.00
<i>Total service :</i>				\$35.00

<b>Service :</b> Oil and Filter Change, Mount and Balance 2 tires (Service )				
<b>Date :</b>	10/15/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$92.95
<b>Reference :</b>	13231	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 41,672
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change, Mount and Balance 2 tires	1.00	\$92.95	\$92.95
<i>Total service :</i>				\$92.95

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	11/21/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	7401	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 44,724
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>

Other	Oil and Filter Change	1.00	\$44.95	\$44.95
			<i>Total service :</i>	\$44.95

<b>Service :</b> Body Repair stemming from an accident (With a deer) Front Fascia, Core Return, Grille, headlamp, radiator seal. Repaint. (Service )				
<b>Date :</b>	11/29/2018	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$3,127.65
<b>Reference :</b>	CHCB20385	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 44,742
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Body Repair stemming from an accident (With a deer) Front Fascia, Core Return, Grille, headlamp, radiator seal. Repaint.	1.00	\$3,127.65	\$3,127.65
			<i>Total service :</i>	\$3,127.65

<b>Service :</b> Replace Battery (Service )				
<b>Date :</b>	2/4/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$240.00
<b>Reference :</b>	14418	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 47,684
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Battery	1.00	\$240.00	\$240.00
			<i>Total service :</i>	\$240.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	2/20/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	8736	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 48,196
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
			<i>Total service :</i>	\$44.95



<b>Service :</b>	Replace Front and Rear Brakes as well as Front and Rear Rotors, Mount and Balance 2 tires. (Service )				
<b>Date :</b>	4/23/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$834.00
<b>Reference :</b>	13758	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	52,026
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Front and Rear Brakes as well as Front and Rear Rotors, Mount and Balance 2 tires.	1.00	\$834.00	\$834.00	
				<i>Total service :</i>	\$834.00

<b>Service :</b>	Oil and Filter Change (Service )				
<b>Date :</b>	4/20/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95
<b>Reference :</b>	14699	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	51,978
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

<b>Service :</b>	Oil and Filter Change (Service )				
<b>Date :</b>	5/23/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95
<b>Reference :</b>	13817	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	54,366
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	oil and filter change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

<b>Service :</b>	Replace Front Pass side Headlight (Service )				
<b>Date :</b>	5/21/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$35.00
<b>Reference :</b>	14998	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	0
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace Front Pass side Headlight	1.00	\$35.00	\$35.00	
				<i>Total service :</i>	\$35.00

<b>Service :</b>	Fan Motor (Service )				
<b>Date :</b>	6/26/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$372.00
<b>Reference :</b>	14118	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	56,272
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Fan Motor	1.00	\$372.00	\$372.00	
				<i>Total service :</i>	\$372.00

<b>Service :</b>	Oil and Filter Change (Service )				
<b>Date :</b>	7/22/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95
<b>Reference :</b>	13983	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	57,678
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

<b>Service :</b>	Emission and State inspection, Replace Left Front Upper Ball Joint (Service )				
<b>Date :</b>	8/5/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$451.00
<b>Reference :</b>	14245	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	58,754
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Emission and State inspection, Replace Left Front Upper Ball Joint	1.00	\$451.00	\$451.00	
				<i>Total service :</i>	\$451.00

<b>Service :</b>	Oil and Filter Change (Service )				
<b>Date :</b>	8/27/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95
<b>Reference :</b>	14335	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	60,660
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Oil and Filter Change	1.00	\$44.95	\$44.95	
				<i>Total service :</i>	\$44.95

<b>Service :</b>	Fan Motor for Radiator (Service )				
<b>Date :</b>	9/12/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$285.00
<b>Reference :</b>	14051	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	61,608
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Fan Motor for Radiator	1.00	\$285.00	\$285.00	
				<i>Total service :</i>	\$285.00

<b>Service :</b>	Replace the Heater Core (Took Longer due to removal and reinstall of police Equip) (Service )				
<b>Date :</b>	10/21/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$1,666.44
<b>Reference :</b>	CHCS37514	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	63,297
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Replace the Heater Core	1.00	\$1,666.44	\$1,666.44	
				<i>Total service :</i>	\$1,666.44

<b>Service :</b>	Mount and Balance 2 Tres, Replace Right Front Lower Arm, Front End Alignment (Service )				
<b>Date :</b>	11/15/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$802.00
<b>Reference :</b>	14804	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	64,979
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Mount and Balance 2 Tres, Replace Right Front Lower Arm, Front End Alignment	1.00	\$802.00	\$802.00	
				<i>Total service :</i>	\$802.00

<b>Service :</b>	Mount and Balance 2 Tires, Replace Wiper Blades, Oil and Filter Change (Service )				
<b>Date :</b>	12/9/2019	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$120.95
<b>Reference :</b>	15259	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	66,262
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>	
Other	Mount and Balance 2 Tires, Replace Wiper Blades, Oil and Filter Change	1.00	\$120.95	\$120.95	
				<i>Total service :</i>	\$120.95

<b>Service :</b>	Oil and Filter Change (Service )					
<b>Date :</b>	2/10/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95	
<b>Reference :</b>	16287	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	69,191	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change			1.00	\$44.95	\$44.95
<i>Total service :</i>						\$44.95

<b>Service :</b>	Replace Starter (Service )					
<b>Date :</b>	3/28/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$248.00	
<b>Reference :</b>	15888	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	71,289	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace the Starter			1.00	\$248.00	\$248.00
<i>Total service :</i>						\$248.00

<b>Service :</b>	Replace and reprogram Transmission Control Module, Update HVAC Software (Service )					
<b>Date :</b>	4/27/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$0.00	
<b>Reference :</b>	CHCS46228	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b>	72,470	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace and reprogram Transmission Control Module, Update HVAC Software			1.00	\$0.00	\$0.00
<i>Total service :</i>						\$0.00

<b>Service :</b>	Oil and Filter Change (Service )					
<b>Date :</b>	4/10/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b>	\$44.95	
<b>Reference :</b>	16168	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b>	72,126	
<b>Type</b>	<b>Description</b>			<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change			1.00	\$44.95	\$44.95
<i>Total service :</i>						\$44.95

<b>Service :</b> Replace Control Relay (Service )				
<b>Date :</b>	5/22/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$79.85
<b>Reference :</b>	CHCS47246	<b>Vendor responsible :</b>	Videon Dodge	<b>Odometer :</b> 73,510
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Control Relay	1.00	\$79.85	\$79.85
<i>Total service :</i>				\$79.85

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b>	6/30/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	16387	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 75,715
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Repair Push Bumper Bracket (Service )				
<b>Date :</b>	7/10/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$120.00
<b>Reference :</b>	16052	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 0
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Repair Push Bumper Bracket	1.00	\$120.00	\$120.00
<i>Total service :</i>				\$120.00

<b>Service :</b> Mount and Balance 2 tires (Service )				
<b>Date :</b>	7/3/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$54.00
<b>Reference :</b>	16485	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 77,411
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Mount and Balance 2 tires	1.00	\$54.00	\$54.00
<i>Total service :</i>				\$54.00

<b>Service :</b>	Emission and State Inspection (Service )			
<b>Date :</b>	9/21/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$76.00
<b>Reference :</b>	16590	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 79,538
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Emission and State Inspection	1.00	\$76.00	\$76.00
<i>Total service :</i>				\$76.00

<b>Service :</b>	Oil and Filter Change (Service )			
<b>Date :</b>	11/18/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	15575	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 82,503
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b>	Replace Left sideLower Arm (Service )			
<b>Date :</b>	11/11/2020	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$412.00
<b>Reference :</b>	15555	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 81,858
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace left side lower arm	1.00	\$412.00	\$412.00
<i>Total service :</i>				\$412.00

<b>Service :</b>	Oil and Filter Change (Service )			
<b>Date :</b>	2/4/2021	<b>Technician responsible :</b>	N/D	<b>Cost :</b> \$44.95
<b>Reference :</b>	15734	<b>Vendor responsible :</b>	Thorntons Gulf	<b>Odometer :</b> 85,280
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Heater Hoses, Coolant (Service )				
<b>Date :</b> 2/16/2021		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$270.00
<b>Reference :</b> 17118		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 85,995
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Heater Hoses, Coolant	1.00	\$270.00	\$270.00
<i>Total service :</i>				\$270.00

<b>Service :</b> Oil and Filter Change (Service )				
<b>Date :</b> 4/29/2021		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$44.95
<b>Reference :</b> 16836		<b>Vendor responsible :</b> Thorntons Gulf		<b>Odometer :</b> 88,326
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Oil and Filter Change	1.00	\$44.95	\$44.95
<i>Total service :</i>				\$44.95

<b>Service :</b> Replace Radiator, Fan Motors and Blades, Replace Thermostat, Replace #1 Spark Plug, Replace Water Pump Assembly (Antifreez & Pump Water) (Service )				
<b>Date :</b> 6/17/2021		<b>Technician responsible :</b> N/D		<b>Cost :</b> \$1,661.46
<b>Reference :</b> CHCS65295		<b>Vendor responsible :</b> Videon Dodge		<b>Odometer :</b> 89,846
<b>Type</b>	<b>Description</b>	<b>Qty.</b>	<b>Unit cost</b>	<b>Total cost</b>
Other	Replace Radiator, Fan Motors and Blades, Replace Thermostat, Replace #1 Spark Plug, Replace Water Pump Assembly (Antifreez & Pump Water)	1.00	\$1,661.46	\$1,661.46
<i>Total service :</i>				\$1,661.46
<i>Total of the vehicle :</i>				\$16,953.84