

Detailed services/breakdown

My company
Tuesday, September 21, 2021
16:34

Display criteria

Period : All

Vehicle(s) : Chevrolet/Tahoe/2015

Vehicle : 67-73 - Chevrolet/Tahoe/2015/JMP9812

Service : Upfitted with new equipment. (Service)				
Date :	6/9/2015	Technician responsible :	N/D	Cost : \$7,165.00
Reference :	IN000101467	Vendor responsible :	Metropolitan Communications	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Upfitted with new equipment.	1.00	\$7,165.00	\$7,165.00
Total service :				\$7,165.00

Service : Oil and filter change, tire rotation. Daytime running light issue. (Service)				
Date :	7/23/2015	Technician responsible :	N/D	Cost : \$122.14
Reference :	541216	Vendor responsible :	Faulkner	Odometer : 5,412
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change, tire rotation. Daytime running light issue.	1.00	\$122.14	\$122.14
Total service :				\$122.14

Service : Oil and filter change. Tire rotation. (Service)				
Date :	10/30/2015	Technician responsible :	N/D	Cost : \$58.23
Reference :	546109	Vendor responsible :	Faulkner	Odometer : 13,431
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change. Tire rotation.	1.00	\$58.23	\$58.23
Total service :				\$58.23

Service : Oil and filter change. State inspection & emissions test. (Service)				
Date : 2/1/2016		Technician responsible : N/D		Cost : \$91.64
Reference : 550582		Vendor responsible : Faulkner		Odometer : 20,958
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change. State inspection & emissions tes	1.00	\$91.64	\$91.64
<i>Total service :</i>				\$91.64

Service : Recall #15577. Reprogram transfer case shift control. (Service)				
Date : 2/1/2016		Technician responsible : N/D		Cost :
Reference : 550582		Vendor responsible : Faulkner		Odometer : 20,958
Type	Description	Qty.	Unit cost	Total cost
<i>Total service :</i>				\$0.00

Service : Oil & filter change. Multipoint inspection. (Service)				
Date : 5/4/2016		Technician responsible : N/D		Cost : \$58.60
Reference : 555525		Vendor responsible : Faulkner		Odometer : 28,717
Type	Description	Qty.	Unit cost	Total cost
Other	Oil & filter change. Multipoint inspection.	1.00	\$58.60	\$58.60
<i>Total service :</i>				\$58.60

Service : Rotate & balance 4 wheels (Service)				
Date : 6/30/2016		Technician responsible : N/D		Cost : \$63.55
Reference : 558561		Vendor responsible : Faulkner		Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Rotate & balance 4 wheels	1.00	\$63.55	\$63.55
<i>Total service :</i>				\$63.55

Service : Change oil & filter. Rotate tires. (Service)				
Date : 7/26/2016		Technician responsible : N/D		Cost : \$58.60
Reference : 559761		Vendor responsible : Faulkner		Odometer : 35,994
Type	Description	Qty.	Unit cost	Total cost
Other	Change oil & filter. Rotate tires.	1.00	\$58.60	\$58.60
<i>Total service :</i>				\$58.60

Service : Oil and Filter Change, check and balance Tires, (Service)				
Date : 11/3/2016		Technician responsible : N/D		Cost : \$93.52
Reference : 564784		Vendor responsible : Faulkner		Odometer : 43,563
Type	Description	Qty.	Unit cost	Total cost
Other	oil and finlter change, rotate tires	1.00	\$93.52	\$93.52
<i>Total service :</i>				\$93.52

Service : Oil and filter change, Mount and balance 4 tires, Suspension Alignment, State and Emission Inspection, replace air filter (Service)				
Date : 2/10/2017		Technician responsible : N/D		Cost : \$420.95
Reference : 569498		Vendor responsible : Faulkner		Odometer : 51,414
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change, Mount and balance 4 tires, Suspension Alignment, State and Emission Inspection, replace air filter	1.00	\$420.95	\$420.95
<i>Total service :</i>				\$420.95

Service : Replace Fuel Feed Pipe, Replace Wiper Blades, Replace HVAC Module, *Diagnosed AC Issue. (Recomended to replace AC Condensor which was schedualed for a later date) (Service)				
Date : 3/28/2017		Technician responsible : N/D		Cost : \$198.20
Reference : 571819		Vendor responsible : Faulkner		Odometer : 55,803
Type	Description	Qty.	Unit cost	Total cost

Other	Replace Fuel Feed Pipe, Replace Wiper Blades, Replace HVAC Module,	1.00	\$198.20	\$198.20
<i>Total service :</i>				\$198.20

Service : replace air conditionaing condenser, oil filter and lube (Service)				
Date :	5/1/2017	Technician responsible :	N/D	Cost : \$1,008.59
Reference :	573420	Vendor responsible :	Faulkner	Odometer : 58,610
Type	Description	Qty.	Unit cost	Total cost
Other	air conditioner condenser, oil and filter change	1.00	\$1,008.59	\$1,008.59
<i>Total service :</i>				\$1,008.59

Service : Replace and mount new tire (Service)				
Date :	1/14/2018	Technician responsible :	N/D	Cost : \$180.14
Reference :	281623	Vendor responsible :	Goodyear Auto Service Center	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replace and mount new tire	1.00	\$180.14	\$180.14
<i>Total service :</i>				\$180.14

Service : Oil and Filter Change, Replace Air Filter, Rotate Tires, Add chemical addative to fuel tank, INduction Service, Fuel Kit (Service)				
Date :	2/6/2018	Technician responsible :	N/D	Cost : \$297.94
Reference :	585360	Vendor responsible :	Faulkner	Odometer : 74,986
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Replace Air Filter, Rotate Tires, Add chemical addative to fuel tank, INduction Service, Fuel Kit	1.00	\$297.94	\$297.94
<i>Total service :</i>				\$297.94

Service : Replace Battery (Service)				
Date :	2/22/2018	Technician responsible :	N/D	Cost : \$210.00
Reference :	13387	Vendor responsible :	Thorntons Gulf	Odometer : 76,102
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	\$210.00	\$210.00
<i>Total service :</i>				\$210.00

Service : Emission and State Insp.,Replace HVAC Module, Alignment (Service)				
Date :	3/20/2018	Technician responsible :	N/D	Cost : \$872.69
Reference :	586874	Vendor responsible :	Faulkner	Odometer : 77,464
Type	Description	Qty.	Unit cost	Total cost
Other	P18069454	1.00	\$872.69	\$872.69
<i>Total service :</i>				\$872.69

Service : Oil and Filter Change, Replace Front Seat Belt (Warranty) (Service)				
Date :	8/13/2018	Technician responsible :	N/D	Cost : \$78.01
Reference :	593040	Vendor responsible :	Faulkner	Odometer : 82,187
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and filter change. Replace front Seat Belt (Warranty)	1.00	\$78.01	\$78.01
<i>Total service :</i>				\$78.01

Service : Reprogram The Power Steering Control Module, Oil and Filter Change, Rotate Tires, Fuel System Treatment, Resurface Rotors,Replace Rear Brakes and Rear Rotors (Service)				
Date :	1/18/2019	Technician responsible :	N/D	Cost : \$898.03
Reference :	599591	Vendor responsible :	Faulkner	Odometer : 88,083
Type	Description	Qty.	Unit cost	Total cost
Other	Reprogram The Power Steering Control Module, Oil and Filter Change, Rotate Tires, Fuel System Treatment, Resurface Rotors,Replace Rear Brakes and Rear Rotors	1.00	\$898.03	\$898.03

Total service : \$898.03

Service : Emission and State Inspection, Oil and Filter Change, Front and Rear Brakes (Service) Date : 4/24/2019 Technician responsible : N/D Cost : \$180.47 Reference : 13476 Vendor responsible : Mike Ivey's Auto Repair, Inc. Odometer : 91,142				
Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection, Oil and Filter Change, Front and Rear Brakes	1.00	\$180.47	\$180.47
Total service :				\$180.47

Service : Reprogram Brake Control Module, Inspect and Dignose Squeak from Brake Pedal (No Work Done), Diagnose Entertainment Black Screen (No work Done) (Service) Date : 10/23/2019 Technician responsible : N/D Cost : \$269.90 Reference : 611587 Vendor responsible : Faulkner Odometer : 96,743				
Type	Description	Qty.	Unit cost	Total cost
Other	Reprogram Brake Control Module, Inspect and Dignose Squeak from Brake Pedal (No Work Done), Diagnose Entertainment Black Screen (No work Done)	1.00	\$269.90	\$269.90
Total service :				\$269.90

Service : Replace Battery (Service) Date : 11/5/2019 Technician responsible : N/D Cost : \$249.91 Reference : 14041 Vendor responsible : Mike Ivey's Auto Repair, Inc. Odometer : 0				
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Battery	1.00	\$249.91	\$249.91
Total service :				\$249.91

Service : Oil and Filter Change, Mount and Balance 4 Tires, (Service)				
Date :	12/3/2019	Technician responsible :	N/D	Cost : \$244.35
Reference :	14114	Vendor responsible :	Mike Ivey's Auto Repair, Inc.	Odometer : 98,108
Type	Description	Qty.	Unit cost	Total cost
Other	Oil and Filter Change, Mount and Balance 4 Tires,	1.00	\$244.35	\$244.35
<i>Total service :</i>				\$244.35

Service : Replace Starter (Service)				
Date :	1/8/2020	Technician responsible :	N/D	Cost : \$454.30
Reference :	615189	Vendor responsible :	Faulkner	Odometer : 99,212
Type	Description	Qty.	Unit cost	Total cost
Other	replace starter	1.00	\$454.30	\$454.30
<i>Total service :</i>				\$454.30

Service : Emission and State Inspection, Replace Front Brakes, Rotate all 4 tires. (Service)				
Date :	4/29/2020	Technician responsible :	N/D	Cost : \$328.62
Reference :	14421	Vendor responsible :	Mike Ivey's Auto Repair, Inc.	Odometer : 102,281
Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State Inspection, Replace Front Brakes, Rotate all 4 tires.	1.00	\$328.62	\$328.62
<i>Total service :</i>				\$328.62

Service : 2 Front Rotors (Service)				
Date :	6/18/2020	Technician responsible :	N/D	Cost : \$160.00
Reference :	16026	Vendor responsible :	Thorntons Gulf	Odometer : 103,238
Type	Description	Qty.	Unit cost	Total cost
Other	2 Front Rotors	1.00	\$160.00	\$160.00
<i>Total service :</i>				\$160.00

Service : Replace Valve Stem and Clean the Rim, Oil and Filter Change (Service)				
Date :	8/4/2020	Technician responsible :	N/D	Cost : \$204.35
Reference :	622373	Vendor responsible :	Faulkner	Odometer : 103,525
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Valve Stem and Clean the Rim, Oil and Filter Change	1.00	\$204.35	\$204.35
<i>Total service :</i>				\$204.35

Service : Replace Driver side Headlamp (Service)				
Date :	8/10/2020	Technician responsible :	N/D	Cost : \$920.00
Reference :	16623	Vendor responsible :	Thorntons Gulf	Odometer : 0
Type	Description	Qty.	Unit cost	Total cost
Other	Replace Driver side Headlamp	1.00	\$920.00	\$920.00
<i>Total service :</i>				\$920.00

Service : Replace the Transmission with a Remanufactured Transmission, DEX6 QRT Bottle, S Gasket, Clamp, 2 S Seal's (Service)				
Date :	11/27/2020	Technician responsible :	N/D	Cost : \$4,684.79
Reference :	626453	Vendor responsible :	Faulkner	Odometer : 104,810
Type	Description	Qty.	Unit cost	Total cost
Other	Replace the Transmission with a Remanufactured Transmission, DEX6 QRT Bottle, S Gasket, Clamp, 2 S Seal's	1.00	\$4,684.79	\$4,684.79
<i>Total service :</i>				\$4,684.79

Service : Emission and State inspection, Oil and Filter Change (Service)				
Date :	3/11/2021	Technician responsible :	N/D	Cost : \$120.95
Reference :	16758	Vendor responsible :	Thorntons Gulf	Odometer : 105,268
Type	Description	Qty.	Unit cost	Total cost
Other	Emission and State inspection, Oil and Filter Change	1.00	\$120.95	\$120.95
<i>Total service :</i>				\$120.95

Total of the vehicle : *\$19,693.47*