

Veh #	Year	Make	Model	VIN	Purchase cost	
13	2007	Ford	F350 Utility	F31YX7EA	\$34,071.00	
Date	Miles/Hrs	Description of Repairs			Repair Cost	Shop
12/26/06		Radio Installation			\$267.57	CyberComm
2/21/07	2173	PM Service			\$49.10	On-Site
5/30/07	4070	PM Service			\$51.10	On-Site
8/22/07	6867	PM Service			\$51.10	On-Site
11/28/07	8934	PM Service			\$53.10	On-Site
7/16/08	14960	PM Service			\$59.90	On-Site
11/19/08	17746	PM Service			\$59.90	On-Site
3/25/09	20944	Wheel Balance / PM Service			\$70.15	Rodman
12/23/09	25164	PM Service			\$57.80	On-Site
4/21/10	27272	PM Service			\$57.80	On-Site
5/13/10		Mirror Assy- Left			\$381.32	Rodman
7/14/10	28938	Tire Repair			\$28.61	NE Tire
8/25/10	29846	PM Service			\$59.50	On-Site
12/29/10	32527	PM Service			\$67.00	On-Site
8/17/11	37204	PM Service			\$62.55	On-Site
2/10/12		Battery- 65-60			\$99.80	Allied
3/13/12	41863	Tires- (4) Wrangler SRA LT275/70R18			\$773.96	Sullivan
4/24/12	42497	PM Service			\$64.60	On-Site
1/9/13	47098	PM Service			\$66.60	On-Site
9/25/13	50600	PM Service			\$67.65	On-Site
3/19/14	53049	Ma.Insp			\$29.00	TD&I
6/11/14	54496	PM Service			\$72.70	On-Site
2/25/15	57032	PM Service			\$72.70	On-Site
3/24/15		Ma.Insp			\$99.95	Tri.St
2/25/16		Re Upolster Driver Seat Bottom			\$231.60	Mark's
3/22/16	62340	Ma.Insp			\$99.95	Tri.St
8/4/16	64248	PM Service			\$75.70	On-Site
3/16/17		Ma.Insp			\$99.95	Tri.St
4/21/17	68036	PM Service			\$76.75	On-Site
6/27/17		Battery- Exide 65CP			\$126.19	Allied
12/7/18		Front & Rear Shocks / Tires (4) Firestone			\$1,198.81	Firestone
4/9/18	73555	Front Brake pads & Rotors			\$638.36	Firestone
11/30/18	77320	Change Vehicle Number From #17 to #13				
12/13/18	77326	PM Service			\$95.75	
3/5/19	77499	R&R U joints rear and seal			\$538.56	Sammy's

5/1/19	77520	Remove utility body replace with flat bed	\$3,950.00	Cary auto
9/12/19		New Battery	\$165.00	P&E
12/12/19	80853	PM service	\$101.75	on site
6/3/20	81124	PM service	\$88.00	on site
6/20/20	82501	MA state insp.	\$135.00	on site
10/20/20		R&R alternator	\$315.00	P&E
1/26/21		PM service		on site
1/29/21		Replace HVAC blower motor	\$275.33	Sammies
1/26/21		PM service	\$94.50	
			\$11,029.66	
8/11/21	87166	MA state insp.	\$35.00	ATG
9/30/21	87198	PM service	\$95.90	On-site
5/24/22	91439	PM service	\$147.80	On-site
8/12/22	93197	Rear brake job w/ backer plates	\$1,941.05	Sammies
1/24/23	95543	PM service	\$117.00	On-site
3/28/23		New right rear tire	\$416.77	NE Tire
7/18/23		MA state insp.	\$185.00	ATG
8/10/23		Fix firestone's bad work/ball joints	\$116.05	CSG
8/16/23		Front end repairs/ tie rods and ball joints	\$2,240.08	Firestone
9/28/23	99557	PM service H5454	\$117.00	On-site
1/25/24		PM service	\$117.00	On-site
5/30/24	105337	PM service H5790	\$123.40	On-site
7/9/24	106492	MA state insp.	\$195.00	ATG
			\$16,876.71	