


Vehicle Details

Friday, November 18, 2016

11:08:48 AM

Vehicle Name 2008 Ford 1-Ton Unit 22



Purchase Date
Purchase Price \$54,437.00
Purchase Mileage
Sold Date
Sold Price
Sold Mileage

Color Yellow
License Plate Number PA 4239
VIN Number 1FDAW57R58EA84220
Notes Replacing in 2016

Future Expenses

Past Expenses

| | | | | |
|---------------------|---|------------|--------|----------|
| Triple D Auto Parts | Brake replacement, lights repaired | 7/25/2016 | | \$353.47 |
| Point Spring | Annual Inspection | 6/16/2016 | 60,962 | \$65.00 |
| Point Spring | Semi-Annual Inspection | 12/17/2015 | 58,876 | \$60.00 |
| Point Spring | Semi-Annual Inspection | 12/7/2015 | 58,876 | \$60.00 |
| In-House | Cracked weld on hitch plate | 7/27/2015 | | \$0.00 |
| In-House | transmission fluid leak | 6/16/2015 | | \$0.00 |
| Point Spring | Semi-Annual Inspection | 5/14/2015 | 55,062 | \$60.00 |
| In-House | New U-Joint Install | 5/11/2015 | | \$97.68 |
| In-House | Radiator hose leak | 5/11/2015 | 55,054 | \$0.00 |
| In-House | Air Filter light activated | 1/5/2015 | 52,032 | \$0.00 |
| Point Spring | Semi-Annual Inspection | 12/17/2014 | 51,835 | \$60.00 |
| In-House | Strobe light not activating | 8/12/2014 | | \$0.00 |
| Meegan Ford | Heater/AC not blowing but can hear fan | 7/8/2013 | 44,000 | \$0.00 |
| In-House | Hydraulic oil on floor below Unit | 7/5/2012 | | \$0.00 |
| In-House | Front brakes squealing | 1/28/2010 | 19,410 | \$0.00 |
| Kenny Ross | Wrench light activated | 10/27/2009 | | \$0.00 |
| Kenny Ross | Radiator leaking | 4/27/2009 | 14,005 | \$0.00 |
| Kenny Ross | Radiator is leaking | 4/1/2009 | 13,347 | \$0.00 |
| Kenny Ross | Antifreeze leaking | 4/1/2009 | 13,353 | \$0.00 |
| Kenny Ross | Recall alert for Diesel Particulate Filter regeneration | 1/23/2009 | | \$0.00 |
| Point Spring | truck pulls to right | 5/16/2008 | 7,250 | \$0.00 |
| Kenny Ross | No heat coming from air vents | 4/29/2008 | 9,929 | \$0.00 |
| Kenny Ross | Rear window leaks | 4/28/2008 | 9,512 | \$0.00 |

| | | | | |
|------------|---|----------|-------|--------|
| Kenny Ross | Hydraulic tank leaking, inside tread wear; oil leak near front driver side tire | 4/3/2008 | 9,496 | \$0.00 |
|------------|---|----------|-------|--------|

| | | | | |
|----------|---------------------------|----------|--|--------|
| In-House | Check air filter light on | 1/3/2008 | | \$0.00 |
|----------|---------------------------|----------|--|--------|

