







Vectrax

CNC knee mill	9030177 NV	220V/440V	S/N: 4766
	9030176 NV	8.5A/4.25A	S/N: 4767
		3ph motor.	
		3 HP/2.2kW	3 axis CNC with M15-10
		1720 rpm	Centroid Controllers
			(240V, 3ph)
			Automatic Oiler



Delta

110V/6.6A
 1/2 HP
 1ph motor
 3450 rpm




NORTON

Surface Grinder 1952 H5818

220V/440V
 4A/2A
 1.5 HP
 3ph motor
 3000 rpm

Brown & Sharpe
 Permanent Magnet
 Chuck.
 Turbine Oil System

Bridgeport1




Knee mill
With Newall DRO
Manual Oiler
One of them with
broken power feed.

J-149159
J-153107
220V/440V
4A/3.8A/1.9A
1 HP
3ph motor

Bridgeport


Bridgeport2_



Knee mill
J-240087
220V-440V
3A-6A
2 HP
3ph motor
With Newall DRO
Manual Oiler
With broken power
feed.

Bridgeport

SouthBend Lathe_1.



South Bend


13"x4' Manual Lathe

- 16575 T
- 16572 T
- 16573 T
- 16577 T
- 16576 T


230V 6.4A
3ph motor.
2 HP
1730 rpm

All lathes have guards,
chucks and tailstocks.
Two of them have taper
attachments.


SouthBend Lathe_2



SouthBend Lathe_4



SouthBend Lathe_3.



SouthBend Lathe_5.

