## Courtney's Service Center Inc

628 Mt Royal Blvd Pittsburgh, PA. 15223

Phone: 412-486-9856 Fax: 412-486-5645

INVOICE

8430

		-		_
1 B		$I \cap$	IC	_
	<b>/II/</b>	/( )		_
	$\mathbf{v}$			_

**Shaler Township** 

Glenshaw, PA 15116

Home 412-486-9700

300 Wetzel Rd

Printed Date: 03/04/2022

Work Completed: 03/04/2022

2021 Ford - Police Interceptor Utility - 3.3L, V6 (204CI) VIN(W)

Odometer In: 26376

Lic #: MG5713M

Unit #: 21-4 VIN #: 1FM5K8AWX MNA10850

Part Description / Number

Sale Ext **Labor Description** Qty

Ext

**EMISSION TEST** 

39.95

**Current Estimate** 39.95 0.00 Org. Estimate 39.95 Revisions

[ Payments - ]

Labor: Parts:

39.95 0.00

SubTotal: Tax:

39.95 0.00 39.95

Total: Bal Due: \$39.95

Customer Number: 44

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature

Vehicle Received: 3/4/2022

Date

Email Address: courtneysservice@aol.com



## − ⑤ − Shaler Township

PENNSYLVANIA

300 Wetzel Road; Glenshaw, PA 15116 412-486-9700

## INVOICE/WORK ORDER

Date/Time	3-4-22 4		Requested by:		
Unit #					<i>T</i>
Lic#		Odometer	26,376		
VIN#	Work done by:				
	HOURS		DESCRIPTION		
	2.5	Inspec	+19N)		0
		Em 15:	tien)		0
					0
		Oil ch	Belince 4 tires		0
					0
	1(8)				0
				TOTAL	0
PARTS QUANTITY			DESCRIPTION		
4	tines				
1	7502 Firth				
6/12		01/			
		2.			
		¥			
			Sh.	TOTAL	0