

Work History Report

Cumberland County
Courthouse

Date Produced: 3/6/2024
Account: 19 District Attorneys Office
Reg: JZF0823 PA
Vehicle Details DODGE DURANGO 4.7 2009
Silver

310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num V8 4.7L 345CID FI GAS N 2 / Vin 1D8HB38P69F711360 Mileage 180550

Invoice Number I003063 Date 3/6/2024 Mileage 180550 Job Value 220.60

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
Decommissioned vehicle, removed sirens, lights, and all radios.	220.60			

Invoice Number I002672 Date 8/17/2023 Mileage 174063 Job Value 56.07

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	31.05	CNV85372 Oil Filter advance	1	2.62
		CNVWWFlu Windshield Washer Fluid d Clearv	1	1.32
		CNV75-053 5W30 Oil syn blend	6	19.08

Invoice Number I002587 Date 6/27/2023 Mileage 172472 Job Value 60.41

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
Shop Labor- Cumberland County. Checked a/c. Evacuated and recharged a/c system.	51.75	CNVR134 R134 Freon	2	6.66

Invoice Number I002345 Date 2/23/2023 Mileage 168209 Job Value 173.08

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	31.05	CNV85372 Oil Filter advance	1	3.95
Rotate Tires, 4 lug nuts on LR threads were cross threaded. Installed 4 new lug nuts	25.88	CNVWWFlu Windshield Washer Fluid d Clearv	1	1.20
State Inspection	31.05	CNV75-053 5W30 Oil syn blend	6	19.08
State Emission Inspection	25.88	CNVEMI Emissions, Phone Transaction Fee	1	1.57
RF marker light inoperative, removed headlight assembly and found bulb blown. Cleaned connection and installed new bulb	10.35	CNV194 Light Bulb	1	0.67
		CNV611-26 Lug Nut g	4	20.40

Invoice Number I002028 Date 9/6/2022 Mileage 163590 Job Value 62.28

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	30.15	CNV85372 Oil Filter advance	1	3.25
		CNV5w-30 Oil	7	25.68
		PPC CNVWWFlu Windshield Washer Fluid d Clearv	1	1.20

Invoice Number I001767 Date 4/7/2022 Mileage 160489 Job Value 16.05

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
Replaced wiper blades.	10.05	CNVDL20 Wiper Blade	1	3.00
		CNVDL24 Wiper Blade	1	3.00

Invoice Number I001644 Date 2/2/2022 Mileage 158261 Job Value 458.99

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	30.15	CNV85372 Oil Filter advance	1	3.14
State Inspection	30.15	CNV5w-30 Oil	6	11.94
State Emission Inspection	25.13	PPC		
Front brake pads getting low and rotors have heat marks.	75.38	CNVWWFlu d Clearv	1	1.20
R&R Front Brake Pads and Rotors, Clean and Lubricated slider pins and caliper bracket.		CNVEMI Emissions, Phone Transaction Fee	1	1.57
Sway bar link bushings torn. R&R Front sway bar links RF and LF	40.20	CNVVG108 Front Brake Pads 4	1	29.99
Front shocks worn out and leaking, replace RF and LF shock absorbers	40.20	CNV53005D Front Brake Rotor L	2	78.38
		CNVV18750 Front Sway Bar Link 026	2	32.18
		CNVTS34-3 Front Shock Absorber 1561B	2	57.38

Invoice Number I001439 Date 10/6/2021 Mileage 156118 Job Value 356.79

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
Shop Labor- Cumberland County. Light lens are all cloudy. Replaced both headlamp and fog lamp light assemblies. Adjusted lights.	69.03	CNVCH251 Headlight Assembly-left side 8121V	1	119.79
		CNVCH251 Headlamp Assembly -pass. side 9121	1	119.79
		CNV923-80 Fog Light Assembly 1	2	46.18

Invoice Number I001380 Date 9/2/2021 Mileage 155332 Job Value 513.66

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
Belt screech while driving, unable to duplicate noise. A/C compressor leaking believe possibly low on oil and cause strain on the belt. Replace a/c compressor and filter, replaced belt tensioner assembly as well. Pulleys had some noise to them. Evac and recharge system test drove to verify everything is working properly.	138.06	CNV39120 Belt Tensioner Assembly	1	56.09
		CNVB1546 4 seasons A/C Compressor Kit	1	310.85
		CNVR134A Refrigerant Per Pound AZ	2	6.66

Invoice Number I001276 Date 7/9/2021 Mileage 154073 Job Value 100.48

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	27.61	CNV85372 Oil Filter advance	1	3.14
A/C not blowing cold, vehicle was low on Freon. Low side valve was leaking, replaced valve and evac and recharged A/C.	46.02	CNV5w-30 Oil	6	12.90
		PPC		
		CNVWWFlu d Clearv	1	1.15
		CNVR134A Refrigerant Per Pound AZ	2	6.66

Invoice Number K11140 Date 1/20/2021 Mileage 149385 Job Value 206.09

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

NULL

NULL

NULL

State Inspection

Replaced wiper blades

Rear Brakes Getting Low Replaced

Labor	Value	Parts	Qty	Value
Service	27.61	CNVWWFlu d	1	1.15
Rotate Tires	13.81	CNV5w-30 Oil	7	13.98
State Emissions Inspection	23.01	Petro		
Emissions Phone Transaction Fee	1.57	CNV85372 advance	1	3.14
State inspection	27.61	CNVDL20 az	1	3.00
replace wiper blades	9.20	CNVDL24A Z	1	3.00
Rear Brakes	46.02	CNVDG967 AZ	1	28.99

Invoice Number K11076 Date 12/16/2020 Mileage 148611 Job Value 63.66

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Tested battery and charging system. Both test good. Checked for ses codes has code p0622 generator field control circuit. Checked code diagnostics cleaned wire connection to alternator and main connector to fuse box.

Labor	Value	Parts	Qty	Value
Battery light came on	63.66			

Invoice Number K10957 Date 10/7/2020 Mileage 174244 Job Value 460.69

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Tested Battery and Charging system found alternator intermittenly not charging. Replaced alternator and belt

Found Waterpump leaking while checking alternator replaced waterpump

Labor	Value	Parts	Qty	Value
Battery Light Coming On	106.10	CNV196150 35Fisher	1	150.56
Coolant Leak	106.10	CNV293506 0890Fisher	1	25.25
		CNV425120 -4350IMFisher	1	54.78
		er CNVPIABX3 fisher	2	15.90

Invoice Number K10705 Date 6/15/2020 Mileage 144541 Job Value 185.78

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Replaced Air Filter

Check and charge AC

Check Engine Light On Code PO456 Small evap leak Replaced Fuel Cap

Labor	Value	Parts	Qty	Value
Service	26.53	CNVWWFlu d	1	1.15
Replace air filter	10.61	CNV5w-30 Oil	7	13.98
Charge AC	53.05	Petro		
Check Engine Light On	53.05	CNV85372 advance	1	3.14
		CNV87750A DV	1	5.03
		CNVR134A AZ	2	6.66
		CNV10838Y ADV	1	8.59

Invoice Number K10393 Date 1/6/2020 Mileage 142603 Job Value 314.14

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description NULL

Emission Inspection and reset emission monitors after battery replacement.

NULL

State Inspection

Replaced master window switch.

Labor	Value	Parts	Qty	Value
Change Battery	26.53	CNVMT-65 Interstate Battery	1	127.95
State Emissions Inspection	42.44	CNV901-45 Master Window Switch	1	47.99
Emissions Phone Transaction Fee	1.57	0 az		
State inspection	31.83			
Driver and passenger front windows wont go up or down at times.	31.83			

Invoice Number K10115 Date 8/23/2019 Mileage 139860 Job Value 46.49

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Labor	Value	Parts	Qty	Value
Service	27.63	CNVWWFlu Windshield Washer Fluid	1	1.15
		CNV5w-30 Oil	7	13.02
		Petro		
		CNV85372M Oil Filter	1	2.69
		P ADV.		

Invoice Number K9876 Date 5/7/2019 Mileage 137420 Job Value 218.52

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Checked and charged AC

Checked TPMS system. Replaced RF tire sensor.

Labor	Value	Parts	Qty	Value
Check AC	55.25	CNVR134A Refrigerant Per Pound	2	6.66
Check TPMS	110.50	AZ		
		CNVSE1000 Tire Sensor	1	42.11
		1HP ADV		

Invoice Number K9549 Date 12/17/2018 Mileage 134695 Job Value 104.88

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

NULL

NULL

State Inspection

Labor	Value	Parts	Qty	Value
Service	28.10	CNVWWFlu Windshield Washer Fluid	1	1.15
State Emissions Inspection	22.48	CNV5w-30 Oil	6	12.24
Emissions Phone Transaction Fee	1.65	Petro		
State inspection	33.72	CNVPH2 Oil Filter	1	3.54
		BC		

Invoice Number K8664 Date 11/21/2017 Mileage 130404 Job Value 227.29

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description NULL

NULL

State Inspection

plugged hole in rf tire nail close to sidewall tire will need replaced

Mounted and balanced a new right front tire. Picked up tire at Highlands.

Labor	Value
State Emissions Inspection	23.09
Emissions Phone Transaction Fee	1.65
State inspection	34.63

plug tire	14.43	CNV333333	Wheel Weights	2	1.00
Replace right front tire.	28.86				

Invoice Number K8534 Date 9/25/2017 Mileage 129941 Job Value 152.34

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL

Checked front ac for leaks. No exterior leaks found possibly evaporator core leak. Added ac system stop-leak to system and recharged ac system.

Labor	Value	Parts	Qty	Value
Service	28.86	CNVWWFliu Windshield Washer Fluid	1	1.15
Rotate Tires	17.32	CNV5w-30 Oil	7	10.43
Front AC is not cold	57.72	Petro CNVPH2 Oil Filter	1	3.31
		BC CNVR134A Refrigerant	2	5.57
		AZ CNVBD151 ac stop leak	1	25.99
		az		

Invoice Number K8384 Date 8/2/2017 Mileage 129133 Job Value 65.29

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Checked system for leaks. could not find any leaks. recharged system and added dye.

Labor	Value	Parts	Qty	Value
Charge AC	57.72	CNVR134A Refrigerant	2	5.57
		AZ		

Invoice Number K8315 Date 7/5/2017 Mileage 128773 Job Value 92.31

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Recharge Front AC System.
Replaced right wiper blade

Labor	Value	Parts	Qty	Value
Charge AC	57.72	CNVR134A Refrigerant	2	5.15
Replace blades	11.54	AZ CNVCWP20 Wiper Blade 20 Inch	2	15.90
		-51-CQ		

Invoice Number K7843 Date 11/17/2016 Mileage 124834 Job Value 105.32

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL

NULL
State Inspection

Labor	Value	Parts	Qty	Value
Service	29.12	CNVWWFliu Windshield Washer Fluid	1	1.15
State Emissions Inspection	23.30	CNV5w-30 Oil	7	9.69
Emissions Phone Transaction Fee	1.65	Petro CNVPH2 Oil Filter	1	3.47
State inspection	34.94	BC		

Invoice Number K7589 Date 7/26/2016 Mileage 122542 Job Value 96.24

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Replaced passenger side headlight bulb.
Checked trouble codes and found codes set for brake light switch. Replaced brake light switch and adjusted.

Labor	Value	Parts	Qty	Value
passenger side headlight is out	17.47	CNVH13 az Headlight bulb	1	13.87
abs and esp lights in dash come on	46.59	CNV508334 Brake Light Switch	1	16.31
		4AA shively		

Invoice Number	K7398	Date	5/2/2016	Mileage	119277	Job Value	44.78
Vehicle Details	JZF0823 PA DODGE DURANGO 2009						
Work Description	Replaced drivers side headlight bulb and left front side marker bulb. Replaced center brake light bulb						
Labor	Value	Parts		Qty	Value		
drivers headlight is out	17.68	CNVH13 az Headlight bulb		1	13.87		
center brake light is out	11.79	CNVLT194B Light Bulb 194 X AZ CNVLT921D light bulb 921 X az		1	0.20		

Invoice Number	K7367	Date	4/19/2016	Mileage	118853	Job Value	146.38
Vehicle Details	JZF0823 PA DODGE DURANGO 2009						
Work Description	Lube Oil Filter Changed NULL Checked window operation. Window switch is faulty. Replaced drivers power window switch.						
Labor	Value	Parts		Qty	Value		
Service	29.47	CNVWWFlu Windshield Washer Fluid d		1	1.15		
Rotate Tires	23.58	CNV5w-30 Oil Petro		6	8.94		
Drivers power window stops working at times	29.47	CNVPH2 az Oil Filter CNV901-45 window switch 0 az		1	4.00		

Invoice Number	K7110	Date	12/23/2015	Mileage	115212	Job Value	33.27
Vehicle Details	JZF0823 PA DODGE DURANGO 2009						
Work Description	Checked steering and suspension all checks good. Drove for noise over speed bumps could not duplicate. Found radiator cap leaking coolant. Replaced radiator cap and refilled coolant.						
Labor	Value	Parts		Qty	Value		
noise over speed bumps	26.35	CNV7016 az Radiator Cap		1	4.92		

Invoice Number	K6991	Date	11/3/2015	Mileage	113551	Job Value	744.49
Vehicle Details	JZF0823 PA DODGE DURANGO 2009						
Work Description	Lube Oil Filter Changed NULL NULL NULL Replaced air filter Replaced front brakes front rotors and hardware kit. Exhaust clamp broke on muffler. Pushed muffler further back onto pipe and installed new clamps. Checked wipers and found switch is faulty. Replaced wipercomination switch. Replaced left front lower ball joint. Replaced left front outer tie rod. Mounted and balanced 4 new tires. Picked up tires at Highlands.						
Labor	Value	Parts		Qty	Value		
Service	26.35	CNVWWFlu Windshield Washer Fluid d		1	1.15		
State Emissions Inspection	21.08	CNV5w-30 Oil Petro		6	8.94		
Emissions Phone Transaction Fee	1.47	CNVPH2 Oil Filter BC		1	3.20		
State Inspection	31.62	CNVSA9762 air filter		1	10.50		
replace air filter	10.54	az					
Replace front brakes and rotors	52.70	CNV53005 Brake RotorDisc		2	48.64		
exhaust leak	31.62	az					
wipers not working on high speed	63.24	CNVVG108 front brakes		1	38.69		
replace left lower ball joint	105.40	4 az					
replace left tie rod	26.35	CNVH5780 hardware kit Q az		1	12.67		
replace tires	79.05	CNV17128 Exhaust Clamp az		2	6.80		
		CNVSW544 Combination Switch 5 az		1	81.17		

CNVK80765	Ball Joint advance	1	39.44
CNVES8003	Tie Rod 21 advance	1	31.87
CNV755056	P2457017 tire -Already paid for PO 383highland 153351	4	0.00

Invoice Number K6534 Date 5/1/2015 Mileage 107272 Job Value 43.13
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	26.35	CNVWWFluid Windshield Washer Fluid	1	1.15
		CNV5w-30 Oil	7	10.43
		Petro CNVPH2 Oil Filter	1	3.20
		BC		

Invoice Number K6337 Date 2/4/2015 Mileage 104051 Job Value 550.14
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Installed step bars on vehicle.
 NULL
 Removed climate control head. Installed 3 bulbs in control head.

Labor	Value	Parts	Qty	Value
install step bars on vehicle	105.40	CNV23-263 step bars	1	300.00
Replace blades	10.54	0 az		
climate control head will not illuminate	105.40	CNV26 A 26 Flex Wiper Blade	1	19.00
		AZ		
		CNVCWP20 Wiper Blade 20 Inch	1	7.20
		-51-CQ		
		CNVL194B Light Bulb 194	3	0.60
		X AZ		

Invoice Number K6274 Date 1/7/2015 Mileage 103591 Job Value 131.75
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Service call to Old prison. Jump start vehicle and bring back to garage.
 Check and charge battery. Battery checked good. looked for a drain on battery. Found rechargeable radio and flashlight were staying on after vehicle shut off. Rewired both so they shut off with key.

Labor	Value	Parts	Qty	Value
Service Call	52.70			
Check battery	79.05			

Invoice Number K6082 Date 10/8/2014 Mileage 101447 Job Value 228.81
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Lube Oil Filter Changed
 NULL
 NULL
 NULL
 replaced rear brakes
 Replaced left front outer tie rod.

Labor	Value	Parts	Qty	Value
Service	25.31	CNVWWFluid Windshield Washer Fluid	1	1.15
State Emissions Inspection	16.88	CNV5w-30 Oil	7	10.43
Emissions Phone Transaction Fee	1.47	Petro CNVPH2 Oil Filter	1	3.20
State Inspection	25.31	BC		
replace rear brakes	42.19	CNVVG967 rear brakes	1	30.59
replace left front tie rod end	42.19	az		
		CNVES8003 outer tie rod	1	26.09
		21 az		

Invoice Number K5696 Date 4/14/2014 Mileage 95734 Job Value 42.40
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	25.31	CNVWWFlu Windshield Washer Fluid	1	1.15
		CNV5w-30 Oil	6	10.74
		Petro		
		CNVPH2 Oil Filter	1	3.20
		BC		

Invoice Number K5478 Date 12/31/2013 Mileage 92455 Job Value 129.49
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description NULL

Labor	Value	Parts	Qty	Value
Change Battery	22.54	CNVMT65 Interstate Battery	1	104.95

Invoice Number K5423 Date 11/20/2013 Mileage 91185 Job Value 134.63
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description NULL
 NULL
 NULL
 NULL
 Replaced right front outer tie rod

Labor	Value	Parts	Qty	Value
State Emissions Inspection	18.03	CNV269-36 Tie Rod End	1	38.75
Emissions Phone Transaction Fee	1.47	33 napa		
State Inspection	27.05			
Rotate Tires	13.52			
right front outer tie rod has excessive play	33.81			

Invoice Number K5360 Date 10/16/2013 Mileage 89920 Job Value 43.98
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	27.05	CNVWWFlu Windshield Washer Fluid	1	0.99
		CNV5w-30 Oil	6	10.74
		Petro		
		CNVPH2 Oil Filter	1	3.20
		BC		

Invoice Number K5046 Date 5/17/2013 Mileage 84733 Job Value 18.03
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Hand washed car

Labor	Value	Parts	Qty	Value
wash car	18.03			

Invoice Number K5029 Date 5/7/2013 Mileage 84314 Job Value 169.69
 Vehicle Details JZF0823 PA DODGE DURANGO 2009
 Work Description Lube Oil Filter Changed
 NULL
 Replaced left front side marker bulb
 Replaced drivers seat cushion cover
 Removed running boards

Labor	Value
Service	27.05
Replace blades	11.27

bulb out	13.52	Petro			
replace drivers seat cover	56.35	CNVPH2	Oil Filter	1	3.20
remove running boards	22.54	BC			
		CNVCWP20	Wiper Blade 20 Inch	1	7.20
		-51-CQ			
		CNVDLF26	Wiper Blade 26 Flex	1	14.39
		AZ			
		CNVL194B	Light Bulb 194	1	0.44
		X AZ			
		CNV111111	cover-ALREADY paid for by DA	1	0.00
		11	Office		

Invoice Number K4737 Date 12/11/2012 Mileage 79410 Job Value 222.31

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description NULL
 NULL
 NULL
 NULL
 Lube Oil Filter Changed
 Replaced right front lower ball joint

Labor	Value	Parts	Qty	Value
State Emissions Inspection	16.24	CNVWWFlu	1	0.99
Emissions Phone Transaction Fee	1.47	d		
State Inspection	24.36	CNV5w-30	6	10.74
Rotate Tires	16.24	Petro		
Service	24.36	CNVPH2	1	3.20
ball joint has excessive play	81.20	BC		
		CNVPCH50	1	39.51
		5-1376 cq		

Invoice Number K4533 Date 9/4/2012 Mileage 75192 Job Value 59.13

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed
 replaced right front side marker bulb

Labor	Value	Parts	Qty	Value
Service	24.36	CNVPH2	1	2.50
right front side marker bulb	16.24	CNVWWFlu	1	0.99
		d		
		CNV5w-30	6	10.74
		Petro		
		CNV194	1	0.30
		CQ		

Invoice Number K4352 Date 5/29/2012 Mileage 70446 Job Value 173.10

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed
 NULL
 Replaced front brake pads.
 NULL
 NULL

Labor	Value	Parts	Qty	Value
Service	19.87	CNVPH2	1	2.50
Rotate Tires	13.24	CNVWWFlu	1	0.99
Check Brakes Replace front brake pads	33.11	d		
Replace blades	8.28	CNV5w-20	6	10.74
Replace Brake light bulb	9.93	PPC		
		CNVBMD10	1	53.24
		84 CQ		
		CNVRX3022	2	16.00
		1 AZ		
		CNV3157	1	1.20
		Light Bulb		

Invoice Number K4215 Date 2/29/2012 Mileage 64913 Job Value 34.48

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	19.87	CNVPH2 Oil Filter	1	2.50
		CNVWWFlu Windshield Washer Fluid	1	0.99
		CNV5w-20 Oil	6	9.12
		PPC		

Invoice Number K4101 Date 12/30/2011 Mileage 61770 Job Value 33.14

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description NULL
Emissions Inspection

Labor	Value	Parts	Qty	Value
State Inspection	18.08			
Emissions Inspection	15.07			

Invoice Number K3655 Date 5/23/2011 Mileage 50948 Job Value 69.01

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	18.08	CNVPH2 Oil Filter	1	2.50
Replace Tum Signal Bulb	9.04	CNVWWFlu Windshield Washer Fluid	1	0.99
Replace blades	7.53	CNV5w-20 Oil	6	9.12
		PPC		
		CNV3157 Light Bulb	1	1.75
		CNVCWP22 Windshield Wiper Blade -51-CQ	2	16.00

Invoice Number K3480 Date 2/16/2011 Mileage 45889 Job Value 151.44

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description NULL
Lube Oil Filter Changed
Replace all brake pads

Labor	Value	Parts	Qty	Value
Rotate Tires	7.53	CNVPH2 Oil Filter	1	2.50
Service	18.08	CNVWWFlu Windshield Washer Fluid	1	0.99
Check brakes	45.20	CNV5w-20 Oil	6	7.56
		PPC		
		CNVVG967 Brake Pads	1	31.19
		AZ		
		CNVVG108 Brake Pads	1	34.39
		4 AZ		

Invoice Number K2887 Date 3/30/2010 Mileage 26866 Job Value 31.71

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	19.42	CNVPH2 Oil Filter	1	2.50
		CNVWWFlu Windshield Washer Fluid	1	0.89
		CNV5w-20 Oil	6	6.90
		PPC		

Invoice Number K2754 Date 12/31/2009 Mileage 20384 Job Value 87.24

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
State Inspection	41.28			
Emissions Inspection	15.00			
Take Vehicle out to Middlesex Township to have Emissions Inspection done.	30.96			

Invoice Number K2568 Date 8/31/2009 Mileage 13281 Job Value 36.05

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	20.64	CNVPH2 Oil Filter	1	2.50
		CNVWWFlu Windshield Washer Fluid	1	0.89
		d		
		CNV5w-20 Oil	6	10.02
		PPC		

Invoice Number K2195 Date 1/30/2009 Mileage 0 Job Value 112.59

Vehicle Details JZF0823 PA DODGE DURANGO 2009

Work Description NULL

Labor	Value	Parts	Qty	Value
Take new battery to Middlesex Township to have battery replaced in new vehicle.	20.64	CNVMT-65 Interstate Battery	1	89.95
		INTER		

