Work History Report

Date Produced: 10/8/2024
Account: 6 Emergency Preparedness
Reg: 69467-MG PA
Vehicle Details CARRY ON TRAILER 2004

Cumberland County Courthouse
310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num TRAILER / **Vin** 4YMUKI0IXVH001639 **Mileage**

Invoice Number K11016 **Date** 11/9/2020 **Mileage** 0 **Job Value** 175.13
Vehicle Details 69467-MG PA CARRY ON TRAILER 2004
Work Description Bent mesh back into place and welded back on repainted gate and mesh

Labor	Value	Parts		Qty	Value
Re weld wire mesh onto trailer gate	159.15	CNV271915 AZ	Rust-Oleum Paint	2	13.98

Invoice Number K7413 **Date** 5/9/2016 **Mileage** 0 **Job Value** 415.17
Vehicle Details 69467-MG PA CARRY ON TRAILER 2004
Work Description Pick up new tires at highlands. Replaced tires.
Install new wiring and rear lights.
Greased and tightened wheel bearings. Replaced Right side bearing that was locked up.

Labor	Value	Parts		Qty	Value
Tires	58.94	CNV470225 Highland	2057515 Rubbermaster	2	118.98
Rewire trailer	117.88	CNVC7423 AZ	LED Light and wire Set	1	48.74
Grease wheel bearings	58.94	CNVSET13 AZ	Bearing	1	5.69