1-800-753-7566
www.ahequipment.com

A & H EQUIPMENT COMPANY

Remit To: 620 West Beaver St.
Zelienople, PA 16063
Phone: 412-257-1160
Fax: 412-257-4471

1405B Hagy Way
Harrisburg, PA 17110-9264
Phone: 717-724-0310
Fax: 717-724-0309

Ship to: SAME AS BELOW Actual Billed Invoice

Invoice to:
CITY OF ST MARYS
11 LAYFAYETTE STREET
ST MARYS PA 15857

Attention: Ike Kraus

Branch		
HARRISBURG	*REPRINT*	
Date	Time	Page
03/29/21	12:55:09 (B)	01
Account No.	Phone No.	Invoice No.
STMAR001	8147811718	X06188
Ship Via	Purchase Order	
Ike		
	Salesperson	
	JGS / JGS	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000077	2110	1311	06-05V-9880		
	2110	36276	2FZHAZDE26AW85287		

Payment Terms - Net 30 days

SEGMENT# 1 C JHERB NA 02/24/21 02/24/21
Rotec Bearing Concern
COMPLAINT:
Rotec Bearing Concern
CAUSE:
The Rotec bearing is bad and will need to be replaced.
Replace stop tooth blocks
CORRECTION:
Remove and replaced the Rotec Bearing and the stop tooth blocks. Replaced front and rear 5000 psi gauges.

45548H-30	BEARING,HARDENE	1	
	BEARING,HARDENED RAC		
46846D-30	GAUGE,PRESS,0-5	2	
	GAUGE,PRESS,0-5000PS		
		PARTS	851.16
		LABOR	1100.00
11000002		SEGMENT TOTAL==>	1951.16

SEGMENT# 2 C CUST NA 02/24/21 02/24/21
Debris Body Concern
COMPLAINT:
Float Ball Weldment Concern
CAUSE:
The weldments for the float ball cages are deteriorated and need to be replaced.
CORRECTION:
Remove float balls and screens, cut out damaged metal, prep

CONTINUED ON PAGE 02

Thank You.
Your business is appreciated!

Important Terms and Conditions appear on the Reverse Side or Page 2 hereof

PLEASE REMIT TO:
A & H Equipment Co.
620 West Beaver St.
Zelienople, PA 16063

A&H EQUIPMENT

1-800-753-7566

www.ahequipment.com

A & H EQUIPMENT COMPANY

Remit To: 620 West Beaver St.
Zelienople, PA 16063
Phone: 412-257-1160
Fax: 412-257-4471

1405B Hagy Way
Harrisburg, PA 17110-9264
Phone: 717-724-0310
Fax: 717-724-0309

Ship to: SAME AS BELOW

Invoice to:
CITY OF ST MARYS
11 LAYFAYETTE STREET
ST MARYS PA 15857

Attention: Ike Kraus

Branch		
HARRISBURG		
Date	Time	Page
03/29/21	12:55:09 (B)	02
Account No.	Phone No.	Invoice No.
STMAR001	8147811718	X06188
Ship Via	Purchase Order	
Ike		
	Salesperson	
	JGS / JGS	

SERVICE INVOICE

STK#/FLEET#			HRS	PIN/EIN	WARRANTY DATE	HRS
000077	2110		1311	06-05V-9880		
	2110		36276	2FZHAZDE26AW85287		

body and weld new weldments for the float ball in place.
Replace float ball housing and screens.

FRT	FREIGHT	1	
SUBLET	SP- WELDING	1	
48533D-30	RIVET INSERT,MO	8	N
59376D-30	FLOAT SEAT RING	2	N
62463-30	FLOAT BALL CAGE	4	
	FLOAT BALL CAGE SHRO		
63715F-30	FLOAT BALL CAGE	2	
	FLOAT BALL CAGE WELD		

	PARTS	1929.66
	LABOR	230.00
	SUBLET	274.21
11000002	SEGMENT TOTAL==>	2433.87

SEGMENT# 3 C JHERB NA 02/24/21 02/24/21
Evaluation
COMPLAINT:
Vactor Evaluation
CAUSE:
Customer requests a full evaluation on truck
CORRECTION:
Performed evaluation. Sent evaluation estimate of repairs to Ike.

	LABOR	399.00
11000002	SEGMENT TOTAL==>	399.00

SEGMENT# 4 C BARRY NA 03/19/21 03/19/21
Water System Concerns
COMPLAINT:

CONTINUED ON PAGE 03

Thank You.
Your business is appreciated!

Important Terms and Conditions appear on the Reverse Side or Page 2 hereof

PLEASE REMIT TO:
A & H Equipment Co.
620 West Beaver St.
Zelienople, PA 16063

A&H EQUIPMENT

1-800-753-7566

www.ahequipment.com

A & H EQUIPMENT COMPANY

Remit To: 620 West Beaver St.
Zelienople, PA 16063
Phone: 412-257-1160
Fax: 412-257-4471

14058 Hagy Way
Harrisburg, PA 17110-9264
Phone: 717-724-0310
Fax: 717-724-0309

Ship to: SAME AS BELOW

Invoice to:
CITY OF ST MARYS
11 LAYFAYETTE STREET
ST MARYS PA 15857

Attention: Ike Kraus

Branch		
HARRISBURG		
Date	Time	Page
03/29/21	12:55:09 (B)	03
Account No.	Phone No.	Invoice No.
STMAR001	8147811718	X061B8
Ship Via	Purchase Order	
Ike		
	Salesperson	
	JGS / JGS	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000077	2110	1311	06-05V-9880		
	2110	36276	2FZHAZDE26AW85287		

Per the evaluation the following items will need to be repaired or replaced.

CAUSE:
Both Y Strainer filters are bad and need replaced.
The Right Rear level sensor is leaking and needs to be repaired.

CORRECTION:
Removed level sensor cleaned and put pipe sealant on it and reinstalled it. Removed both 3" Y strainers and installed two new ones. Tested and verified repairs.

TEMCOM

41280-30	SCREEN,80 MESH,	2	
	SCREEN,80 MESH,3		
		PARTS	57.92
		LABOR	97.75
11000002		SEGMENT TOTAL==>	155.67

SEGMENT# 5 C BARRY NA 03/19/21 03/19/21
Leader Hose Concern

COMPLAINT:
Per the evaluation the following items will need to be repaired or replaced.

CAUSE:
The leader hose is worn and needs to be replaced

CORRECTION:
Removed and replaced new leader hose. Tested and verified repairs.

TEMCOM

LH1X10	LdHose,1"X10'	1	
		PARTS	188.04

CONTINUED ON PAGE 04

Thank You.
Your business is appreciated!

Important Terms and Conditions appear on the Reverse Side or Page 2 hereof

PLEASE REMIT TO:
A & H Equipment Co.
620 West Beaver St.
Zelienople, PA 16063

A&H EQUIPMENT

1-800-753-7566

www.ahequipment.com

A & H EQUIPMENT COMPANY

Remit To: 620 West Beaver St.
Zelienople, PA 16063
Phone: 412-257-1160
Fax: 412-257-4471

14058 Hagy Way
Harrisburg, PA 17110-9264
Phone: 717-724-0310
Fax: 717-724-0309

Ship to: SAME AS BELOW

Invoice to:
CITY OF ST MARYS
11 LAYFAYETTE STREET
ST MARYS PA 15857

Attention: Ike Kraus

Branch		
HARRISBURG		
Date	Time	Page
03/29/21	12:55:09 (B)	04
Account No.	Phone No.	Invoice No.
STMAR001	8147811718	X06188
Ship Via	Purchase Order	
Ike		
		Salesperson
		JGS / JGS

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000077	2110	1311	06-05V-9880		
	2110	36276	2FZHAZDE26AW85287		

LABOR 28.80

11000002 SEGMENT TOTAL==> 216.84

SEGMENT# 6 C BARRY NA 03/19/21 03/19/21

Hydraulic System Service

COMPLAINT:

Per the evaluation the following items will need to be repaired or replaced.

CAUSE:

The hydraulic system is due for a service. Change filters and oil.

CORRECTION:

Drained fluid and changed filter. Refilled with ISO 32. (55 gals). Tested and verified repairs.

TEMCOM

HYDRAULIC FLUID	HYDRAULIC FLUID	55	15.44	849.20
42431A-30	FILTER ELEMENT	1	147.55	147.55
			PARTS	996.75
			LABOR	129.95
11000002			SEGMENT TOTAL==>	1126.70

SEGMENT# 7 C BARRY NA 03/19/21 03/26/21

Hydraulic Leak Concern

COMPLAINT:

Per the evaluation the following items will need to be repaired or replaced.

CAUSE:

There is a hydraulic leak under the hydraulic tank, diag time will be needed to diagnose the leak. If additional time or parts are needed customer approval will be needed.

CONTINUED ON PAGE 05

Thank You.
Your business is appreciated!

Important Terms and Conditions appear on the Reverse Side or Page 2 hereof

PLEASE REMIT TO:
A & H Equipment Co.
620 West Beaver St.
Zelienople, PA 16063

1-800-753-7566
www.ahequipment.com

A & H EQUIPMENT COMPANY

Remit To: 620 West Beaver St.
Zelienople, PA 16063
Phone: 412-257-1160
Fax: 412-257-4471

1405B Hagy Way
Harrisburg, PA 17110-9264
Phone: 717-724-0310
Fax: 717-724-0309

Ship to: SAME AS BELOW

Invoice to: CITY OF ST MARYS
11 LAYFAYETTE STREET
ST MARYS PA 15857

Attention: Ike Kraus

Branch		
HARRISBURG		
Date	Time	Page
03/29/21	12:55:09 (B)	05
Account No.	Phone No.	Invoice No.
STMAR001	8147811718	X06188
Ship Via	Purchase Order	
Ike		
		Salesperson
		JGS / JGS

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000077	2110	1311	06-05V-9880		
	2110	36276	2FZHAZDE26AW85287		

CORRECTION:
Ran unit found that the transfer case is over full and is coming out of the breather.
TEMCOM

	LABOR	48.30
11000002	SEGMENT TOTAL==>	48.30

SEGMENT# 8 C BARRY NA 03/19/21 03/19/21
Transfer Case Concern
COMPLAINT:
Per the evaluation the following items will need to be repaired or replaced.
CAUSE:
The Transfer Case is due for a service. Remove and replace oil, and filter.
CORRECTION:
Performed transfer case service. Added 4 gals of ATF and replaced the filter. Tested and verified repairs.
TEMCOM

FRT	FREIGHT	1		
GEAR OIL	GEAR OIL	20		
48051AF-30	FILTER,OIL (480	1	N	
			PARTS	419.60
			LABOR	149.50
11000002			SEGMENT TOTAL==>	569.10

SEGMENT# 9 C BARRY NA 03/19/21 03/19/21
Marker Light Concern
COMPLAINT:
Per the evaluation the following items will need to be

CONTINUED ON PAGE 06

Thank You.
Your business is appreciated!

Important Terms and Conditions appear on the Reverse Side or Page 2 hereof

PLEASE REMIT TO:
A & H Equipment Co.
620 West Beaver St.
Zelienople, PA 16063

1-800-753-7566
www.ahequipment.com

A & H EQUIPMENT COMPANY

Remit To: 620 West Beaver St.
Zelienople, PA 16063
Phone: 412-257-1160
Fax: 412-257-4471

1405B Hagy Way
Harrisburg, PA 17110-9264
Phone: 717-724-0310
Fax: 717-724-0309

Ship to:
SAME AS BELOW

Invoice to:
CITY OF ST MARYS
11 LAYFAYETTE STREET
ST MARYS PA 15857

Attention: Ike Kraus

Branch		
HARRISBURG		
Date	Time	Page
03/29/21	12:55:09 (B)	06
Account No.	Phone No.	Invoice No.
STMAR001	8147811718	X06188
Ship Via	Purchase Order	
Ike		
	Salesperson	
	JGS / JGS	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000077	2110	1311	06-05V-9880		
	2110	36276	2PZHAZDE26AW85287		

repaired or replaced.
CAUSE:
The marker light lens is missing and needs to be replaced.
CORRECTION:
Installed new marker light cover. Tested and verified repairs.
TEMCOM

GRO/92183	YELLOW LENS	1 N	
		PARTS	7.41
		LABOR	8.05
11000002		SEGMENT TOTAL==>	15.46

SEGMENT#10 C BARRY NA 03/19/21 03/19/21
Chassis Concerns
COMPLAINT:
Per the evaluation the following items will need to be repaired or replaced.
CAUSE:
The left side mirror hear wires are disconnected.
Reconnect wires and check for functionality. Additional parts and labor may be needed.
There is an air leak. Find source of air leak and correct.
The turn signal assembly is not working as designed and needs to be replaced.
The front hub is leaking oil and needs to be replaced.
CORRECTION:
Removed and installed new turn signal assembly. Tested and verified operation.
Removed, cleaned, and installed new seals on front left hub. Topped off with 1qt of 80-90 gar oil. Removed left

CONTINUED ON PAGE 07

Thank You.
Your business is appreciated!

Important Terms and Conditions appear on the Reverse Side or Page 2 hereof

PLEASE REMIT TO:
A & H Equipment Co.
620 West Beaver St.
Zelienople, PA 16063

1-800-753-7566
www.ahequipment.com

A & H EQUIPMENT COMPANY

Remit To. 620 West Beaver St.
Zelienople, PA 16063
Phone: 412-257-1160
Fax: 412-257-4471

1405B Hagy Way
Harrisburg, PA 17110-9264
Phone: 717-724-0310
Fax: 717-724-0309

Ship to: SAME AS BELOW

Invoice to: CITY OF ST MARYS
11 LAYFAYETTE STREET
ST MARYS PA 15857

Attention: Ike Kraus

Branch		
HARRISBURG		
Date	Time	Page
03/29/21	12:55:09 (B)	07
Account No.	Phone No.	Invoice No.
STMAR001	8147811718	X06188
Ship Via	Purchase Order	
Ike		
	Salesperson	
	JGS / JGS	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000077	2110	1311	06-05V-9880		
	2110	36276	2FZHAZDE26AW85287		

side mirror and found out it is not a heated mirror. Put mirror back on truck. Found the air leak on the air tank marked 12. Fixed the leak and verified repairs.

TEMCOM

A06-32389-001	SWITCH TURN SIG	1	N
STM/330-3122	GASKET HUB	2	N

PARTS	363.61
LABOR	525.00
11000002 SEGMENT TOTAL==>	888.61

SEGMENT#11 C CUST DELETED 03/19/21 03/19/21
Float Ball Weldment Concern

SEGMENT#12 C BARRY DELETED 03/19/21 03/19/21
Pressure Gauge Concerns
CAUSE:
Pressure gauges are not working

****** WORK ORDER TOTALS ******	
PARTS	4814.15
LABOR	2716.35
SUBLET	274.21
SHOP SUPPLIES	262.16
TOTAL CHARGE	8066.87

Thank You.
Your business is appreciated!

Important Terms and Conditions appear on the Reverse Side or Page 2 hereof

PLEASE REMIT TO:
A & H Equipment Co.
620 West Beaver St.
Zelienople, PA 16063