

CUSTOMER #: 987653

325046



INVOICE

Shaler Township Police
300 Wetzel Road
Glenshaw, PA 15116

PAGE 1

110-112 RT. 908
NATRONA HEIGHTS, PA 15065
FORD (724) 294-2000
CHRYSLER JEEP DODGE (724) 295-5000
www.cochran.com

HOME: CONT:724-294-2000
BUS: CELL:724-294-2000 SERVICE ADVISOR: 996572 AMANDA ANDERSON

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG. Includes details for a 2021 Ford Explorer Hybrid.

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Includes dates for 01JAN21 IS and 01JAN21 DD.

Table with columns: R.O. OPENED, READY, OPTIONS: DLR:07320. Includes times 08:34 and 16:02.

Main service list table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists various charging system repairs and parts.

PARTS: 1462.63 LABOR: 1978.02 OTHER: 0.00 TOTAL LINE A: 3440.65
verified concern charging system message on dash, retrieved cmdtc's b1ld9 - battery fault, referenced ssm 15650 to inspect F208 125amp fuse in high voltage battery junction box, depowered system and removed fuse and tested, good fuse, positioned vehicle on lift and inspected connector 1168 as per ssm direction and found c1168 swollen with green corrosion on both side of connector, rear aux battery harness and front portion of harness needed for connector replacement. disassembled vehicle and replaced aux battery harness and secondary engine harness for corrosion at c1168, cleared dtc's, performed battery monitoring system reset, performed road test, performed self test after repairs will all systems pass, verified repairs.

B PERFORM VEHICLE CHECK UP
99P PERFORM VEHICLE CHECK UP
996604 ISDP (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

Bottom section table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes a disclaimer on behalf of the servicing dealer and a 'PLEASE PAY THIS AMOUNT' section.