

Work History Report

Cumberland County
Courthouse

Date Produced: 8/29/2024
Account: 27 Juvenile Probation
Reg: JUV1 PA
Vehicle Details CHEVY EQUINOX 2.4 2011
silver

310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num 2.4L ECOTEC / Vin 2CNFLCEC3B6445103 Mileage 154963

Invoice Number I003197 Date 5/10/2024 Mileage 154963 Job Value 124.20

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Shop Labor- Cumberland County. Checked ses codes, has code p0420, catalyst system low efficiency. Checked code diagnostics. Replaced downstream oxygen sensor and test drove. Light stayed off.	77.21	CNV21068 Oxygen Sensor	1	44.99

Invoice Number I003112 Date 4/1/2024 Mileage 154063 Job Value 132.42

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	33.09	CNVWWFluid Clearv Windshield Washer Fluid	1	1.32
Rotate Tires	16.55	CNV75-053 5W30 Oil syn blend	6	14.03
State Inspection	33.09	CNVEMI Emissions, Phone Transaction Fee	1	1.57
State Emission Inspection	27.58	CNV9018R Oil Filter	1	3.19

Invoice Number I002945 Date 1/4/2024 Mileage 151547 Job Value 68.18

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Shop Labor- Cumberland County. Light was off now. Checked for abs codes, had history code U0100-71 lost communication with TCM and ECM. Cleaned wire connectors and grounds to abs module.	66.18			

Invoice Number I002772 Date 9/29/2023 Mileage 148785 Job Value 157.25

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Shop Labor- Cumberland County. Check engine and low power lights on. Checked for codes, has code p2138 -00, APP sensor 1-2 not plausible and ebcm code U0100-71 lost communication with ecm. Checked all connectors in APP sensor circuit, took connectors x112, x206, B107, ECM and BCM connectors apart to clean and applied dielectric grease to all. Also took ground wires off and cleaned. Cleared codes and test drove.	155.25			

Invoice Number I002758 Date 9/25/2023 Mileage 148717 Job Value 55.51

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	31.05	CNVWWFluid Clearv Windshield Washer Fluid	1	1.32
		CNV75-053 5W30 Oil syn blend	5	15.90
		CNV84082 Oil Filter	1	5.24

Invoice Number I002518 Date 5/24/2023 Mileage 145087 Job Value 861.90

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
State Emission Inspection	25.88	CNVEMI Emissions, Phone Transaction Fee	1	1.57
State Inspection	31.05	CNV110488 Goodyear Assur MaxLife 235/60R17 545	4	478.28
Shop Labor- Cumberland County. Mounted and balanced all 4 tires. Went to Highlands to pick up tires.	103.50	CNV333333 Wheel Weights	8	8.00
Shop Labor- Cumberland County. Replaced front brakes and rotors.	77.63	CNV142 Front Brakes	1	28.99
		CNV72006 Brake Rotor	2	91.00
		CNVTIRE Tire Disposal Fee	4	14.00
		DISPOSAL		

Invoice Number I002353 Date 2/28/2023 Mileage 143317 Job Value 71.92

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	41.40	CNVWWFlu Windshield Washer Fluid	1	1.20
		d Clearv		
		CNV75-053 5W30 Oil syn blend	6	19.08
		CNV84082 Oil Filter	1	5.24
		CNVDL13 Rear Wiper	1	3.00

Invoice Number I001920 Date 7/5/2022 Mileage 138094 Job Value 75.38

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Check engine light on, no drivability issues. Found P2138 Throttle pedal position sensor correlation, stored in PCM.	75.38			
Found no issues with pedal assembly, removed all connectors to PCM and throttle assembly. Unable to get vehicle to act up again.				

Invoice Number I001858 Date 6/3/2022 Mileage 137573 Job Value 148.52

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
PM Service, Check Lights, Brakes and overall safety of vehicle	30.15	CNV0w-20- Oil	5	18.95
Rotate Tires	15.08	stpsyn AZ		
State Emission Inspection	25.13	CNVWWFlu Windshield Washer Fluid	1	1.20
State Inspection	30.15	d Clearv		
Shop Labor- Cumberland County. Reconditioned headlamps. Lens were getting discolored.	20.10	CNVEMI Emissions, Phone Transaction Fee	1	1.57
		CNV84082 Oil Filter	1	4.19

Invoice Number I001708 Date 3/9/2022 Mileage 135303 Job Value 102.50

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Shop Labor- Cumberland County. Checked for ses codes. Has code p2138 throttle pedal sensor voltage correlation. Checked wiring from pcm to throttle position sensor. Took all connectors apart in circuit to clean and applied dielectric grease to connectors and pcm connectors. Cleaned throttle bore and relearned idle. Cleared code and test drove. No issues.	100.50			

Invoice Number I001648 Date 2/3/2022 Mileage 134988 Job Value 22.05

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Replaced wiper blades.	10.05	CNVDLF24 Wiper Blade	1	6.00
		CNVDLF17 Wiper Blade	1	6.00

Invoice Number I001647 Date 2/3/2022 Mileage 134988 Job Value 225.43

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Reduced power and check engine light on, check ecm and found code P2138 throttle pedal position switch D/E voltage correlation. Found sensors in pedal assembly faulty, replaced throttle pedal assembly and test drove to verify vehicle is fixed	125.63	CNV840225 Throttle Pedal Assembly 79	1	97.80

Invoice Number I001566 Date 12/15/2021 Mileage 134023 Job Value 121.17

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Shop Labor- Cumberland County. Checked for codes, has code P15A1-00 fuel economy mode switch error. Diagnosed trouble code. Found switch faulty. Replaced fuel economy mode switch and cleared code.	92.04	CNV207671 Switch -fuel economy mode 21	1	29.13

Invoice Number I001447 Date 10/12/2021 Mileage 132916 Job Value 266.58

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
Complaint of exhaust being loud. Found exhaust manifold had cracked, R&R exhaust manifold.	184.08	CNV674940 Exhaust Manifold	1	80.50

Invoice Number I001376 Date 8/31/2021 Mileage 132142 Job Value 119.67

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	27.61	CNV5w-30 Oil PPC	5	10.75
Replaced air and cabin filters.	27.61	CNVWWFluid Clearv	1	1.15
Shop Labor- Cumberland County. Checked tire for leaks, leaking around rim. Removed tire and cleaned corrosion off rim. Mounted tire.	27.61	CNV84082 Oil Filter	1	4.19
		CNV83727 Air Filter	1	11.19
		CNV6057C Cabin Filter	1	7.56

Invoice Number I001161 Date 5/10/2021 Mileage 129792 Job Value 372.92

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Labor	Value	Parts	Qty	Value
State Inspection	27.61	CNVEMI Emissions, Phone Transaction Fee	1	1.57
State Emission Inspection	23.01	CNVSBK75 RF Sway bar link 0189	1	37.06
Clunk noise from LF found sway bar links had play. Replaced LF and RF sway bar links	69.03	CNVSBK75 LF Sway bar link 0188	1	38.96
Checked condition of battery as it was original, tested weak replaced with new battery	46.02	CNV47-775 East Penn Battery	1	127.66

Invoice Number K10949 Date 10/2/2020 Mileage 127482 Job Value 43.83

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Labor	Value	Parts	Qty	Value
Service	26.53	CNVWWFluid Windshield Washer Fluid	1	1.15
		CNV5w-30 Oil Petro	5	10.75
		CNVR84082 Oil Filter advance	1	3.40

Invoice Number K10831 Date 8/11/2020 Mileage 126229 Job Value 455.03

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Replaced LF Wheel speed sensor and bearing. Found tone ring broke on wheel bearing damaging the wheel speed sensor.
Found Transmission Lines Rusted Through From Trans To Radiator Replaced Both

Labor	Value	Parts	Qty	Value
ABS Light Coming On	132.63	CNV914231 LF Wheel bearingHub assembly	1	109.49
Fluid Leak	79.58	57ADV		
		CNV208113 LF Wheel speed sensor	1	47.95
		72GRAHAM		
		CNV234671 Transmission Cooler Line	1	40.83
		81GRAHAM		
		CNV234671 Transmission Cooler Line	1	40.56
		82GRAHAM		

Invoice Number K10643 Date 5/13/2020 Mileage 124637 Job Value 477.59

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Checked codes has code P0013. Replaced both variable valve timing solenoids and cleared code.
Replaced spark plugs
NULL
NULL
State Inspection
Replaced rear brakes rotors and hardware kit.

Labor	Value	Parts	Qty	Value
Check engine light is on	79.58	CNV126790 Variable Timing Solenoid	1	34.01
Replace spark plugs	53.05	99 az		
State Emissions Inspection	21.22	CNV126791 Variable Timing Solenoid	1	34.01
Emissions Phone Transaction Fee	1.57	00 az		
State inspection	31.83	CNV41-108 Spark Plug	4	28.76
Replace rear brakes and rotors	79.58	az		
		CNVH5813 Brake Hardware Kit	1	6.91
		Q az		
		CNVVG127 Brake Pads	1	27.30
		5 az		
		CNV72010D Brake RotorDisc	2	75.78
		G az		

Invoice Number K10367 Date 12/18/2019 Mileage 122774 Job Value 126.04

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL

Labor	Value	Parts	Qty	Value
Service	27.63	CNVWWFlu Windshield Washer Fluid	1	1.15
Rotate Tires	16.58	d		
		CNV5w-30 Oil	6	12.90
		Petro		
		CNV59018R Oil Filter Equinox	1	4.39
		AZ		
		CNV611236 Lug Nuts	20	61.40
		ADV		

Invoice Number K10044 Date 7/15/2019 Mileage 119004 Job Value 274.52

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Checked for transmission and engine codes none. Test drove to check transmission operation.
Transmission checks out normal but heard a loud grinding noise coming from front wheel bearings.
Checked wheel bearings and found right front wheel bearing is out.

Labor	Value	Parts	Qty	Value
Check transmission felt funny like its stuck in a high gear.	138.13	CNV513288 Wheel Hub and bearing advance	1	134.39

Invoice Number K9929 Date 5/29/2019 Mileage 117604 Job Value 538.71

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

NULL

NULL

State Inspection

Charged ac system and added dye. Checked for leaks and found condenser leaking. Replaced ac condenser. Evacuated and recharged ac system.

Labor	Value	Parts	Qty	Value
Service	27.63	CNVWWFluid Windshield Washer Fluid	1	1.15
State Emissions Inspection	22.10	CNV5w-30 Oil	6	11.16
Emissions Phone Transaction Fee	1.65	Petro		
State inspection	33.15	CNVS9018R Oil Filter Chevy Equinox AZ	1	4.45
AC is blowing warm air	276.25	CNV208397 Condenser 94 carlisle	1	131.99
		CNV524743 Seal 73 carlisle	2	10.20
		CNVR134A Refrigerant Per Pound AZ	3	9.99
		CNV11111 Refrigerant oil dye	1	4.99

Invoice Number K9663 Date 2/5/2019 Mileage 114112 Job Value 27.63

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Checked tire could not find any leaks

Labor	Value	Parts	Qty	Value
Check for tire leaking	27.63			

Invoice Number K9582 Date 1/4/2019 Mileage 113500 Job Value 61.94

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

NULL

Labor	Value	Parts	Qty	Value
Service	27.63	CNVWWFluid Windshield Washer Fluid	1	1.15
Rotate Tires	16.58	CNV5w-30 Oil	5	10.20
		Petro		
		CNVS9018R Oil Filter Equinox AZ	1	4.39

Invoice Number K9351 Date 9/18/2018 Mileage 108333 Job Value 44.89

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Labor	Value	Parts	Qty	Value
Service	28.10	CNVWWFluid Windshield Washer Fluid	1	1.15
		CNV5w-30 Oil	5	9.25
		Petro		
		CNVS9018R Oil Filter Equinox AZ	1	4.39

Invoice Number K9099 Date 5/30/2018 Mileage 103116 Job Value 351.10

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Replaced air filter

Rotated tires and replaced 3 rusted lug nuts.

Replaced front brakes brake hardware kit and rotors

NULL

NULL

State Inspection

Labor	Value
Service	28.10

replace air filter	11.24	d	CNV5w-30 Oil	5	9.25
Rotate Tires	16.86		Petro		
replace front brakes and rotors	84.30		CNVS9018R Oil Filter Chevy Equinox AZ	1	4.39
State Emissions Inspection	22.48		CNVSA1046 Air Filter	1	18.99
Emissions Phone Transaction Fee	1.65		5 az		
State inspection	33.72		CNV611-23 Wheel Nut	3	14.97
			6.1 az		
			CNV611-23 Front Brakes	1	26.15
			1 az		
			CNV72006D Brake RotorDisc	2	58.86
			G az		
			CNVH5838 Brake Hardware Kit	1	14.99
			Q az		

Invoice Number K8756 **Date** 1/5/2018 **Mileage** 97353 **Job Value** 61.30

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety. Checked all tires for leaks. Right rear tire was 27psi. Replaced tire valve core in right rear tire.

Labor	Value	Parts	Qty	Value
Service	28.10	CNVWWFlu Windshield Washer Fluid	1	1.15
Low tire light coming on	16.86	d		
		CNV5w-30 Oil	5	8.80
		Petro		
		CNVS9018R Oil Filter Chevy Equinox AZ	1	4.39

Invoice Number K8391 **Date** 8/4/2017 **Mileage** 92547 **Job Value** 62.61

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety. NULL

Labor	Value	Parts	Qty	Value
Service	28.86	CNVWWFlu Windshield Washer Fluid	1	1.15
Rotate Tires	17.32	d		
		CNV5w-30 Oil	6	8.94
		Petro		
		CNVS9018R Oil Filter Chevy Equinox AZ	1	4.34

Invoice Number K8204 **Date** 5/10/2017 **Mileage** 88354 **Job Value** 159.80

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description NULL
NULL
State Inspection
Replaced cabin air filter
Changed transmission fluid.

Labor	Value	Parts	Qty	Value
State Emissions Inspection	23.09	CNVCAF18 Cabin Air Filter	1	7.49
Emissions Phone Transaction Fee	1.65	17P az		
State inspection	34.63	CNV06822 castrol dextron 6 az	5	27.45
replace cabin air filter	17.32			
Change transmission fluid	46.18			

Invoice Number K8123 **Date** 4/6/2017 **Mileage** 85850 **Job Value** 40.71

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Replaced wiper blades

Labor	Value	Parts	Qty	Value
replace wiper blades	5.77	CNV228684 Wiper Blade	1	17.47
		13 carlisle		
		CNV228684 Wiper Blade	1	17.47
		14 carlisle		

Invoice Number K8101 Date 3/24/2017 Mileage 85666 Job Value 82.32

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
plugged hole in tire right rear tire had a nail in it
Rotated tires and relearned tire pressure sensors

Labor	Value	Parts	Qty	Value
Service	28.86	CNVWWFlu Windshield Washer Fluid	1	1.15
plug tire	14.43	CNV5w-30 Oil	5	7.45
Rotate Tires	23.09	Petro CNVS9018R Oil Filter	1	4.34
		CNV710-10 tire plug 36 Napa	1	1.00

Invoice Number K7894 Date 12/12/2016 Mileage 80672 Job Value 63.02

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL

Labor	Value	Parts	Qty	Value
Service	29.12	CNVWWFlu Windshield Washer Fluid	1	1.15
Rotate Tires	17.47	CNV5w-30 Oil	6	8.94
		Petro CNVS9018R Oil Filter AZ	1	4.34

Invoice Number K7594 Date 7/27/2016 Mileage 74983 Job Value 450.70

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed
Replaced cracked exhaust manifold gasket and O2 Sensor

Labor	Value	Parts	Qty	Value
Service	29.12	CNVWWFlu Windshield Washer Fluid	1	1.15
Exhaust Leak	232.96	CNV5w-30 Oil	6	8.94
		Petro CNVPH2 Oil Filter BC	1	3.47
		CNV126098 Manifold 23 Graham	1	89.60
		CNV245050 Gasket 57	1	12.21
		CNV126226 Gasket 68	1	8.49
		CNV234-42 Oxygen Sensor 42	1	60.76

Invoice Number K7502 Date 6/16/2016 Mileage 73127 Job Value 942.36

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description NULL
NULL
NULL
Replaced front brakes.
Replaced rear brakes and rotors
Replaced all 4 tires.

Labor	Value	Parts	Qty	Value
State Inspection	34.94	CNVDG142 Brake Pads 1 Az	1	27.99
State Emissions Inspection	23.30	CNVDG127 Brake Pads	1	27.99
Emissions Phone Transaction Fee	1.47	5 AZ		
Front brakes	58.24	CNV72010 Rotors Az	2	75.24
Rear brakes	116.48	CNV755032 Goodyear Assurance. 2356017 383	4	466.04
All Tires	101.92	Highland CNV2222 Wheel Weights	1	2.75

Invoice Number K7272 Date 3/7/2016 Mileage 70397 Job Value 42.93

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	29.47	CNVWWFlu Windshield Washer Fluid	1	1.15
		d		
		CNV5w-30 Oil	5	7.45
		Petro		
		CNVAL9018 Oil Filter	1	2.86
		AZ		

Invoice Number K6580 Date 5/19/2015 Mileage 58960 Job Value 93.58

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

NULL

NULL

NULL

Labor	Value	Parts	Qty	Value
Service	26.35	CNVWWFlu Windshield Washer Fluid	1	1.15
State Emissions Inspection	21.08	d		
Emissions Phone Transaction Fee	1.47	CNV5w-30 Oil	5	7.45
State Inspection	31.62	Petro		
		CNVAL9018 Oil Filter	1	2.46
		az		

Invoice Number K6294 Date 1/14/2015 Mileage 53020 Job Value 65.76

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

NULL

Labor	Value	Parts	Qty	Value
Service	31.62	CNVWWFlu Windshield Washer Fluid	1	1.15
Rotate Tires	21.08	d		
		CNV5w-30 Oil	5	7.45
		Petro		
		CNVAL9018 Oil Filter	1	2.46
		AZ		

Invoice Number K5948 Date 8/5/2014 Mileage 45898 Job Value 65.75

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

Replaced Air Filter

Labor	Value	Parts	Qty	Value
Service	25.31	CNVWWFlu Windshield Washer Fluid	1	1.15
Replace air filter	10.55	d		
		CNV5w-30 Oil	5	7.45
		Petro		
		CNVAL9018 Oil Filter	1	2.46
		Az		
		CNVSA1046 Air Filter	1	16.83
		5 Az		

Invoice Number K5777 Date 5/21/2014 Mileage 42033 Job Value 26.19

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Replaced rear wiper blade

Checked front wiper blades blades are still in good condition. Cleaned front wiper blades and cleaned bugs off windshield.

Labor	Value	Parts	Qty	Value
replace rear wiper blade	10.55	CNVCWP20 Wiper Blade	1	7.20
check front wipers	8.44	-51-CQ		

Invoice Number K5724 Date 4/29/2014 Mileage 40734 Job Value 94.08

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

NULL
NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	25.31	CNVWWFlu Windshield Washer Fluid	1	1.15
Rotate Tires	10.55	CNV5w-30 Oil	5	8.95
State Emissions Inspection	16.88	Petro		
Emissions Phone Transaction Fee	1.47	CNVAL9018 Oil Filter	1	2.46
State Inspection	25.31	az		

Invoice Number K5482 Date 1/6/2014 Mileage 35059 Job Value 59.48

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

NULL

Labor	Value	Parts	Qty	Value
Service	27.05	CNVWWFlu Windshield Washer Fluid	1	0.99
Rotate Tires	18.03	CNV5w-30 Oil	5	8.95
		Petro		
		CNVAL9018 Oil Filter	1	2.46
		az		

Invoice Number K5210 Date 8/5/2013 Mileage 29455 Job Value 45.03

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Replaced both wiper blades

Labor	Value	Parts	Qty	Value
replace wipers	11.27	CNV228684 Wiper Blade	1	16.88
		13 graham		
		CNV228684 Wiper Blade	1	16.88
		14 graham		

Invoice Number K5119 Date 6/20/2013 Mileage 27324 Job Value 46.87

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	27.05	CNVWWFlu Windshield Washer Fluid	1	0.99
		CNV5w-30 Oil	5	8.95
		Petro		
		CNV7082 Oil Filter	1	7.88
		napa		

Invoice Number K4956 Date 4/11/2013 Mileage 22046 Job Value 104.69

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

NULL
NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	27.05	CNVWWFlu Windshield Washer Fluid	1	0.99
State Emissions Inspection	18.03	CNV5w-30 Oil	5	8.95
Emissions Phone Transaction Fee	1.47	Petro		
State Inspection	27.05	CNV7082 Oil Filter	1	7.88
Rotate Tires	11.27	napa		

Invoice Number K4566 Date 9/20/2012 Mileage 15694 Job Value 60.42

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed
NULL

Labor	Value	Parts	Qty	Value
Service	24.36	CNV7082 Oil Filter	1	7.88
Rotate Tires	16.24	napa CNVWWFlu d CNV5w-30 Petro	1	0.99
		Windshield Washer Fluid		
		Oil	5	8.95

Invoice Number K4407 Date 6/29/2012 Mileage 13211 Job Value 35.51

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description NULL
Emissions Inspection
NULL

Labor	Value	Parts	Qty	Value
State Inspection	19.87			
Emissions Inspection	13.24			
Emissions Phone Transaction Fee	2.40			

Invoice Number K4153 Date 1/26/2012 Mileage 9472 Job Value 49.43

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed
NULL

Labor	Value	Parts	Qty	Value
Service	19.87	CNVWWFlu d CNV5w-20 PPC	1	0.99
Rotate Tires	13.24	Oil	5	6.84
		CNVPF-457 G AZ	1	6.49
		Oil Filter		

Invoice Number K3939 Date 10/24/2011 Mileage 5119 Job Value 32.69

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	18.08	CNVPH2 Oil Filter	1	2.50
		CNVWWFlu d CNV5w-20 PPC	1	0.99
		Windshield Washer Fluid		
		Oil	6	9.12

Invoice Number K3940 Date 10/4/2011 Mileage 5119 Job Value 38.07

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	18.08	CNV7082 Oil Filter	1	7.88
		CNVWWFlu d CNV5w-20 PPC	1	0.99
		Windshield Washer Fluid		
		Oil	6	9.12

Invoice Number K3400 Date 12/29/2010

Mileage 135609

Job Value 225.17

Vehicle Details JUV1 PA CHEVY EQUINOX 2011

Work Description Lube Oil Filter Changed

NULL

NULL

NULL

replace rear rotors

check for nosie

Labor

Value

Parts

Qty

Value

Service	19.42
State Inspection	29.13
Emissions Inspection	15.00
Take Vehicle to Middlesex Township to have Emissions Inspection Done	29.13
replace rear rotors	38.84
check for nosie	19.42

CNVPH2	Oil Filter	1	2.50
CNVWWFlu	Windshield Washer Fluid	1	0.99
d			
CNV5w-20	Oil	6	7.56
PPC			
CNV426505	rotor	2	59.18