Work History Report

Date Produced: 1/21/2025
Account: 28 Adult Probation
Reg: ADU10 PA
Vehicle Details DODGE CHARGER 3.5 2009

Cumberland County Courthouse
310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num V6 3.5L 3497CC 215CID FI GAS N / **Vin** 2B3KK43V69H578793 **Mileage** 100809

Invoice Number I003034 **Date** 2/20/2024 **Mileage** 100809 **Job Value** 62.24
Vehicle Details ADU10 PA DODGE CHARGER 2009

Labor	Value
State Inspection	33.09
State Emission Inspection	27.58

Parts		Qty	Value
CNVEMI	Emissions, Phone Transaction Fee	1	1.57

Invoice Number I002422 **Date** 3/31/2023 **Mileage** 100113 **Job Value** 132.30
Vehicle Details ADU10 PA DODGE CHARGER 2009

Labor	Value
PM Service check lights,brake and overall safety of vehicle	31.05
State Emission Inspection	25.88
State Inspection	31.05
Shop Labor- Cumberland County. Replaced right rear outer brake light bulb.	15.53

Parts		Qty	Value
CNV85372 advance	Oil Filter	1	3.95
CNVWWFliud Clearv	Windshield Washer Fluid	1	1.20
CNV75-053	5W30 Oil syn blend	6	19.08
CNVEMI	Emissions, Phone Transaction Fee	1	1.57
CNV3157	Light Bulb	1	0.99

Invoice Number I002256 **Date** 1/9/2023 **Mileage** 99815 **Job Value** 16.35
Vehicle Details ADU10 PA DODGE CHARGER 2009

Labor	Value
Replaced wiper blades.	10.35

Parts		Qty	Value
CNVDL22 / az	Wiper Blade	2	6.00

Invoice Number I001775 **Date** 4/11/2022 **Mileage** 99343 **Job Value** 575.25
Vehicle Details ADU10 PA DODGE CHARGER 2009

Labor	Value
PM Service check lights,brake and overall safety of vehicle	30.15
Rotate Tires	15.08
State Inspection	30.15
State Emission Inspection	25.13
Washers not spraying, removed hood insulation and found both nozzles broken. Installed new nozzles and replaced hood insulation clips	30.15
Front sway bar links clunking, found joints to have movement. Replaced and greased	50.25
Rear shocks blown and sway bar links worn out. R&R links and shocks.	75.38

Parts		Qty	Value
CNV85372 advance	Oil Filter	1	3.14
CNV5w-30 PPC	Oil	6	11.94
CNVWWFliud Clearv	Windshield Washer Fluid	1	1.20
CNVEMI	Emissions, Phone Transaction Fee	1	1.57
CNV58115	Washer Nozzles	1	17.09
CNV700-576	Retaining Clips	9	6.30
CNVSBK750154	Front Sway Bar Link	2	72.04
CNV34460	Rear Shock Absorber	2	111.54
CNVSBK7470	Rear Sway Bar Link Kit	2	43.02
CNVSM5533	Rear Shock Mount Kit	2	49.12

Invoice Number I001406 **Date** 9/17/2021 **Mileage** 98891 **Job Value** 23.01
Vehicle Details ADU10 PA DODGE CHARGER 2009

Labor	Value

Shop Labor- Cumberland County. Trunk will not latch. Removed cover on trunk latch. Latch emergency release handle was stuck. lubed latch and handle. Trunk latches now.	23.01	

Invoice Number I001111 **Date** 4/9/2021 **Mileage** 98722 **Job Value** 640.92

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description RF Tire had wear on inside edge, took vehicle to Carlisle Cadillac to have aligned, 4 wheel alignment was done

Labor	Value
State Emission Inspection	23.01
State Inspection	27.61
PM Service check lights,brake and overall safety of vehicle	27.61
Mount and balance 4 tires, picked up tires at highlands, replaced 1 aluminum valve stem corroded badly and broke upon disassembly	92.04

Parts		Qty	Value
CNVEMI	Emissions, Phone Transaction Fee	1	1.57
CNV85372 advance	Oil Filter	1	3.14
CNV5w-30 PPC	Oil	6	12.90
CNVWWFliu d Clearv	Windshield Washer Fluid	1	1.15
CNV37576	Uniroyal TP Touring 225/60/18	4	354.96
CNV33333	TIRE DISPOSAL FEE	4	8.00
CNV609-14 2	Valve Stem Kit	1	12.98
CNV333333 3333	Took Car to Calirlisle cadillac for alignment	1	69.95
CNV333333	Wheel Weights	8	4.00

Invoice Number K10588 **Date** 4/9/2020 **Mileage** 96505 **Job Value** 319.35

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL
NULL
NULL
State Inspection
Replaced rear brakes and rotors.

Labor	Value
Service	26.53
Rotate Tires	15.92
State Emissions Inspection	21.22
Emissions Phone Transaction Fee	1.57
State inspection	31.83
Replace rear brakes and rotors	79.58

Parts		Qty	Value
CNVWWFliu d	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	6	12.90
CNV85372 advance	Oil Filter	1	3.14
CNVYH1455 68P advance	Brake RotorDisc	2	88.38
CNVGMKD1 057 advance	Brake Pads	1	33.14

Invoice Number K10068 **Date** 7/25/2019 **Mileage** 95259 **Job Value** 27.63

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Checked tire for leaks. Found tire leaking around rim. Removed tire and cleaned corrosion off rim seats. Installed tire.

Labor	Value
Left front tire loosing air	27.63

Parts	Qty	Value

Invoice Number K9763 **Date** 3/19/2019 **Mileage** 95531 **Job Value** 154.10

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description State Inspection
NULL
NULL
Replaced RF outter tie rod end.

Labor	Value
State inspection	33.15
State Emissions Inspection	22.10

Emissions Phone Transaction Fee	1.65
Tie Rod End	55.25

Invoice Number K9643 **Date** 1/29/2019 **Mileage** 95327 **Job Value** 195.42

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Went to Courthouse to jump start car and drive back to garage.
Replaced battery cleaned cables and installed jack and spare tire back into trunk correctly.

Labor	Value
Service Call	41.44
Battery is dead	41.44

Parts		Qty	Value
CNV49H8 advance	Battery	1	110.54

Invoice Number K8966 **Date** 3/29/2018 **Mileage** 94569 **Job Value** 177.78

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description State Inspection
NULL
NULL
Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
Removed 2 front tires removed tires. Cleaned bead area from corrosion. Replaced broken valve stems on tire sensors.

Labor	Value
State inspection	33.72
State Emissions Inspection	22.48
Emissions Phone Transaction Fee	1.65
Service	28.10
Tires Loosing air.	56.20

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	6	11.10
CNVPH2 BC	Oil Filter	1	3.31
CNV917325	Oil Level Dipstick	1	11.99
CNV20020	TPMS Service Pack	1	2.19
CNV20016	Cap	1	1.89

Invoice Number K8092 **Date** 3/22/2017 **Mileage** 93215 **Job Value** 28.86

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Checked window. Unjammed window. Lubed window tracks and latch. Window slides freely now.

Labor	Value
Sliding window in security cage wont slide	28.86

Parts		Qty	Value

Invoice Number K7979 **Date** 1/25/2017 **Mileage** 93036 **Job Value** 59.37

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description NULL
NULL
State Inspection

Labor	Value
State Emissions Inspection	23.09
Emissions Phone Transaction Fee	1.65
State inspection	34.63

Parts		Qty	Value

Invoice Number K7657 **Date** 8/25/2016 **Mileage** 91028 **Job Value** 67.98

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.
NULL

Labor	Value
Service	29.12
Rotate Tires	23.30

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	6	8.94
CNVPH2 BC	Oil Filter	1	3.47

Invoice Number K7552 **Date** 7/7/2016 **Mileage** 90478 **Job Value** 419.95

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Checked codes. Found Radiator cooling fan code. Checked and found passenger side coling fan was locked up. Blades broken and puncture radiator. Replaced fan blades and radiator.

Labor	Value
Check engine Light on	232.96

Parts		Qty	Value
CNV5072330AB Shively	Fan Motor	1	128.75
CNV5137713AA	Fan Blades	1	31.88
CNV5137718AA	Nut	1	2.38
CNVAXA053 AZ	Anti-freeze Mixable 5050	2	21.98

Invoice Number K7556 **Date** 7/7/2016 **Mileage** 0 **Job Value** 170.99

Vehicle Details ADU10 PA DODGE CHARGER 2009

Labor	Value

Parts		Qty	Value
CNVB13157Az	Radiator	1	168.99

Invoice Number K7213 **Date** 2/5/2016 **Mileage** 88573 **Job Value** 325.98

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description NULL
NULL
NULL
Replaced third brake light due to leds being burnt out.
Replaced left front axle shaft.

Labor	Value
State Emissions Inspection	23.58
Emissions Phone Transaction Fee	1.47
State Inspection	35.36
Third brake light is not working	29.47
left front cv boots leaking grease	106.09

Parts		Qty	Value
CNV923-232 az	third brake lamp	1	60.12
CNV10833Naz	cv axle	1	67.89

Invoice Number K6902 **Date** 9/30/2015 **Mileage** 86289 **Job Value** 253.46

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
Replaced all lug nuts due to starting to round off. Had to chisel off a few that were rounded and would not come off.
NULL

Labor	Value
Service	26.35
Rotate Tires	21.08
Replaced lug nuts	52.70
Replace blades	10.54

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	6	8.94
CNVPH2BC	Oil Filter	1	3.20
CNV641-3380 Napa	Lug Nuts	20	111.60
CNV8900101 6 Graham	Wiper Blade 22 inch	2	15.90

Invoice Number K6422 **Date** 3/17/2015 **Mileage** 81121 **Job Value** 116.89

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
NULL
NULL
NULL

Labor	Value
Service	26.35

Rotate Tires	21.08	a CNV5w-30 Petro	Oil	6	8.94
State Emissions Inspection	21.08	CNVPH2 BC	Oil Filter	1	3.20
Emissions Phone Transaction Fee	1.47				
State Inspection	31.62				

Invoice Number K6192 **Date** 11/21/2014 **Mileage** 79134 **Job Value** 42.19

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Removed passenger seat side trim panel. Epoxied broken retainer to seat trim. Installed and secured seat trim panel to seat.

Labor	Value
passenger seat trim is loose seat can not be adjusted	42.19

Parts		Qty	Value

Invoice Number K5947 **Date** 8/5/2014 **Mileage** 75878 **Job Value** 89.33

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
Replaced air filter
Replaced cabin filter

Labor	Value
Service	25.31
replace air filter	10.55
replaced cabin filter	10.55

Parts		Qty	Value
CNVWWFliud	Windshield Washer Fluid	1	1.15
CNV5w-30 Petro	Oil	6	8.94
CNVPH2 BC	Oil Filter	1	3.20
CNVCA9838 az	air filter	1	10.22
CNVCAF1805C az	cabin filter	1	17.41

Invoice Number K5859 **Date** 6/25/2014 **Mileage** 74474 **Job Value** 775.79

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Hooked on computer and checked. Diagnosed abs codes c102 c1043. Found left rear speed sensor faulty.
Replaced left rear abs wheel speed sensor.
Replaced front brakes and rotors
Mounted and balanced 4 new tires. Had to replace the valve stem retaining rings valve core and tpms sensor seal on 3 wheels.

Labor	Value
ABS light is on	42.19
replace left rear abs sensor	42.19
car shakes when braking	52.74
replace tires	84.38

Parts		Qty	Value
CNVSU8480 az	abs wheel speed sensor	1	16.81
CNVDG1058 az	front brakes	1	26.67
CNV43087 az	Brake RotorDisc	2	53.32
CNV732-312-500 STTC	Goodyear Eagle RSA 2256018	4	448.00
CNV20013 az	tpms service pack	2	3.66
CNV20030 az	tpms service pack	1	1.83

Invoice Number K5638 **Date** 3/13/2014 **Mileage** 70874 **Job Value** 188.43

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
NULL
NULL
NULL
Replaced rear brakes

Labor	Value
Service	25.31

State Emissions Inspection	16.88	u CNV5w-30 Petro	Oil	7	11.64
Emissions Phone Transaction Fee	1.47	CNVPH2 BC	Oil Filter	1	3.20
State Inspection	25.31	CNVDG105 7ASD az	Brake Pads	1	40.40
Rotate Tires	16.88				
replace rear brakes	42.19				

Invoice Number K5382 **Date** 10/25/2013 **Mileage** 67214 **Job Value** 14.02

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Replaced left rear turn signal bulb

Labor	Value	Parts		Qty	Value
left rear ts out	13.52	CNV3157	Light Bulb	1	0.50

Invoice Number K5364 **Date** 10/17/2013 **Mileage** 66935 **Job Value** 68.75

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL

Labor	Value	Parts		Qty	Value
Service	27.05	CNVWWFliu d	Windshield Washer Fluid	1	0.99
Replace blades	11.27	CNV5w-30 Petro	Oil	6	10.74
		CNVPH2 BC	Oil Filter	1	3.20
		CNVCWP22 -51-CQ	Windshield Wiper Blade	2	13.50

Invoice Number K5127 **Date** 6/21/2013 **Mileage** 62545 **Job Value** 76.03

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
Replaced left rear inner brake light bulb

Labor	Value	Parts		Qty	Value
Service	27.05	CNVWWFliu d	Windshield Washer Fluid	1	0.99
Rotate Tires	18.03	CNV5w-30 Petro	Oil	6	10.74
brake light out	13.52	CNVPH2 BC	Oil Filter	1	3.20
		CNV3157	Light Bulb	1	0.50

Invoice Number K4842 **Date** 2/5/2013 **Mileage** 58085 **Job Value** 90.53

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
NULL
NULL

Labor	Value	Parts		Qty	Value
Service	27.05	CNVWWFliu d	Windshield Washer Fluid	1	0.99
State Emissions Inspection	18.03	CNV5w-30 Petro	Oil	6	10.74
Emissions Phone Transaction Fee	1.47	CNVPH2 BC	Oil Filter	1	3.20
State Inspection	27.05				

Invoice Number K4468 **Date** 8/6/2012 **Mileage** 52159 **Job Value** 49.34

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL

Labor	Value
Service	19.87

Rotate Tires	13.24	CNVWWFliud	Windshield Washer Fluid	1	0.99
		CNV5w-20 PPC	Oil	6	10.74

Invoice Number K4248 **Date** 3/21/2012 **Mileage** 47137 **Job Value** 83.23

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
Emissions Inspection
NULL
NULL

Labor	Value	Parts		Qty	Value
Service	19.87	CNVPH2	Oil Filter	1	2.50
State Inspection	19.87	CNVWWFliud	Windshield Washer Fluid	1	0.99
Emissions Inspection	13.24	CNV5w-20 PPC	Oil	6	9.12
Emissions Phone Transaction Fee	2.40				
Rotate Tires	13.24				

Invoice Number K3897 **Date** 9/13/2011 **Mileage** 40325 **Job Value** 467.04

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Mount balance 4 tires. Pick tires up at highland tires.
NULL

Labor	Value	Parts		Qty	Value
Replace all 4 tires.	45.20	CNV225-60-18	Uniroyal Tigerpaw Tires	4	410.84
Tire Disposal Fee	9.00				

Invoice Number K3879 **Date** 9/2/2011 **Mileage** 40097 **Job Value** 39.35

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed

Labor	Value	Parts		Qty	Value
Service	18.08	CNVPH2	Oil Filter	1	2.50
		CNVWWFliud	Windshield Washer Fluid	1	0.99
		CNV10w-30 AZ	Oil	6	15.78

Invoice Number K3880 **Date** 9/2/2011 **Mileage** 40097 **Job Value** 10.20

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Replaced air filter

Labor	Value	Parts		Qty	Value
Replace air filter	3.01	CNVSA9005 AZ	Air Filter	1	7.19

Invoice Number K3800 **Date** 8/1/2011 **Mileage** 38881 **Job Value** 11.44

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description NULL

Labor	Value	Parts		Qty	Value
Replace Brake light bulb	9.04	CNV3157	Light Bulb	2	2.40

Invoice Number K3521 **Date** 3/9/2011 **Mileage** 35147 **Job Value** 91.32

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description NULL
Lube Oil Filter Changed
NULL
NULL
NULL

Labor	Value
Rotate Tires	7.53
Service	18.08
State Inspection	15.07
Emissions Inspection	15.00
Take Vehicle to Middlesex Township to have Emissions Inspection Done	22.60

Parts		Qty	Value
CNVPH2	Oil Filter	1	2.50
CNVWWFliud	Windshield Washer Fluid	1	0.99
CNV5w-20 PPC	Oil	6	7.56

Invoice Number K3318 **Date** 11/8/2010 **Mileage** 30952 **Job Value** 39.15

Vehicle Details ADU10 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed

Labor	Value
Service	19.42

Parts		Qty	Value
CNVPH2	Oil Filter	1	2.50
CNVWWFliud	Windshield Washer Fluid	1	0.89
CNV5w-20 PPC	Oil	6	14.34