

VEHICLE CONDITION REPORT

Truck Number: 06
Date Inspected: 7/23
Make/Model/Year: 2011 F-350 Utility with Plow
VIN#: 1FDRF3B62BEC42542
Mileage: 120,937

Interior Condition: Poor
Exterior Condition: Poor
Tires: Good
Does it start? Yes – needs to be jumped
Is it drivable off the lot? Yes
Is it currently inspected? No
Body Style: Utility with Plow
Engine Type: Gas
Transmission Condition: Fair

SELLING VEHICLE AS IS, NO RETURNS.









