Work H	listory	, Rep	ort		Cumber Courthe	rland Count ouse	у	
Date Produced:	8/29/2024				310 Aller	n Road		
Account:	11	Sheriff Dep	t.		Suite 501			
Reg:	CAR16 PA	5			Carlisle			
Vehicle Details	Ram 1500 5.7	2015			PA			
Venicle Details	black	2015			17013-33	123		
	bluch							
Eng Code / Num	18229 /			Vin 1C6R	R7XT2FS642116	Mileage	140470	
Invoice Number	1003279	Date 6/2	7/2024	Mileage	140470	Job Value	441.20	
Vehicle Details	CAR16 PA Ram	n 1500 2015						
Labor Removed all Radio, L from vehicle. Remove				Parts			Qty	Value
Invoice Number	1003250	Date 6/1	1/2024	Mileage	140463	Job Value	296.35	
Vehicle Details	CAR16 PA Ram	n 1500 2015						
Labor			Value	Parts			Qty	Value
PM Service check lig	hts,brake and ove	rall safety of	33.09	CNVWWFliu	Windshield Washer	Fluid	ردی 1	1.35
vehicle Rotate Tires			16.55	d Clearv CNV75-053	5W30 Oil syn blend		7	17.85
RF hub has play, R&I	R hub assembly a	nd cleaned	88.24	CNV84060M			1	3.14
spindle				P ADVANCE CNVSB5151 51	RF Hub Assembly		1	134.13
Invoice Number	1003088	Date 3/1	9/2024	Mileage	135538	Job Value	62.24	
Vehicle Details	CAR16 PA Ram							
Labor			Value	Parts			Qty	Value
State Inspection			33.09	CNVEMI	Emissions, Phone T	ransaction Fee	QUy	1.57
State Emission Inspe	ction		27.58					
Invoice Number	1003067	Date 3/7	/2024	Mileage	134636	Job Value	17.03	
Vehicle Details	CAR16 PA Ram	n 1500 2015						
Labor			Value	Parts			Qty	Value
Replaced wiper blade	es.		11.03	CNVDL22 / az	Wiper Blade		2	6.00
Invoice Number	1003030	Date 2/1	6/2024	Mileage	133789	Job Value	63.41	
Vehicle Details	CAR16 PA Ram	n 1500 2015						
Labor			Value	Parts			Qty	Value
PM Service check lig vehicle 3rd brake ligh		rall safety of	38.61	CNVWWFliu d Clearv	Windshield Washer	Fluid	1	1.32
volliolo ora prato ligit	. out			CNV75-053	5W30 Oil syn blend		7	17.85
				CNV84502 ADVANCE	Oil Filter		1	3.14
				CNVLT921B X AZ	light bulb 921		1	0.49
Invoice Number	1002933	Date 12/	29/2023	Mileage	130487	Job Value	55.36	
Vehicle Details	CAR16 PA Ram	n 1500 2015						
Labor PM Service check lig vehicle	hts,brake and ove	rall safety of	Value 31.05	Parts CNVWWFliu d Clearv	Windshield Washer	Fluid	Qty 1	Value 1.32

Page 1 of 11

CNV75-053 5W30 Oil syn blend	7	17.85
CNV84060M Oil Filter	1	3.14
ADVANCE		

Invoice Number 1002725 Date 9/7/20)23	Mileage	125531 Job Value	190.10	
Vehicle Details CAR16 PA Ram 1500 2015					
Labor	Value	Parts		Qty	Value
PM Service check lights,brake and overall safety of vehicle	31.05	CNV85372 advance	Oil Filter	1	2.62
Rotate Tires	15.53	CNVWWFliu d Clearv	Windshield Washer Fluid	1	1.32
Front brake pads low, R&R brake pads and clean caliper brackets	31.05	CNV75-053	5W30 Oil syn blend	7	22.26
While checking tire PSI found LR valve stem leaking.	25.88	CNVMD108	Front Brake Pads	1	53.18
Dismount tire and install new valve stem		4 CNVTPM20 20VK	Valve Stem	1	5.21
Invoice Number 1002584 Date 6/27/2	2023	Mileage	123648 Job Value	18.02	<u> </u>
Vehicle Details CAR16 PA Ram 1500 2015					
Labor	Value	Parts		Qty	Value
3rd brake light inoperative, installed new bulb and	10.35	CNVLT921B	light bulb 921	1	0.49
cleaned connector. Remove rear AED sticker on rear window	5.18	X AZ			
Invoice Number 1002553 Date 6/9/20)23	Mileage	3333 Job Value	48.38	
Vehicle Details CAR16 PA Ram 1500 2015	-	5			
Labor	Value	Parts		Qty	Value
			2 inch drop hitch	1	24.68
		CNV129067 1	1/4 clevis hook	2	16.12
		CNV129072 3	Lock Spring Clip	1	7.58
Invoice Number 1002460 Date 4/24/2	2023	Mileage	121527 Job Value	41.55	
Vehicle Details CAR16 PA Ram 1500 2015					
Labor	Value	Parts		Qty	Value
Remove front grill, and removed headlight. R&R bulb	31.05	CNVH11	LF Head Light Bulb	1	10.50
Invoice Number 1002413 Date 3/27/2	2023	Mileage	119916 Job Value	139.66	
Vehicle Details CAR16 PA Ram 1500 2015					
Labor	Value	Parts		Qty	Value
PM Service check lights,brake and overall safety of vehicle. Adjusted rear tail gate strikers and lubricated	51.75	CNVWWFliu d Clearv	Windshield Washer Fluid	1	1.20
latches.	05.00	CNV75-053	5W30 Oil syn blend	7	22.26
State Emission Inspection State Inspection	25.88 31.05		Emissions, Phone Transaction Fee	1	1.57
	01.00	CNV84060M P ADVANCE	Oil Filter	1	3.95
Invoice Number 1002368 Date 3/6/20)23	Mileage	118669 Job Value	238.39	
Vehicle Details CAR16 PA Ram 1500 2015		2			
Labor	Value	Parts		Qty	Value
R&R battery and cleaned connections. Battery testing	31.05	CNV94R-	Battery *3 Yr Warranty*	ررپ 1	194.99
weak, vehicle has been jumped several times. Drivers side mirror glass fell out, installed glass from old mirror.	10.35	DLG			

Invoice Number	1002326	Date 2/10/2	023	Mileage	117928	Job Value	94.62	
Vehicle Details	CAR16 PA Rar	n 1500 2015						
Labor Installed battery tend	er		Value 51.75	Parts CNV85244	Butt Connectors	(Red Shrink Wrap)	Qty 2	Value 0.92
				AZ CNVNOCO	NOCO GENIUS TENDER	2D BATTERY	1	39.95
Invoice Number	1002301	Date 2/1/20	23	Mileage	117643	Job Value	448.39	
Vehicle Details	CAR16 PA Rar	n 1500 2015						
Labor Driver side mirror cra panel, and mirror. In for proper operation.			Value 41.40	Parts CNV60196C	Driver Side Mirro	or Assembly	Qty 1	Value 406.99
Invoice Number	1002261	Date 1/10/2	023	Mileage	116836	Job Value	107.81	
Vehicle Details	CAR16 PA Rar	n 1500 2015						
Labor Fuel cap light on, che ECM for stored code gas cap, checked for leaks present tested defective. Installed n went off.	s. Found no code evap leaks at cha leak detection an	s or issues with arcoal canister. No d found pump was	Value 77.63	Parts CNVLDP12	Leak Detection F	Pump	Qty 1	Value 28.18
Invoice Number	1002136	Date 11/1/2	022	Mileage	114517	Job Value	532.75	
Vehicle Details	CAR16 PA Rar	m 1500 2015						
Labor Removed steering co inspected all wiring for pinched. Removed S wiring internally. Fou internally. R&R clock operation.	or any areas rubb Steering wheel air Ind clock spring to	ed through or bag and inspected be defective	Value 150.75	Parts CNV685283 00AA	Steering Wheel (Clock Spring	Qty 1	Value 380.00
Invoice Number	1002116	Date 10/20/2	2022	Mileage	114346	Job Value	910.28	
Vehicle Details	CAR16 PA Rar	m 1500 2015						
Labor PM Service check lig vehicle	hts,brake and ove	erall safety of	Value 30.15	Parts CNV5w-30 PPC	Oil		Qty 7	Value 29.19
Pick up 4 tires at Hig Mounted and balance			100.50		Windshield Was	her Fluid	1	1.20
					Wheel Weights	Soodycor Wronglor	8	8.00
				572	AT	Goodyear Wrangler	4	731.24
				SPOSAL	TIRE DISPOSAL	- FEE	4	8.00
Invoice Number	1001903	Date 6/24/2	022	Mileage	109228	Job Value	63.02	
Vehicle Details	CAR16 PA Rar	n 1500 2015						
Labor PM Service, Check L vehicle	ights, Brakes and	d overall safety of	Value 30.15	Parts CNV0w-20- stpsyn AZ	Oil		Qty 7	Value 26.53
					Windshield Was	her Fluid	1	1.20
				CNV84060M P ADVANCE	Oil Filter		1	3.14
Invoice Number	1001762	Date 4/6/202	22	Mileage	106265	Job Value	66.75	
Vehicle Details	CAR16 PA Rar	m 1500 2015		-				
Labor			Value					

Shop Labor- Cumberland County. Rear view mirror is loose. Had to drill out mirror retaining screw to remove mirror. 62.81

Tightened all screws in mirror mount that were loose, reinstalled mirror. Also reattached camera mounting tab to windshield that fell off.

Invoice Number 1001684 Date 2/24/2	022	Mileage	104781	Job Value	347.41	
Vehicle Details CAR16 PA Ram 1500 2015						
Labor PM Service check lights,brake and overall safety of vehicle	Value 30.15	Parts CNV5w-30 PPC	Oil		Qty 7	Value 13.93
Rotate Tires	15.08		Windshield Washer Fluid	I	1	1.20
State Inspection	30.15 25.13	CNVEMI	Emissions, Phone Trans	action Fee	1	1.57
State Emission Inspection Front lower ball joints had play, R&R front lower ball	25.13 140.70	CNV84060M P	Oil Filter		1	3.14
joints.		ADVANCE CNVJBJ114 2	Lower Ball Joint		2	84.36
Invoice Number 1001650 Date 2/4/20)22	Mileage	103780	Job Value	16.05	
Vehicle Details CAR16 PA Ram 1500 2015						
Labor Replaced wiper blades.	Value 10.05	Parts CNVDL22 / az	Wiper Blade		Qty 2	Value 6.00
Invoice Number 1001415 Date 9/23/2	2021	Mileage	99780	Job Value	467.00	
Vehicle Details CAR16 PA Ram 1500 2015						
Labor	Value	Parts			Qty	Value
PM Service check lights,brake and overall safety of vehicle	27.61	CNV5w-30 PPC	Oil		7	15.05
R&R Front Brake Pads and Rotors, complaint of vibratior found heat spots on rotors. Cleaned and lubricated slider		CNVWWFliu d Clearv	Windshield Washer Fluid	I	1	1.15
pins and brackets. R&R Rear Brake Pads and Rotors, complaint of vibration		CNV84060M P	Oil Filter		1	3.14
Found brake pads were not moving freely causing the rotors to get hots spots. Cleaned and lubricated slider pins and cleaned brackets.	00.00	ADVANCE CNV53005D G	Front Brake Rotor		2	107.76
		CNVDG108 4	Front Brake Pads		1	28.95
			Rear Brake Rotors		2	114.32
			Rear Brake Pads		1	28.96
Invoice Number 1001342 Date 8/10/2	2021	Mileage	97793	Job Value	14.80	
Vehicle Details CAR16 PA Ram 1500 2015						
Labor	Value	Parts			Qty	Value
R&R Right rear turn signal bulb and cleaned connectors.	13.81	CNV3157	Light Bulb		1	0.99
Invoice Number 1001210 Date 5/28/2	.021	Mileage	94462	Job Value	626.75	
Vehicle Details CAR16 PA Ram 1500 2015						
Labor	Value	Parts			Qty	Value
Rotate Tires PM Service check lights,brake and overall safety of	13.81	CNV5w-30 PPC	Oil		7	15.05
vehicle Remove & Replace Front Suspension Coil Spring, R&R	27.61	CNVWWFliu d Clearv	Windshield Washer Fluid	1	1	1.15
Both Sides		CNV84060M P	Oil Filter		1	3.14
Remove & Replace Rear Shock absorbers Replace air filter	69.03 13.81	ADVANCE	SRT Strut Assembly		2	267.96
		, CNV34258	SRT Rear Shock Absorb	er	2	85.02
		CNVPA5462	Air Filter		1	13.12

Invoice Number	1001103	Date	4/7/202	.1	Mileage	92523	Job Value	52.19	
Vehicle Details	CAR16 PA D	ODGE RAM	1500 20	15					
Labor State Inspection State Emission Inspe	ection			Value 27.61 23.01	Parts CNVEMI	Emissions, Phone	e Transaction Fee	Qty 1	Value 1.57
Invoice Number	K11128	Date	1/13/20	21	Mileage	89663	Job Value	239.62	
Vehicle Details	CAR16 PA D	ODGE RAM	1500 20	15					
Work Descriptio	n Lube Oil Filt Replaced fro				Lights wipers	and over all safe	ety.		
Labor Service				Value 27.61	Parts CNVWWFliu d	Windshield Wash	er Fluid	Qty 1	Value
Front brakes worn of	ut			69.03	CNV5w-30	Oil		7	15.05
					Petro CNV84060 advance	Oil Filter		1	3.14
					CNVSB7800 73 Fishers	Brake RotorDisc		2	80.50
						Front Brakes		1	39.14
Invoice Number	K10852	Date	8/21/20	20	Mileage	84665	Job Value	253.91	
Validada Datada	CAR16 PA D	ODGE RAM	1500 20	15					
Vehicle Details Work Descriptio	Test drove v cover replac	ehicle una	able to ve	erify conc	ern checked c		s fluid.Pulled trar	smission	pan
Work Descriptio Labor	Test drove v	ehicle una	able to ve	erify conc 1 added ne Value	ern checked c ew fluid Parts	ondiiton of tran	s fluid.Pulled trar	Qty	Value
Work Descriptio	Test drove v cover replac NULL	vehicle una ced both fi	able to ve	erify conc d added ne	ern checked c ew fluid Parts CNVWWFliu d	ondiiton of tran Windshield Wash	s fluid.Pulled trar	Qty 1	Value
Work Descriptio	Test drove v cover replac NULL	vehicle una ced both fi	able to ve	erify conc d added ne Value 26.53	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro	ondiiton of tran Windshield Wash Oil	s fluid.Pulled trar	Qty 1 7	Value 1.15
Work Descriptio	Test drove v cover replac NULL	vehicle una ced both fi	able to ve	erify conce d added ne Value 26.53 106.10	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance	Windshield Wash Oil Oil Filter	s fluid.Pulled trar er Fluid	Qty 1 7 1	Value 1.15 15.05 3.14
Work Descriptio	Test drove v cover replac NULL	vehicle una ced both fi	able to ve	erify conce d added ne Value 26.53 106.10	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV461TF1 75Fisher CNV527700	Windshield Wash Oil Oil Filter Transmisson filter	s fluid.Pulled trar er Fluid	Qty 1 7	Value 1.15 15.05 3.14 23.85
Work Descriptio	Test drove v cover replac NULL	vehicle una ced both fi	able to ve	erify conce d added ne Value 26.53 106.10	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV461TF1 75Fisher	windshield Wash Oil Oil Filter Transmisson filter ATF4	s fluid.Pulled trar er Fluid	Qty 1 7 1	Value 1.15 15.05 3.14 23.85 54.16
Work Descriptio	Test drove v cover replac NULL	vehicle una ced both fi g properly	able to ve	erify conce d added ne 26.53 106.10 15.92	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV461TF1 75Fisher CNV527700 2FATF4Fish er CNVAZP-10	Windshield Wash Oil Oil Filter Transmisson filter ATF4	s fluid.Pulled trar er Fluid	Qty 1 7 1 1 8	Value
Work Descriptio	Test drove v cover replac NULL	vehicle una ced both fi g properly Date	able to ve ilters and 5/4/202	erify conc d added ne 26.53 106.10 15.92	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV84061TF1 75Fisher CNV461TF1 75Fisher CNV527700 2FATF4Fish er CNVAZP-10 CA az	Windshield Wash Oil Oil Filter Transmisson filter ATF4 Brake Cleaner	s fluid.Pulled trar er Fluid ^r kit	Qty 1 7 1 1 8 2	Value 1.1 15.0 3.1 23.8 54.1
Work Descriptio	Test drove v cover replace NULL e it wasnt shifting K10628 CAR16 PA D	vehicle una ced both fi g properly Date ODGE RAM	able to v ilters and 5/4/202 1500 20	erify conc d added ne 26.53 106.10 15.92	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV84061TF1 75Fisher CNV461TF1 75Fisher CNV527700 2FATF4Fish er CNVAZP-10 CA az	Windshield Wash Oil Oil Filter Transmisson filter ATF4 Brake Cleaner	s fluid.Pulled trar er Fluid ^r kit	Qty 1 7 1 1 8 2	Value 1.1 15.0 3.1 23.8 54.1
Work Descriptio	Test drove v cover replace NULL e it wasnt shifting K10628 CAR16 PA Du n Replaced 3r	vehicle una ced both fi g properly Date ODGE RAM	able to v ilters and 5/4/202 1500 20	erify conc d added ne 26.53 106.10 15.92	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV461TF1 75Fisher CNV527700 2FATF4Fish er CNVA2P-10 CA az Mileage Parts	Windshield Wash Oil Oil Filter Transmisson filter ATF4 Brake Cleaner	s fluid.Pulled trar er Fluid ^r kit	Qty 1 7 1 1 8 2	Value 1.1 15.0 3.1 23.8 54.1 3.9 3.9
Work Descriptio	Test drove v cover replace NULL e it wasnt shifting K10628 CAR16 PA Du n Replaced 3r	vehicle una ced both fi g properly Date ODGE RAM d brake lig	able to v ilters and 5/4/202 1500 20	erify conce d added ne 26.53 106.10 15.92 0 15 Value 13.26	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV461TF1 75Fisher CNV527700 2FATF4Fish er CNV527700 2FATF4Fish er CNVAZP-10 CA az Mileage Parts CNVLT921B	Windshield Wash Oil Oil Filter Transmisson filter ATF4 Brake Cleaner 80352	s fluid.Pulled trar er Fluid ^r kit	Qty 1 7 1 1 8 2 13.75	Value 1.1 15.0 3.1 23.8 54.1 3.9 3.9
Work Descriptio	Test drove v cover replac NULL e it wasnt shifting K10628 CAR16 PA Du n Replaced 3r ut K10589 CAR16 PA Du	vehicle una ced both fi g properly Date ODGE RAM d brake lig Date	able to ve ilters and 5/4/202 1500 20 ght bulb	erify conce d added ne 26.53 106.10 15.92 0 15 Value 13.26	ern checked c ew fluid Parts CNVWWFliu d CNV5w-30 Petro CNV84060 advance CNV461TF1 75Fisher CNV527700 2FATF4Fish er CNV527700 2FATF4Fish er CNVAZP-10 CA az Mileage Parts CNVLT921B X az	Windshield Wash Oil Oil Filter Transmisson filter ATF4 Brake Cleaner 80352	s fluid.Pulled trar er Fluid r kit Job Value	Qty 1 7 1 1 8 2 13.75 Qty 1	Value 1.15 15.05 3.14 23.85 54.16 3.98

Invoice Number	K10569	Date	3/27/2	020	Mileage	79920	Job Value	179.34	
Vehicle Details	CAR16 PA DOD	DGE RAN	۸ 1500 20	015					
Work Description	n Checked door handle cable.	handle	found ca	able broken.	Removed dr	rivers door panel t	o replaced inte	rior door	
Labor Drivers door interior	door handle is not	opening	door.	Value 106.10	Parts CNV912-61 0 advance	Door Release Cable		Qty 1	Value 71.24
Invoice Number	K10556	Date	3/12/2	020	Mileage	79335	Job Value	118.44	
Vehicle Details	CAR16 PA DOD	DGE RAN	۸ 1500 20	015					
Work Description	n Lube Oil Filter Replaced wipe NULL NULL State Inspecti	er blade		ed Brakes L	ights wipers	and over all safety	/.		
Labor				Value	Parts			Qty	Value
Service				26.53	d	Windshield Washer	Fluid	1	1.15
replace wiper blades				10.61	CNV5w-30	Oil		7	15.05
State Emissions Insp Emissions Phone Tra				21.22 1.57	Petro CNV84060M	Oil Filter		1	2.48
State inspection				31.83	P advance			-	
				01.00	CNVDL22 az	Wiper Blade		2	6.00
Invoice Number	K10421	Date	1/14/2	020	Mileage	77155	Job Value	14.25	
Vehicle Details	CAR16 PA DOD				mileuge	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		1 1125	
Work Description									
	Inteplaced sid	brane n	Sile batb						
Labor				Value	Parts			Qty	Value
Third brake light is or	ut			13.26	CNV7443 AZ	Light Bulb		1	0.99
Invoice Number	K10277	Date	11/5/20	019	Mileage	74354	Job Value	64.32	
Vehicle Details	CAR16 PA DOD				. 3				
		-		-	ights wipers	and over all safety	/.		
Labor				Value	Parts			Qty	Value
Service				27.63		Windshield Washer	Fluid	1	1.15
Rotate Tires				16.58	d CNV5w-30	Oil		7	14.49
					Petro CNV84060M	Oil Eiltor		1	2.48
					P advance	On Thite			2.40
Invoice Number	K10069	Date	7/26/2	019	Mileage	69580	Job Value	14.30	
Vehicle Details	CAR16 PA DOD	DGE RAN	۸ 1500 20	015					
Work Description	n Replaced thire	d brake	light bul	b.					
Labor				Value	Parts			Qty	Value
Third brake light is or	ut			13.81		light bulb 921		Q C y	0.49
5					X az	5			
Invoice Number	K10055	Date	7/19/2	019	Mileage	69119	Job Value	69.10	
Vehicle Details	CAR16 PA DOD	DGE RAN	۸ 1500 20	015					
Work Description	n Lube Oil Filter Replaced Air F		ed check	ed Brakes L	ights wipers	and over all safety	/.		
Labor				Value	Parts			Qty	Value
Service									
				27.63		Windshield Washer	Fluid	1	
Replace air filter				27.63 13.81	CNVWWFliu d CNV5w-30		Fluid	-	1.15
Replace air filter					d	Windshield Washer Oil Oil Filter	Fluid	1 7 1	

Invoice Number	K9883	Date	5/8/2019	9	Mileage	66433	Job Value	14.41	
Vehicle Details	CAR16 PA DO	DGE RAN	1500 201	15					
Work Description	Replaced rig	ht license	e plate bu	ılb.					
Labor				Value	Parts			Qty	Value
License plate light is	out			13.81	CNVLT194B X AZ	Light Bulb 194		1	0.60
Invoice Number	K9783	Date	3/26/20	19	Mileage	64384	Job Value	297.71	
Vehicle Details	CAR16 PA DO	DGE RAN	1500 201	15					
Work Description	Lube Oil Filt NULL NULL State Inspec NULL Replaced rea	tion			Lights wipers	and over all safe	ty.		
Labor				Value	Parts			Qty	Value
Service				27.63		Windshield Washe	er Fluid	ریپ 1	1.15
State Emissions Insp	ection			22.10	d CNV5w-30			7	12.00
Emissions Phone Tra	ansaction Fee			1.65	Petro	Oil		7	13.02
State inspection				33.15	CNVS10060 az	Oil Filter		1	1.99
Rotate Tires				16.58	CNVPXD96	Brake Pads		1	32.49
Rear brakesRotors				82.88	7H ADV CNVYH1453 65P ADV	Rotors		2	61.08
Vehicle Details	CAR16 PA DO	DGE RAN		15	Mileage	62258 bund new fuel pu	Job Value	221.00 el pressur	e.
Vehicle Details Work Descriptior	CAR16 PA DO Checked for	DGE RAN codes no	1500 201 ne. Check	15 ked fuel p ve faulty	ressure and fo	ound new fuel pu		el pressur nodule.	
Invoice Number Vehicle Details Work Description Labor Cranks alot before it	CAR16 PA DO Checked for instantly. Fu	DGE RAN codes no	1500 201 ne. Check check val	15 ked fuel p	ressure and fo	ound new fuel pu	mp bleeds off fu aced fuel pump n	el pressur	Value
Vehicle Details Work Descriptior Labor	CAR16 PA DO Checked for instantly. Fu	DGE RAN codes no	1500 201 ne. Check check val	15 Ked fuel p ve faulty Value 221.00	ressure and fo pump is under Parts CNVEFG14	ound new fuel pu r warranty. Repla Fuel Pump Module	mp bleeds off fu aced fuel pump n	el pressur nodule. Qty	
Vehicle Details Work Description Labor Cranks alot before it Invoice Number	CAR16 PA DO Checked for instantly. Fu	DGE RAN codes no el pump Date	1500 201 ne. Check check val 2/14/20	15 ked fuel p ve faulty Value 221.00 19	ressure and fo pump is under Parts CNVEFG14 39 az	ound new fuel pu warranty. Repla Fuel Pump Module warranty	mp bleeds off fu aced fuel pump n 9- Part is under	el pressur nodule. Qty 1	Value
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO	DGE RAN codes no el pump Date DGE RAN	N 1500 201 ne. Check check val 2/14/20 N 1500 201	15 ked fuel p ve faulty Value 221.00 19	ressure and fo pump is under Parts CNVEFG14 39 az Mileage	ound new fuel pu r warranty. Repla Fuel Pump Module warranty 61993	mp bleeds off fu aced fuel pump n e- Part is under Job Value	el pressur nodule. Qty 1 168.92	Value 0.00
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu	DGE RAN codes no el pump Date DGE RAN	1500 201 ne. Check check val 2/14/20 1500 201 r is bad no	15 ked fuel p ve faulty Value 221.00 19	ressure and fo pump is under Parts CNVEFG14 39 az Mileage	ound new fuel pu r warranty. Repla Fuel Pump Module warranty 61993	mp bleeds off fu aced fuel pump n e- Part is under Job Value er electrical circu	el pressur nodule. Qty 1 168.92	Value 0.00 r. Value
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console	DGE RAW codes no el pump Date DGE RAW it breake	1500 201 ne. Check check val 2/14/20 1500 201 r is bad no	15 ked fuel p ve faulty 221.00 19 15 o power o Value 55.25	ressure and for pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa	Fuel Pump Module warranty 61993 Replaced maste	mp bleeds off fu aced fuel pump n e- Part is under Job Value er electrical circu reakerFuse	el pressur nodule. Qty 1 168.92 uit breake Qty 1	Value 0.00
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535	DGE RAW codes no el pump Date DGE RAW it breaker DATE	1500 201 ne. Check check val 2/14/20 1500 201 r is bad no 12/11/20	15 ked fuel p ve faulty Value 221.00 19 15 o power o Value 55.25	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31	Fuel Pump Module warranty 61993 Replaced maste	mp bleeds off fu aced fuel pump n e- Part is under Job Value er electrical circu	el pressur nodule. Qty 1 168.92 uit breake Qty	Value 0.00 r. Value
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center Invoice Number Vehicle Details	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535 CAR16 PA DO	DGE RAW codes no el pump Date DGE RAW it breaker DGE RAW es code i	1500 201 ne. Check check val 2/14/20 1500 201 r is bad no 12/11/20 1500 201 s for fuel	15 xed fuel p ve faulty Value 221.00 19 15 o power o Value 55.25 018 15 level sen:	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa Mileage	Fuel Pump Module warranty 61993 Replaced master 150 amp Circuit Br 59669	mp bleeds off fu aced fuel pump n - Part is under Job Value er electrical circu reakerFuse Job Value	el pressur nodule. Qty 1 168.92 uit breake Qty 1 390.83	Value 0.00 r. Value 113.67
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center Invoice Number Vehicle Details Work Description	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535 CAR16 PA DO Checked coo	DGE RAW codes no el pump Date DGE RAW it breaker DGE RAW es code i	1500 201 ne. Check check val 2/14/20 1500 201 r is bad no 12/11/20 1500 201 s for fuel	15 ked fuel p ve faulty Value 221.00 19 15 o power o Value 55.25 018 15 level sen: code.	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa Mileage	Fuel Pump Module warranty 61993 Replaced master 150 amp Circuit Br 59669	mp bleeds off fu aced fuel pump n - Part is under Job Value er electrical circu reakerFuse Job Value	el pressur nodule. Qty 1 168.92 iit breake Qty 1 390.83 el pump a	Value 0.00 r. Value 113.67
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center Invoice Number Vehicle Details Work Description Labor	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535 CAR16 PA DO Checked coo level sensor	DGE RAW codes no el pump d Date DGE RAW it breaked DGE RAW es code i assembly	A 1500 201 ne. Check check val 2/14/20 A 1500 201 r is bad no 12/11/20 A 1500 201 s for fuel C Cleared	15 xed fuel p ve faulty Value 221.00 19 15 o power o Value 55.25 018 15 level sen:	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa Mileage sor faulty. Ren	Fuel Pump Module warranty 61993 Replaced master 150 amp Circuit Br 59669	mp bleeds off fu aced fuel pump n - Part is under Job Value er electrical circu reakerFuse Job Value and replaced fue	el pressur nodule. Qty 1 168.92 uit breake Qty 1 390.83	Value 0.00 r. Value 113.67
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center Invoice Number Vehicle Details Work Description Labor SES light on fuel gau	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535 CAR16 PA DO Checked coo level sensor ge reads inaccu	DGE RAW codes no el pump d Date DGE RAW it breaked DGE RAW es code i assembly	A 1500 201 ne. Check check val 2/14/20 A 1500 201 r is bad no 12/11/20 A 1500 201 s for fuel C Cleared	15 ked fuel p ve faulty Value 221.00 19 15 15 15 15 15 15 15 15 15 15	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa Mileage sor faulty. Ren Parts CNVEFG14	Fuel Pump Module warranty 61993 Replaced master 150 amp Circuit Br 59669 moved fuel tank	mp bleeds off fu aced fuel pump n - Part is under Job Value er electrical circu reakerFuse Job Value and replaced fue	el pressur nodule. Qty 1 168.92 iit breake Qty 1 390.83 el pump a Qty	Value 0.00 r. Value 113.67 nd Value
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center Invoice Number Vehicle Details Work Description Labor SES light on fuel gau Invoice Number	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535 CAR16 PA DO Checked coo level sensor ge reads inaccu	DGE RAW codes no el pump d Date DGE RAW it breaked DGE RAW es code i assembly rate. Date	A 1500 201 ne. Check check val 2/14/20 A 1500 201 r is bad no 12/11/20 A 1500 201 s for fuel c. Cleared	15 ked fuel p ve faulty Value 221.00 19 15 15 15 15 15 15 15 15 15 15	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa Mileage sor faulty. Ren Parts CNVEFG14 39 az	Fuel Pump Module warranty. Repla 61993 Replaced master 150 amp Circuit Br 59669 moved fuel tank Fuel Pump Module	mp bleeds off fu aced fuel pump n - Part is under Job Value er electrical circu reakerFuse Job Value and replaced fue	el pressur nodule. Qty 1 168.92 it breake Qty 1 390.83 el pump a Qty 1	Value 0.00 r. Value 113.61 nd Value
Vehicle Details Work Description Labor Cranks alot before it Invoice Number	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535 CAR16 PA DO Checked coo level sensor ge reads inaccu K9505 CAR16 PA DO	DGE RAW codes no el pump d Date DGE RAW it breaked DGE RAW les code i assembly rate. DATE	A 1500 201 ne. Check check val 2/14/20 A 1500 201 r is bad no 12/11/20 A 1500 201 s for fuel Cleared 11/29/20 A 1500 201	15 ked fuel p ve faulty Value 221.00 19 15 15 15 15 15 15 15 15 15 15	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa Mileage sor faulty. Ren Parts CNVEFG14 39 az Mileage	Fuel Pump Module warranty. Repla 61993 Replaced master 150 amp Circuit Br 59669 moved fuel tank Fuel Pump Module 59341	mp bleeds off fu aced fuel pump n Job Value er electrical circu reakerFuse Job Value and replaced fue	el pressur nodule. Qty 1 168.92 iit breake Qty 1 390.83 el pump a Qty 1	Value 0.00 r. Value 113.67 nd Value
Vehicle Details Work Description Labor Cranks alot before it Invoice Number Vehicle Details Work Description Labor Lost power to center Vehicle Details Work Description Labor SES light on fuel gau Invoice Number Vehicle Details	CAR16 PA DO Checked for instantly. Fu starts K9685 CAR16 PA DO Master circu console K9535 CAR16 PA DO Checked coo level sensor ge reads inaccu K9505 CAR16 PA DO Lube Oil Filt	DGE RAW codes no el pump d Date DGE RAW it breaked DGE RAW les code i assembly rate. DATE	A 1500 201 ne. Check check val 2/14/20 A 1500 201 r is bad no 12/11/20 A 1500 201 s for fuel Cleared 11/29/20 A 1500 201	15 ked fuel p ve faulty Value 221.00 19 15 15 15 15 15 15 15 15 15 15	ressure and fo pump is under Parts CNVEFG14 39 az Mileage out of breaker. Parts CNV782-31 70 napa Mileage sor faulty. Ren Parts CNVEFG14 39 az Mileage	Fuel Pump Module warranty. Repla 61993 Replaced master 150 amp Circuit Br 59669 moved fuel tank Fuel Pump Module 59341	mp bleeds off fu aced fuel pump n Job Value er electrical circu reakerFuse Job Value and replaced fue	el pressur nodule. Qty 1 168.92 iit breake Qty 1 390.83 el pump a Qty 1	Value 0.00 r. Value 113.67 nd Value

Rotate Tires			16.86	CNV5w-30	Oil		7	14.28
				Petro CNVPH1006 0 BC	Oil Filter		1	3.25
Invoice Number	K9466	Date	11/9/2018	Mileage	58071	Job Value	33.72	
Vehicle Details	CAR16 PA DO	DDGE RAN	1500 2015					
Work Descriptio				uel level sensor. C loved to replace fi		to fuel tank. Cleaı r.	red code.	lf
Labor			Valu	ie Parts			Qty	Value
Check engine light c	ame on		33.72				QLY	Value
Invoice Number			8/20/2018	Mileage	54381	Job Value	47.45	
Vehicle Details	CAR16 PA DO			kes Lights wipers	and over all ca	faty		
work Descriptio		er change			and over all sa	liety.		
Labor			Valu				Qty	Value
Service			28.10	d	Windshield Was	her Fluid	1	1.15
				CNV5w-30 Petro	Oil		7	12.95
				CNVPH1006 0 BC	Oil Filter		1	3.25
Invoice Number	K9035	Date	4/30/2018	Mileage	49260	Job Value	321.22	
Vehicle Details	CAR16 PA DO	DDGE RAM	1500 2015					
				kes Lights wipers	and over all sa	fetv.		
Work Description	NULL	er enang				icty.		
	NULL							
	State Inspec							
	Replaced fro	ont brakes	and rotors.					
	NULL							
Labor			Valu				Qty	Value
Service			28.10	CNVWWFliu d	Windshield Was	her Fluid	1	1.15
State Emissions Insp			22.48	CNV5w-30	Oil		7	12.95
Emissions Phone Tra	ansaction Fee		1.65	Petro CNVPH1006	Oil Eiltor		1	3.04
State inspection Replaced front brake	a and ratara		33.72 84.30	0 BC			1	3.04
Rotate Tires	s and rotors		16.86	CNVDG108 4C AZ	Brake Pads		1	30.99
Notate Thes			10.00	CNV53005D G AZ	Brake Rotor		2	81.98
Invoice Number	K8721	Date	12/19/2017	Mileage	44015	Job Value	47.37	
Vehicle Details	CAR16 PA DO							
Work Descriptio	n Lube Oil Filt	er Chang	ed checked Bra	kes Lights wipers	and over all sa	fety.		
Labor			Valu	ie Parts			Qty	Value
Service			28.86	CNVWWFliu	Windshield Was	her Fluid	1	1.15
				d CNV5w-30	Oil		7	12.32
				Petro				
				CNVPH1006 0 BC	Oil Filter		1	3.04
Invoice Number	K8545	Date	9/29/2017	Mileage	40229	Job Value	18.31	
Vehicle Details	CAR16 PA DO	DDGE RAM	1500 2015					
Work Descriptio	n NULL							
Labor			Valu	ie Parts			Qty	Value
Replace Brake light l	oulb		17.32	CNV3157	Light Bulb		ری پ 1	0.99
			11.52	0				5.00

Invoice Number	K8467	Date	8/31/2017	Mileage	38909	Job Value	62.80	
Vehicle Details	CAR16 PA D	ODGE RAM	۸ 1500 2015					
Work Description	Lube Oil Filt NULL	ter Change	ed checked Brake	s Lights wipers	and over all saf	ety.		
Labor Service			Value 28.86		Windshield Wasł	ner Fluid	Qty 1	Value 1.15
Rotate Tires			17.32	d CNV5w-30	Oil		7	10.43
				Petro CNVPH1006 0 BC	Oil Filter		1	3.04
Invoice Number	K8338	Date	7/13/2017	Mileage	36967	Job Value	23.09	
Vehicle Details	CAR16 PA D	ODGE RAM	۸ 1500 2015					
Work Description	Checked all	brakes br	akes are still goo	d. No problem f	found with brak	es at this time.		
Labor			Value	Parts			Qty	Value
brakes are squealing			23.09				~.,	
Invoice Number	1/0400	Data	5/8/2017		22274	Jah Valua	109.79	
Vehicle Details	CAR16 PA D			Mileage	33371	Job Value	109.79	
Work Description	Replaced ai Removed le drain hole in	r filter ft rear tai n lens. Re		ed water out of ght bulb.		ety. trobe light and dri	lled wate	er
Labor			Value	Parts			Qty	Value
Service			28.86	CNVWWFliu d	Windshield Wash	ner Fluid	1	1.15
replace air filter			11.54	CNV5w-30	Oil		7	10.43
Water in left taillight I plug tire	ens		28.86 14.43	Petro CNVPH1006	Oil Filter		1	3.04
				0 BC CNVSA9401	Air Filter		1	7.49
				az CNV7443	Light Bulb		1	0.99
				AZ CNV710-10 36 Napa	tire plug		1	1.00
Invoice Number	K8153	Date	4/19/2017	Mileage	32438	Job Value	59.37	
Vehicle Details	CAR16 PA D			Mileage	52450	JOD Value	57.57	
Work Description			1300 2013					
Labor			Value	Parts			Qty	Value
State Emissions Insp			23.09					
Emissions Phone Tra State inspection	ansaction Fee		1.65 34.63					
Invoice Number	K8146	Date	4/18/2017	Mileage	32438	Job Value	59.37	
Vehicle Details	CAR16 PA D					302 / 4144		
Work Description								
Labor			Value	Parts			Qty	Value
State inspection			34.63				- /	
State Emissions Insp			23.09					
Emissions Phone Tra	ansaction Fee		1.65					

	K8103	Date	3/27/2017	Mileage	31470	Job Value	458.97	
Vehicle Details	CAR16 PA DC	DGE RAN	1500 2015					
Work Descriptio	n Replaced pa	ssenger si	de mirror had to r	remove door pa	anel to run wiri	ng for mirror.		
Labor Passenger mirror ne	eds replaced		Value 57.72	Parts CNV682858 64AB shively	Mirror		Qty 1	Value 401.25
Invoice Number	K7945	Date	1/6/2017	Mileage	28317	Job Value	68.72	
Vehicle Details	CAR16 PA DC	DGE RAN	1500 2015					
Work Descriptio	n Lube Oil Filte NULL	er Change	ed checked Brakes	Lights wipers	and over all saf	fety.		
Labor			Value	Parts			Qty	Value
Service			28.86	CNVWWFliu	Windshield Wash	her Fluid	1	1.15
Rotate Tires			23.09	d CNV5w-30	Oil		7	10.43
				Petro CNVPH1006 0 BC	Oil Filter		1	3.19
Invoice Number	K7914	Date	12/21/2016	Mileage	27253	Job Value	66.70	<u> </u>
Vehicle Details	CAR16 PA DC			micage	27233		00.70	
Work Descriptio	shorts to gro	und. Fou		rough on steer	ing shaft under	v again. Checked v dash. Repaired wi		
Labor			Value	Parts			Qty	Value
Truck has no power	to console		58.24	CNVBPMAX -50-RP az	Fuse		2	6.46
		Date	58.24		Fuse 25556	Job Value	11.65	6.46
Truck has no power			11/21/2016	-50-RP az		Job Value		6.46
Truck has no power Invoice Number Vehicle Details	K7847 CAR16 PA DC	DGE RAN	11/21/2016 1500 2015	-50-RP az Mileage	25556	Job Value icle is still under v	11.65	6.46
Truck has no power Invoice Number Vehicle Details	K7847 CAR16 PA DC	DGE RAN	11/21/2016 1500 2015	-50-RP az Mileage	25556		11.65	Value
Truck has no power Invoice Number Vehicle Details Work Descriptio Labor	K7847 CAR16 PA DC nChecked air	DGE RAN bag code	11/21/2016 1500 2015 scan not read the Value	-50-RP az Mileage codes with our	25556		11.65 varranty.	
Truck has no power Invoice Number Vehicle Details Work Descriptio Labor Air Bag light on	K7847 CAR16 PA DC nChecked air	DGE RAM bag codes Date	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016	-50-RP az Mileage codes with our Parts	25556 r scanner. Vech	icle is still under v	11.65 varranty. Qty	
Truck has no power Invoice Number Vehicle Details Work Descriptio Labor Air Bag light on Invoice Number Vehicle Details	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC	DGE RAN bag codes Date DGE RAN	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016	-50-RP az Mileage codes with our Parts Mileage	25556 r scanner. Vech	icle is still under v	11.65 varranty. Qty	
Truck has no power Invoice Number Vehicle Details Work Descriptio Labor Air Bag light on Invoice Number Vehicle Details	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached o	DGE RAN bag codes Date DGE RAN	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015	-50-RP az Mileage codes with our Parts Mileage	25556 r scanner. Vech	icle is still under v	11.65 varranty. Qty	
Truck has no power Invoice Number Vehicle Details Work Description Labor Air Bag light on Invoice Number Vehicle Details Work Description Labor	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached o	DGE RAN bag code: Date DGE RAN camera m	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015 sount and camera Value	-50-RP az Mileage codes with our Parts Mileage to windshield Parts CNV81840	25556 r scanner. Vech 24511	icle is still under v	11.65 varranty. Qty 23.12 Qty	Value
Truck has no power Invoice Number Vehicle Details Work Descriptio Labor Air Bag light on Invoice Number Vehicle Details Work Descriptio Labor camera mount came Invoice Number	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached of off windshield K7729	DGE RAW bag code: Date DGE RAW camera m	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015 sount and camera Value 17.47 9/26/2016	-50-RP az Mileage codes with our Parts Mileage to windshield Parts CNV81840 az	25556 r scanner. Vech 24511 adhesive	icle is still under v Job Value	11.65 varranty. Qty 23.12 Qty 1	Value
Truck has no power Invoice Number Vehicle Details Work Descriptio Labor Air Bag light on Invoice Number Vehicle Details Work Descriptio Labor camera mount came Invoice Number Vehicle Details	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached o off windshield K7729 CAR16 PA DC	DGE RAW bag code: DGE RAW camera m DGE RAW	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015 sount and camera Value 17.47 9/26/2016	-50-RP az Mileage codes with our Parts Mileage to windshield Parts CNV81840 az Mileage	25556 r scanner. Vech 24511 adhesive 22659	icle is still under v Job Value Job Value	11.65 varranty. Qty 23.12 Qty 1	Value
Truck has no power Invoice Number Vehicle Details Work Descriptio Labor Air Bag light on Invoice Number Vehicle Details Work Descriptio Labor camera mount came Invoice Number Vehicle Details	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached o off windshield K7729 CAR16 PA DC n Lube Oil Filto	DGE RAW bag code: DGE RAW camera m DGE RAW	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015 nount and camera Value 17.47 9/26/2016 1500 2015	-50-RP az Mileage codes with our Parts Mileage to windshield Parts CNV81840 az Mileage Lights wipers Parts	25556 r scanner. Vech 24511 adhesive 22659 and over all saf	icle is still under v Job Value Job Value	11.65 varranty. Qty 23.12 Qty 1	Value
Truck has no power Invoice Number Vehicle Details Work Description Labor Air Bag light on Invoice Number Vehicle Details Work Description Labor camera mount came Invoice Number Vehicle Details Work Description Labor Service	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached o off windshield K7729 CAR16 PA DC n Lube Oil Filto	DGE RAW bag code: DGE RAW camera m DGE RAW	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015 nount and camera Value 17.47 9/26/2016 1500 2015 ed checked Brakes Value 29.12	-50-RP az Mileage codes with our Parts Mileage to windshield Parts CNV81840 az Mileage Lights wipers Parts CNVWWFliu	25556 r scanner. Vech 24511 adhesive 22659	icle is still under v Job Value Job Value	11.65 varranty. Qty 23.12 Qty 1 73.44	Value Value 5.65
Truck has no power Invoice Number Vehicle Details Work Description Labor Air Bag light on Invoice Number Vehicle Details Work Description Labor camera mount came Invoice Number Vehicle Details Work Description Labor	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached o off windshield K7729 CAR16 PA DC n Lube Oil Filto	DGE RAW bag code: DGE RAW camera m DGE RAW	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015 nount and camera Value 17.47 9/26/2016 1500 2015 ed checked Brakes Value	-50-RP az Mileage codes with our Parts Mileage to windshield Parts CNV81840 az Mileage Lights wipers Parts CNVWWFliu d CNV5w-30	25556 r scanner. Vech 24511 adhesive 22659 and over all saf	icle is still under v Job Value Job Value	11.65 varranty. Qty 23.12 Qty 1 73.44	Value Value 5.65
Truck has no power Invoice Number Vehicle Details Work Description Labor Air Bag light on Invoice Number Vehicle Details Work Description Labor camera mount came Invoice Number Vehicle Details Work Description Labor Service	K7847 CAR16 PA DC n Checked air K7808 CAR16 PA DC n Reattached o off windshield K7729 CAR16 PA DC n Lube Oil Filto	DGE RAW bag code: DGE RAW camera m DGE RAW	11/21/2016 1500 2015 scan not read the Value 11.65 11/1/2016 1500 2015 nount and camera Value 17.47 9/26/2016 1500 2015 ed checked Brakes Value 29.12	-50-RP az Mileage codes with our Parts Mileage to windshield Parts CNV81840 az Mileage Lights wipers Parts CNVWWFliu	25556 c scanner. Vech 24511 adhesive 22659 and over all saf Windshield Wash Oil	icle is still under v Job Value Job Value	11.65 varranty. Qty 23.12 23.12 1 73.44 Qty 1	Value 5.65 Value 1.15

	K7448	Date	5/26/2016	5	Mileage	17570	Job Value	69.82	
Vehicle Details	CAR16 PA DC	DGE RAN	1500 2015	i					
Work Description		er Chang	ed						
	NULL								
Labor			•	Value	Parts			Qty	Value
Service				9.47	CNVWWFliu d	Windshield Washe	er Fluid	1	1.15
Rotate Tires			23	3.58	CNV5w-30	Oil		7	10.43
					Petro CNVPH1006	Oil Filter		1	3.19
					0 BC				
Invoice Number	K7370	Date	4/19/2016	5	Mileage	15517	Job Value	60.41	
Vehicle Details	CAR16 PA DC	DGE RAM	1500 2015	j					
Work Description	n NULL NULL NULL								
Labor			,	Value	Parts			Qty	Value
State Inspection			35	5.36					
State Emissions Insp	pection		23	3.58					
Emissions Phone Tra	ansaction Fee		1.	.47					
Invoice Number	K7167	Date	1/20/2016	5	Mileage	11641	Job Value	46.13	
Vehicle Details	CAR16 PA DC	DGE RAN	1500 2015	5					
Work Description	n Lube Oil Filte	er Chang	ed						
Labor			,	Value	Parts			Qty	Value
Service			29	9.47	CNVWWFliu d	Windshield Washe	er Fluid	1	1.15
					CNV5w-30	Oil		7	10.43
					Petro CNVPH1006	Oil Filter		1	3.08
					Petro CNVPH1006 0 BC	Oil Filter		1	3.08
Invoice Number	K6936	Date	10/12/201	15	CNVPH1006	Oil Filter 5664	Job Value	1 21.43	3.08
Invoice Number Vehicle Details	K6936 CAR16 PA DC			-	CNVPH1006 0 BC		Job Value		3.08
Vehicle Details	CAR16 PA DC	DGE RAN ver point	1500 2015 found no p	power. Re	CNVPH1006 0 BC Mileage emoved cente	5664	Job Value s to get to fuse b	21.43	3.08
Vehicle Details	CAR16 PA DC n Checked pow	DGE RAN ver point	A 1500 2015 , found no p d fuse and r	power. Re	CNVPH1006 0 BC Mileage emoved cente	5664		21.43	3.08
Vehicle Details Work Description	CAR16 PA DC Checked pow underneath.	DGE RAN ver point	1500 2015 found no p fuse and r	power. Re reassemb	CNVPH1006 0 BC Mileage emoved cente led. Parts	5664		21.43 ox	
Vehicle Details Work Description Labor	CAR16 PA DC n Checked pow underneath. ot working	DGE RAM ver point Replaced	1500 2015 found no p fuse and r	power. Re reassemb Value 1.08	CNVPH1006 0 BC Mileage emoved cente led. Parts	5664 er console piece		21.43 ox Qty	Value
Vehicle Details Work Description Labor Check power point n	CAR16 PA DC n Checked pow underneath. ot working	DGE RAN ver point Replaced Date	A 1500 2015 found no p fuse and r 2 ⁻ 10/2/2015	power. Re reassemb Value 1.08	CNVPH1006 0 BC Mileage emoved cente led. Parts CNV222222	5664 er console piece 15 Amp Fuse	es to get to fuse b	21.43 ox Qty 1	Value
Vehicle Details Work Description Labor Check power point n Invoice Number	CAR16 PA DC n Checked pow underneath. ot working K6913 CAR16 PA DC	DGE RAA ver point Replaced Date	A 1500 2015 found no p fuse and r 2 10/2/2015 A 1500 2015	power. Re reassemb Value 1.08	CNVPH1006 0 BC Mileage emoved cente led. Parts CNV222222	5664 er console piece 15 Amp Fuse	es to get to fuse b	21.43 ox Qty 1	Value
Vehicle Details Work Description Labor Check power point n Invoice Number Vehicle Details	CAR16 PA DC n Checked pow underneath. ot working K6913 CAR16 PA DC n Lube Oil Filto	DGE RAA ver point Replaced Date	A 1500 2015 found no p d fuse and r 2 ⁻ 10/2/2015 A 1500 2015 ed	power. Re reassemb Value 1.08	CNVPH1006 0 BC Mileage emoved cente led. Parts CNV222222	5664 er console piece 15 Amp Fuse	es to get to fuse b	21.43 ox Qty 1 65.01	Value
Vehicle Details Work Description Labor Check power point no Invoice Number Vehicle Details Work Description	CAR16 PA DC n Checked pow underneath. ot working K6913 CAR16 PA DC n Lube Oil Filto	DGE RAA ver point Replaced Date	A 1500 2015 found no p fuse and r 2 ⁻¹ 10/2/2015 A 1500 2015 ed	power. Re reassemb Value 1.08	CNVPH1006 0 BC Mileage emoved cente led. Parts CNV222222 Mileage Parts CNVWWFliu	5664 er console piece 15 Amp Fuse	es to get to fuse b Job Value	21.43 ox Qty 1	Value 0.35
Vehicle Details Work Description Labor Check power point n Invoice Number Vehicle Details Work Description Labor	CAR16 PA DC n Checked pow underneath. ot working K6913 CAR16 PA DC n Lube Oil Filto	DGE RAA ver point Replaced Date	A 1500 2015 found no p fuse and r 2 10/2/2015 A 1500 2015 ed	power. Re reassemb Value 1.08	CNVPH1006 0 BC Mileage emoved cente led. Parts CNV222222 Mileage Parts	5664 er console piece 15 Amp Fuse 5269	es to get to fuse b Job Value	21.43 ox Qty 1 65.01 Qty	Value 0.35 Value