

Work Order# 81024	Technician: Euan	Start Date: 9/19/25	Mileage In: 33401 Mileage Out:
Front Fairing			
INNER Fairing brackets.			
Front Tire / Rear tire			
Engine guard (chrome) cracked Lower RH mount.			
Front LH blue passing lamp.			
Front Fender w/ Lower trim			
Viffy stand w/ spring			
outer primary cover			
Fuel tank?			
LH Rear Floorboard standoff / RH Rear standoff.			
LH Floorboard. / RH Floorboard			
Exhaust crossover heatshield			
LH / RH Bag guards			
FH / LH Rear slip on mufflers.			
All heatshields for complete system			
Saddlebags Top/bottoms.			
RH Accessory BAG ON bag guards.			
* FRAME / Rear master cyl / motor mount mounting			
Completion Date:		Technician Signature:	
9/19/25.		Euan Mayhew	

Subframe off center look at Rear tire alignment ~~blurred~~
 Incorrect R. caliper mount BOTH. P. PADS 25%. R. Fluid 1%.
 Fluid discolored
 F. PADS 10%. Rusty PADS / stuck on Rotors used. Force to
 Remove. Front Rotors discolored. F. Fluid 4%. Fluid level low