Work History Report

Date Produced: 9/24/2024
Account: 6 Emergency Preparedness
Reg: MG0496F PA
Vehicle Details WELLS CARGO TRAILER -SPILL TRAILER S. 2012
White

Cumberland County Courthouse
310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num ENCLOSED 7K LBS. / **Vin** 1WF200F23C8087416 **Mileage** 0

Invoice Number I002633 **Date** 7/27/2023 **Mileage** 0 **Job Value** 31.05
Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Labor	Value	Parts		Qty	Value
State Inspection	31.05				

Invoice Number I001955 **Date** 7/21/2022 **Mileage** 0 **Job Value** 32.15
Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Labor	Value	Parts		Qty	Value
State Inspection	30.15				

Invoice Number I001272 **Date** 7/8/2021 **Mileage** 0 **Job Value** 105.82
Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Labor	Value	Parts		Qty	Value
Pick up trailer connector from Lowes. Connector was drug on the ground and wore through. Remove old connector and wire in new plug	55.22	CNV184566	Reese 7Way Trailer Connector	1	9.48
State Inspection	27.61				
PM Service check lights,brakes and overall safety of trailer. Greased wheel bearings and door hinges.	11.51				

Invoice Number K10730 **Date** 6/25/2020 **Mileage** 0 **Job Value** 45.09
Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012
Work Description State Inspection
Checked tire pressures and greased wheel bearings on trailer.

Labor	Value	Parts		Qty	Value
State inspection	31.83				
check air pressure and grease wheel bearings	13.26				

Invoice Number K10003 **Date** 6/26/2019 **Mileage** 0 **Job Value** 118.99
Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012
Work Description Checked tire pressures and greased wheel bearings on trailer.
State Inspection
Mounted 4 new tires.

Labor	Value	Parts		Qty	Value
check air pressure and grease wheel bearings	13.81	CNV17-413-50 az	Valve Stem 1.25 Rubber	4	0.96
State inspection	33.15	CNV222222	Tire- Already paid for by OEP	4	0.00
Replace tires	69.06				

Invoice Number K9171 **Date** 6/27/2018 **Mileage** 0 **Job Value** 47.77

Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Work Description Checked tire pressures and greased wheel bearings on trailer.
State Inspection

Labor	Value	Parts		Qty	Value
check air pressure and grease wheel bearings	14.05				
State inspection	33.72				

Invoice Number K8298 **Date** 6/26/2017 **Mileage** 0 **Job Value** 49.06

Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Work Description State Inspection
Checked tire pressures and greased wheel bearings on trailer.

Labor	Value	Parts		Qty	Value
State inspection	34.63				
check air pressure and grease wheel bearings	14.43				

Invoice Number K7463 **Date** 6/3/2016 **Mileage** 0 **Job Value** 185.42

Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Work Description NULL
Checked trailer brakes and found wiring cut to both left side brakes. Ran new wiring and wired into both left side brakes.

Labor	Value	Parts		Qty	Value
State Inspection	34.94	CNV85244 AZ	Butt Connectors (Red Shrink Wrap)	8	2.88
Trailer brakes do not work	145.60				

Invoice Number K7462 **Date** 6/1/2016 **Mileage** 0 **Job Value** 185.84

Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Work Description NULL
Checked trailer brakes and found wiring cut to both left side brakes. Ran new wiring and wired into both left side brakes.

Labor	Value	Parts		Qty	Value
State Inspection	35.36	CNV85244 AZ	Butt Connectors (Red Shrink Wrap)	8	2.88
trailer brakes do not work	145.60				

Invoice Number K6586 **Date** 5/20/2015 **Mileage** 0 **Job Value** 42.16

Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Work Description NULL
Checked tire pressures and greased wheel bearings on trailer.

Labor	Value	Parts		Qty	Value
State Inspection	31.62				
check air pressure and grease wheel bearings	10.54				

Invoice Number K5747 **Date** 5/6/2014 **Mileage** 0 **Job Value** 56.96

Vehicle Details MG0496F PA WELLS CARGO TRAILER -SPILL TRAILER 2012

Work Description NULL
Checked tire pressures and greased wheel bearings on trailer.
Drilled out and replaced ground screw to light.

Labor	Value	Parts		Qty	Value
State Inspection	25.31				
check air pressure and grease wheel bearings	10.55				
rear center clearance light out	21.10				