

Work History Report

Cumberland County
Courthouse

Date Produced: 8/29/2024
Account: 27 Juvenile Probation
Reg: JUV11 PA
Vehicle Details Dodge Charger 3.5 2009

310 Allen Road
Suite 501
Carlisle
PA
17013-3323

Eng Code / Num 4808 / Vin 2B3KK43V49H578792 Mileage 116209

Invoice Number I003066 Date 3/7/2024 Mileage 116209 Job Value 95.06

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
P2096-DOWNSTREAM FUEL TRIM SYSTEM 1 LEAN. Found downstream O2S not functioning properly, replaced and test drove vehicle with no issues	55.15	CNV15510 Oxygen Sensor	1	37.91

Invoice Number I003051 Date 2/28/2024 Mileage 115948 Job Value 1297.80

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
State Inspection	33.09	CNVEMI Emissions, Phone Transaction Fee	1	1.57
State Emission Inspection	27.58	CNV333333 Wheel Weights	8	8.00
Tires worn on edges, pick up 4 tires as highlands. Mounted and balanced 4 tires	110.30	CNV407795 225/60/18 Goodyear Assurance 374	4	413.28
LF outer tie rod end has excessive play, install new tie rod end	33.09	CNVTIRE TIRE DISPOSAL FEE DISPOSAL	4	20.00
C2205 Steering angle sensor internal, B1BO2 Driver air bag squib open, code stored in ABS module. Reached out to dealers to find that part is no longer available, from my knowledge most SAS are in a clock spring. Asked dealer if this sensor was possibly integrated into the clock spring as an update. Dealer was unable to verify this. Made Dennis aware that replacing clock spring may not repair the issue. Removed air bag and clock spring, found new clock spring did not have SAS integrated into it. Installed new clock spring and reset. Air bag code still stored, believe issue will still occur. No issues to use vehicle.	165.45	CNVES8004 LF Outer Tie Rod End 31	1	45.99
		CNV680348 Clock Spring 98AB	1	317.50
		CNVINV 4 Wheel Alignment From Carlisle 79307 Cadillac INV#79307	1	119.95

Invoice Number I002986 Date 1/24/2024 Mileage 115117 Job Value 17.03

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
Replaced wiper blades.	11.03	CNVDL22 / az Wiper Blade	2	6.00

Invoice Number I002826 Date 10/31/2023 Mileage 114004 Job Value 99.00

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	31.05	CNV85372 Oil Filter advance	1	2.62
Shop Labor- Cumberland County. Replaced air and cabin air filters.	31.05	CNVWWFlu Windshield Washer Fluid d Clearv	1	1.32
		CNV75-053 5W30 Oil syn blend	6	15.30
		CNV89909 Cabin Filter	1	8.74
		CNV87843 Air Filter	1	6.92

Invoice Number I002762 Date 9/27/2023 Mileage 112954 Job Value 33.05

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
Test drove vehicle, could hear a dragging noise at times. Found splash guard underneath had come down, reattached shield and checked over vehicle. No other issues found	31.05			

Invoice Number I002699 Date 8/28/2023 Mileage 112388 Job Value 312.33

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
Found brake reservoir empty, found brake lines at LF of vehicle rubbed through on plastic hanger. Removed 2 main brake lines and LF brake line to ABS module. Made 3 new lines and bled system. Verified no leaks and test drove vehicle.	258.75	CNVAB32 AZ Brake Fluid	2	9.98
		CNVCNC-3 25 AZ 316 CopperNickel Brake Line Per FT	8	9.60
		CNVCNC52 5 5/16 Copper Brake Line	8	18.24
		CNVCNC42 4 1/4 Copper Brake Line	8	13.76

Invoice Number I002647 Date 8/3/2023 Mileage 112086 Job Value 558.88

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
Code C2200 Brake Module Internal. ABS module faulty, R&R ABS module, recalibrate steering angle sensor and program module to vehicle. Test drove vehicle no further issues	129.38	CNV680483 05AC ANTI LOCK BRAKE MODULE	1	427.50

Invoice Number I002436 Date 4/10/2023 Mileage 110355 Job Value 270.69

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
State Emission Inspection	25.88	CNVEMI Emissions, Phone Transaction Fee	1	1.57
State Inspection	31.05	CNV3157 Light Bulb	1	0.99
Rotate Tires	15.53	CNV10834N CV Axle Shaft-Duralast Gold	1	84.99
Shop Labor- Cumberland County. Replaced left rear outer brake light bulb.	15.53			
Shop Labor- Cumberland County. Right front axle c/v boots are torn. Replaced right front axle shaft assembly.	93.15			

Invoice Number I002226 Date 12/20/2022 Mileage 108738 Job Value 62.32

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	30.15	CNV85372 advance Oil Filter	1	3.95
		CNV5w-30 PPC Oil	6	25.02
		CNVWWFluid Clearv Windshield Washer Fluid	1	1.20

Invoice Number I001763 Date 4/6/2022 Mileage 103316 Job Value 333.61

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	30.15	CNV85372 advance Oil Filter	1	3.14
Rotate Tires	15.08	CNV5w-30 PPC Oil	6	11.94
State Inspection	30.15	CNVWWFluid Clearv Windshield Washer Fluid	1	1.20
State Emission Inspection	25.13			
Rear brake rotors rusted over on inside, R&R Rear brake pads and rotors. Cleaned caliper brackets and lubricated slider pins	75.38	CNVEMI Emissions, Phone Transaction Fee	1	1.57
		CNVGNAD1 057 Rear Brake Pads	1	29.99
		CNVYH1455 69P Rear Brake Rotor	2	107.88

Invoice Number I001416 Date 9/23/2021 Mileage 102097 Job Value 84.87

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
Low tire light was on, found LF,RF and LR tires low. Checked tires for leaks, the valve stem assembly on all 3 tires were leaking. Dismounted outward tire bead and removed all 3 valve stems and thoroughly cleaned around seating area for valve stem. Installed new valve stem assembly and gasket, verified that there were no more leaks at valve stems	69.03	CNVTPM20 TPMS Valve Kit 14VK	3	15.84

Invoice Number I001175 Date 5/14/2021 Mileage 100717 Job Value 167.14

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
Jump start vehicle, check battery and charging system. Battery was dead, replaced battery and cleaned all connections.	27.61	CNV94R-77 East Penn Battery 5	1	137.53

Invoice Number I001081 Date 3/25/2021 Mileage 100716 Job Value 238.61

Vehicle Details JUV11 PA Dodge Charger 2009

Labor	Value	Parts	Qty	Value
PM Service check lights,brake and overall safety of vehicle	27.61	CNV85372 Oil Filter advance	1	3.14
State Inspection	27.61	CNV5w-30 Oil PPC	6	12.90
State Emission Inspection	23.01	CNVWWFlu Windshield Washer Fluid d Clearv	1	1.15
Left front axle shaft boot torn, throwing grease. Removed axle shaft cleaned all grease off and installed new axle shaft	73.63	CNVEMI Emissions, Phone Transaction Fee CNV10833N DLG New CV Axle Shaft	1	1.57
			1	65.99

Invoice Number K10608 Date 4/27/2020 Mileage 100035 Job Value 273.42

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description NULL
NULL
State Inspection
NULL
Replaced wiper blades
Replaced front brakes and rotors

Labor	Value	Parts	Qty	Value
State Emissions Inspection	21.22	CNVDL22 Wiper Blade az	2	6.00
Emissions Phone Transaction Fee	1.57	CNVP1056 Pad Installation kit az	1	3.52
State inspection	31.83	CNVVG105 Brake Pads 8az	1	31.12
Rotate Tires	10.61	CNV43087D Brake RotorDisc G az	2	75.36
replace wiper blades	10.61			
Replace front brakes and rotors	79.58			

Invoice Number K10459 Date 1/29/2020 Mileage 98986 Job Value 16.92

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description plugged hole in left rear tire

Labor	Value	Parts	Qty	Value
plug tire	15.92	CNV710-10 tire plug 36 Napa	1	1.00

Invoice Number K10265 Date 10/30/2019 Mileage 96942 Job Value 45.89

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Labor	Value	Parts	Qty	Value
Service	27.63	CNVWWFlu Windshield Washer Fluid d	1	1.15
		CNV5w-30 Oil Petro	6	12.42

Invoice Number	K9742	Date	3/8/2019	Mileage	92170	Job Value	137.08
Vehicle Details	JUV11 PA DODGE CHARGER 2009						
Work Description	Lube Oil Filter Changed checked Brakes Lights wipers and over all safety. NULL NULL NULL State Inspection Replaced wiper blades						
Labor	Value	Parts	Qty	Value			
Service	27.63	CNVWWFlu d	1	1.15	Windshield Washer Fluid		
Rotate Tires	16.58	CNV5w-30 Petro	6	12.24	Oil		
State Emissions Inspection	22.10	CNVPH2 BC	1	3.54	Oil Filter		
Emissions Phone Transaction Fee	1.65	CNVDL22 az	2	6.00	Wiper Blade		
State inspection	33.15						
replace wiper blades	11.05						

Invoice Number	K9435	Date	10/30/2018	Mileage	89763	Job Value	110.67
Vehicle Details	JUV11 PA DODGE CHARGER 2009						
Work Description	Diagnose Trouble codes. Run tests to determine problems. Code p0132 oxygen sensor is bad. Replaced oxygen sensor bank 1 sensor 1 on passenger side. Cleared code and test drove.						
Labor	Value	Parts	Qty	Value			
Check Engine Light on	78.68	CNV15510 az	1	29.99	Oxygen Sensor		

Invoice Number	K9309	Date	8/31/2018	Mileage	87605	Job Value	45.89
Vehicle Details	JUV11 PA DODGE CHARGER 2009						
Work Description	Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.						
Labor	Value	Parts	Qty	Value			
Service	28.10	CNVWWFlu d	1	1.15	Windshield Washer Fluid		
		CNV5w-30 Petro	6	11.10	Oil		
		CNVPH2 BC	1	3.54	Oil Filter		

Invoice Number	K9030	Date	4/27/2018	Mileage	83970	Job Value	28.10
Vehicle Details	JUV11 PA DODGE CHARGER 2009						
Work Description	Checked for noise. Removed left front wheel to locate noise. Found a stone jammed in backing plate. Removed stone from left front brake backing plate.						
Labor	Value	Parts	Qty	Value			
Loud screeching noise when the car is moving	28.10						

Invoice Number	K8971	Date	4/2/2018	Mileage	83855	Job Value	85.95
Vehicle Details	JUV11 PA DODGE CHARGER 2009						
Work Description	NULL NULL State Inspection Checked right rear tire for leaks. Found tire leaking around valve stem. Removed tire from rim and tire pressure sensor. Put sealer around valve stem seal to rim. Installed tire and rebalance.						
Labor	Value	Parts	Qty	Value			
State Emissions Inspection	22.48						
Emissions Phone Transaction Fee	1.65						
State inspection	33.72						
Right rear tire is low	28.10						

Invoice Number K8528 Date 9/20/2017 Mileage 83107 Job Value 915.33

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Checked tire. TPMS sensor was broken. Replaced TPMS sensor. Tires were worn out. Replaced all 4 tires. Picked up tires at Highland Tires. Replaced valve stems in TPMS sensors and replaced sensor caps and seals. Had to chisel off lug nuts that were rounde

Labor	Value	Parts	Qty	Value
Check Flat tire	288.60	CNV333333 Wheel Weights	8	4.00
		CNV97709 2256018 Tiger Paw Touring Highlands	4	464.04
		CNV28291 TPMS Sensor AZ	1	54.80
		CNV920210 TPMS Sensor CapsSeals Napa	3	10.86
		CNV20020 Sensor Stem AZ	1	2.16
		CNV9066K TPMS Sensor Stem ADV	1	6.99
		CNV20016 TPMS Sensor CapSeal AZ	1	1.88
		CNV611-25 Lug Nuts 8 Az	20	80.00

Invoice Number K7897 Date 12/14/2016 Mileage 81057 Job Value 104.57

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description State Inspection
NULL
NULL
Lube Oil Filter Changed checked Brakes Lights wipers and over all safety.

Labor	Value	Parts	Qty	Value
State inspection	34.94	CNVWWFlu Windshield Washer Fluid	1	1.15
State Emissions Inspection	23.30	CNV5w-30 Oil	6	8.94
Emissions Phone Transaction Fee	1.65	Petro		
Service	29.12	CNVPH2 Oil Filter BC	1	3.47

Invoice Number K7425 Date 5/16/2016 Mileage 79589 Job Value 359.63

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Replaced gas tank due to running over debris and puncturing tank. Removed drive shaft and exhaust pipe to get fuel tank down. Switched over vents and pumps. Reinstalled tank. Reinstalled drive shaft and exhaust system.

Labor	Value	Parts	Qty	Value
Gas Tank	353.64	CNV680518 Gas tank PO 155506 91AB Shively	1	0.00
		CNV22222 PB Blaster	1	3.99

Invoice Number K7243 Date 2/24/2016 Mileage 76833 Job Value 29.47

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Test drove and could not find anything wrong with steering. Checked fluids and all fluids were at proper level. Test drove Adult Probation 10 to compare and both vehicles drove the same.

Labor	Value	Parts	Qty	Value
Check power steering.	29.47			

Invoice Number K7153 Date 1/13/2016 Mileage 76094 Job Value 156.59

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed

NULL
NULL
NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	29.47	CNVWWFlu Windshield Washer Fluid	1	1.15
Rotate Tires	23.58	d CNV5w-30 Oil	6	8.94
State Emissions Inspection	23.58	Petro		
Emissions Phone Transaction Fee	1.47	CNVPH2 Oil Filter	1	3.36
State Inspection	35.36	BC		
Replace blades	11.79	CNV890010 Wiper Blade 22 inch	2	15.90
		16 Graham		

Invoice Number K6693 Date 7/9/2015 Mileage 69460 Job Value 250.85

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed

NULL
Checked for codes in all systems. Has abs code c102b. Diagnosed code and found a faulty wheel speed sensor. Replaced right rear wheel speed sensor and cleared code.
Replaced rear brakes

Labor	Value	Parts	Qty	Value
Service	26.35	CNVWWFlu Windshield Washer Fluid	1	1.15
Rotate Tires	13.18	d CNV5w-30 Oil	6	8.94
ABS ESP and T CASE lights are on	79.05	Petro		
replace rear brakes	52.70	CNVPH2 Oil Filter	1	3.20
		BC		
		CNVSU8479 abs sensor	1	17.28
		az		
		CNV DGC10 Brake Pads	1	45.00
		57 az		

Invoice Number K6262 Date 12/30/2014 Mileage 64010 Job Value 84.26

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed

NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	25.31	CNVWWFlu Windshield Washer Fluid	1	1.15
State Emissions Inspection	16.88	d CNV5w-30 Oil	6	8.94
Emissions Phone Transaction Fee	1.47	Petro		
State Inspection	25.31	CNVPH2 Oil Filter	1	3.20
		BC		

Invoice Number K5787 Date 5/21/2014 Mileage 61773 Job Value 31.64

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Road tested car on 81 to Newville and back. Tested hard braking coming off ramps. No Vibrations found. Could not duplicate problem.

Labor	Value	Parts	Qty	Value
Check for vibration when braking and driving.	31.64			

Invoice Number K5443 Date 12/10/2013 Mileage 60264 Job Value 46.55

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description NULL
NULL
NULL

Labor	Value	Parts	Qty	Value
State Emissions Inspection	18.03			
Emissions Phone Transaction Fee	1.47			
State Inspection	27.05			

Invoice Number K5318 Date 9/24/2013 Mileage 60053 Job Value 89.06

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
Test drove for vibration. Checked tires found a wheel weight fell off rt. front tire. Balanced and rotated tires.

Labor	Value	Parts	Qty	Value
Service	27.05	CNVWWFlu d	1	0.99
vibration in steering wheel	45.08	CNV5w-30 Oil Petro CNVPH2 BC	6 1	10.74 3.20

Invoice Number K5319 Date 9/24/2013 Mileage 60053 Job Value 27.27

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description NULL

Labor	Value	Parts	Qty	Value
Replace blades	11.27	CNVCWP22 -51-CQ	2	16.00

Invoice Number K4902 Date 3/13/2013 Mileage 57132 Job Value 170.88

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Test drove and verified vibration. Removed front wheels and found brake rotors slightly warped. Replaced front brakes rotors.

Labor	Value	Parts	Qty	Value
Check brakes. Vibrating when applied	67.62	CNV43087 AZ	2	71.52
		CNVVG105 8 AZ	1	29.74

Invoice Number K4702 Date 11/16/2012 Mileage 55302 Job Value 97.15

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description NULL
NULL
NULL
Replaced right front marker light bulb
balanced all 4 tires and rotated tires

Labor	Value	Parts	Qty	Value
State Emissions Inspection	16.24	CNV194 CQ	1	0.30
Emissions Phone Transaction Fee	1.47			
State Inspection	24.36			
marker light out	12.18			
front end shakes at speed	40.60			

Invoice Number K4429 Date 7/12/2012 Mileage 53824 Job Value 86.37

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
Replaced air filter and cabin air filter

Labor	Value	Parts	Qty	Value
Service	19.87	CNVPH2 Oil Filter	1	2.50
Replace air filter cabin air filter	9.93	CNVWWFlu Windshield Washer Fluid	1	0.99
		CNV10w-30 Oil	6	21.95
		AZ		
		CNVCAF18 Cabin Air Filter	1	19.95
		05C AZ		
		CNVSA9838 Air Filter	1	9.19
		AZ		

Invoice Number K4144 Date 1/25/2012 Mileage 51041 Job Value 95.91

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
NULL
Emissions Inspection
NULL
NULL

Labor	Value	Parts	Qty	Value
Service	19.87	CNVPH2 Oil Filter	1	2.50
Rotate Tires	13.24	CNVWWFlu Windshield Washer Fluid	1	0.99
State Inspection	19.87	CNV5w-20 Oil	6	9.12
Emissions Inspection	13.24	PPC		
Emissions Phone Transaction Fee	2.40	CNV3157 Light Bulb	2	2.40
Replace Brake light bulb	8.28			

Invoice Number K3841 Date 8/22/2011 Mileage 48484 Job Value 50.77

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
check over for werid smell looked over and test drove could not find nothing wrong

Labor	Value	Parts	Qty	Value
Service	18.08	CNVPH2 Oil Filter	1	2.50
check over for werid smell looked over and test drove could not find nothing wrong	18.08	CNVWWFlu Windshield Washer Fluid	1	0.99
		CNV5w-20 Oil	6	9.12
		PPC		

Invoice Number K3578 Date 4/15/2011 Mileage 42539 Job Value 39.35

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed

Labor	Value	Parts	Qty	Value
Service	18.08	CNVPH2 Oil Filter	1	2.50
		CNVWWFlu Windshield Washer Fluid	1	0.99
		CNV10w-30 Oil	6	15.78
		AZ		

Invoice Number K3399 Date 12/29/2010 Mileage 36651 Job Value 105.73

Vehicle Details JUV11 PA DODGE CHARGER 2009

Work Description Lube Oil Filter Changed
NULL
NULL
NULL

Labor	Value
Service	19.42

State Inspection	29.13	d				
Emissions Inspection	15.00	CNV5w-20	Oil		6	7.56
Take Vehicle to Middlesex Township to have Emissions Inspection Done	29.13	PPC				