

VEHICLE CONDITION REPORT

Truck Number: n/a
Date Inspected: No inspection
Make/Model/Year: Caterpillar 926 Wheel Loader
VIN#: 94ZO1523
Mileage: 11,024.8 Hours

Interior Condition: Bad
Exterior Condition: Bad
Tires: Bad
Does it start? No
Is it drivable off the lot? No
Is it currently inspected? N/A
Body Style: Wheel loader
Engine Type: Diesel
Transmission Condition: Fair

SELLING VEHICLE AS IS, NO RETURNS.









