**SELLER INFORMATION - Please type or print all information clearly** (If your info is same for all just fill out top of first report)

Name of Seller: Town of Amherst Dept: Engineering Dept. **FLEET #** E083

Item Location Address: 1100 North Forest Road

City: Williamsville State: New York Zipcode: 14221

Contact Name: William Burke Phone: ( 716 ) 631-7154 Fax: ( 716 ) 631-7222

**ITEM INFORMATION - Please type or print the item or vehicle information clearly -** Fill out only the parts appropriate for this item

Year: 2006 Make: Chevrolet Model: Silverado 2500 Body Style: Pickup Ext Cab

VIN / Serial: 1GCHC29U66E200761 Miles: 76746 Hours:

Engine Make/Model: 6.0L SFI VORTEC Cyl: 8 Gas ☒ Diesel ☐ Hybrid ☐ Electric ☐

Horsepower: Transmission: 4-SPEED W/OVERDRIVE AUTO ☒ MANU ☐ Single Axle ☒ Dual Axle ☐

Tire Type/Size: LT245/75R16E Good ☐ Fair ☒ Poor ☐ Plow or Attachment Type: N/A Dump Box Size: N/A

Features: 2WD ☒ 4WD ☐ A/C ☒ Does Unit Operate/Drive: YES ☒ NO ☐

## OVERALL CONDITION OF ITEM AND ADDITIONAL OWNERSHIP INFORMATION

| | | | |
|---|---|---|---|
| Body: | Good ☒ | Fair ☒ | Poor ☐ |
| Interior: | Good ☒ | Fair ☒ | Poor ☐ |
| Mechanical: | Good ☐ | Fair ☒ | Poor ☐ |

Does Vehicle Start: YES ☒ NO ☐ UNKNOWN ☐

Keys Available: YES ☒ NO ☐

Bill of Sale Only (No Title): ☐ Transferable Registration: ☐

Clean Title Available: ☒ Certificate of Origin Only: ☐

Please describe any overhauls or maintenance for your item in the box below. Items that have more complete descriptions receive higher bid prices. You should pressure wash your equipment, broom-clean vehicles, and wash the windows before taking digital photographs of your online auction merchandise

Mechanical Needs extensive brake work, including all new brake lines.
Engine - Transmission are good.
A/C works

Body : Some minor rust at the inside bottom of the doors. Minor surface rust on rear bumper.
Fuel cap cover rust.
Truck bed is spray lined.

Interior : Charcoal color vinyl seats, floor, and mats that are in fair to good condition.
Small vinyl cracks (no rips) in the drivers seat, and the edge of passenger seat.

☒ **ADDITIONAL INFO** Check the box if you provided more info on back of report or on attached sheets