

Vehicle Number 28

PAINT ~~FEET~~ 90 FORD cube VAN
 Mechanic service sheet.xls
 MG 3613D
 51515 OIL
 NOVEMBER

Date	Mileage	Service	Comment
1/5/06	88496	New license Plate BRACKET & PLATE	
		Fuel GA sending unit cut hole in Bed Floor	
		took off intake - new gasket - V. Cover gasket	
		All new VAC HOSES & SMALL INTAKE COOLING LINES	
		New MAP sensor + TPS sensor	
4/7/07	88847	Repaired R.R. Box Light	
10/2/08	90126	grease oil filter - R Front tie Rod End - Stabilizer Links -	
		Back up Alarms - installed 8 Red & 3 yellow Reflectors	
		Repaired DRIVES side window Hold Down - Adjusted DRIVER Side MIRROR (inspection)	
10/6/08	90126		
9/11/09	90592	PRIMARY line TO STARTER Solenoid IGN Switch	
9/2/09	90592	Repair turn Signal light wiring, LR Tail Light Assembly	
9/9/09	90592	NEW NEUTRAL - Back up light Switch - R Front tire	
9/10/09	90592	Clean & retape all Rear wiring - Firewall Junction Block is	
9/10/09	90592	all completed - new Cat Converter	
9/16/09		New MUFFLER - TRANS should be checked	
4/23/09		Stahley checked TRANS OK	
9/24/07	90610	CAT Converter Engine needs timing chain OR CAM & ALSO HEADS ARE LEAKING oil	
1st thru 20		HEAD GASKET	
4-11	91865	new engine Rings Bearings gaskets oil pump power steering hoses. motor mount	
2-6-12	92360	oil & Filter grease New Hose air Filter system Fix cab corner	
12-14-12	93229	new ALT Reg & Battery. oil & Filter. grease CHECK LIGHTS BRAKES	
4-2-13	93315	NEW ALT & Reg. Reg started out	
9-18-13	93780	new front brakes and callipers. New Front Shocks	
1-17-14	93911	oil & Filter. grease check brakes Top Fluids.	

495

*

