

Vehicle Inspection Form

Inventory ID: <u>940</u>	Asset Number: _____	Fair Market Value: _____																	
Short Description: Year <u>2001</u> Make <u>GMC</u> Model <u>VAN</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 200px;"> <tr><td>1</td><td>9</td><td>T</td><td>9</td><td>9</td><td>2</td><td>5</td><td>R</td><td>9</td><td>1</td><td>1</td><td>1</td><td>9</td><td>6</td><td>1</td><td>9</td><td>0</td></tr> </table>		1	9	T	9	9	2	5	R	9	1	1	1	9	6	1	9	0	Title Restriction: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N
1	9	T	9	9	2	5	R	9	1	1	1	9	6	1	9	0			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr><td>6</td><td>6</td><td>0</td><td>5</td><td>7</td></tr> </table>		6	6	0	5	7	<input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: _____												
6	6	0	5	7															

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: _____

This vehicle was maintained every 5000/6000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: Now **Maintenance Records:** ☐ Available ☒ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed **Condition:** ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive **Condition:** _____

Exterior: **Color:** Red **Windows:** ☐ No Cracked Glass ☐ Cracked _____

Minor: ☒ Dents ☒ Scratches ☒ Dings **Tire Condition:** _____ **Tread:** _____ **#Flat** _____ **Hubcaps #** _____

Major Damage to: _____

Additional Damage: _____

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: **Color** Black ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: TORN

Damage to Dash/Floor: _____

Radio: ☐ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC **Air Bags:** ☐ Driver's Side ☐ Dual

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: _____

Manufacturer _____ **Model** _____ **Serial #** _____

☐ Tool Box ☐ Light Bar ☒ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: SEWER UTILITY - 1139 EDWARDS RD

For more information contact: JOHN PIETROWSKI

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.